This document was too large to scan as a single document. It has been divided into smaller sections.

Section 1 of 3

Document Information							
Document #	Document # 0201741/02-RCA-0272 Revision						
Title	QUARTERLY NOTIFICATION OF CLASS 1 MODIFICATIONS TO THE HANFORD FACILITY RESOURCE CONSERVATION AND RECOVERY ACT (RCRA) PERMIT, DANGEROUS WASTE PORTION (QUARTER ENDING MARCH 31, 2002 - PERMIT CONDITION I.C.3)						
Date	04/09/2002						
Originator	J. HEBDON, R. H. GURSKE, R. D. (ROBY) EN	Originator Co.	DOE, FH, PNNL				
Recipient	L. E. RUUD	Recipient Co.	DOEC				
References			<u> </u>				
Keywords							
Projects							
Other Information							

ENVIRONMENTAL PORTAL DISTRIBUTION COVERSHEET

REGULATORY INFORMATION

Page 1 of 2

Author

Addressee

Correspondence No

J Hebdon/DOE

L E Ruud/DOEC

0201741

R H Gurske/FH

DOE RL 02 RCA 0272 CC Recd 04/15/2002

R D Enge/PNNL

Subject

QUARTERLY NOTIFICATION OF CLASS 1 MODIFICATIONS TO THE HANFORD FACILITY RESOURCE CONSERVATION AND RECOVERY ACT (RCRA) PERMIT DANGEROUS WASTE PORTION (QUARTER ENDING MARCH 31 2002 – PERMIT CONDITION I C 3)

DISTRIBUTION

Approval	Date	Name	Location	w/at
		Environmental Portal	A3 01	X
		Fluor Hanford		
		L E Borneman	T6 16	X
		R C Bowman	A1 14	X
		R C Brunke	N1 26	X
		S B Cherry	B3 15	X
		S B Clifford	N1 25	X
		K F Clouse	N1 25	X
		L M Culley	B 3 70	X
		N R Dahl	N2 57	X
		T T Daniels	B3 70	X
		L P Diediker	N1 24	X
		B J Dixon	R3 32	X
		R H Engelmann	N1 25	X
		R H Gurske	H8 73	X
		K A Hadley	T5 57	X
		J W Hales	A1 14	X
		J S Hertzel	A1 14	X
		J E Hyatt	N1 24	X
		L G Juguilon	H8 73	X
		C A Kooiker	N2 57	X
		A G Miskho	N1 26	X
		T W Noland	H8 67	X
		J K Perry	L1 04	X
		S M Price	H8 67	X
		F A Ruck III	N1 26	X
		A R Sherwood	N1 26	X

ENVIRONMENTAL PORTAL

For Questio s or D t but on/MSIN Cor ect

Co tact

376 8111 or 372 3931

A 6001 538S (02/98)

ENVIRONMENTAL PORTAL DISTRIBUTION COVERSHEET

REGULATORY INFORMATION

Page 2 of 2

Author

J Hebdon/DOE

R H Gurske/FH

Addressee

L E Ruud/DOEC

Correspondence No

0201741

DOE RL 02 RCA 0272 CC Recd 04/15/2002

R D Enge/PNNL

Subject

QUARTERLY NOTIFICATION OF CLASS 1 MODIFICATIONS TO THE HANFORD FACILITY RESOURCE CONSERVATION AND RECOVERY ACT (RCRA) PERMIT DANGEROUS WASTE PORTION (QUARTER ENDING MARCH 31 2002 – PERMIT CONDITION I C 3)

DISTRIBUTION

DISTRIBUTION					
Approval	Date	Name	Location	w/att	
		Fluor Hanford continued			
		S A Szendre	N1 26	X	
		S A Thompson	N1 25	X	
		D J Watson	X3 79	X	
		J F Williams Jr	N1 25	X	
		L F Willis	H8 73	X	
		Pacific Northwest National Laborator	y		
		S D Cooke (PNNL)	K1 67	X	
		R D Enge (PNNL)	P7 75	X	
		A K Ikenberry (PNNL)	P7 79	X	
		K A Poston (PNNL)	P7 79	X	
		Bechtel Hanford Inc			
		^BHI Document & Info Services		X	
		R J Landon (BHI)	H0 02	X	
		R H Wyer (BHI)	H0 09	X	
		U S Department of Energy, Richland	l Operations Of	fice	
		J J Bevelacqua	H6 60	X	
		J B Hall	A2 15	X	
		A P Larsen	A5 15	X	
		E M Mattlin	A5 15	X	
		A C McKarns	A5 15	X	
		H M Rodriguez	A5 15	X	
		S D Stubblebine	H6 60	X	
		B D Williamson	A4 52	X	



Department of Energy

Richland Operations Office P O Box 550 Richland Washington 99352

APR 09 2002

02 RCA 0272

Ms L E Ruud Permit Specialist Nuclear Waste Program State of Washington Department of Ecology 1315 West Fourth Avenue Kennewick Washington 99336

Dear Ms Ruud

QUARTERLY NOTIFICATION OF CLASS 1 MODIFICATIONS TO THE HANFORD FACILITY RESOURCE CONSERVATION AND RECOVERY ACT (RCRA) PERMIT DANGEROUS WASTE PORTION (QUARTER ENDING MARCH 31 2002–PERMIT CONDITION I C 3)

In accordance with Condition I C 3 of the Hanford Facility RCRA Permit enclosed for your notification are the Class 1 modifications to the Hanford Facility RCRA Permit DW Portion Modifications this quarter included updating information in the List of Attachments Part III and Part V of the RCRA Permit DW Portion The List of Attachments Class 1 modifications pertain to Attachment 4 The Part III Class 1 modifications pertain to the 305 B Storage Facility Liquid Effluent Retention Facility and 200 Area Effluent Treatment Facility 242 A Evaporator and 325 Hazardous Waste Treatment Units The Part V Class 1 modifications pertain to the 300 Area Waste Acid Treatment System The Class 1 modifications are being made to ensure that all activities conducted are in compliance with the RCRA Permit DW Portion

Should you have any questions regarding this information please contact Dee W Lloyd Regulatory Compliance and Analysis Division on (509) 372 2299

Joel Hebdon Director

Regulatory Compliance and

Analysis Division

DOE Richland Operations Office

Richard H Gurske Director Environment & Regulation

Fluor Hanford Inc

Roby D Enge Director

Environment Safety Health and Quality Pacific Northwest National Laboratory

Enclosure

cc w/encl

F W Bond Ecology

L J Cusack Ecology

R D Enge PNNL

R Gay CTUIR

R H Gurske FHI

A K Ikenberry PNNL

F Jamison Ecology

cc w/o encl

M Anderson Moore Ecology

R Jim YN

R J Landon BHI

M A Wilson Ecology

S A Thompson FHI

P Sobotta NPT

Administrative Record H6 08

HF Operating Record G1 27

Ecology NWP Kennewick Library

Environmental Portal LMSI



Department of Energy Richland Operations Office

DOCUMENT RECEIPT VERIFICATION

Document Title

02-RCA-0272

QUARTERLY NOTIFICATION OF CLASS 1 MODIFICATIONS TO THE HANFORD FACILITY RESOURCE CONSERVATION AND RECOVERY ACT (RCRA) PERMIT DANGEROUS WASTE PORTION (DW PORTION) (QUARTER ENDING MARCH 31 2002 PERMIT CONDITION I C 3)

Addressee

Ms Laura Ruud
Permit Specialist
Nuclear Waste Program
State of Washington
Department of Ecology
1315 West Fourth Avenue
Kennewick Washington 99336

RECEIVED

Date Received

APR 0 9 2002

Department of Ecology NWP Kennewick

Receiver Signature

Hanford Facility RCRA Permit Modification Notification Forms List of Attachments Attachment 4, Hanford Emergency Management Plan

Page 1 of 3

Index

Page 2 of 3 Section 14 0 Subsection 14 3 7

Page 3 of 3 Appendix A Page 5 of 6

Hanford Facility RCRA Permit Modification Notification Form Unit Permit Part & Chapter Hanford Emergency Management Plan List of Attachments, Attachment 4

Description of Modification

14.3 7 Plan Locations

Copies of this plan are maintained at

RL and ORP Emergency Preparedness program offices

each contractor Emergency Preparedness office and other locations as specified by the respective contractor

Hanford Fire Department (area fire stations)

Occurrence Notification Center

DOE Hanford Emergency Operations Center (primary and alternate) and

the Patrol Operations Center

Copies of the plan are also maintained at the following offsite agencies (per their request) to meet the WAC 173 303 350(4) requirement

Kennewick Pasco Police Department

- West Richland Police Department
- Washington State Patrol-

Adams County Sheriff's Office

Pasco Fire Department

* Richland-Fire-Department

College Place Fire Department

- City of Kennewick

Kadlec Medical Center

Our Lady of Lourdes Health Center

Kennewick General Hospital

Benton County Emergency Management Center

Franklin County Emergency Management Center and

Grant County Emergency Management Center

Copies of location specific documentation are provided to offsite agencies as requested. Per agreement with Ecology location specific documentation is offered to offsite agencies every two years

Modification Class 123	Class 1	Class 11	Class 2	Class 3
Please check one of the Classes	X			
Relevant WAC 173 303 830 Appendix I Modification	A 1			

Enter wording of the modification from WAC 173 303 830, Appendix I citation

A General Permit Provisions

1 Administrative and informational changes

Submitted by Co Operator	Reviewed by RL		Reviewed by Ecolo	gy	Reviewed by Eco	ology
Banffin Date	Karend Flynn K L Flynn	0//22/02 Date	M Anderson Moore	Date	LE Ruud	Date

¹ Class 1 modifications requiring prior Agency approval

² This is only an advanced notification of an intended Class ¹1 2 or 3 modification, this should be followed with a formal modification request and consequently implement the required Public Involvement processes when required

³ If the proposed modification does not match any modification listed in WAC 173 303 830 Appendix I then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology or down graded to ¹1 if appropriate

Hanford Facility RCRA Permit Modification Notification Form Permit Part & Chapter Unit List of Attachments Attachment 4 Hanford Emergency Management Plan Documentation Crosswalk Matrix Description of Modification Appendix A Page 4 of 6 REQUIREMENT HOW DOES REQUIREMENT WHERE IS REQUIREMENT REQUIREMENT DESCRIPTION SOURCE APPLY TO HANFORD MET IN DOCUMENTATION C p f co g ncy plan A copy f h ont gen y plan and 11 re 10 ns 10 m. plan hall be () Maint ned at he fac 1 y and (b) S brint dt all local pol departments fire departmen h p als and at and loc 1 merg ncy respons teams that may be 11 d po provide mergency ervi S 1 vel DOE/RL-94 0 WAC 173 303 350(4) f DOE/RL 94-02 are ma ntained hroughout and with fifs to ag no es C pi f section 14.3.7 (Permit req iremen) being provided Its te agenc because no agency as q es d'inem then asked in 1994 Per agreeme t with Ecology location-spec fic. documentation is ffered to ffs agencies very two years DOE/RL-94-02 and loc 10 pe f docume atto vis d'accord g to hes criteri Mak g hanges hes doc ments mus ls be acc mpl hed S 1 vel DOE/RL-94 02 on g ncy plan f necessary where () Appl big loo he facly permit are reced, (b) The plan fashs in an integration of the glob he facly hanges (ts design struction, operation must tenation other instance) with which was dangerous was not tents or in which yet with the group of the mergency (d) The femerg ncy or ordinaters hange () The femerg ncy equipment of the mergency of the hanges WAC 173 303 350(5) Amendme to The w er perat hill re ew and mmed ly ame dith (Permi rea iremen) acco danc w h WAC 173 303 830 wh appl bi RL coordinates plan g ac to w h hree LEPCs Be C ty Frank C un y and Gran C y S 1 | DOE/RL-94 0 Owners perators mus coord nat pr paredn ss and pr ve 10 pian g and co g y plan ing fforts conducted der WAC 173 3 3 340 and 350 w h local WAC 173 303 355(1) ty Frankl sec ions 3 1 3 1 1 and 3 4 g omm ees tabl hed p rs an T l III f h 1986 S perfu d (Permi rea ireme) merg cy plan Amendments and Reau horiza ion A Appr p and gener lly ac ept d mp er models ho ld be l zed to determu h impac f po en l atastroph rel as d f plos other ac id l releases f hazardous cons ents E acuat pl ns prepar d purs an to WAC 173 303 355(2) Th DOE Hanford EOC co tai Site I vol. DOE/RL-94-02 ec ns 2 2 2 3 3 and 1 3 3 2 model g q pme p d ct impac f rel ases WAC 173 303 350(3)(d) mus include hos iff ed persons and areas de if d hro gh hes model g fforts Emergen y dina A all miner mu be i as implyee her be facily premi liwih hiresponsibily fi coo dina ng ili mergi cy espons meas re. Thi mergincy coo di must be hiro ghly familiar will library to familiar will be filled for the filled control of the mergin familiar will be filled for the filled control of the mergin familiar will be filled for the filled control of the mergin familiar will be filled for the filled control of the filled co WAC 173 303 360(1) D yme by h Hanf dI d S 1 1 DOE/RL 94 0 C mmand S ructure and ff w h 134 and 22 ppo g (Perm req remen) aspets filef ly cong ypl requed by WAC 173 303 350() all perat ns and acces the facly holoa to and pripe es fall wastes handled, he loca to fall records with he facly and he fac lity lyou I add to h pers mus have h h rity minut thes es need d to arry g ncy plan WAC 173 303 S | | DOE/RL9 0 Emergen y procedures. The fillowing procedures must be implimeded the vening Alarmace on can be ac mol hed merg ny () When er the an mm actual merg y ua merg ney cord or (h des g ee wh th merg y cord mus mmed ney () Act emal fac l y larms comm ca y where applicable of fy ll fac l y pers l and () Not fy ppr p local ag which so gna ed espons rol fith h lp ded by h d erer f h ve (fire/911) or the Hanf rd I de C mmand ns 134 and 5 1 360(2)() call) Sys em and taff w h ppo g perso 1 Nf made Hanf d agen es w h des gnated respons rol agen es are accompl hed 911 lephones to reques ass and (fre ambulan 1 w f me) Class 11 Modification Class Class 1 Class 2 Class 3 X Please check one of the Classes Relevant WAC 173 303 830 Appendix I Modification A 1 Enter wording of the modification from WAC 173 303 830, Appendix I citation A General Permit Provisions 1 Administrative and informational changes Reviewed by Ecology Submitted by Co Operator Reviewed by RL Reviewed by Ecology aren I Flyan 01/02/02 Date Date G B Griffin K L Flynn LE Ruud Date

Date

M Anderson Moore

¹Class 1 modifications requiring prior Agency approval

² This is only an advanced notification of an intended Class ¹1 2 or 3 modification this should be followed with a formal modification request and consequently implement the required Public Involvement processes when required

³ If the proposed modification does not match any modification listed in WAC 173 303 830 Appendix I then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology or down graded to 1 if appropriate

Hanford Facility RCRA Permit Modification List of Attachments Attachment 4, Hanford Emergency Management Plan

Replacement Sections

Index

Section 14 0

Appendix A

Hanford Facility RCRA Permit Modification List of Attachments Attachment 4, Hanford Emergency Management Plan

Replacement Sections

Index

Section 14 0

Appendix A

14 0 PROGRAM ADMINISTRATION

The basic purpose of program administration is to establish and maintain effective organizational management and control of the emergency management program. Even though the program is now available to ORP and its contractors RL retains the primary responsibility to oversee coordinate and assess the emergency management programs of the Hanford Site contractors. RL will ensure the preparation and maintenance of plans and procedures necessary for RL/ORP to carry out its responsibilities during an emergency and will schedule through ORP any activities (i.e. drills exercises assessments) of ORP contractors.

14 1 EMERGENCY MANAGEMENT PROGRAM ADMINISTRATOR

The RL/ORP Managers have the responsibility for administering the overall emergency management program for the Hanford Site. The RL/ORP Managers have delegated the authority to develop implement and maintain the emergency management program to the RL SES director however key program decisions and/or policy changes will be coordinated with ORP prior to implementation. The RL Emergency Preparedness staff of RL SES carries out these responsibilities.

Each site contractor shall designate an individual to administer the site level emergency management program and/or to administer/assess the facility level emergency management program. This individual shall also assist as necessary in the development and maintenance of this plan and applicable implementing procedures, development of the Hanford Emergency Readiness Assurance Plan (ERAP) and annual updates, development and conduct of training and exercise programs, coordination of assessment activities, development of related documentation and coordination of emergency resources.

Each building organization shall designate an individual (e.g. BED BW emergency preparedness coordinator) responsible to administer the emergency management program at the facility level

14 1 1 Emergency Management Functions at the U S Department of Energy, Richland Operations Office

The RL/ORP Emergency Preparedness staff functions as appropriate to the responsibilities described above related to overseeing site contractor emergency preparedness programs include

ensuring that hazards assessments and hazards surveys for emergency planning are adequately performed and documented

reviewing and recommending approval of the annual Hanford ERAP developed by site contractors and RL/ORP and submitting it to the CSO and the DOE HQ Director of Emergency Management for inclusion in the annual report

assessing facility emergency preparedness programs to verify compliance with appropriate Federal and state directives and policy and providing the results/conclusions to the CSO and the DOE HQ Director of Emergency Management

submitting DOE Order requirement exemption requests as necessary for approval by the Under Secretary which document the basis for each exemption and establishes and justifies alternatives equivalent to or exceeding the Order

reviewing and approving the Hanford Site emergency exercise program and reviewing exercise evaluation and quarterly corrective action status reports and

reviewing written reports of evaluations of declared events

RL Emergency Preparedness staff functions to ensure that RL/ORP can carry out its responsibilities in an emergency include

ensuring that annual budgets and mission and function statements reflect implementation policies and decisions

assigning a senior emergency preparedness representative to the Emergency Management Advisory Committee

revising and updating this plan and the *Emergency Plan Implementing Procedures* (DOE 0223) in accordance with DOE 0 1511 and other appropriate Federal and state regulations and ensuring integration within the overall emergency management program

interfacing with Federal tribal state and local emergency management organizations

maintaining and negotiating agreements with state and county response agencies Federal assistance agencies and maintaining agreements with medical and fire support agencies

providing training to state and local emergency response personnel as requested

recruiting and training staff for the DOE Hanford EOC

maintaining the DOE Hanford EOC facility and equipment and

maintaining the DOE Region 8 RAP

Additional organizational responsibility authority and functions within RL for implementing requirements from DOE O 151 1 and other DOE Directives and Federal and state laws are delineated in the Richland Operations Office Functions Responsibilities and Authorities Manual

14 2 EMERGENCY READINESS ASSURANCE PROGRAM

1421 Hanford Emergency Readiness Assurance Plan

Based upon the organization and management of the Hanford Site emergency management program individual facility ERAPS are not provided. Rather RL/ORP and site contractor Emergency Preparedness personnel participate in the preparation of a consolidated Hanford ERAP.

The Hanford ERAP shall be a planning tool to identify and develop needed resources and improvements. The Hanford ERAP shall highlight any significant changes in emergency management programs (i.e. planning bases organizations exemptions) from previous ERAPs as well as comparing actual achievements to goals milestones and objectives. If applicable the Hanford ERAP shall be reviewed for classified or controlled information prior to submittal

Site contractor Emergency Preparedness personnel shall submit initial or updated emergency planning and preparedness activities information as indicated above to RL SES by September 30 each year for review and inclusion in the Hanford ERAP. The information shall cover a planning cycle of five years beginning the next October 1

The RL Emergency Preparedness staff shall review and finalize the Hanford ERAP for approval by the RL SES director. The RL staff will obtain concurrence from ORP prior to ERAP approval by the RL SES director. The consolidated Hanford ERAP shall be submitted to the CSO and DOE HQ Director of Emergency Management by November 30 each year.

14 2 2 Emergency Readiness Assurance Assessments/Appraisals

RL/ORP shall periodically review the ability of contractor operated facilities to meet requirements of the DOE Emergency Management System. Appraisals and assessments shall be based on specific standards and criteria published by the DOE HQ Director of Emergency Management. Appraisal findings shall be acknowledged by the appraised activity within 90 days of receipt of findings with a corresponding plan for correction. The RL/ORP appraising organization shall determine closure of open or unresolved appraisal findings.

Additionally RL/ORP shall assess the emergency management program of each site contractor under its supervision. Each site contractor shall be assessed at least once every 3 years. RL/ORP shall notify the CSO of its assessment schedule.

Contractor operated facilities shall conduct an annual internal readiness assurance assessment of their emergency management programs. Corrective actions shall be tracked and status reports provided to RL/ORP. In addition, site contractors shall assist external organizations (i.e., RL/ORP, DOE HQ) in scheduling and conducting evaluations appraisals and assessments of their respective facilities, respond to external evaluation appraisal, and assessment findings within 90 days of receipt of findings, and resolve all evaluation appraisal, and assessment findings with the responsible organization or request approval for an exemption to the requirements.

RL/ORP and contractor assessment results shall be provided to the CSO and DOE HQ Director of Emergency Management through documentation in the Hanford ERAP

1423 Lessons Learned

RL/ORP and each site contractor emergency management program shall include a system to track and identify correction of findings or lessons learned from training drills exercises and actual responses

14 2 4 Emergency Operations Metrics Data

RL/ORP and site contractors are required to report Emergency Operations metrics data quarterly. The metrics data is based on performance measures developed by the DOE HQ Office of Security and Emergency Operations.

Site contractors shall submit applicable metrics data to RL SES within five working days after the last day of the previous fiscal year quarter for review and inclusion in the consolidated Hanford metrics data spreadsheet. Data may be projected as necessary in order to meet the submittal date.

RL SES shall review collate and finalize the metrics data and electronically disseminate the consolidated Hanford metrics data spreadsheet to the CSO and DOE HQ Office of Emergency Operations within 15 days after the last day of the previous fiscal year quarter

14 3 DOCUMENT CONTROL

This plan and RL/ORP and site contractor implementing procedures shall be controlled distribution documents. RL/ORP and site contractors shall use a document control system to ensure that controlled copies are up to date and available at locations where they may be needed in an emergency. RL/ORP and site contractors shall determine the internal and external controlled copy distribution of the emergency plan and respective implementing procedures.

14 3 1 Review and Update of the Hanford Emergency Management Plan and U S Department of Energy Richland Operations Office/Office of River Protection and Site Contractor Implementing Procedures

This plan and the *Emergency Plan Implementing Procedures* (DOE 0223) will be reviewed annually by the RL/ORP and the appropriate response organizations and agencies RL SES is responsible for the coordination of this review and any resulting actions RL SES will identify specific changes deemed necessary and will ensure implementation of the revisions

Revising and updating of this plan and/or the *Emergency Plan Implementing Procedures* (DOE 0223) may be initiated at any time deemed necessary by RL SES. Changes and/or amend ments shall be incorporated by RL SES concurred upon by ORP and site contractors and approved by the RL/ORP Manager or his designee.

A controlled copy of the approved plan and the *Emergency Plan Implementing Procedures* (DOE 0223) shall be submitted to the DOE HQ Director of Emergency Management the CSO and to the DOE HQ EOC

Site contractor emergency plans (e.g. building emergency plans) and implementing procedures shall be reviewed at least annually

14 3 1 1 Review and Update Based on WAC 173-303

Portions of this plan together with Hanford Site location/activity specific documentation established to meet contingency plan requirements must be reviewed and immediately amended if necessary whenever

applicable regulations or the Hanford Facility RCRA Permit are revised

this plan or the location/activity specific building emergency plan/procedure fails in an emergency

the Hanford Site facilities/activities change (e.g. design operation maintenance etc.) in a way that materially increases the potential for fires explosions or releases of dangerous waste or dangerous waste constituents or in a way that changes the response necessary in an emergency or

the list of emergency equipment changes

14 3 2 Review of Agreements

Agreements with local state and Federal officials and agencies (as contained in Appendix B) are maintained by RL SES and are reviewed and/or updated at least annually Updates may be initiated either by RL or by the agreement official or agency. Updates are documented by amendment marks on individual pages of the agreement unless comprehensive amendments are required. Agreements shall be reviewed annually and revised as necessary. RL SES shall maintain documentation of the annual review.

14 3 3 Classified Information

RL/ORP and site contractors shall ensure that emergency preparedness documents such as plans procedures scenarios and assessments are reviewed as necessary for classified and Unclassified Controlled Nuclear Information (UCNI) by an authorized derivative classifier or UCNI reviewing official

14 3 4 Supporting Documents

RL SES shall maintain copies of documents and records that support the emergency management program (i.e. technical data hazards assessments ERAPs and plans and procedures) Records of training drills and exercises shall be maintained to document status of the program and provide direction for improvements

Hanford Site contractors shall maintain records that will provide documentation of the facility emergency preparedness program and to support the preparation of the ERAP work plans etc

14 3 5 Vital Records

A program shall be established to ensure that vital records regardless of media essential to continued functioning or reconstruction of an organization during and after an emergency are maintained and available per 36 CFR 1236

The vital records program ensures the protection and availability of information critical to effective emergency response management and the protection of the legal rights and interests of citizens the Federal government and its employees and DOE contractors and site personnel. The RL Office of Site Services is responsible to ensure that a vital records program for the Hanford Site is in place.

RL/ORP and site contractors shall annually review their respective records indicated on the vital records submittal listing and determine necessary additions to or deletions from the list RL SES should ensure that the retrieval process for vital records is evaluated annually as part of a Hanford sitewide emergency exercise

Each site contractor and RL/ORP shall provide designated storage locations for vital records as appropriate RL/ORP and site contractor documents identified as vital records such as this plan emergency procedures and building emergency plans shall be stored at the DOE Hanford EOC in paper form so they can be used without reliance on mechanical equipment Other emergency operating records and rights and interests records designated as vital need not be kept at the DOE Hanford EOC

1436 Emergency Records

RL/ORP and site contractor emergency procedures shall provide for documentation of emergency records that contain information for review and reconstruction of major communications and actions taken during a declared emergency. These records include logs and documentation produced by the respective emergency response organizations (i.e. Incident Command Organization and the DOE Hanford EOC). RL SES shall maintain emergency records generated during the operation of the DOE Hanford EOC and may also request copies of emergency records generated at other emergency response locations.

In addition provisions shall be in place for the control monitoring and maintenance of permanent records of onsite personnel exposures to internal/external radiological and nonradiological hazardous materials in response to emergency conditions. Exposure records shall be stored in accordance with existing site records retention requirements

14 3 7 Plan Locations

Copies of this plan are maintained at

RL and ORP Emergency Preparedness program offices

each contractor Emergency Preparedness office and other locations as specified by the respective contractor

Hanford Fire Department (area fire stations)

Occurrence Notification Center

DOE Hanford Emergency Operations Center (primary and alternate) and

the Patrol Operations Center

Copies of the plan are also maintained at the following offsite agencies (per their request) to meet the WAC 173 303 350(4) requirement

Pasco Police Department

Section 14 0 Rev 2 February 5 2002 Page 8 of 8

Program Administration

Adams County Sheriff's Office
Pasco Fire Department
College Place Fire Department
Kadlec Medical Center
Our Lady of Lourdes Health Center
Kennewick General Hospital
Benton County Emergency Management Center
Franklin County Emergency Management Center and
Grant County Emergency Management Center

Copies of location specific documentation are provided to offsite agencies as requested Per agreement with Ecology location specific documentation is offered to offsite agencies every two years

APPENDIX A DOCUMENTATION CROSSWALK MATRIX

REQUIREMENT SOURCE	REQUIREMENT DESCRIPTION	HOW DOES REQUIREMENT APPLY TO HANFORD?	WHERE IS REQUIREMENT MET IN DOCUMENTATION?
WAC 173 303 340 Introduction	Prepa ed ess and prevent on Fac I t es must be des gned constructed maintai ed and operat d to minimize the possib I ty of fire explosion or any inplanned sudden or o sudden release of d ge ous waste o da gerous waste constituents to a r soil or surfa e or ground wate which could threaten the public health or the environment. This sect in describes preparations a dipre entive meas es which help a oid o mit gate such sit atio s	Under the Dangerous Waste Regulations (State authorized RCRA program) the Hanford Site is a singular facility with over 60 TSD units and many more locations where generator activities take place. For the purposes of these regulations.	N/A
WAC 173 303 340(1) (Perm t req ement)	Required equipment Required equipment All facilities must be equipped with the following unless it can be do mo strated to the department that none of the hards posed by waste had led at the facility could require a particular kind of equipment the specified below (a). An itemal communications or alarm system capable of providing immediate emergency instruction to facility personnel (b). A device such as a tilephone or a hand held two way radio capable of summoning emergency assistance from local police departments is fire departments or state or local emergency response teams (c). Portable fire extinguishers fire control equipment (including special exting a hing equipment such as that using foam nertigation or dry chemicals) spill or to equipment and decontamination equipment and (d). Water at adequate olume and possure to supply water hose streams foam producing equipment automatic sprinklers or water spray systems. All facility communications or alarm systems fire protect or equipment spill control equipment and decontamination in equipment to where required must be tested and maintained as necessary to assure its proper operation in time of emergency.	Required equipment is evaluated on a s te wide basis (Hanfo d Fire Department) and a location spec f c bas s for TSD units a d 90-day accumulation areas Each location does not necessarily require each type of equipment Lists of appropriate equipment are documented in accordance with WAC 173 303 350(3)(e)	See line item fo WAC 173 303 350(3)(e)
WAC 173 303 340(2) (Permit req eme t)	Access to common to solarms Posonnel must have immediate access to the signal gid ces described in the situations below (a) Whene end a gerous wasters be ground more dispread or otherwise handled all personel in olved most have immediate access to an item I alarm or emergency communication delice either directly or thoughts all or order contact with another employee unless such a device is not equired in subsection (1) of this section (b) If there is energy is one employee on the possible of the facility is operating the must have immediate access to a delice such as a telephone or a hand held two way radio capable of someoning external energy experience.	Site personnel are pro ded access to signaling de ces	None required to document compliance
WAC 173 303 340(3) (Perm t equirement)	Aisle space The ow or operato must maintain aisle space to allow the u obstructed mo eme t f personnel f e p otection equipment spill control equipme t a d deco taminat o equipment to a y area of facility operation in an emergency unless it can be demonstrated to the department that aisle space is not needed for any of these purposes	This requirement is met at TSD units and 90 day accumulation area where appropriate	N/A

REQUIREMENT SOURCE	REQUIREMENT DESCRIPTION	HOW DOES REQUIREMENT APPLY TO HANFORD?	WHERE IS REQUIREMENT MET IN DOCUMENTATION?
WAC 173 303 340(4) (Permit requirement)	Arrangeme its with local authorities. The owner or operator must attempt to make the following in generits as apping to following the potential need finite critical fittes one attempt to make the potential need finite critical fittes one attempt to make the facility and the potential need finite critical fittes one attempt to familiarize police fitted epartments and emergency response teams with the layout of the facility properties of dangerous waste handled at the facility and associated	Arrangements are addressed on a site wide basis Memoranda of Understanding which RL enters into are described in DOE/RL 94 02 Table 3 I	See line item for WAC 173 303 350(3)(c)
	hazards places where facility personnel would normally be working entral ces to roads inside the facility and possible evacuation routes (b) Arrangements to familiarize local hospitals with the properties of dangerous waste handled at the facility and the types of injuries or illnesses which could result from fires explosions or releases at the facility (c) Agreements with state emergency response teams emergency response contractors and equipment suppliers and (d) Where more than one party might respond to an emergency agreements designating primary emergency authority and agreements with any others to provide support to the primary emergency authority	Hanford Site emergency responders (Hanford Fire Department and Hanford Patrol) must be familiar with items 340(4)(a) The City of Richland Benton County Sheriff and Washington State Patrol will be familiar as necessary	
WAC 173 303 340(5)	Where state or local authorities decline to enter into such agreements the owner or operator must document the refusal in the operating record	The operating record is the set of documents maintained to demonstrate compl ance with WAC 173 303 and the Hanford Site RCRA Permit	None If authorities decline the documentation will be maintained in accordance with DOE/RL 91 28
WAC 173 303 350(1)	Purpose The purpose of this section and WAC 173 303 360 is to lessen the potential impact on the public health and the environment in the event of an emergency circumstance including a fire explosion or unplanned sudden or nonsudden release of dangerous waste or dangerous waste constituents to air soil surface water or ground water by a facility. A contingency plan must be de eloped to lessen the potential impacts of such emergency circumstances and the plan must be implemented immediately in such emergency circumstances.	DOE/RL 94-02 is the site wide plan meeting site wide contingency planning requirements. Location specific/acti ity specific elements are contained in documentation for operating TSD units and 90-day accumulation areas.	The contingency plan consists of portions of DOE/RL 94 02 and location spec fc/act vity specific documentation
WAC 173 303 350(2)	Each owner or operator must have a contingency plan at his facility. A contingency plan must be developed to lessen the potential impacts of such emergency circumstances and the plan must be implemented immediately in such emergency circumstances.	Facility = Hanford Site according to the regulations (See section 1 4 1 of this plan for definition)	The contingency plan consists of portio s of DOE/RL 94 02 and location specific/activity specific documentation
WAC 173 303 350(3)(a) (Permit requirement)	The contingency plan must contain the following (a) A description of the actions which facility personnel must take to comply with this section and WAC 173 303 360	The site level description of actions is addressed in this plan. Location specific/act ity specific documentation utilizes generic response descriptions or creates more detailed descriptions appropriate for the location.	Site level DOE/RL 94 02 section 1 3 4 Unit le el location specific documentation
WAC 173 303 350(3)(b) (Permit requirement)	The contingency plan must contain the following (b) A description of the actions which will be taken in the event that a dangerous waste shipment which is damaged or otherwise presents a hala of the public health and the environment arrives at the facility and is not acceptable to the owner or operator but cannot be transported purs ant to the equilibrium ements of WAC 173 303 370(5) Manifest system reasons for not accepting dangerous waste shipments	The site level description of actions is addressed in this plan. For TSD units that receive offsite waste shipments location specific documentation addresses these circumstances.	Site level DOE/RL-94-02 section 1 3 4 Unit le el location specific documentation

	X
	F
	Ĺ
	ストンチ
	÷
	۰
	Į
	7
	6 I
	ຄ
	3
`	Ξ
	Ö
	lanjora
	*5
	-
	€
	3
	Ö
	ġ
(Ю
	ď
	3
	⋜
•	ت
	~
	₹
	2
	₩
	2
	Ω
(Ю
	4
	3
	≋
	10
	≊
	ement rian
	₹
	Tian.
	7
	-3

Page	February 5		Apper
ge 3 of 6	/ 5 2002	Rev 2	ppendix A

REQUIREMENT SOURCE	REQUIREMENT DESCRIPTION	HOW DOES REQUIREMENT APPLY TO HANFORD?	WHERE IS REQUIREMENT MET IN DOCUMENTATION?
WAC 173 303 350(3)(c) (Permit requirement)	The contingency plan must co tain the following (c) A description of the arrangements agreed to by local police departments fire departments hospitals contractors and state and local emergency response teams to coordinate emerge cy services as requed in WAC 173 303 340(4)	DOE/RL 94-02 section 3 7 and Table 3 1 contain this formation. This requirement is met at the site le. el. No location-specific information is needed to meet this requirement.	Site le el DOE/RL 94 02 sections 3 2 3 3 3 1 3 3 2 3 4 3 4 1 1 3 4 1 2 3 4 1 3 3 7 and Table 3 1
WAC 173 303 350(3)(d) (Permit req rement)	The contingency plan must contain the following (d) A current list of names addresses and pho e numbers (office and home) of all persons qualified to act as the emergency coordinator required der WAC 173 303 360(1) Where more than one person's I sted one must be named as primary emergency coordinator and others must be listed in the order in which they will assume responsibility as alternates. For new fac littles only this list may be provided to the department at the time of facility certification (as required by WAC 173 303 810(14)(a)(i)) rather than as part of the permit application.	DOE/RL 94 02 section 2 2 discusses personnel job titles which will fill duties and responsibilities of the Emergency Coordinator described in WAC 173 303 360. Locat on specific/activity specific documentation for TSD units and 90-day accumulation areas include information on job title work location and work phone number for Emergency Coordinator names and home phone numbers are maintaled separate from the contingency plan document on file in accordance with Hanford Facility RCRA Permit, DW Portion General Condition II A 4 and is updated at a minimum on a monthly basis	Site le el None Un t le el location specific docume tation
WAC 173 303 350(3)(e) (Perm t requirement)	The contingency plan must co tain the foliowing (e) A list of all emergency equipme that the facility (such as fire extinguishing systems spill control equipment communications and alarm systems and decontamination equipment) where this equipment its required. This list must be kept up to date in addition, the plan must include the location and a physical description of each item on the list and a brief outline of its capabilities and	DOE/RL 94 02 Appendix C contains the list of Hanford Fire Department equipment Location specific documentation for TSD un ts and 90 day accumulation areas contain equipment lists for their respective locations	S te le el DOE/RL 94-02 Appendix C Unit le el App opriate equipment identif ed in location specific docume tation
WAC 173 303 350(3)(f) (Permit requirement)	The contingency plan must contain the following (f) An evacuation plan for facility personnel where there is a poss b lity that evacuation could be necessary. This plan must describe the sign I(s) to be used to begin evacuation evacuation roles and alternate elacuation routes.	The site wide signals are delineated in DOE/RL 94 02 Table 5 1 No location signal information is required unless unique devices are used at the location. Site wide evacuation routes are contained in DOE/RL-94 02 Fig. re. 7.3 Location specific elacuation routes will be provided in TSD units and 90 day accumulation area documentation. Evacuation routes for occupied buildings are provided through postings.	Site le el DOE/RL 94 02 Figure 7 3 and Table 5 1 Unit le el location spec f'e documentation

REQUIREMENT SOURCE	REQUIREMENT DESCRIPTION	HOW DOES REQUIREMENT APPLY TO HANFORD?	WHERE IS REQUIREMENT MET IN DOCUMENTATION?
WAC 173 303 350(4) (Permit requ rement)	Cop es of contingency plan A copy f the contingency plan and all revisions to the plan shall be (a) Maintained at the fa I ty and (b) S bmitted to all local police departments fire depart c ts hosp tals and state and local emergency response teams that may be called upon t pro de emergency services	Copies of DOE/RL 94 02 are maintained throughout the Hanford Site and with offsite agencies. Copies of location specific documentation are projected to offsite agencies as requested. Per agreement with Ecology location specific documentation is offered to offsite agencies every two years.	S te level DOE/RL 94-02 section 14 3 7
WAC 173 303 350(5) (Permit requirement)	Amendments The owner or operator shall review and immediately amend the contingency plan if necessary whene er (a) Applicable regulations or the facility permit are relised (b) The plan fails in an emergency (c) The facility changes (in its design construction operation maintenance or other circumstances) in a way that materially increases the pote that for fires explosions or releases of dangerous waste or dangerous waste construction of the state of the	DOE/RL 94 02 and location specific documentation is revised according to these criteria. Making changes to these documents must also be accomplished in accordance with WAC 173 303 830 when applicable.	Site level DOE/RL 94 02 section 14 3 1 1
WAC 173 303 355(1) (Permit requirement)	Owners or ope ators must coordinate preparedness and prevention planning and conting cy planning efforts conducted under WAC 173 3 3 340 and 350 with local emergency planning committees established pursuant to Title III of the 1986 Superfund Ame dments and Reauthorization Act	RL coordinates planning actions with three LEPCs Benton County Franklin County and Grant County	Site level DOE/RL 94 02 sections 3 1 3 1 1 and 3 4
WAC 173 303 355(2)	Appropriate a digenerally accepted computer models should be utilized to determ the impacts of a potential catastrophic air release due to fire explosion or other accidental releases of hazardous constituents. Evacuation plans prepared pursuant to WAC 173 303 350(3)(d) must include those effected persons and areas identified through these modeling efforts.	The DOE Hanford EOC contains modeling equipment to predict impacts of air releases	Site level DOE/RL 94 02 sections 2 2 2 3 3 and 1 3 3 2
WAC 173 303 360(1) (Permit requi ement)	Eme gency coordinato At all times there must be at least one employee either on the facility premises of on call with the responsibility for coordinating all emergency response meas the emergency coord ato must be thoroughly familiar with all aspects of the facility's contingency plan required by WAC 173 303 350(2) all operations and activates at the facility the location and properties of all wastes handled the location of all records within the facility and the facility layout in addition this person must be authority to commit the resources needed to carry out the contribution.	Duty met by the Hanford Incident Command Structure and staff with supporting on-call personnel	Site level DOE/RL 94 02 section 1 3 4 and 2 2
WAC 173 303 360(2)(a) (Permit req ement)	Emergency procedu es The following procedures must be implemented in the event of an emergency (a) Whene er there is an imminent or actual emergency situation the emerge cy coold nator (or his designed when the emergency coordinator is on call) must immediately (i) Act attenternal facility alarms or communication systems where applicable to of fy all facility personnel and (ii) Notify appropriate state or local agencies with designated response roles if their help is needed	Alarm activation can be accomplished by the discoverer of the event (fire/911) or the Hanford Incident Command System and staff with supporting on call personnel Notification made to non Hanford agencies with designated response roles agencies are accomplished in 911 telephones to request assistance (fire ambulance law enforcement)	Site level DOE/RL 94 02 sections 1 3 4 and 5 2 1

REQUIREMENT SOURCE	REQUIREMENT DESCRIPTION	HOW DOES REQUIREMENT APPLY TO HANFORD?	WHERE IS REQUIREMENT MET IN DOCUMENTATION?
WAC 173 303 360(2)(b) (Permit requ ement)	Eme gency p oced e (b) Whenever there is a el ase fire or explosion the em ge y oo d at m st immed ately identify the character e act sou ce amount and areal e tent of any ele s d mate ials	Hanford Incident Command System and staff w th support ng on call personnel	Site level DOE/RL 94 02 sections 2 2 1 1 2(f) and 2 2 1 1 3(g)
WAC 173 303 360(2)(c) (Permit requirement)	Eme gency p oced res (c) Concurre tly the emergency coord ator shall assess possible hazards to human health a d the e ironment (considering direct induct) immediate and lo g term effects) that may result from the release fire or explosion	Ha ford Inc de t Command System and staff with supporting on-call personnel	S te level DOE/RL 94 02 section 4 2
WAC 173 303 360(2)(d) (Perm t equ rement)	Emergency procedures (d) If the emergency coordinator determines that the facility has had a clease fre or explosion which could threaten human health or the environment he must report his find ngs as follows (i) If his assessment indicates that e acuation of local areas may be ad isable he must mmed ately notify appropriate local a tho ties. He mist be available to help appropriate officials decide whether local areas should be elected and (i) He must immed ately notify the department a die the the golernment official designated as the on scene coordinator or the National Response Center (using their 24 hour toll fice number (800) 424 8802)	Hanford Incident Command System and staff with support g on-call personnel ONC personnel notify local authorities field according to the Hanford Incident Command Structure Site contractor environmental single point-of contact personnel perform the assessment report not fication to Ecology and RL (the on scene coordinator on behalf of the Hanford Incident Command Structure NRC is not called	Site level DOE/RL 94 02 sections 2 2 1 1 2(a) &(d) 2 2 1 1 3(a)&(e) 5 1 1 5 1 1 2 5 1 2 and 5 1 2 1
WAC 173 303 360(2)(e) (Perm t eq ement)	Eme gency procedures (e) His assessment report must include (i) Name and telephone numbe of reporter (i) Name and address of facility (ii) Time and type of not dent (e.g. release fire) (iv) Name and quantity of material(s) involved to the extent known (i) The end to find the facility	Site contractor environmental single po 1 of-contact personnel perform the assessment report notification to Ecology a d RL after obtaining it from location specific personnel	Site level DOE/RL 94 02 sections 2 2 1 1 2(d) 2 2 1 1 3(e) 5 1 1 5 1 1 2 and 5 1 2 1
WAC 173 303 360(2)(f) (Permit requ ement)	Emergency procedures (f) During an emergency the emergency coordinator must take all reaso able eas s ecessary to ensure that f es e plosions a d releases do not occurror o spread to othe dangerous waste at the facility. These meas res must include where applicable stopping processes and operations collecting and contain g released waste and remoing or isolating containers.	Hanford Incident Command System and staff with supporting on call personnel	Site le el DOE/RL 94 02 sect ons 2 2 1 1 2(f) and 2 2 1 1 3(g)
WAC 173 303 360(2)(g) (Permit requirement)	Eme gency procedures (g) If the facility stops operations in response to a fire e plosion or release the emergency coordinator must monitor for leaks pressure buildup gas ge to o ruptures in valies pipes or other equipment where er this is appropriate	Hanford Incident Command System and staff with supporting on-call personnel	S te le el DOE/RL 94 02 sections 2 2 1 1 2(f) and 2 2 1 1 3(g)
WAC 173 303 360(2)(h) (Permit requ rement)	Emergency procedures (h) Immediately after an emergency the emergency coordinator must ploside for treating storing or disposing of reconstruction of the containing at education of the containing at the facility.	Onsite Reco ery Director with supporting on call personnel	Site level DOE/RL 94 02 section 9 2 3

REQUIREMENT SOURCE	REQUIREMENT DESCRIPTION	HOW DOES REQUIREMENT APPLY TO HANFORD?	WHERE IS REQUIREMENT MET IN DOCUMENTATION?
WAC 173 303 360(2)(1) (Permit requirement)	Emergency procedures (1) The emergency coordinator must ensure that in the affected area(s) of the facility (1) No waste that may be incompatible with the released material is treated stored or disposed of until cleanup procedures are completed and (ii) All emergency eq ipment listed in the contingency plan is cleaned and fit for its intended use before operations are resumed	Onsite Recovery Director with supporting on call personnel	Site level (I) DOE/RL 94-02 sect on 9 2 3 Site level (ii) DOE/RL 94-02 section 11 2
WAC 173 303 360(2)(j) (Permit requirement)	Emergency procedures (j) The owner or operator must notify the department and appropriate local authorities that the facility is in compliance with (i) of this subsection before operations are resumed in the affected area(s) of the facility	Site contractor environmental single point-of-contact personnel perform this notification when applicable on behalf of the Onsite Recovery Director	Site le el DOE/RL 94 02 section 5 1 2 3
WAC 173 303 360(2)(k) (Permit requirement)	Emergency procedures (k) The owner or operator must note in the operating record the time date and deta is of any incident that requires implementing the contingency plan. Within f fleen days after the incident, he must submit a written report on the incident to the department. The report must include (i) Name address and telephone number of the owner or operator (ii) Name address and telephone number of the facility (iii) Date it me and type of incident (e.g. fire explosion) (i.) Name and quality of material(s) involved (v) The extent of injuries if any (vi) An assessment of actual or potential hazards to human health or the environment where this is applicable (vii) Estimated quantity and disposition of recovered material that resulted from the incident continued to prevent reoccurrence of the incident.	Site contractor management through RL ensures the note in the operating record is performed and prepares the 15-day report to Ecology	Site level DOE/RL 94 02 section 5 1 2 2
40 CFR 761 65(c)(1)(1) and (c)(7)(11) SPCC Plans for PCBs	Temporary Storage Areas (less than 30-days) (c)(1)(1) PCB containers containing liquid PCBs at concentrations of ≥50 ppm, provided a Spill Pre-ention Control and Countermeasure Plan has been prepared for the temporary sto age a ea in accordance with part 112 of this chapter and the liquid PCB waste is in packaging authorized in the DOT Hazardous Materials Regul tios at 49 CFR parts 171 through 180 or stationary bulk storage tanks (including rolling stock such as but of 1 m ted to tanker trucks as specified by DOT) (c)(7)(ii) The owness o operators of any facility using containers described in paragraph (c)(7)(1) of this section shall prepare and implement a Spill Pre-ention Control and Countermeasure (SPCC) Plan as described in Part 112 of this title. In complying with 40 CFR Part 112 the owner or operator shall read oil(s) as PCB(s) whenever it appears. The exemptions for storage capacity 40 CFR 112 1(d)(2) and the amendment of SPCC plans by the Regional Administrator. 40 CFR 112 4 shall not apply unless some fraction of the liquids stored in the container are oils as defined by section 311 of the Clean Water Act.	When SPCC plans apply to Hanford Site activities the information notice ered in site wide documentation must be addressed in location specific documentation	Site level DOE/RI, 94 02 sections 1 1 (fourth paragraph) 1 2 (first bullet sixth dash and second bullet fourth dash) and 2 2 1 1 2 (first paragraph) Unit level appropriate location specific documentation

Hanford Facility RCRA Permit Modification Notification Forms Part III, Chapter 2 and Attachment 18 305 B Storage Facility

Page 1 of 10

ı	n	a	ρ	Y

Page 2 of 10	Hanford Facility RCRA Permit Condition III 2 A
Page 3 of 10	Chapter 3 0 Table 3-1
Page 4 of 10	Chapter 4 0 Section 4 1 1 2
Page 5 of 10	Chapter 4 0 Section 4 1 1 6 4
Page 6 of 10	Chapter 4 0 Section 4 1 1 6 5 a
Page 7 of 10	Chapter 4 0 Section 4 1 1 6 7
Page 8 of 10	Chapter 4 0 Figure 4 6
Page 9 of 10	Chapter 4 0 Figure 4 7
Page 10 of 10	Chapter 6 0 Section 6 2 1 1

Hanford Facility RCRA Permit Modification Notification Form Unit: Permit Part & Chapter: 305-B Storage Facility Part III, Chapter 2 and Attachment 18 Description of Modification: Hanford Facility RCRA Permit, Condition III.2.A: COMPLIANCE WITH APPROVED PERMIT APPLICATION III.2.A. The Permittees shall comply with all the requirements set forth in Attachment 18, including all Class 1 Modifications specified below, and the Amendments specified in Condition III.2.B. Enforceable portions of the application are listed below; all subsections, figures, and tables included in these portions are also enforceable, unless stated otherwise: Section 1.0 Part A, Form 3, Permit Application, from Class 1 Modification for quarter ending December 31, 2001 Section 2.1.2 The 305-B Storage Unit, from Class 1 Modification for quarter ending March 31, 2001 Section 2.2.1 General Requirement from Class 1 Modification for quarter ending March 31, 2001 Section 2.5 Performance Standard, from Class 1 Modification for quarter ending March 31, 2001 Section 2.6 Buffer Monitoring Zones, from Class 1 Modification for quarter ending March 31, 2001 Section 2.8 Manifest System, from Class 1 Modification for quarter ending March 31, 2001 Chapter 3.0 Waste Characteristics, from Class 1 Modification for quarter ending March 31, 2002 December 31, 2001 Chapter 4.0 Process Information, from Class 1 Modification for quarter ending December 31, 2000 March 31, 2002 Chapter 6.0 Procedures to Prevent Hazards, from Class 1 Modification for quarter ending March 31, 2001 March 31, 2002 Chapter 7.0 Building Emergency Procedure, from Class 1 Modification for quarter ending June 30, 2001 Personnel Training, from Class 1 Modification for quarter ending September 30, 2001 Chapter 8.0 Chapter 11.0 Closure and Post-Closure Requirements, from Class 1 Modification for quarter ending September 30, 2000 Chapter 12.0 Reporting and Recordkeeping, from Class 1 Modification for quarter ending June 30, 1999 Section 13.8 Toxic Substances Control Act, from Class 1 Modification for quarter ending September 30, 2000 Other Requirements, from Class 1 Modification for quarter ending September 30, 2000 Section 13.9 Hanford Site and 300-Area Topographic Maps, Plates 2-2 Through 2-9, from Class 1 Appendix 2A Modification for quarter ending June 30, 2001 Modification Class: 123 Class¹1 Class 1 Class 2 Class 3 X Please check one of the Classes: Relevant WAC 173-303-830, Appendix I Modification: A.1. Enter wording of the modification from WAC 173-303-830, Appendix I citation A. General Permit Provisions 1. Administrative and Informational changes Reviewed by RL Program Office: Submitted by Co-Operator: Reviewed by Ecology: Reviewed by Ecology: Rt Christenen 4/1/02 3-15-02 A.K. Ikenberry F. Jamison L.E. Ruud Date Date Date Date

¹ Class 1 modifications requiring prior Agency approval.

² This is only an advanced notification of an intended Class ¹1, 2, or 3 modification, this should be followed with a formal modification request, and consequently implement the required Public Involvement processes when required.

³ If the proposed modification does not match any modification listed in WAC 173-303-830 Appendix I, then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology, or down graded to ¹1, if appropriate.

Description of Modification:

Chapter 3.0, Table 3-1:

Parameter*	Metho	od ^b	Ra	tionale for Sele	ction
	Physical Sc				
Visual inspection	l inspection Field method - observe phas solids in waste		Ensure that waste matches that descri waste acceptance documentation; ider prohibited by LDR requirements relat downstream TSD unit acceptance crit		on; identify waste ts related to
	Chemical So	creening .			
Water miscibility/separable organics Water mix screen ASTM Method D5232-92			waste acceptan separable organ LDR requirement unit acceptance	ents related to do	on; identify ste prohibited by ownstream TSD
Water reactivity	Water mix screen ASTM Method D5232-92	waste acceptan	ste matches that ce documentation th WAC 173-303	n; ensure	
pН	Ensure that wa waste acceptan	ste matches that ce documentation th WAC 173-303	described on on; ensure		
Cyanides	Cyanide screen HAZCAT	nide screen Ensure that waste matches			
Sulfides	Sulfide screen HAZCAT TM	Ensure that waste matches that described on waste acceptance documentation; ensure compliance with WAC 173-303-395(1)(b)			
	Pre-Shipmen				
Mercury (total)	Generator knowledge or S 7470/7471	W-846 Method		prohibited by LI istream TSD uni	OR requirements t acceptance
Toxicity characteristic organic compounds	Generator knowledge or S and 8260 (volatile organic 8270 (semivolatile organic	compounds) and	Identify waste Form 3	not identified on	the Part A,
Polycyclic aromatic hydrocarbons	Generator knowledge or S or 8100	W-846 Method 8270		not identified on ste with >1% so	
 Addition parameters can be used on current vacurrent waste acceptance criteria. Procedures based on EPA SW-846, unless of cases, method will be reliable. 			Operation limits	s transfer/shipme	
Modification Class: 123		Class 1	Class 11	Class 2	Class 3
Please check one of the Classes:		X			
Relevant WAC 173-303-830, Appe	ndix I Modification:	A.1.		-la-va-	
Enter wording of the modification f A. General Permit Provisions 1. Administrative and Informati		, Appendix I citat	ion_	71	f
Submitted by Co Occasion Paris	ved by RL Program Office:	Reviewed by	Ecology:	Reviewed	by Ecology:
	Christenson 4/1/02				

¹ Class 1 modifications requiring prior Agency approval.

² This is only an advanced notification of an intended Class ¹1, 2, or 3 modification, this should be followed with a formal modification request, and consequently implement the required Public Involvement processes when required.

³ If the proposed modification does not match any modification listed in WAC 173-303-830 Appendix I, then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology, or down graded to ¹1, if appropriate.

Description of Modification:

Chapter 4.0, Section 4.1.1.2:

4.1.1.2 Container Management Practices [D-1a(2)]

Management practices and procedures for containers of dangerous waste are in place at the 305-B Storage Facility to assure the safe receipt, handling, preparation for transport, and transportation of waste. These practices and procedures are summarized below.

<u>Inspection of Containers.</u> A system of daily, weekly, monthly, and yearly inspections is in place to ensure container integrity, check for proper storage location, prevent capacity overrun, etc. These inspection procedures are detailed in Section 6.2.

Container Handling. All unit staff is instructed in proper container handling safeguards as part of their training (refer to Section 8.1.2 for further details). For example, employees are instructed to open all high-vapor-pressure liquids in the flammable liquid bulking module to avoid buildup of vapors in the unit. Containers are always kept closed except when adding or removing waste, in accordance with WAC 173-303-630(5)(a).

Containers are not opened, handled or stored in a manner that would cause the container to leak or rupture. Small containers (five gallons or less capacity) are stored on ventilated shelving or in approved flammable liquid storage lockers (if appropriate). Containers over five gallons capacity are stored on the floor of the appropriate storage cell, in cabinets, or stored in the appropriate containment area on the high bay floor under Section 4.3.2. Unnecessary handling not required for redistribution or preparation for transport and disposal by either labpacking or bulking is minimized. Crane or chain hoist, or forklift moves drums manually. For manual movement, hand trucks specifically designed for drum handling are used. Crane and chain hoist operations are performed following the appropriate Hoisting and Rigging procedures: using a choker chain or drum hoist. When using the forklift, a drum hoist is used or the drums are carried on pallets. Drums are never carried on the forks or "speared" by slipping the forks under the chime. When waste handling operations are conducted, a minimum of two persons is present in the unit.

Modification Class: 123	Class 1	Class ¹ 1	Class 2	Class 3
Please check one of the Classes:	X			
Relevant WAC 173-303-830, Appendix I Modification:	A.1.			
Enter wording of the modification from WAC 173-303-830, A. General Permit Provisions 1. Administrative and Informational changes	Appendix I cit	tation	a .	
	Reviewed	by Ecology:	Reviewed	

¹ Class 1 modifications requiring prior Agency approval.

Date

R.F. Christensen

A.K. Ikenberry

Date

F. Jamison

Date

L.E. Ruud

Date

² This is only an advanced notification of an intended Class ¹1, 2, or 3 modification, this should be followed with a formal modification request, and consequently implement the required Public Involvement processes when required.

³ If the proposed modification does not match any modification listed in WAC 173-303-830 Appendix I, then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology, or down graded to ¹1, if appropriate.

Description of Modification:

Chapter 4.0, Section 4.1.1.6.4:

4.1.1.6.4 Flammable Cell. The flammable-cell (cell 4) is located south of the alkaline, Washington State Criteria waste, and non-regulated waste cell. As with the other three cells described above, this cell is constructed of epoxy-painted concrete block walls 4 feet high and incorporates a 1 foot deep sump along its west end. The secondary containment volume of the individual sump for this cell is 119 gallons, and total containment volume of the cell is 687 gallons. A diagram of this cell is provided in Figure 4-4.

Ignitable organic waste materials are stored in this cell that also exhibits the characteristics of corrosivity, toxicity as well as reactivity. Three Factory Mutual-approved flammable liquid storage cabinets are utilized for storage of various classes of flammable liquids as defined by the UFC. The capacities of the various cabinets are shown in Table 4-2. The following cabinets also are used for storage in this cell: one for combustibles, one for aerosols, two for flammable solids, and one for overflow from one of the other cabinets.

Total ignitable Waste Storage capacity of the 305-B Storage Facility highbay, including the organics cell, Cell 5, Ignitable drum storage area, and highbay storage area is limited by the following UBC restrictions for Class B occupancy:

- · Class 1A flammable liquids: 120 gallons
- Class 1B flammable liquids: 240 gallons
- Class 1C flammable liquids: 360 gallons
- Maximum Class 1A, 1B, and 1C at any one time: 480 gallons
- Maximum Class 1A, 1B and 1C stored in Cell 8 self contained storage module for flammable liquids is 240 gallons
- Class 2 combustible liquids: 480 gallons
- Class 3A combustible liquids: 1320 gallons
- Combustible fibers, loose: 100 cubic feet
- Combustible fibers, baled: 1000 cubic feet
- · Flammable gases in any one cylinder: 3000 cubic feet
- Liquefied flammable gases: 60 gallons

To maintain required aisle spaces and functional usability, the liquid capacity of the organics cell (cell 4) is set at 1000 gallons.

Modification Class				Class 1	Class ¹ 1	Class 2	Class 3
Please check one o	of the Clas	ses:		X			
Relevant WAC 17	3-303-830	, Appendix I Modifica	tion: A	A.1.			
A. General Permi	t Provisio	cation from WAC 173- ns formational changes	303-830, <i>E</i>	Appendix I ci	tation		
Submitted by Co-C		Reviewed by RL Program	m Office:	Reviewed b	y Ecology:	Reviewed b	y Ecology:
WWW VI TO		R.F. Christensen	7	F. Jamison	Date	L.E. Ruud	

¹Class 1 modifications requiring prior Agency approval.

² This is only an advanced notification of an intended Class ¹1, 2, or 3 modification, this should be followed with a formal modification request, and consequently implement the required Public Involvement processes when required.

³ If the proposed modification does not match any modification listed in WAC 173-303-830 Appendix I, then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology, or down graded to ¹1, if appropriate.

Description of Modification:

Chapter 4.0, Section 4.1.1.6.5.a:

4.1.1.6.5.a. Flammable Liquids Storage Module. The flammable liquid storage module is a self-contained storage module (cell 8) that allows additional storage space for flammable waste. The flammable liquid storage module is blocated along the south on the southeast wall, it and is connected to the buildings fire suppression system. The flammable liquid storage module has a 2-hour fire rated containment system so that according to the UFC, an unlimited capacity is allowed. However, the flammable waste storage capacity of the flammable liquid storage module is limited by the 240-gallon capacity of the module's secondary containment system. No more than 240 gallons of any combination of flammable liquid classes will be stored in the module. This flammable waste storage capacity is in addition to the flammable storage limits for the highbay. A diagram showing the module location in the highbay is provided in Figure 4-7.

Class 1	Class ¹ 1	Class 2	Class 3
X			
	Class 1 X	Class 1 Class 1 X	Class 1 Class 1 Class 2

Relevant WAC 173-303-830, Appendix I Modification:

A.1.

Enter wording of the modification from WAC 173-303-830, Appendix I citation

A. General Permit Provisions

1. Administrative and Informational changes

Submitted by Co-O		Reviewed by RL Program		Reviewed by E	cology:	Reviewed by	Ecology:
De Carroll for	3-15-02	Tet Christenson	4/1/02				
A.K. Ikenberry		R.F. Christensen	Date	F. Jamison	Date	L.E. Ruud	Date

¹Class 1 modifications requiring prior Agency approval.

² This is only an advanced notification of an intended Class ¹1, 2, or 3 modification, this should be followed with a formal modification request, and consequently implement the required Public Involvement processes when required.

³ If the proposed modification does not match any modification listed in WAC 173-303-830 Appendix I, then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology, or down graded to ¹1, if appropriate.

Hanford Facility RCRA Permit Modification Notification Form Permit Part & Chapter: 305-B Storage Facility Part III, Chapter 2 and Attachment 18 Description of Modification: Chapter 4.0, Section 4.1.1.6.7: 4.1.1.6.7 Oxidizer Waste Drum Universal and Recycling Waste Storage Area. A second section of the high bay (cell 12) has been dedicated to storage of drum quantities of oxidizer universal and recycling waste before offsite shipment. The area is 10ft x 7ft in size. All material in this area is stored in DOT approved containers and Waste drums stored in this area is stored on pallets to prevent contact with spilled waste in the event of an incident. Sump containment capacity in this area is approximately 55 gallons and total containment capacity is approximately 255 gallons. Maximum storage in this area will be eight 55-gallon drums. A diagram of this area is included in Figure 4-6. Modification Class: 123 Class¹1 Class 3 Class 1 Class 2 X Please check one of the Classes: Relevant WAC 173-303-830, Appendix I Modification: A.1. Enter wording of the modification from WAC 173-303-830, Appendix I citation A. General Permit Provisions 1. Administrative and Informational changes Reviewed by RL Program Office: Submitted by Co-Operator: Reviewed by Ecology: Reviewed by Ecology: 3-15-02 Tet Chesterson A.K. Ikenberry R.F. Christensen Date F. Jamison Date L.E. Ruud Date

¹ Class 1 modifications requiring prior Agency approval.

² This is only an advanced notification of an intended Class ¹1, 2, or 3 modification, this should be followed with a formal modification request, and consequently implement the required Public Involvement processes when required.

³ If the proposed modification does not match any modification listed in WAC 173-303-830 Appendix I, then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology, or down graded to ¹1, if appropriate.

Hanford Facility RCRA Permit Modification Notification Form Permit Part & Chapter: 305-B Storage Facility Part III, Chapter 2 and Attachment 18 Description of Modification: Chapter 4.0, Figure 4-6: Figure 4-6. Segregated High Bay Drum Storage Areas Packaging Supplies Floor Slope Acid Drum Storage Area Cell 13 Oxidizer Universal and Recycling Drum Storage Area Sampling Hood 1 cm = 60 cm1.egend Secondary Containment Trench Concrete Ledge Palletized Drum Storage Concrete Curb Sump Blockages Large Drum Cabinet A (exopy coated concrete) 360.68cm l x 317.5cm W x 121.92cm H 313.69cm l x 8.89cm W x 15.24cm H epoxy coated angle iron sealed to the floor stainless steel splash wall Modification Class: 123 Class¹1 Class 1 Class 2 Class 3 X Please check one of the Classes: Relevant WAC 173-303-830, Appendix I Modification: A.1. Enter wording of the modification from WAC 173-303-830, Appendix I citation A. General Permit Provisions 1. Administrative and Informational changes Submitted by Co-Operator: Reviewed by RL Program Office: Reviewed by Ecology: Reviewed by Ecology: 3-15-02 A.K. Ikenberry Date R.F. Christensen Date F. Jamison Date L.E. Ruud Date

¹Class 1 modifications requiring prior Agency approval.

² This is only an advanced notification of an intended Class ¹1, 2, or 3 modification, this should be followed with a formal modification request, and consequently implement the required Public Involvement processes when required.

³ If the proposed modification does not match any modification listed in WAC 173-303-830 Appendix I, then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology, or down graded to ¹1, if appropriate.

Hanford Facility RCRA Permit Modification Notification Form

Unit:

305-B Storage Facility


Permit Part & Chapter:

Part III, Chapter 2 and Attachment 18

Description of Modification:

Chapter 4.0, Figure 4-7:

Figure 4-7. High Bay Storage Area (Page 1 of 2)



Modification Class: 123 Class 1 Class 1 Class 2 Class 3

Please check one of the Classes: X

Relevant WAC 173-303-830, Appendix I Modification: A.1.

Enter wording of the modification from WAC 173-303-830, Appendix I citation

A. General Permit Provisions

1. Administrative and Informational changes

Submitted by Co-Op	erator:	Reviewed by RL Program	n Office:	Reviewed by Ed	cology:	Reviewed by	Ecology:
DeCarroll for	3-15-02	Tex Chustenson	4/1/02				
A.K. Ikenberry	Date	R.F. Christensen	Date	F. Jamison	Date	L.E. Ruud	Date

¹Class 1 modifications requiring prior Agency approval.

² This is only an advanced notification of an intended Class ¹1, 2, or 3 modification, this should be followed with a formal modification request, and consequently implement the required Public Involvement processes when required.

³ If the proposed modification does not match any modification listed in WAC 173-303-830 Appendix I, then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology, or down graded to ¹1, if appropriate.

Page 10 of 10

Hanford Facility RCRA Permit Modification Notification Form Unit Permit Part & Chapter 305-B Storage Facility Part III Chapter 2 and Attachment 18

Description of Modification

Chapter 6 0 Section 6 2 1 1

Quarterly Once Every Four Months and Annual Inspections In addition to the several layers of management inspection of 305 B Storage Facility safety inspections are performed to assure the fire protection system eye wash/shower unit, and walk in hood ventilation systems are in working order. The Hanford 300 Area Fire Department performs—once every four months—a inspection of fire suppressant and notification systems (i.e. sprinkler system and pull boxes). This inspection includes flow tests of the sprinklers to assure no blockage in the system lines as well as activation of the alarm system to assure proper operation of pull boxes. On an annual basis, the Fire Department performs a full inspection of the sprinkler system, heat detectors and pull boxes. A complete flow test is performed from the furthest valve to assure flow through

the entire system Fire extinguishers are also checked for proper pressure and function Records of these fire inspections and the Hanford Fire Department keeps their results Documentation of any required corrective actions is kept in the 305 B Storage Facility Operating Record

PNNL facilities support staff perform additional documented inspections of the two emergency eye wash/shower units and the walk in hood airflow. The safety showers and airflow of the walk in hood are inspected quarterly. The emergency eyewash/safety showers are checked for proper operation, and the walk in hood ventilation face velocity must meet a 125-fpm minimum requirements. Records of these safety equipment inspections and their results as well as documentation of any required corrective actions are maintained by the preventive maintenance staff in PNNL s Facilities Management Department and Technical Services Department

Modification Class 12 3 Please check one of the Classes	Class 1	Class ¹ 1	Class 2	Class 3
	X A 1			7
Enter wording of the modification from WAC 173 303 830, A General Permit Provisions 1 Administrative and Informational changes	Appendix I c	<u>itation</u>		. "
Submitted by Co Operator Reviewed by RL Program Office Reviewed by RL Program Office Reviewed by RL Program Office Reviewed by RL Program Office		by Ecology	Reviewed	by Ecology
A K Ikenberry Date R F Christensen Date	F Jamisoi	n Date	LE Ruud	Date

¹Class 1 modifications requiring prior Agency approval

² This is only an advanced notification of an intended Class ¹1 2 or 3 modification this should be followed with a formal modification request and consequently implement the required Public Involvement processes when required

³ If the proposed modification does not match any modification listed in WAC 173 303 830 Appendix I then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology or down graded to ¹1 if appropriate

Hanford Facility RCRA Permit Modification Part III, Chapter 2 and Attachment 18 305 B Storage Facility

Replacement Sections

Index

Chapter 3 0

Chapter 4 0

Chapter 6 0

2	3 0	WASTE ANALYSIS [C]	3 3
3 4	3 1	CHEMICAL BIOLOGICAL AND PHYSICAL ANALYSIS [C 1]	3 3
5	3 1 1	Containerized Waste	3 5
6	312	***	3 5
7	313	· · · · · · · · · · · · · · · · · · ·	3 5
8	314	Landfill Waste [C 1b]	3 5
9		Waste Incinerated and Waste Used in Performance Tests [C 1c]	3 5
10	316		3 5
11			, ,
12	3 2	WASTE ANALYSIS PLAN [C 2]	3 5
13	321	Facility Description	3 5
14	322	Description of Facility Processes and Activities	3 6
15	3 2 3	Identification/EPA Classification and Quantities of Hazardous Wastes Managed	
16		Within the 305 B Storage Facility	3 10
17	324	Description of Hazardous Waste Management Units	3 10
18	• - /	2	
19	33	SELECTING WASTE ANALYSIS PARAMETERS	3 10
20	331	Parameter Selection Process	3 10
21	3 3 2		3 12
22	3 3 3	Special Parameter Selection Requirements	3 12
23		- France	
24	3 4	SELECTING SAMPLING PROCEDURES	3 13
25	341	Sampling Strategies and Equipment	3 13
26	3 4 2	Sampling Preservation and Storage	3 13
27	3 4 3	Sampling QA/QC Procedures	3 13
28	3 4 4	Health and Safety Protocols	3 17
29			
30	3 5	SELECTING A LABORATORY AND LABORATORY TESTING AND	
31		ANALYTICAL METHODS	3 17
32	351	Selecting a Laboratory	3 17
33	3 5 2	Selecting Testing and Analytical Methods	3 18
34			
35	3 6	SELECTING WASTE RE EVALUATION FREQUENCIES	3 18
36			
37	37	SPECIAL PROCEDURAL REQUIREMENTS	3 19
38	3 7 1	Procedures for Receiving Waste From off site Generators	3 19
39	372	Procedures for Ignitable Reactive and Incompatible Wastes	3 20
40	373	Procedures To Ensure Compliance With LDR Requirements	3 21
41			
42		TABLES	
43 44	Table	3 1 Summary of Test Parameters Rationales and Methods	3 23

CONTENTS

This page intentionally left blank

2 3 4	The purpose of this Waste Analysis Plan (WAP) is to document the waste acceptance process sampling methodologies analytical techniques and processes that are undertaken for sampling and analysis of dangerous and or mixed waste managed in the 305 B Storage Facility
5 6	This chapter also provides information on the chemical biological and physical characteristics of the waste stored at the 305 B Storage Facility
7	3 1CHEMICAL, BIOLOGICAL, AND PHYSICAL ANALYSIS [C 1]
8 9	The dangerous waste and RMW stored at 305 B Storage Facility can be categorized as originating from five basic sources
10 11 12 13 14	Listed Waste from specific and nonspecific sources Discarded commercial chemical products Waste from research activities using radioactive isotopes Waste from chemicals synthesized or created in research laboratories Discarded commercial products exhibiting dangerous waste characteristics and/or criteria
15 16 17	Each of these waste categories is discussed below including waste descriptions hazard characteristics and bases for hazard designations. This information includes that which must be known to treat store or dispose of the waste as required under WAC 173 303 806(4)(a)(ii)
18 19 20	<u>Listed Waste from Specific and Nonspecific Sources</u> Waste from specific and nonspecific sources consist of those listed waste identified in WAC 173 303 9904 The Part A Form 3 for 305 B Storage Facility identifies the waste from this category with their estimated annual management quantities
21 22 23 24 25 26 27 28 29 30	Halogenated and nonhalogenated solvents are in the form of spent solvents. Degreasing solvents (F001) as well as spent halogenated solvents (F002) are used primarily in research although some commercial applications do exist (e.g. printing duplicating). Spent non halogenated solvents (F003-F004 and F005) also come primarily from research laboratories although some is generated through maintenance applications. Manufacturing activities are not performed at Hanford therefore dangerous waste from specific sources (WAC 173-303-9904 K. Waste) typically are not generated at PNNL. However small quantities of K. listed waste have been generated from treatability studies and sample characterization activities at PNNL from time to time and could be stored at 305 B. Storage Facility. W001 state source waste (PCB electrical equipment waste) has been generated in limited amounts in the past and could be stored at 305 B. Storage Facility if other generation activities occur.
31 32 33 34 35 36 37 38	F listed waste is designated on the basis of process knowledge (i.e. information from container labels or material safety data sheets) or by sampling. Sampling is performed if the generating unit does not have sufficient information to document the composition and characteristics of the waste. The waste generator is responsible for specifying the characteristics of the waste on the basis of knowledge of the chemical products used (i.e. information supplied by the manufacturer) and the process generating the waste. These listed waste are all designated as dangerous waste (DW) or extremely hazardous waste (EHW) based on the criteria given in WAC 173 303 100. Waste F027 is designated as an LDR waste under 40 CFR 268 31 (dioxin containing waste).
39 40	Waste code W001 is assigned to wastes meeting the criteria given in WAC 173 303 9904 and not exempted by WAC 173 303 071(3)(k)
41 42 43 44	<u>Discarded Chemical Products</u> Discarded chemical products consist of those products described in WAC 173 303 081 The Part A Form 3 for 305 B Storage Facility identifies all of the discarded chemical products listed in WAC 173 303 9903 and specifies an estimated maximum annual management quantity based on prior experience. The Part A permit application lists all of these waste codes however

30 WASTE ANALYSIS [C]

13

14

15

16 17

18

19

20

21

22

23

24

25

26

27

39

40

41

42

43

44

45

46

47

- because the wide variety of research activities conducted at Hanford presents the potential to generate any of these waste
- These waste (P waste and U waste) are typically received at 305 B Storage Facility in the manufacturer's original container. These containers typically consist of glass and polyethylene jars or bottles and metal cans that have a volume equal to or less than 4 liters.
- Waste in this category are designated on the basis of the generator's knowledge. As these waste are usually in original containers information on the container label is verified by generator knowledge (i.e. knowledge that material is in its original container) and is used to identify contents. Waste in as procured containers (i.e. original container with intact label) are not sampled. These listed waste contain those designated as DW as well as those designated as EHW. These waste are also subject to LDR regulations under 40 CFR 268 including disposal prohibitions and treatment standards.
 - Waste from Research Activities Using Radioactive Isotopes Dangerous waste from research activities using radioactive isotopes are RMW. These waste are generated in laboratories performing chemical and physical research and consist primarily of radiologically contaminated chemicals. These waste are designated on the basis of the generator's knowledge or on the basis of sampling and analysis. The generator's knowledge is used if the generator has kept accurate records of the identities and concentrations of constituents present in the waste. For example, many generating units keep log sheets for accumulation containers in satellite areas to keep a record of waste constituents. If information available from the generator is inadequate for waste designation the waste are sampled and the results of the analysis are used for designation These waste include those designated as state only dangerous waste under WAC 173 303 100 and also those designated as characteristic dangerous waste under WAC 173 303 090 The Part A Permit Application for 305 B Storage Facility includes all categories of toxic and persistent waste (i.e. both DW and EHW). The wide variety of research activities conducted at Hanford presents the potential that these waste could be generated and require subsequent management at 305 B Storage Facility Similarly the Part A Form 3 permit application includes the characteristic dangerous waste categories D001 through D043 (i.e. ignitable corrosive reactive and TCLP toxic due to metals or organics content)
- Flammables (i.e. flash point less than 100. Fahrenheit) will not be stored in the below grade RMW cell however ignitables (D001 due to oxidizer content) will be stored in this cell. Flammable RMW is not stored below grade due to Fire Code restrictions. These waste are stored above the RMW cell in a flammable storage module. The flammable RMW module is equipped with secondary containment to provide greater than 100% secondary containment volume.
- The waste in this category includes those designated as either DW or EHW. The waste could also be federal LDR waste regulated under 40 CFR 268 as well as state LDR waste regulated under WAC 173 303 140 (e.g. organic/carbonaceous waste).
- Waste from Chemicals Synthesized or Created in Research Laboratories Waste from chemicals synthesized or created in research laboratories typically consist of organics in quantities of 100 g or less received in small containers
 - These waste are designated on the basis of the generator's knowledge or on the basis of sampling and analysis. The generator's knowledge is used if the generating unit has kept accurate records of the identities and concentrations of constituents present in the waste (e.g. log sheets for accumulation containers). If information available from the generating unit is inadequate for waste designation, the waste are sampled and the results of the analysis are used for designation. These waste include those designated as state only dangerous waste under WAC 173 303 100 and also those designated as characteristic dangerous waste under WAC 173 303 090. The Part A. Form 3 for 305 B. Storage Facility includes all categories of toxic and persistent waste (i.e. both DW and EHW). The wide variety of research activities conducted at Hanford presents the potential that these wastes could be generated and require subsequent management at 305 B. Storage Facility.

- The wastes in this category includes those designated as either DW or EHW. These wastes could also be
- federal LDR wastes regulated under 40 CFR 268 as well as state LDR wastes regulated under
- WAC 173 303 140 (e.g. organic/carbonaceous wastes)
- 4 <u>Discarded Chemical Products Exhibiting Dangerous Waste Characteristics and/or Criteria</u> Many
- discarded chemical products handled in 305 B Storage Facility are not listed in WAC 173 303 9903 and
- 6 are still considered dangerous waste since they exhibit at least one dangerous waste characteristic and/or
- 7 criterion (WAC 173 303 090 and WAC 173 303 100) These wastes are included with those listed in the
- Part A Form 3 under waste codes D001 through D043 WT01 WT02 WP01 WP02 and WP03 These
- 9 containers typically consist of glass and polyethylene jars or bottles and metal cans that have a maximum
- 10 volume of 4 liters
- Waste in this category are designated based on the generator's knowledge. As these waste are usually in
- their original containers information on the container label is verified by the generator's knowledge and is
- used to identify the contents. These waste contain those designated as DW as well as those designated as
- 14 EHW These waste could also be federal LDR waste regulated under 40 CFR 268 as well as state LDR
- waste regulated under WAC 173 303 140 (e.g. organic/carbonaceous waste)

16 311 Containerized Waste

- 17 The container storage areas at 305 B Storage Facility meet the containment system requirements of
- 18 WAC 173 303 630(7)(c) Testing or documentation that the dangerous waste stored at 305 B Storage
- 19 Facility does not contain free liquids is not required

20 3 1 2 Waste in Tank Systems

This section does not apply to the 305 B Storage Facility because wastes are not stored in tanks

22 3 1 3 Waste in Piles [C 1a]

23 This section does not apply to the 305 B Storage Facility because wastes are not stored in piles

24 3 1 4 Landfill Waste [C 1b]

This section does not apply to the 305 B Storage Facility because wastes are not placed in landfills

26 3 1 5 Waste Incinerated and Waste Used in Performance Tests [C 1c]

This section does not apply to the 305 B Storage Unit because wastes are not incinerated

28 3 1 6 Waste to be Land Treated

This section does not apply to the 305 B Storage Facility because waste does not undergo land treatment

30 3 2WASTE ANALYSIS PLAN [C 2]

- This section describes the procedures used to obtain the information necessary to manage waste in
- accordance with the requirements of WAC 173 303 (Ecology 2000)

33 3 2 1 Facility Description

- The 305 B Storage Facility is a dangerous waste and RMW storage unit owned and operated by the
- 35 Department of Energy and co operated by Pacific Northwest National Laboratory The unit is used for
- 36 the collection consolidation packaging storage and preparation for transport and disposal of both
- dangerous waste and RMW It is an integral part of the Hanford Site's waste management system
- 38 The 305 B Storage Facility is a one story frame and masonry building with basement constructed in the
- early 1950s with an attached two story high metal and concrete building constructed in January 1978
- referred to in this document as the high bay. The unit is located within the 300 Area, and was formerly
- 41 used for engineering research and development. Unit upgrades were completed in 1988 to meet

- requirements for storage of dangerous waste and RMW Waste storage under interim status began in
- 2 March 1989

3 2 2 Description of Facility Processes and Activities

- A variety of small volume chemical wastes are generated by PNNL's research laboratory activities. These
- wastes are brought to the 305 B Storage Facility and segregated by compatibility for storage in the unit
- 6 until enough waste is accumulated to fill a labpack or bulking container usually a 30 55 gallon drum
- When a sufficient number of shipping containers of waste have accumulated they are manifested for
- 8 shipment generally to permitted off site recycling treatment or disposal facilities
- 9 Dangerous wastes are stored in the high bay. The high bay has been equipped with a secondary
- containment system to facilitate storage of containerized wastes. In addition, four storage cells, have
- been constructed within the high bay area for segregated storage of incompatible waste streams. Each of
- the cells is approximately 14 x 14 enclosed by 4 high concrete block walls each cell has its own
- separate secondary containment system Drum quantity storage for incompatible wastes is allowed in
- these cells and in separated areas of the high bay
- Radioactive mixed waste (RMW) is stored in the basement of the original wing of the building in an area
- approximately 18 x 32 Flammable RMW cannot be stored below grade (per Uniform Fire Code) and is
- stored in an independent area on the first floor of the original wing in the RMW flammable storage
- 18 module

- Most of the information necessary to manage waste at 305 B Storage Facility is obtained from generating
- 20 units without the need to perform detailed chemical physical and biological analysis. This approach is
- 21 used for the following reasons
- Waste stored at 305 B Storage Facility are generated on the Hanford Site and/or by PNNL research
- programs effective administrative control can be maintained over individual waste generating units
- 24 (1 e the same organization generates the waste and operates the storage unit)
 - Wastes stored at 305 B Storage Facility may be discarded chemical products for which knowledge of
- waste characteristics is available without further analysis
- 27 Many of the waste stored at 305 B Storage Facility result from research activities that are carefully
- 28 controlled and documented this documentation includes information on chemical constituents
- Information provided by waste generating units is verified before wastes are accepted for transport to
- 30 305 B Storage Facility (e.g. wastes are inspected to verify that they are as described in the disposal
- request) Generating units are not required to sample wastes unless they have inadequate process
- 32 knowledge to designate waste additional LDR information is needed or visual verification failure occurs
- Verification sampling of waste to be shipped offsite from 305 B Storage Facility is required by the
- disposal contractor and the contractor performs these analyses
- 35 Because of the importance of administrative controls for the purposes of waste analysis procedures for
- 36 management of wastes from the time of generation through storage at 305 B Storage Facility are
- described below These procedures demonstrate how sufficient knowledge is obtained from generating
- units to properly manage dangerous and mixed waste at 305 B Storage Facility. In the event that such
- knowledge is not available sampling and analysis is required by 305 B Storage Facility procedures prior
- 40 to shipment to the storage unit
- The 305 B Storage Facility personnel shall collect from the generating unit(s) the information pursuant to
- 42 40 CFR 268 7(a) regarding LDR wastes the appropriate treatment standards whether the waste meets the
- 43 treatment standards and the certification that the waste meets the treatment standards if necessary as
- 44 well as any waste analysis data that supports the generator's determinations. If this information is not
- 45 supplied by the generating unit then the 305 B Storage Facility personnel shall be responsible for
- 46 completion and transmittal of all subsequent information regarding LDR wastes pursuant to
- 47 40 CFR 268 7(b) All waste streams must be re characterized at least annually or when generating unit

- and/or 305 B Storage Facility personnel have reason to believe the waste stream has changed to
- 2 determine compliance with LDR requirements in 40 CFR 268
- 3 <u>Volumetric Description of Waste</u> A wide range of waste volumes is collected from research and support
- 4 activities The largest unit container collected is a DOT container <0.46 m³ while the smallest is a trace
- 5 amount in a small vial
- 6 Large volume containers (greater than 4 L) (commonly contain chemicals such as those listed in
- WAC 173 303 9903 and 9904 and in 40 CFR 261 33) or commercial products which exhibit one or
- 8 more of the dangerous waste characteristics or criteria. Greater than 99 percent of the containers
- 9 generally contain chemicals for which information is easily accessible to determine dangerous
- designation This information is generally obtained from the container label for those waste in original
- containers or from the material safety data sheet (MSDS) for the product
- 12 <u>Notification for Storing of Waste</u> The waste analysis process begins when the waste management
- organization is notified of the presence of a chemical or mixed waste. This notification is accomplished
- by the generating unit completing and transmitting a Chemical Disposal/Recycle Request Form (for
- example see Figure 2 8) The form describes the volume and chemical composition of waste in each
- waste container for disposal Hazard and compatibility information are obtained for each item on the
- disposal request form to ensure the safety of the waste management organization staff that collect and
- transport the waste and to ensure safe and appropriate storage in 305 B Storage Facility
- 19 The compatibility and hazard class are determined using reference material that may include Condensed
- Chemical Dictionary Merck Index 49 CFR NIOSH Sigma Aldrich or any other reference material that
- 21 is applicable. The priority of hazard designation for those substances with multiple hazards or for
- 22 mixtures is the same used by the DOT in 49 CFR 173 2 (DOT 2000) as shown below
- 23 1) Radioactive material
- 24 2) Poison A
- 25 3) Flammable gas
- 26 4) Nonflammable gas
- 5) Flammable liquid
- 28 6) Oxidizer
- 29 7) Flammable solid
- 30 8) Corrosive material (liquid)
- 31 9) Poison B
- 32 10) Corrosive material (solid)
- 33 11) Irritating materials
- 34 12) Combustible liquid (exceeding 110 gal)
- 35 13) Other Regulated Material (ORM) B
- 36 14) ORM A
- 37 (less than 110 gal)
- 38 16) ORM E
- 39 Chemical Disposal and Recycle Requests (CDRR) and other information used for determining waste
- 40 designations and compatibility must meet four distinct needs of the dangerous waste manager and sample
- 41 collector They must enable each to
- 42 Identify those waste which are designated dangerous in accordance with WAC 173 303 and whether
- those waste are DW or EHW
- 44 Determine whether the waste is restricted from land disposal under 40 CFR 268 or
- WAC 173 303 140 and as whether it complies with applicable treatment standards under
- 46 40 CFR 268 or WAC 173 303 140
- 47 Identify and verify specific morphological characteristics of waste in solid or solution form
- 48 Outline how to safely handle transport analyze store and dispose of the waste product or sample

1 Physical Analysis Visual validation as a physical analysis procedure is strongly relied upon to confirm 2 the nature of a waste collected or sampled and to determine the accuracy of the disposal request 3 information received from the generating unit. It is impractical for the waste management organization to 4 chemically analyze each container or vial of waste accepted for storage in 305 B Storage Facility since 5 the amount can exceed 10 000 per year A more realistic approach to reducing risks to safety and the environment and one implemented at 305 B Storage Facility includes trained and experienced personnel 6 7 performing a visual inspection of the waste and direct inquiry of the generating unit's personnel. The 8 waste is inspected to verify that it matches the description on the disposal request. If the waste is a 9 discarded product the contents of the container are inspected to verify that they match the description of 10 the product For other waste e.g. spent solvents waste descriptions are compared with the products in 11 use at the generating unit Generating unit personnel are queried concerning the source of the waste and 12 the materials used in the process generating the waste. This information is compared to the description of 13 the waste on the disposal request. If after visual inspection of the waste and interrogation of the 14 generating unit personnel any doubt remains as to the true identity of the waste the waste is sampled and 15 analyzed by the generating unit as described in Section 3 5

Waste Collection at the Generating Unit When satisfactory information has been obtained from the CDRR Form waste management organization staff visit the generating unit site and make a final inspection of the waste containers to determine whether the disposal request form and contents label information match completely. If the information on the disposal request matches with the container labeling and visual inspection, the waste are approved for storage. If discrepancies are found the generating unit is required to resubmit the disposal request with accurate information. Unknown or unidentified materials are sampled by generating unit staff for identification of constituents and remain at the generating unit until the composition has been determined.

Labeling and Marking After inspection of the waste at the generating unit the approved waste are assigned a unique computer identification number and hazard classification. The waste containers are then marked and labeled in compliance with WAC 173 303 190 (DOT marking and labeling) and Washington Hazardous Waste markings. Waste meeting Washington dangerous waste criteria under WAC 173 303 090 or 173 303 100 are marked. Toxic (for waste designated WT01 or WT02) and/or Persistent. (for waste designated WP01 WP02 or WP03) in accordance with WAC 173 303 630(3). In addition, each waste container is labeled with a list of constituents and/or an appropriate hazard description. The containers are also labeled indicating compatibility group and cell location, and with a unique computer generated identification number created by the tracking system described below. This computerized information helps the waste handlers ensure safe handling, storage, retrieval and transportation of dangerous waste.

Transportation The labeled containers are transported to 305 B Storage Facility by PNNL staff trained in applicable DOT requirements and emergency response. Waste is transported using a truck or light utility vehicle. For transport on roads accessible to the public the vehicles are placarded in compliance with DOT regulations and documented in compliance with WAC 173 303 180. Hanford Facility Permit conditions II P and/or II Q as applicable.

Waste Handling Storage and Tracking at 305 B Storage Facility Waste received at 305 B Storage
Facility is put into 13 separate hazard classifications based on building and fire code restrictions for that type of facility

- 1) Nonflammable RMW
- 44 2) Oxidizers
- 45 3) Acids (organic and inorganic)
- 46 4) Poison

16

17

18

19

20

21

22 23

24

25

26

27

28

29 30

31

32

33

34

- 47 5) Caustics
- 48 6) Halogenated Hydrocarbons
- 49 7) Non Regulated
- 8) Miscellaneous (ORM categories)

- 9) Washington State only waste (e.g. sodium chloride sodium bicarbonate)
- 2 10) Flammable and combustible liquids
- 3 11) Flammable and combustible RMW
 - 12) TSCA waste (PCB and asbestos) waste
- 5 13) Special Case waste (organic peroxides explosives etc.)
- 6 Each hazard class has designated and clearly identified locations within 305 B Storage Facility
- 7 Containers of dangerous waste (10 gal or less) are stored in a specific storage cabinet or shelf designed for
- 8 that hazard class The cabinets are located inside the appropriate storage cell (i.e. acid storage cabinet in
- 9 acid cell) DOT approved containers (typically 10 gal and larger but less than 0 46m³) are segregated by
- hazard class and can be stored in a appropriate storage cell or on the main high bay floor in 305 B Storage
- 11 Facility

- Only sealed containers of nonflammable RMW are received in the below grade RMW storage area
- located in the basement of 305 B Storage Facility Containers of flammable RMW are stored above
- grade in a flammable storage module adjacent to the high bay area. All chemical storage is in accordance
- with fire protection requirements of the 1988 Uniform Fire Code (International Conference of Building
- 16 Officials 1988)
- 17 Storage limits for all chemicals are listed in Table 4.1 (Uniform Building Code Table numbers 9. A and
- 9 B) This table is incorporated into this section by reference
- 19 Recordkeeping and Inventory Control A computer tracking system has been developed to ensure that
- complete records of current inventory packaging and shipping data are maintained Records of the
- 21 initial waste disposal request form waste analysis results if required waste designation and shipping
- 22 manifest are maintained. As waste are received for disposal, the containers are labeled with the
- 23 information described in the <u>Labeling and Marking</u> section above including a unique computer
- 24 identification number. This number is also written on the disposal request form. The label information is
- 25 then entered into the computerized database along with the storage location within 305 B Storage
- 26 Facility
- The endpoint of the process for most waste is proper packaging and transport of the waste to an approved
- 28 recycler or treatment/disposal facility Some commercial chemical products however are redistributed to
- other Hanford Site contractors as described in Section 10.4 Final computer verification of the history
- and ultimate disposal of each waste container is entered when the material is shipped from the
- 31 305 B Storage Facility
- 32 Current waste quantities in inventory are periodically verified and reported to the Unit Operations
- 33 Supervisor The inventory is checked by hazard class and provides a measure of current inventory versus
- 34 established limits
- 35 If it is determined that 305 B Storage Facility inventory is within 5 percent of the limit for a given hazard
- 36 classification additional waste of that hazard class is not accepted into 305 B Storage Facility until the
- 37 inventory has been reduced. Exceptions must be approved by the unit operating supervisor
- 38 Unknown Waste and Waste Constituent Verification Containers with unknown waste compositions are
- 39 not accepted at 305 B Storage Facility. In the event that 305 B Storage Facility staff are required to
- respond to a critical need of a generating unit in the future and pick up an unknown waste it will be
- sampled and analyzed as described in Sections 3 2 1 through 3 2 6
- 42 If for any reason 305 B Storage Facility personnel believe that more stringent analysis of non reagent
- 43 grade chemical waste is needed (i.e. flash cans and mixtures), they will request that the generating unit
- 44 have the waste analyzed by an approved analytical laboratory Reasons for this request may be
- 45 questionable appearance of the waste periodic confirmation of waste composition or historically
- 46 unreliable information from a particular generating unit. There is no established frequency for this
- sampling and analysis it is conducted on an as needed basis. This analysis must be performed in
- 48 accordance with EPA SW 846 procedures (EPA 1986) Analytical laboratories in the area with these

6

7

8

9

12

53

34

36

capabilities include commercial Hanford Site and Battelle operated laboratories. The generating unit
must also provide the laboratory analysis confirming the waste composition when the waste management
organization picks up the waste. This analysis will become part of the 305 B Storage Facility Operating
Record

3 2 3 Identification/EPA Classification and Quantities of Hazardous Wastes Managed Within the 305 B Storage Facility

Refer to Section 3.1 for a description of the types and quantities of wastes managed at 305 B Storage Facility

3 2 4 Description of Hazardous Waste Management Units

- The 305 B Storage Facility Waste Management Units are described in Attachment 18 305 Storage
- Facility Chapter 4 0 of the Hanford Facility RCRA Permit

3 3 SELECTING WASTE ANALYSIS PARAMETERS

- 13 State and federal regulations [WAC 173 303 300(2) and (5)(a) WAC 173 303 140 40 CFR 268 7(a)]
- require that information be obtained documented and/or reported on wastes received by a TSD unit
- These requirements include ensuring that only waste which meets 305 B Storage Facility unit specific
- permit requirements are accepted and reporting the information required by WAC 173 303 380 In
- addition to providing a general description of the waste the focus of the information collected for
- regulatory purposes is to ensure that the 305 B Storage Facility is permitted to accept and store the waste
- The 305 B Storage Facility only accepts wastes that have been characterized properly Before receipt or
- acceptance of waste at the 305 B Storage Facility generators must supply adequate information to
- 21 characterize and manage wastes properly
- One of the most important aspects of operating the 305 B Storage Facility in a safe manner is to ensure
- 23 that incompatible wastes are not mixed together. For the purposes of this document waste are considered
- compatible if when mixed they do not (1) generate extreme heat or pressure fire or explosion or
- 25 violent reaction (2) produce uncontrolled toxic mists dusts or gases in sufficient quantities to threaten
- 26 human health (3) produce uncontrolled flammable fumes or gases in sufficient quantities to pose a risk of
- fire or explosions (4) damage the structural integrity of the device or facility containing the waste or
- 28 (5) through other like means threaten human health or the environment
- Sampling and laboratory analysis could be required to verify or establish waste characteristics for waste
- that is stored at the 305 B Storage Facility. The following are instances where sampling and laboratory
- ol analysis is required
- 32 inadequate information on PNNL generated waste
 - 5 percent waste verification for PNNL generated waste
 - 10 percent waste verification for non PNNL generated waste
- 35 identification and characterization for unknown waste and spills within the unit

3 3 1 Parameter Selection Process

- 37 The selection of analytical parameters is based on the State of Washington's Dangerous Waste
- Regulations WAC 173 303 300 and EPA Waste Analysis at Facilities That Generate Treat Store and
- 39 Dispose of Hazardous Wastes A Guidance Manual (EPA 1994)
- At least five percent of the waste containers received at 305 B during a federal fiscal year (October 1
- 41 through September 30) will undergo confirmation of designation pursuant to Sections 3 2 2 and 3 2 3
- 42 (Test Methods and Sampling Methods respectively) The number of containers needed to meet the
- five percent requirement is five percent of the average of containers for the previous three months. For
- example if 200 containers are received in January 180 in February and 220 in March then 10 containers
- of received waste must undergo confirmation of designation in April All generating units which ship

37

38

39

40

41

performed

1 more than 20 containers through 305 B Storage Facility in a fiscal year will have at least one 1 container 2 sampled and analyzed Containers for which there is insufficient process knowledge or analytical 3 information to designate without sampling and analysis may not be counted as part of the five percent 4 requirement unless there is additional confirmation of designation independent of the generator 5 designation. The generating unit's staff shall not select the waste containers to be sampled and analyzed 6 other than identifying containers for which insufficient information is available to designate 7 Containers of the following are exempt from the confirmation calculation above Laboratory reagents or 8 other unused products such as paint lubricants solvent or cleaning products whether received for 9 redistribution recycling or as waste To qualify for this exemption such materials must be received at 10 305 B Storage Facility in their original containers 11 Prior to acceptance of wastes at 305 B Storage Facility confirmation of designation may be required 12 (Section 3 7 3) The wastes that shall undergo confirmation of designation are identified in Condition III 2 B f of this Permit and may be divided into two groups those that easily yield a 13 14 representative sample (Category I) and those that do not (Category II) The steps for each type are 15 outlined below along with a description of which wastes fall into each category 16 Category I If a waste which easily yields a representative sample is received a representative sample will 17 be taken from the waste containers selected If more than one phase is present each phase must be tested 18 individually. The following field tests will be performed as appropriate for the waste stream Reactivity HAZCATTM oxidizer cyanide and sulfide tests. These tests will not be performed on 19 20 materials known to be organic peroxides ethers and/or water reactive compounds 21 Flashpoint/explosivity by HAZCATTM flammability procedure explosive atmosphere meter or a closed cup flashpoint measurement instrument 22 pH by pH meter¹ or pH paper (SW 846 9041)² This test will not be performed on non aqueous 23 24 materials Halogenated organic compounds by Chlor D TectTM kits 25 Volatile organic compounds by photo or flame ionization tester by gas chromatography with or 26 27 without mass spectrometry or by melting point and/or boiling point determination 28 If the sample data observed meets the parameters specified in its documentation confirmation of 29 designation is complete and the waste may be accepted. If not, the waste is rejected and returned to the 30 generating unit for additional characterization. The waste will be required to be resubmitted with a revised 31 Chemical Disposal/Recycle Request (CD/RR) following the additional characterization activity 32 When mathematically possible the Permittees shall perform confirmation on an equal number of 33 Category I and Category II containers 34 Category II If a representative sample is not easily obtained (for example discarded machinery or shop 35 rags) or if the waste is a labpack or discarded laboratory reagent container the following steps will be

a Visually verify the waste Examine each selected container to ensure that it matches the data provided on the CD/RR form(s) provided to document the waste Labpacks and combination packages must be removed from the outer container. If the waste matches the description specified in its documentation confirmation of designation is complete and the waste may be accepted. If not, the waste is rejected and returned to the generating unit, and the generating unit revises and resubmits the documentation.

¹ These instruments are field calibrated or checked for accuracy daily when in use

² The pH paper must have a distinct color change every 0.5 pH units and each batch of paper must be calibrated against certified pH buffers or by comparison with a pH meter calibrated with certified pH buffers

2

3

4

5 6

18

19 20

24 25

26 27

28

29

30

35

to reflect the actual contents. If necessary, the waste shall be re-designated utilizing the designation methods identified in WAC 173 303 070 through 173 303 100.

Wastes must be analyzed using the Toxicity Characteristic Leaching Procedure (TCLP) in accordance with Appendix II of 40 CFR 261 as amended in order to provide sufficient information for proper management and for decisions regarding LDR pursuant to 40 CFR 268

3 3 2 Criteria and Rational for Parameter Selection

- Waste testing methods parameters and the rationale for these parameters are summarized in Table 3 1
- 8 Waste testing methods and references to these methods are as specified in WAC 173 303 110(3) or
- 9 approved by Ecology in accordance with WAC 173 303 110(5) These methods are summarized in
- Table 3 1 All methods are specified in Chemical Testing Methods WDOE 83 13 (Ecology 1983) and/or
- 11 Test Methods for Evaluating Solid Waste Physical/Chemical Methods EPA SW 846 (EPA 1986)
- Testing parameters for each type of waste were selected to obtain data sufficient to designate the waste
- properly under WAC 173 303 070 meet requirements for Land Disposal Restrictions and to manage the
- waste properly If information on the source of the waste is available then all parameters might not be
- required e.g. exclusion of testing for pesticides from a metal machining operation
- Some of the parameters that are considered for waste received at the 305 B Storage Facility are as follows
 - Physical description used to determine the general characteristics of the waste. This facilitates subjective comparison of the sampled waste with previous waste descriptions or samples. Also a physical description is used to verify the observational presence or absence of free liquids.
- pH used to identify the pH and corrosive nature of an aqueous or solid waste to aid in establishing compatibility strategies and to indicate if the waste is acceptable for treatment and/or storage in the 325 HWTUs
 - Cyanide used to indicate whether the waste produces hydrogen cyanide upon acidification below pH 2
 - Sulfide screen used to indicate if the waste produces hydrogen sulfide upon acidification below pH 2
 - Halogenated hydrocarbon content screen used to indicate whether chlorinated hydrocarbons or polychlorinated biphenyls (PCBs) are present in waste and to determine if the waste needs to be managed in accordance with the regulations prescribed in the *Toxic Substance Control Act of 1976*
- Ignitability used to identify waste that must be managed and protected from sources of ignition or open flame
- HAZCAT TM testing tests used to determine waste characteristics and verify generator knowledge
 The testing procedures for each HAZCAT TM test are included in the HAZCAT Kit

333 Special Parameter Selection Requirements

- The 305 B Storage Facility does not have any process vents that manage hazardous waste with organic
- concentrations of at least 10 part per million by weight percent or pumps or compressors used more than
- 38 300 hours per year that come into contact with hazardous waste with an organic concentration of at least
- 39 10 percent by weight
- 40 A variety of small volume chemical wastes are generated by PNNLs research laboratory activities. These
- 41 containers typically range in sizes from 10 mil to 20 gallon. These wastes are brought to the
- 42 305 B Storage Facility and segregated by compatibility for storage in the unit until enough waste is
- 43 accumulated to fill a labpack or bulking container usually a 30 to 55 gallon drum All containers having
- a design capacity greater than 0 1 m3 to less than or equal to 0 46 m3 are equipped with a cover and

- complies with all applicable Department of Transportation regulations on packaging hazardous waste for
- 2 transport under 49 CFR part 178
- 3 DOT approved intermediate bulk packaging may be utilized for some solid wastes. These containers
- 4 range in size from 0 1cu yard (27 cu ft) to 1 6 cu yard (43 cu ft) and are approved for solid waste only

3 4 SELECTING SAMPLING PROCEDURES

3 4 1 Sampling Strategies and Equipment

- 7 Sample collection methods conform to the representative sample methods referenced in
- 8 WAC 173 303 110(2) The summary of test parameters rationales and sampling methods are identified
- 9 in Table 3.1

5

6

- 10 Representative samples of liquid waste from containers (vertical core sections) are typically obtained
- using a composite liquid waste sampler (COLIWASA) or tubing as appropriate. The sampler is long
- enough to reach the bottom of the container in order to provide a representative sample of all phases of
- the containerized liquid waste. If a liquid waste has more than one phase each phase is separated for
- 14 individual testing depending on the waste management pathways of the phases
- Other waste types that might require sampling are sludge's powders and granules. In general non
- viscous sludge's are sampled using a COLIWASA Highly viscous sludge's and cohesive solids are
- sampled using a trier as specified in SW 846. Dry powders and granules are sampled using a thief also
- as specified in SW 846
- Samplers are constructed of material compatible wit the waste. In general, aqueous liquids are sampled
- 20 using polyethylene samplers organic liquids using glass samplers and solids using polyethylene
- samplers Disposable samplers are used whenever possible to eliminate the potential for cross
- 22 contamination If non disposable sampling equipment is used it is decontaminated between samples
- using the guidelines in the unit sampling procedure
- 24 Representative sampling may be requested by unit staff to ensure proper waste identification. Sampling
- 25 may be performed by unit personnel or the generating unit producing the waste. The number of grab
- samples collected from a container depends on the amount of waste present and on the homogeneity of
- 27 the waste as determined by observation. In some cases, there will be only one container of waste present
- In such cases only one vertical composite sample will be collected (e.g. COLIWASA) If more than one
- container is present a random number of samples will be collected and analyzed statistically using the
- procedures specified in Section 9 2 of SW 846 (EPA 1986)
- In all instances sampling methods will conform to the representative sample method referenced in
- WAC 173 303 110(2) 1e ASTM standards for solids and SW 846 for liquids. The specific sampling
- methods and equipment used varies with the chemical and physical nature of the waste material and the
- 34 sampling circumstances

35

3 4 2 Sampling Preservation and Storage

- 36 All sample containers preservation techniques and hold times follow SW 846 protocol Many samples
- are analyzed at the 305 B Storage Facility utilizing prepackaged test kits and are not preserved

38 3 4 3 Sampling QA/QC Procedures

- 39 Pacific Northwest National Laboratory is committed to maintaining a high standard of quality for all of its
- 40 activities A crucial element in maintaining that standard is a quality assurance program that provides
- 41 management controls for conducting activities in a planned and controlled manner and enabling the
- 42 verification of those activities
- The QA/QC objective of the 305 B Storage Facility is to control and characterize errors associated with
- 44 collected data and to illustrate that waste testing has been performed according to specification in this
- 45 waste analysis plan

- The 305 B Storage Facility has developed procedures to ensure that precision and accuracy are
- 2 maintained throughout the waste analysis process For analysis using SW 846 methods the program will
- follow the QA/QC guidance set forth in SW 846 at a minimum Good laboratory practices which
- 4 encompasses sampling sampling handling housekeeping and safety are followed throughout the process
- 5 There are many elements of QA/QC associated with the sampling processes at the 305 B Storage Facility
- These practices ensure that all data and the decisions based on that data are technically sound statistically
- 7 valid and properly documented
- 8 Activities pertaining to waste analysis include but are not limited to the preparation review and control
- 9 of procedures and the selection of analytical laboratories The Laboratory's QA manual has
- administrative procedures that establish requirements and provide guidance for the preparation of
- analytical and technical (i.e. sampling chain of custody work processes) procedures as well as other
- administrative procedures Procedures undergo a review cycle and once issued are controlled to ensure
- that only current copies are used
- The primary purpose of waste testing is to ensure that the waste is properly characterized in lieu of
- process knowledge data in compliance with RCRA requirements for general waste analysis
- 16 [WAC 173 303 300(2) 40 CFR 264 13] Waste testing also is performed to ensure the safe management
- of waste being stored proper disposition of residuals from incidents that might occur and control of the
- acceptance of waste for storage The specific objectives of the waste sampling and analysis program at
- the 305 B Storage Facility are as follows
- 20 Identify the presence of waste that is substantially different from waste currently stored
- 21 Provide a detailed chemical and physical analysis of a representative sample of the waste before the
- waste is accepted at or transferred from the 305 B Storage Facility to an offsite TSD facility to
- ensure proper management and disposal
 - Provide an analysis that is accurate and up to date to ensure that waste is properly treated and
- 25 disposed of

29

33

- 26 Ensure safe management of waste undergoing storage at the 305 B Storage Facility
- 27 Ensure proper disposal of residuals
- 28 Ensure compliance with LDR s
 - Identify and reject waste that does not meet the 305 B Storage Facility s acceptance requirements
- 30 (e.g. incomplete information)
- 31 Identify and reject waste that does not meet specifications for the 305 B Storage Facility (i.e. Part A
- Form 3 listing restricted from storage at the 305 B Storage Facility)

QA/QC Objectives

- 34 The objectives of the QA/QC program are two fold The first objective is to control and characterize any
- 35 errors associated with the collected data. Quality assurance activities, such as the use of standard
- 36 procedures for locating and collecting samples are intended to limit the introduction of error Quality
- control activities such as the collection of duplicate samples and the inclusion of blanks in sample sets
- are intended to provide the information required to characterize any errors in the data. Other QC
- activities such as planning the QC program and auditing ongoing and completed activities ensure that
- 40 the specified procedures are followed and that the QA information needed for characterizing error is
- 41 obtained
- The second QA/QC objective is to illustrate that waste testing has been performed according to
- specification in this waste analysis plan. The QA/QC activities will include the following
- Field inspections performed and documented by 305 B Storage Facility staff or designee
- depending on the activity The inspections primarily are visual examinations but might include

1 2 3	measurements of materials and equipment used techniques employed and the final products. The purpose of these inspections is to verify that a specific guideline specification or procedure for the activity is completed successfully.
4 5	Field testing – performed onsite by 305 B Storage Facility staff (or designee) according to specified procedures
6 7 8	Laboratory analyses – performed by onsite or offsite laboratories on samples of waste. The purpose of the laboratory analyses is to determine constituents or characteristics present and the concentration or level.
9	Sampling Objectives
10	The data quality objectives (DQO) for the waste sampling and data analyses are as follows
11 12	Determine if waste samples are representative of the contents of the containers at the time the samples were taken
13 14	Determine if waste samples are representative of long term operations affecting the 305 B Storage Facility
15 16	Determine if waste accepted for storage is within the RCRA permit application documentation limitations
17 18	Determine if waste accepted for storage meets the requirements of the 305 B Storage Facility waste acceptance criteria
19	Determine if waste accepted for storage meets the information provided by the generator
20	Data Collection/Sampling Objectives
21 22 23	The acquired data need to be scientifically sound of known quality and thoroughly documented. The DQOs for the data assessment will be used to determine compliance with national quality standards which are as follows.
24 25	Precision – The precision will be the agreement between the collected samples (duplicates) for the same parameters at the same location and from the same collection vessel
26 27 28 29	Representativeness – The representativeness will address the degree to which the data accurately and precisely represent a real characterization of the population parameter variation at a sampling point sampling conditions and the environmental condition at the time of sampling. The issue of representativeness will be addressed for the following points
30 31	Based on the generating process the waste stream and its volume an adequate number of sampling locations are selected
32	The representativeness of selected media has been defined accurately
33	The sampling and analytical methodologies are appropriate
34	The environmental conditions at the time of sampling are documented
35 36	Completeness – The completeness will be defined as the capability of the sampling and analytical methodologies to measure the contaminants present in the waste accurately
37 38 39	Comparability – The comparability of the data generated will be defined as the data that are gathered using standardized sampling methods standardized analyses methods and quality controlled data reduction and validation methods

1 Analytical Objectives

- 2 Analytical data will be communicated clearly and documented to verify that laboratory data quality
- 3 objects are achieved

4

7

9

10

11

12

13

14

15 16

17

18 19

20

21

22 23

24

25

26

30

31

32

33

34

35 36

37 38

42

43

44

45

46

Field Quality Assurance and Quality Control

- Internal QA/QC checks will be established by submitting QA and QC samples to the analytical laboratory. The number of field QA samples will be approximately 5 percent of the total number of field
 - samples taken The 5 percent criterion commonly is accepted for a minimum number of QA/QC samples
- 8 The types and frequency of collection for field QA samples are as follows
 - Field Blanks A sample of analyte free media taken from the laboratory to the sampling site and returned to the laboratory unopened Field blanks are prepared and preserved using sample containers from the same lot as the other samples collected that day A sample blank is used to document contamination attributable to shipping and field handling procedures. This type of blank is useful in documenting contamination of volatile organics samples.
 - Field Duplicates defined as independent samples collected in such a manner that the samples are equally representative of the variables of interest at a given point in space and time. The laboratory will use the field duplicate as laboratory duplicate and/or matrix spikes. Thus, for the duplicate sample, there will be the normal sample analysis, the field duplicate, and the laboratory duplicate (inorganic analysis). Duplicate samples will provide an estimate of sampling precision.

Laboratory Quality Assurance and Quality Control

- All analytical work whether performed by independent laboratories is defined and controlled by a Statement of Work prepared in accordance with administrative procedures. The daily quality of analytical data generated in the analytical laboratories will be controlled by the implementation of an analytical laboratory QA plan. At a minimum, the plan will document the following
 - sample custody and management practices
- requirements for sample preparation and analytical procedures
- instrument maintenance and calibration requirements
- 27 internal QA/QC measures including the use of method blanks
- 28 required sample preservation protocols
- 29 analysis capabilities
 - The types of internal quality control checks are as follows
 - Method Blanks Method blanks usually consist of laboratory reagent grade water treated in the same manner as the sample (i.e. digested extracted distilled) that is analyzed and reported as a standard sample would be reported
 - Method Blank Spike A method blank spike is a sample of laboratory reagent grade water fortified (spiked) with the analytes of interest which is prepared and analyzed with the associated sample batch
 - Laboratory Control Sample A QC sample introduced into a process to monitor the performance of the system
- Matrix Spikes An aliquot of sample spiked with a known concentration of target analyte(s) The spiking occurs prior to sample preparation and analysis Matrix spikes will be performed on 5 percent of the samples (1 in 20) or one per batch of samples
 - Laboratory Duplicate Samples Duplicate samples are obtained by splitting a field sample into two separate aliquots and performing two separate analyses on the aliquots. The analyses of laboratory duplicates monitor the precision of the analytical method for the sample matrix, however, the analyses might be affected by nonhomogeneity of the sample in particular, by nonaqueous samples Duplicates are performed only in association with selected protocols. Duplicates are performed only

1 in association with selected protocols Laboratory duplicates are performed on 5 percent of the 2 samples (1 in 20) or one per batch of samples If the precision value exceeds the control limit then 3 the sample set must be reanalyzed for the parameter in question 4 Known QC Check Sample - This is a reference QC sample as denoted by SW 846 of known 5 concentration obtained from the EPA the National Institute of Standards and Technology or an 6 EPA approved commercial source This QC sample is taken to check the accuracy of an analytical 7 procedure The QC sample is particularly applicable when a minor revision or adjustment has been 8 made to an analytical procedure or instrument. The results of a QC check standard analysis are 9 compared with the true values and the percent recovery of the check standard is calculated 10 PNNL Analytical Chemistry Laboratory QA/QC 11 PNNL s analytical chemistry laboratory may need to be used to analyze samples of high activity 12 dangerous waste It has a rigorous QA plan that ensures that data produced are defensible scientifically 13 valid and of known precision and accuracy and meets the requirements of its clients 14 Offsite Laboratory QA/QC 15 When it is necessary to send samples to an independent laboratory contracts are not awarded until a pre 16 award evaluation of the prospective laboratory has been performed. The pre award evaluation process 17 involves the submittal of its QA plan to PNNL QA staff and the unit operating supervisor. It also may 18 involve a site visit by QA personnel and a technical expert or may consist of a review of the prospective 19 laboratories QA/QC documents and records of surveillances/inspections audits non conformances and 20 corrective actions maintained by PNNL or other Hanford Facility contractors 21 Recordkeeping 22 Records associated with the waste analysis plan and waste verification program are maintained by the 23 waste management organization A copy of the CDRR for each waste stream accepted at the 24 305 B Storage Facility is maintained as part of the operating record. Generators maintain their sampling 25 and analysis records The waste analysis plan will be revised whenever regulation changes affect the 26 waste analysis plan 27 Staff of the 305 B Storage Facility has a goal of continuous improvement by ensuring that all analytical 28 data produced is of known accuracy and precision exceeds all industry standards and is scientifically 29 valid Using the above practices and following the appropriate 305 B Storage Facility operating 30 procedures staff can monitor and ensure that progress is being made in the quality of the data produced 31 344 **Health and Safety Protocols** 32 During all sampling activities precautions will be taken to ensure that waste containers do not expel gases 33 and/or pressurized liquids. All personnel will be properly trained in safety and handling techniques 34 3 SSELECTING A LABORATORY AND LABORATORY TESTING AND ANALYTICAL 35 **METHODS** 36 351 Selecting a Laboratory 37 Laboratory selection is limited only a few laboratories are equipped to handle mixed waste because of 38 special equipment and procedures that must be used to minimize personnel exposure. Preference will be 39 given to any PNNL facility or other laboratories on the Hanford Facility that exhibit demonstrated experience and capabilities in three major areas 40 41 comprehensive written QA/QC program based on DOE RL requirements specifically for that 42 laboratory 43 audited for effective implementation of QA/QC program

participate in performance evaluation samples to demonstrate analytical proficiency

1	All laboratories (onsite or offsite) are required to have the following QA/QC documentation
2 3	Daily analytical data generated in the contracted analytical laboratories is controlled by the implementation of an analytical laboratory QA plan
4 5	Before commencement of the contract for analytical work the laboratory will have their QA plan available for review At a minimum the QA plan will document the following
6	sample custody and management practices
7	requirements for sample preparation and analytical procedures
8	instrument maintenance and calibration requirements
9	internal QA/QC measures including the use of method blanks
10	required sample preservation protocols
11	analysis capabilities
12	3 5 2 Selecting Testing and Analytical Methods
13 14 15 16 17 18 19	PNNL waste generators may need to conduct analyses to provide information to fill out Chemical Disposal & Recycle Requests (CDRRs) and to determine compatibility safety and operating information. As needed 305 B Storage Facility staff also will conduct analyses to determine completeness of information and if the waste meets the acceptance criteria for disposal treatment or storage at one of the Hanford Facility permitted treatment/storage/disposal areas or that of one of the offsite TSD facilities. Testing and analytical methods will depend on the type of analysis sought and the reason for needing the information.
20 21	Chemists and/or appropriate personnel working under approved QA guidelines perform all testing Analytical methods will be selected from those that are described in Section 3.3.1
22	3 6SELECTING WASTE RE EVALUATION FREQUENCIES
23 24 25 26	Some analysis will be needed to verify that waste streams received by the 305 B Storage Facility conform to the information on the CDRR and or the waste analysis sheet supplied by the generator. If discrepancies are found between information on the CDRR hazardous waste manifest shipping papers waste analysis documentation and verification analysis then the discrepancy will be resolved by
27 28	returning waste to the generator or sample and analyze the materials in accordance with WAC 173 303 110 and/or
29 30	reassessing and redesignating the waste repackaging and labeling as necessary or return to the generator
31 32	Periodic re evaluation provides verification that the results from the initial verification are still valid Periodic re evaluation also checks for changes in the waste stream
33	Exceptions to physical screening for verification are
34 35 36 37	Analysis and characterization as required by WAC 173 303 300(2) are performed on each waste before acceptance at the 305 B Storage Facility to determine waste designation and characteristics. The characterization of the waste based on this information is reviewed each time a waste is accepted. The information must be updated by the generator when the waste stream changes or if the following occurs
38 39	The 305 B Storage Facility personnel have reason to suspect a change in the waste based on inconsistencies in packaging labeling or visual inspection of the waste
40	The information submitted previously does not match the characteristics of the waste submitted

- Sampling and laboratory analysis could be required to verify or establish waste characteristics for waste 1 2 that is stored at the 305 B Storage Facility The following are instances where sampling and laboratory 3 analysis are required 4 inadequate information on PNNL generated waste 5 waste streams generated onsite will be verified at 5 percent of each waste stream 6 inadequate information before waste was shipped or discrepancy discovered 7 waste streams received from offsite generators will be verified at 10 percent of each waste stream 8 applied per generator per shipment 9 identification and characterization for unknown waste and spills 10 3 7SPECIAL PROCEDURAL REQUIREMENTS 11 Procedures for Receiving Waste From off site Generators 12 Most of the waste stored at 305 B Storage Facility is generated on the Hanford Site and/or by PNNL 13 research programs within the 300 Area Additional requirements for waste generated outside the 14 300 Area include proper manifesting (if appropriate) to 305 B Storage Facility and proper packaging for 15 transport over public roadways Although PNNL waste generated outside of the 300 Area is considered 16 to be generated offsite since it may be transported to 305 B Storage Facility on roads accessible to the 17 public it is under the same administrative controls as waste that are generated onsite (i.e. in the 18 300 Area) 19 The generator is responsible for identifying waste composition accurately and arranging for the transport 20 of the waste The 305 B Storage Facility maintains a copy of any pertinent operating record in 21 accordance with WAC 173 303 and the time frames described in Attachment 33 Chapter 12 of the 22 Hanford Facility RCRA Permit Dangerous Waste Portion General Information Portion) The waste 23 tracking methods are as follows 24 Inspection of Shipping Papers/Documentation - The necessary shipment papers for the entire 25 shipment are verified (i.e. signatures are dated, all waste containers included in the shipment are 26 accounted for and correctly indicated on the shipment documentation there is consistency throughout 27 the different shipment documentation and the documentation matches the labels on the containers) 28 Inspection of Waste Containers - The condition of waste containers is checked to verify that the 29 containers are in good condition (i.e. free of holes and punctures) 30 Inspection of Container Labeling - Shipment documentation is used to verify that the containers are labeled with the appropriate Hazardous/Dangerous Waste labeling and associated markings 31 32 according to the contents of the waste container 33 Acceptance of Waste Containers - The 305 B Storage Facility personnel sign the Shipment 34 documents and retain a copy 35 If Shipment will be received from or destined offsite then a Uniform Hazardous Waste Manifest will be 36 prepared identifying the 305 B Storage Facility as the receiving unit (Hanford Facility Permit 37 Condition II P The 305 B Storage Facility operations staff will sign and date the manifest to certify that the dangerous waste covered by the manifest was received. The transporter will be given at least one 38 39 copy of the signed manifest A copy of the manifest will be returned to the generator within 30 days of 40 receipt at the 305 B Storage Facility A copy of the manifest also will be retained in the 305 B Storage
- For onsite waste transfers subject to Hanford RCRA Permit Dangerous Waste Portion Condition II Q 1
- documentation meeting that requirement will be prepared and accompany the shipment. The
- documentation will be maintained in the Operating Record

Facility operating record

3

4

5 6

7

8 9

10

11 12

13

14 15

16 17

18

19

20

21

22

26

Response to Significant Discrepancies

The primary concern during acceptance of containers for storage is improper packaging or manifest discrepancies. Containers with such discrepancies are not accepted at the 305 B Storage Facility until the discrepancy has been resolved. Depending on the nature of the condition, such discrepancies can be resolved through the use of one or more of the following alternatives.

Incorrect or incomplete entries on the Uniform Hazardous Waste Manifest can be corrected or completed with concurrence of the onsite generator or offsite generator. Corrections are made by drawing a single line through the incorrect entry. Corrected entries are initialed and dated by the individual making the correction.

The waste packages can be held and the onsite generator or offsite waste generator requested to provide written instructions for use in correcting the condition before the waste is accepted

Waste packages can be returned as unacceptable

If a noncompliant dangerous waste package is received from an offsite waste generator and the waste package is non returnable because of condition packaging etc. and if an agreement cannot be reached among the involved parties to resolve the noncompliant condition, then the issue will be referred to DOE RL and Ecology for resolution. Ecology will be notified in writing if a discrepancy is not resolved within 15 days after receiving a noncompliant shipment. Pending resolution such waste packages, although not accepted might be placed in the 305 B Storage Facility. The package(s) will be segregated from other waste and an entry will be made into the 305 B Storage Facility logbook describing the actions that were taken to store the packages in a safe manor until a resolution has been reached.

Activation of Contingency Plan for Damaged Shipment

- If waste shipments arrive at the 305 B Storage Facility in a condition that presents a hazard to public health or the environment the Building Emergency Procedure is implemented as described in the Hanford Facility RCRA Permit Attachment 18 Chapter 7 0 for the 305 B Storage Facility
 - 3 7 2 Procedures for Ignitable Reactive and Incompatible Wastes
- Ignitable reactive and incompatible wastes are stored in compliance with Uniform Fire Code Division II regulations for Container and Portable Tank Storage Inside Buildings (International Conference of
- 29 Building Officials 1988) Containers of ignitable reactive and incompatible wastes are stored in
- 30 individual flammable material storage cabinets within the storage cells
- Section 6.5.2 describes procedures used at 305 B Storage Facility to determine the compatibility of
- dangerous wastes so that incompatible wastes are not stored together. Chemical wastes stored in
- 33 305 B Storage Facility are separated by compatibility chemical makeup and hazard class and stored in
- areas having appropriate secondary containment as described in Section 4 1 1 6
- 35 As shown in Figures 4.1 through 4.10 each storage area has individual storage configurations secondary
- 36 containment structures are provided to assure that incompatible materials will not commingle if spilled
- Further segregation is provided by chemical storage cabinets located throughout the facility in various
- areas as shown in Figures 4.1 through 4.10. Cabinet types are noted in those figures and capacities
- described in Table 4.2 Incompatible wastes are never placed in the same container or in unwashed
- 40 containers that previously held incompatible waste
- Compliance with WAC 173 303 395(1)(b) is assured by utilizing this system and the procedure for
- 42 handling ignitable or reactive waste and mixing of incompatible waste as described in Section 6.5.2

1 3 7 3 Procedures To Ensure Compliance With LDR Requirements

2 LDR Waste Analysis Requirements

- 3 The Hazardous and Solid Waste Amendments of 1984 prohibit the land disposal of certain types of waste
- 4 that are subject to RCRA Many of the waste types stored at the 305 B Storage Facility fall within the
- 5 purview of these land disposal restrictions (LDRs) Information presented below describes how
- 6 generators and 305 B Storage Facility personnel characterize document and certify waste subject to
- 7 LDR requirements

8

18

35

Waste Characterization

- 9 Before being received at the 305 B Storage Facility the RCRA waste characteristics the level of toxicity
- characteristics and the presence of listed waste are determined during the physical and chemical analyses
- process This information allows waste management personnel to make all LDR determinations
- 12 accurately and complete appropriate notifications and certifications

13 Sampling and Analytical Procedures

- 14 The LDR characterization and analysis is generally performed as part of the waste characterization and
- analysis process If waste is sampled and analyzed for LDR characterization, then only EPA or equivalent
- methods are used to provide sufficient information for proper management and for decisions regarding
- 17 LDRs pursuant to 40 CFR 268

Frequency of Analysis

- Before acceptance and during the waste characterization and analysis process all LDR characterizations
- and designations are made. The characterization and analysis process is performed when a CDRR is
- submitted for waste pick up unless there is insufficient data or if the waste stream has changed
- Instances where sampling and laboratory analysis may be required to determine accurate LDR
- 23 determinations include the following
- 24 when waste management personnel have reason to suspect a change in the waste based on
- 25 inconsistencies on the CDRR packaging or labeling of the waste
- when the information submitted previously by a generator does not match the characteristics of the
- 27 waste that was submitted
- when the offsite TSD facility rejects the waste because the fingerprint samples are inconsistent with
- the waste profile provided by the 305 B Storage Facility that was established using generator
- 30 information
- Dangerous waste types listed in Table 3.1 are sampled as needed on an individual container or batch basis
- before they are collected from the point of generation or prior to shipment offsite. After the dangerous
- 33 constituents have been characterized these waste streams will not be analyzed again until process or raw
- 34 material changes occur

Documentation and Certification

- The 305 B Storage Facility has and will continue to receive and store LDR waste Because 305 B Storage
- Facility personnel determine designations and characterization including LDR determinations all
- 38 notifications and certifications as required by 40 CFR 268 are prepared by qualified staff for
- 39 PNNL generated waste The 305 B Storage Facility staff collects from the generator(s) the information
- 40 pursuant to 40 CFR 268 regarding LDR wastes. The notifications and certifications are submitted to
- onsite and offsite TSD units during the waste shipment process. Additionally, any necessary LDR
- 42 variances are prepared and submitted by PNNL qualified staff
- The 305 B Storage Facility staff requires applicable LDR information/notifications from non PNNL
- 44 generators

certifications are sent to Records Storage

Where an LDR waste does not meet the applicable treatment standards set forth in 40 CFR 268 1 Subpart D or exceeds the application prohibition levels set forth in 40 CFR 268 32 or Section 3004(d) of 2 RCRA the 305 B Storage Facility provides to the onsite and offsite TSD a written notice that includes 3 the following information 4 5 EPA hazardous waste number the corresponding treatment standards and all applicable prohibitions set forth in WAC 173 303 6 40 CFR 268 32 or RCRA Section 3004(d) 7 8 the manifest number associated with the waste all available waste characterization data 9 10 identification of underlying hazardous constituents In instances where 305 B Storage Facility staff determines that a restricted waste is being managed that 11 can be land disposed without further treatment 305 B Storage Facility staff submits a written notice and 12 certification to the onsite or offsite TSD where the waste is being shipped stating that the waste meets 13 applicable treatment standards set forth in WAC 173 303 140 (40 CFR 268 Subpart D) and the 14 applicable prohibition levels set forth in 40 CFR 268 32 or RCRA Section 3004(d) The notice includes 15 the following information 16 17 EPA hazardous waste number corresponding treatment standards and applicable prohibitions 18 waste tracking number associated with the waste 19 20 all available waste characterization data 21 identification of underlying hazardous constituents 22 The certification accompanying any of the previously described notices is signed by an authorized representative of the generator and states the following 23 I certify under penalty of law that I personally have examined and am familiar with the waste through 24 analysis and testing or through knowledge of the waste to support this certification that the waste 25 complies with the treatment standards specified in 40 CFR Part 268 Subpart D and all applicable 26 prohibitions set forth in 40 CFR 268 32 or RCRA Section 3004(d) I believe that the information I 27 submitted is true accurate and complete. I am aware that there are significant penalties for submitting a 28 false certification including the possibility of a fine and imprisonment 29 Copies of all notices and certifications described are retained at the TSD unit for at least five years from 30

the date that the waste was last sent to an onsite or offsite TSD unit. After that time the notices and

Table 3 1 Summary of Test Parameters Rationales and Methods

Parameter ^a	Method ^b	Rationale for Selection
	Physical Sere	eening
Visual inspection	Field method observe phases presence of solids in waste	Ensure that waste matches that described on waste acceptance documentation identify waste prohibited by LDR requirements related to downstream TSD unit acceptance criteria
	Chemical Scr	
Water miscibility/separable organics	Water mix screen ASTM Method D5232 92	Ensure that waste matches that described on waste acceptance documentation identify separable organics identify waste prohibited by LDR requirements related to downstream TSD unit acceptance criteria
Water reactivity	Water mix screen ASTM Method D5232 92	Ensure that waste matches that described on waste acceptance documentation ensure compliance with WAC 173 303 395(1)(b)
pH	pH screen SW 846 Method 9041	Ensure that waste matches that described on waste acceptance documentation ensure compliance with WAC 173 303 395(1)(b)
Cyanides	Cyanide screen HAZCAT TM	Ensure that waste matches that described on waste acceptance documentation ensure compliance with WAC 173 303 395(1)(b)
Sulfides	Sulfide screen HAZCAT TM	Ensure that waste matches that described on waste acceptance documentation ensure compliance with WAC 173 303 395(1)(b)
	Pre Shipment	<u> </u>
Mercury (total)	Generator knowledge or SW 846 Method 7470/7471	Identify waste prohibited by LDR requirements related to downstream TSD unit acceptance criteria
Toxicity characteristic organic compounds	Generator knowledge or SW 846 Methods 1311 and 8260 (volatile organic compounds) and 8270 (semivolatile organic compounds)	Identify waste not identified on the Part A Form 3
Polycyclic aromatic hydrocarbons	Generator knowledge or SW 846 Method 8270 or 8100	Identify waste not identified on the Part A Form 3 (for waste with >1% solids and for which WP03 could apply)

Addition parameters can be used on current waste acceptance criteria of the downstream TSD unit

Operation limits transfer/shipments are based on current waste acceptance criteria
b Procedures based on EPA SW 846 unless otherwise noted When regulations require a specific method the method shall be followed

This page intentionally left blank

1		4 0 CONTENTS	
2 3	4 0 4 0	CONTENTS PROCESS INFORMATION [D]	4 1 4 1
4 5 6 7	4 1 4 1 1 4 1 2	CONTAINERS [D 1] Containers With Free Liquids [D 1a] Containers Without Free Liquid That Do Not Exhibit Ignitability or Reactivity [D 1b]	4 1 4 1 4 22
8 9 10	4 2	PROTECTION OF EXTREMELY HAZARDOUS WASTE IN CONTAINERS [D 2]	4 22
11 12 13 14 15 16 17 18		PREVENTION OF REACTION OF IGNITABLE REACTIVE AND INCOMPATIBLE WASTE IN CONTAINERS [D 3] Management of Ignitable or Reactive Waste in Containers [D 3a] Management of Incompatible Waste in Containers [D 3b] Waste Piles [D 3d] Surface Impoundments [D 3e] Incinerators [D 3f] Landfills [D 3g Land Treatment [D 3h]	4 22 4 22 4 23 4 23 4 23 4 23 4 23 4 23
20		FICURES	
21 22	Figure 4	FIGURES 1 Acids and Oxidizers Cell	4 7
23	Figure 4		4 8
24 25	Figure 4		4 9
26	Figure 4	4 Organics Cell	4 12
27	Figure 4	Flammable Liquid Bulking Module and Compressed Gases (Cell 5)	4 13
28	Figure 4	6 Segregated High Bay Drum Storage Areas	4 14
29	Figure 4	7 High Bay Storage Area	4 15
30	Figure 4	8 Flammable Radioactive Mixed Waste Storage Area	4 17
31	Figure 4	9 Radioactive Mixed Waste Storage	4 18
32	Figure 4	10 RMW Storage Cell Containment Pan Installation	4 19
33 34 35 36 37	_	11 Flammable Liquids Storage Module	4 25

	Quarter Ending 3/31/2002		3/2002
[TABLES	
2 3 1	Table 4 1	Exempt Amounts of Hazardous Materials Liquids & Chemicals Presenting a Physical Hazard	4 20
5	Table 4 2	Storage Devices Used at the 305 B Storage Facility	4 24

DOE RL 90 01 Rev 1G

Class 1 Modification

40 PROCESS INFORMATION [D]

2 41 CONTAINERS [D 1]

- 3 The following sections describe the types of containers stored at the 305 B Storage Facility
- 4 411 Containers With Free Liquids [D 1a]
- 5 Containers with free liquids are discussed below
- 6 4111 Description of Containers [D 1a(1)]
- 7 Most waste stored at the 305 B Storage Facility are received in their original as procured containers
- 8 Containers of hazardous materials entering 305 B Storage Facility are inspected before being accepted for
- 9 storage Generating units are responsible for placing the materials in adequate containers Repackaged
- materials must be placed in containers that are new and compatible with the materials to be stored
- 11 Containers in poor condition or inadequate for storage are not accepted at the unit. If transport is by unit
- 12 personnel such containers are not accepted for transport Refer to Section 6.4.1 for inspection before
- 13 transport performed by unit personnel Container in poor condition or inadequate for storage means a
- container which is not intact or undamaged and which is not securely sealed to prevent leakage during
- 15 storage transport and ultimate offsite disposal Examples of acceptable packaging include laboratory
- 16 reagent bottles DOT containers spray cans sealed ampules with spetums paint cans leaking containers
- 17 which have been overpacked etc. Unit operations personnel have the authority to determine whether a
- container is in poor condition or inadequate for storage using the criteria of WAC 173 303 190 and
- 19 professional judgment whether the packaging may leak during handling storage and/or disposal
- 20 As with all waste repackaged containers of dangerous waste are marked and/or labeled to describe the
- 21 contents of the container and the major hazards of the waste as required under WAC 173 303
- 22 Containers are also marked with a unique identifying number assigned by the unit's computerized waste
- 23 tracking system
- 24 All flammable liquid waste are stored in compatible DOT specified shipping containers and/or in
- Underwriter's Laboratory (UL) listed and Factory Mutual (FM) approved flammable storage cabinets
- 26 Solid chemicals are stored on shelving in specifically designated areas based on the DOT hazard
- 27 classification
- All containers utilized for offsite transport of dangerous waste at the unit are selected and shall comply
- 29 with all applicable criteria found in WAC 173 303 190
- 30 4 1 1 2 Container Management Practices [D 1a(2)]
- 31 Management practices and procedures for containers of dangerous waste are in place at the 305 B Storage
- 32 Facility to assure the safe receipt handling preparation for transport and transportation of waste. These
- 33 practices and procedures are summarized below
- 34 <u>Inspection of Containers</u> A system of daily weekly monthly and yearly inspections is in place to
- 35 ensure container integrity check for proper storage location prevent capacity overrun etc. These
- 36 inspection procedures are detailed in Section 6.2
- 37 Container Handling All unit staff is instructed in proper container handling safeguards as part of their
- 38 training (refer to Section 8 1 2 for further details) For example employees are instructed to open all
- 39 high vapor pressure liquids in the flammable liquid bulking module to avoid buildup of vapors in the
- 40 unit Containers are always kept closed except when adding or removing waste in accordance with
- 41 WAC 173 303 630(5)(a)

- 1 Containers are not opened handled or stored in a manner that would cause the container to leak or
- 2 rupture Small containers (five gallons or less capacity) are stored on shelving or in approved flammable
- 3 liquid storage lockers (if appropriate) Containers over five gallons capacity are stored on the floor of the
- 4 appropriate storage cell in cabinets or stored in the appropriate containment area on the high bay floor
- 5 under Section 4 3 2 Unnecessary handling not required for redistribution or preparation for transport and
- disposal by either labpacking or bulking is minimized. Crane or chain hoist or forklift moves drums
- 7 manually For manual movement hand trucks specifically designed for drum handling are used Crane
- 8 and chain hoist operations are performed following the appropriate Hoisting and Rigging procedures
- 9 When using the forklift a drum hoist is used or the drums are carried on pallets. Drums are never carried
- on the forks or speared by slipping the forks under the chime When waste handling operations are
- 11 conducted a minimum of two persons is present in the unit
- 12 <u>Lab Packing</u> One of the major functions of the 305 B Storage Facility is the preparation of lab packs for
- 13 offsite recycling treatment and/or disposal of small quantity lab waste generated by DOE RL/PNNL
- 14 activities
- Lab packs are prepared in compliance with WAC 173 303 161 49 CFR 173 12 other applicable
- regulations and permit conditions of the planned receiving facility (recycler treatment facility or
- 17 disposal facility) Permit conditions affecting preparation of lab packs might include types of absorbent
- materials to be used (e.g. no vermiculite)
- 19 Lab packs are prepared in the storage cell containing the hazard class(es) to be placed in the lab pack
- 20 The elephant trunk ventilator system may be used to minimize respirable dusts from the absorbent
- 21 material being used (usually vermiculite. Lab packs may also be prepared in the flammable liquid
- bulking module if appropriate for instance if compatible materials from more than one storage cell are
- being combined in a single lab pack drum Lab packs may be prepared in the high bay storage area if
- storage of the completed lab pack is permitted there per Section 4.3.2
- 25 Partial and completed lab packs are closed labeled and the contents list documented Labpacks are
- 26 stored in the cell from which the containers inside were drawn or in the high bay if appropriate
- Unit personnel wear appropriate protective clothing while handling containers being placed in lab packs
- 28 At a minimum this includes labcoats safety glasses or other protective eyewear and chemical resistant
- 29 gloves More stringent requirements including use of respiratory protection may be imposed if
- 30 appropriate
- 31 <u>Bulking</u> In order to promote greater recycling or treatment of waste and reduce land disposal some
- 32 liquid waste are bulked into larger containers typically 30 or 55 gallon closed head drums. Bulking
- 33 operations for chemicals that are respiratory or flammability hazards are performed in the flammable
- 34 liquid bulking module (Also referred to as cell 5) located in the southwest corner of the unit. Bulking of
- 35 nonvolatile low hazard waste such as saline solutions or ethylene glycol may be done within the
- 36 containment areas of the appropriate storage cell or high bay
- 37 Compatibility of waste to be bulked is determined using the information from generating unit designation
- 38 information process knowledge laboratory analyses and/or the compatibility determinations described in
- 39 Section 6 5
- 40 Containers are transported by hand or forklift to the flammable liquid bulking module area. The receiving
- drum (typically 30 or 55 gallon capacity) is placed in the module and the ventilation system is activated
- 42 A large chemically resistant funnel (either metal or plastic depending on material to be introduced) is
- 43 used to pour the material into the drum. The contents of the smaller containers are then poured one at a
- 44 time into the larger drum. The receiving drum is monitored by unit personnel to make sure no
- 45 incompatibility is observed (e.g. furning bubbling or heat generation). If such incompatibility is

- observed no further material is added and the worker leaves the area closing the module and leaving the
- 2 ventilation on The unit supervisor is notified to evaluate implementation of the contingency plan
- 3 Glass containers which have been emptied (as defined by WAC 173 303 160(2)) as a result of bulking
- 4 activities are crushed onsite by an electric glass crusher which mounts on a 55 gallon drum. If an
- 5 emptied glass container held acutely hazardous waste as defined by WAC 173 303 040(2) the container
- 6 is rinsed at least three times with an appropriate cleaner or solvent before being destroyed. The rinsates
- 7 are managed as dangerous waste. Crushed glass is managed as solid waste in accordance with
- 8 WAC 173 303 160(3)
- 9 Once bulking is complete the bulk container is closed labeled and the contents list documented
- 10 Containers of bulked waste are stored in the cell from which the containers inside were drawn or in the
- 11 high bay if appropriate
- 12 Unit personnel wear appropriate protective clothing while bulking containerized liquid waste. At a
- 13 minimum this includes coveralls disposable splash resistant apron eye protection and chemical resistant
- 14 gloves More stringent requirements including use of respiratory protection may be imposed if
- 15 appropriate

16 4 1 1 3 Secondary Containment System Design and Operation [D 1a(3)]

- 17 Several design features have been engineered into the construction of the 305 B Storage Facility as added
- safeguards for containment of dangerous waste spills or leaks. Design drawings for 305 B Storage
- 19 Facility are included in Appendix 4A The following subsections comment briefly on each of the design
- 20 features

21 4 1 1 4 Requirement for Base or Liner to Contain Liquids [D 1a(4)]

- 22 The base of the facility consists of a 6 inch reinforced poured concrete slab with no cracks or gaps. The
- 23 concrete was mixed in accordance with ASTM 094 Section 5.3 Alternate 2 and all exposed surfaces
- 24 were finished with a smooth troweled surface Expansion joint material is Sonneborn Sonoflex FTM
- 25 polyethylene filler The bonding compound used at the expansion joints was Sonneborn Sonobond™
- 26 two part epoxy. All edges and corners were sealed with a continuous bead of polysulfide sealant
- A chemically resistant sealant paint was applied in February 1989 to the storage cells and high bay floor
- 28 and in October 1990 to drum storage areas noted in Sections 4 1 1 6 6 4 1 1 6 7 and 4 1 1 6 8 Specific
- 29 areas of 1989 application are shown on Plate 4 1 and painting methods (surface preparation and
- 30 application of coatings) are described on Plate 4.2 of Appendix 4A of this permit application. The
- 31 surface coating is Coronado #101 1 (101 Series) Polyamide Epoxy Coating Estimated service life of the
- 32 coating material is 14 years per manufacturer's literature Performance specifications and a compatibility
- 33 chart are provided in Appendix 4B
- 34 The condition of the floor coating is inspected weekly per Section 6.2.1.1 and repairs are made as
- 35 needed Immediate repairs are indicated whenever the coating is observed to have been chipped bubbled
- 36 up scraped or otherwise damaged in a manner that would significantly impact the ability of the coating
- 37 to contain spilled materials Minor nicks and small chips resulting from normal operations will be
- 38 repaired on a periodic basis Repairs are performed in accordance with procedures provided by the
- 39 manufacturer in Appendix 4B

40

4 1 1 5 Containment System Drainage [D 1a(5)]

- 41 The concrete floors in each high bay storage cell are canted toward individual secondary containment
- 42 trenches within those cells These trenches are isolated from each other in order to prevent interaction


- 1 reactions or offsite migration of spilled materials. This provides protection even during simultaneous
- 2 spills
- 3 The floors in the high bay area are also canted toward a separate sump system which is sealed with epoxy
- 4 and blocked to prevent drainage Drums stored in this area are also stored on pallets to prevent contact
- 5 with spilled material in the event of a release Segregated storage areas for incompatible materials have
- 6 been set up in the high bay storage area to prevent commingling of spilled waste during a catastrophic
- 7 (multi drum) spill incident Each area has its own containment trench separated from other trenches with
- 8 concrete and epoxy
- 9 The flammable liquids bulking module along with its purpose of providing a ventilated area for bulking
- of compatible hydrocarbon waste is used as an independent storage cell. The walls of the module
- provide secondary containment which have been sealed at the floor joint by use of grout coated with
- 12 epoxy paint
- For protection of the basement RMW storage area curbing/diking is provided to prevent migration
- Drums are stored on pallets to prevent container contact with spilled materials and drip pans are provided
- 15 to segregate RMW by dangerous waste characteristic as described in Section 4 1 1 6 11. This area has no
- 16 drainage
- 17 Flammable RMW is stored within its own secondary containment devices. The description and capacity
- of the flammable RMW storage area is provided in Section 4 1 1 6 11

19 4 1 1 6 Containment System Capacity [D 1a(6)]

- 20 Secondary containment is provided for all dangerous waste stored at the 305 B Storage Facility Storage
- 21 limits for all chemicals are listed in Table 4 1 (1988 Uniform Building Code). All floors in the high bay
- 22 area are sloped toward sumps which have no drains and are covered with grating to prevent safety
- hazards In addition all floors in the high bay area are coated with an epoxy based coating as described
- 24 in Section 4 1 1 4 Inspection of the containment system to maintain integrity is described in Section 6 2
- 25 Individual secondary containment systems are configured as follows
- 26 41161 Acids and Oxidizers Cell. The acids and oxidizers cell (cell 1) is located at the northwest
- 27 corner of the 305 B Storage Facility high bay floor The cell is constructed of epoxy painted concrete
- 28 block walls 4 foot high and incorporates a 1 foot deep sump at the west end of the cell Six cabinets open
- shelving and a large container storage area are provided within the cell to allow storage of various sizes
- of containers The secondary containment volume of the individual sump for this cell is 67 gallons and
- the total containment volume of the cell is 774 gallons. A diagram of the cell is provided in Figures 4.1
- 32 41162 Poisons and Class 9 Cell The poisons and Class 9 cell (cell 2) is located just south of the acids
- and oxidizers cell along the west wall of the high bay. This cell is also constructed of epoxy painted
- 34 concrete block walls 4 foot high and incorporates a 1 foot deep sump along its west end. Six storage
- 35 cabinets and several sets of open shelving are positioned in the cell to allow storage of various sizes of
- 36 containers The northeast corner of the cell is sectioned off with a 6 inch spill retention berm to allow
- 37 PCB storage for disposal complying with 40 CFR 761 65(b) The secondary containment volume of the
- 38 individual sump for this cell is 117 gallons and the total containment volume of the cell is 782 gallons. A
- 39 diagram of this cell is provided in Figure 4.2

- 1 41163 Alkaline Washington State Criteria Waste Organic Peroxides and Non Regulated Waste
- 2 Cell The alkaline Washington State Criteria waste and non regulated waste cell (cell 3) is located
- 3 South of the poisons and Class 9 cell on the west wall of the high bay area. This cell is also constructed
- 4 of epoxy painted concrete block walls 4ft high and incorporates a 1 foot deep sump along its west end
- 5 Four storage cabinets 3 sets of open shelving and 1 explosion proof refrigerator are positioned in the
- 6 cell to allow storage of various sizes of containers The secondary containment volume of the individual
- sump for this cell is 137 gallons and total containment volume of the cell is 764 gallons. A diagram of
- 8 this cell is provided in Figure 4.3
- 9 4 1 1 6 4 Flammable Cell. The flammable-cell (cell 4) is located south of the alkaline Washington State
- 10 Criteria waste and non regulated waste cell. As with the other three cells described above this cell is
- 11 constructed of epoxy painted concrete block walls 4 feet high and incorporates a 1 foot deep sump along
- 12 its west end. The secondary containment volume of the individual sump for this cell is 119 gallons, and
- total containment volume of the cell is 687 gallons. A diagram of this cell is provided in Figure 4-4
- 14 Ignitable organic waste materials are stored in this cell that also exhibits the characteristics of corrosivity
- 15 toxicity as well as reactivity Three Factory Mutual approved flammable liquid storage cabinets are
- 16 utilized for storage of various classes of flammable liquids as defined by the UFC. The capacities of the
- various cabinets are shown in Table 4.2 The following cabinets also are used for storage in this cell one
- 18 for combustibles one for aerosols two for flammable solids and one for overflow from one of the other
- 19 cabinets
- 20 Total ignitable Waste Storage capacity of the 305 B Storage Facility highbay including the organics cell
- 21 Cell 5 Ignitable drum storage area and highbay storage area is limited by the following UBC restrictions
- 22 for Class B occupancy
- 23 Class 1A flammable liquids 120 gallons
- 24 Class 1B flammable liquids 240 gallons
- 25 Class 1C flammable liquids 360 gallons
- 26 Maximum Class 1A 1B and 1C at any one time 480 gallons
- 27 Maximum Class 1A 1B and 1C stored in Cell 8 self contained storage module for flammable liquids
- 28 is 240 gallons
- 29 Class 2 combustible liquids 480 gallons
- 30 Class 3A combustible liquids 1320 gallons
- 31 Combustible fibers loose 100 cubic feet
- 32 Combustible fibers baled 1000 cubic feet
- Flammable gases in any one cylinder 3000 cubic feet
- 34 Liquefied flammable gases 60 gallons
- 35 41165 Flammable Liquids Bulking Module The flammable liquids bulking module (cell 5) along
- 36 with its purpose of providing a ventilated area for bulking of compatible ignitable waste is used as an
- 37 independent storage cell. The walls of the module provide secondary containment, which have been
- sealed at the floor joint by use of grout coated with epoxy paint Flammable gases in cylinders liquefied
- 39 flammable gases and oxidizing gases will be stored in the bulking module
- Nontransient storage of flammable liquids in the module is 55 gallons. A diagram of the module is
- 41 provided in Figure 4 5
- 42 41165 a. Flammable Liquids Storage Module The flammable liquid storage module is a
- 43 self contained storage module (cell 8) that allows additional storage space for flammable waste. The

- 1 flammable liquid storage module is located along the south wall and is connected to the buildings fire
- 2 suppression system The flammable liquid storage module has a 2 hour fire rated containment system so
- 3 that according to the UFC an unlimited capacity is allowed. However, the flammable waste storage
- 4 capacity of the flammable liquid storage module is limited by the 240-gallon capacity of the module s
- 5 secondary containment system No more than 240 gallons of any combination of flammable liquid
- 6 classes will be stored in the module. This flammable waste storage capacity is in addition to the
- 7 flammable storage limits for the highbay A diagram showing the module location in the highbay is
- 8 provided in Figure 4.7
- 9 41166 Ignitable Waste Drum Storage Area. An additional section of the high bay (cell 8) has been
- dedicated to storage of drum quantities of ignitable waste before offsite shipment. The area is bordered
- on the north and south sides by angle iron (3½in x 6in) bolted to the floor (refer to Plate 2 Appendix 4A
- for detail) and sealed to provide secondary containment. The area is approximately 15ft x 7ft. To further
- 13 enhance containment and to allow greater storage capacity the drums stored in this area are stored in
- 14 flammable liquid drum storage cabinets
- 15 Sump containment capacity of this area is approximately 224 gallons and total containment capacity is
- approximately 431 gallons Maximum storage in this area is approximately six 55 gallon drums and
- 17 12 five gallon drums A diagram of this area is included in Figure 4 6 Additional ignitable waste
- storage is provided for in cell 4 organics cell and the in the Highbay storage area. The high bay storage
- area has five additional flammable liquid drum storage cabinets located along the west side of the high
- 20 bay (refer to Figure 4 7) All of this ignitable waste storage is provided for utilizing flammable liquid
- 21 storage cabinets for added safety
- 22 4 1 1 6 7 Universal and Recycling Waste Storage Area. A second section of the high bay (cell 12) has
- been dedicated to storage of drum quantities of universal and recycling waste before shipment. The area
- 24 is 10ft x 7ft in size. All material in this area is stored in DOT approved containers and is stored on pallets
- 25 to prevent contact with spilled waste in the event of an incident
- Sump containment capacity in this area is approximately 55 gallons and total containment capacity is
- 27 approximately 255 gallons Maximum storage in this area will be eight 55 gallon drums. A diagram of
- this area is included in Figure 4 6
- 29 4 1 1 6 8 Acid Waste Drum Storage Area. A third section of the high bay (cell 13) has been designated
- 30 for storage of drum quantities of acid waste before offsite shipment. The area is approximately
- 31 10ft x 10 ft Waste drums stored in this area are stored on pallets to prevent contact with spilled waste in
- 32 the event of an incident Bulked drums containing acids with oxidizers as a secondary hazard will be
- placed in the cell 1 drum area to prevent any possibility of a reaction with surrounding hazards in the
- 34 high bay drum storage area A diagram of this area is included in Figure 4 6



23 Legend

- 24 1A Liquid Oxidizers (Medium Cabinet)
- 25 1B Solid Oxidizers (Small Cabinet
- 26 1C Inorganic Acids (Medium Cabinet)
- 27 1D Organic Acids (corrosive) (Small Cabinet)
- 28 IE Mercury/Corrosive Solids (Small Shelf)
- 29 15 24cm W x 127cm H epoxy coated concrete block wall
- 30 Secondary Containment Trench
- 31 Drum and Carboy Storage Area





Figure 4 3 Alkaline, Washington State Criteria Waste Organic Peroxides and Non Regulated Waste Cell



1 cm = 60 cm

24 Legend


- 25 3A Alkaline (liquids and solids) (Medium Cabinet)
- 26 3B Alkaline/Oxidizers (Small Cabinet)
- 27 3C Organic Peroxides and temperature sensitive (refrigerator)
- 28 3D Washington State Criteria Waste (2 Large Shelves)
- 29 3E Non Regulated Liquids/Solids (Small Shelf)
- 30 15 24cm W x 127CM H epoxy coated concrete block wall
- 31 Secondary Containment Trench
- 32 Drum and Carboy Storage Area

- 41169 Alkaline Waste Drum Storage Area A fourth section of the high bay (cell 14) has been 1
- 2 designated for storage of drum quantities of alkaline waste before offsite shipment. The area is
- approximately 22ft x 15ft. Waste drums stored in this area are stored on pallets to prevent contact with 3
- spilled waste in the event of an incident Sump containment capacity in this area is approximately 4
- 110 gallons and total containment capacity is approximately 380 gallons. Maximum storage in this area 5
- is thirty two 55 gallon drums. The location of the area is shown on the High Bay Storage Area diagram 6
- 7 Figure 4 7
- 4 1 1 6 10 High Bay Storage Area The high bay storage area along with its partitioned areas mentioned 8
- above is itself a secondary containment area for loading unloading and storage of dangerous waste. The 9
- high bay floor is crowned in the center and sloped at 1/4 inch per foot with drainage to sumps on the east 10
- 11 and west sides of the unit Sump locations are indicated in Figure 4 7
- 12 Due to space limitations in the individual cells and for ease of mechanical handling the high bay floor is
- typically used for storage of nonradioactive chemicals in drums (refer to Figure 4 7) 13
- The high bay floor is also used to store labracks and bulked waste containers before offsite shipment to 14
- 15 licensed treatment disposal or recycling facilities Generally only corrosives oxidizers toxic organic
- solvent mixtures (typically halogenated solvents) antifreeze mixtures contaminated water which is toxic 16
- dangerous waste nonliquid waste ORMs or state only dangerous waste materials are stored in the high 17
- 18 bay storage area
- If waste incompatible with the foregoing are stored in the high bay storage area, they are kept separated 19
- 20 by at least ten feet of distance and stored in individual drip pans for segregation in case of simultaneous
- 21 accidental spillage Compatibility of the materials is determined before acceptance in accordance with
- 22 Section 3 2
- The secondary containment volume of the sumps in the high bay storage area exclusive of the sumps 23
- within individual areas described above is 565 gallons. Maximum storage in the high bay storage area is 24
- thus approximately 5650 gallons (102 drums) The high bay storage is also governed by the building 25
- occupancy maximums of Table 4 1 which includes the inventory of the individual storage cells described 26
- above In order to provide additional separation from spilled liquids and for ease of handling all drums 27
- stored on the high bay floor are stored on pallets A diagram of this cell is provided in Figure 4.7 28
- 4 1 1 6 11 Flammable RMW Storage Area Due to UBC restrictions flammable radioactive mixed 29
- waste cannot be stored in the basement of 305 B Storage Facility with the other radioactive mixed waste 30
- The flammable RMW received by 305 B Storage Facility for storage before disposal is stored in a 31
- separate area above grade in the east portion of the building in a 7ft x 7ft x 7ft flammable liquid storage 32
- module (cell 7) The module is Factory Mutual approved and has four hour fire rated walls and doors 33
- The module has a self contained internal dry chemical fire suppressant system. The module has a 34
- 90 gallon polyethylene coated sump The module is lag bolted to the concrete floor in the flammable 35
- RMW storage area indicated in Figure 4 8 The module has a storage capacity of four 55 gallon drums 36
- or up to 250 gallons of total capacity of all containers stored whichever is greater. This storage area
- 37
- meets the requirements of a one year PCB storage area as defined in 40 CFR 761 65 so flammable mixed 38
- waste also regulated as PCB waste may be stored in this location. A diagram of this cell is provided in 39
- 40 Figure 4 8
- 4 1 1 6 12 RMW Storage Area Radioactive mixed waste that is not flammable per UFC (i e flash point 41
- above 100 F) is stored in a special area in the basement of 305 B Storage Facility For additional 42
- segregation capability there are eight small chemical storage cabinets and four 62in x 62in x 6in 43
- (157cm x 157cm x 15cm) stainless steel container pans with an approximate volume of 91 gallons 44
- (346 liters) The total area within the curbing is 1246 gallons (4716 liters) The containment pans are 45
- mounted to the floor or wall of the cell to provide segregated storage for potentially incompatible mixed 46

- waste streams. A diagram of the RMW storage cell secondary containment pan installation is provided in
- 2 Figure 4 10 Drums stored in this area are stored on pallets to prevent potential contact with spilled waste
- 3 in containment during an emergency A diagram of this area is provided in Figure 4.9
- 4 In normal use the storage capacity of this area is limited by the radionuclide limits imposed by the DOE
- 5 for low inventory facilities These limitations are defined in DOE STD 1027 92 Hazard
- 6 Categorization and Accident Analysis Techniques for Compliance with DOE Order 5480 23 Nuclear
- 7 Safety Analysis Reports and are included in the radiation work permit for the mixed waste storage area
- 8 411613 Explosives Storage Area. Due to UBC restrictions waste classified as explosive by DOT
- 9 regulations are stored in a 3ft x 3ft x 3ft explosives magazine with an 8 cubic foot interior outside cell 1
- 10 The magazine is constructed of steel and certified to have been fabricated per Institute of Makers of
- 11 Explosives (IME) SLP22 type 2 day box requirements No more than 1 pound of explosives is stored in
- the magazine at one time. The location of the magazine is indicated in Figure 4.7
- 13 4117 Control of Run On [D 1a(7)]
- 14 The 305 B Storage Facility was designed to eliminate the likelihood of on site or for that matter off site
- 15 migration via run on and run off The facility is completely enclosed (i.e. complete roof and
- WA 1981)no open walls) and has been constructed upon a foundation so that precipitation cannot cause
- 17 either run on or run off problems

31

32

33 34 

15 24 cm W x 127 H epoxy coated concrete block wall

Secondary Containment Trench

Drum and Carboy Storage Area






Figure 4 6 Segregated High Bay Drum Storage Areas




1 cm = 60 cm



Legend

Figure 4 7 High Bay Storage Area



Legend On next page

Scale 1cm = 120 cm






Figure 4 8 Flammable Radioactive Mixed Waste Storage Area

2

1






27 Legend

- 28 1 Flammable RMW Storage Module
- 29 2 Removable hatch cover for basement access (surrounded by railing)
- 30 All PCB waste stored in Cell 9 shall be stored in trays or drum overpacks that meet all the requirements of 40 CFR 761 65(b) 31

32

Figure 4 9 Radioactive Mixed Waste Storage



Cell 7 Legend

17 18 19

1 2 3

4

5

6 7

8

9

10 11

12

13

14 15 16

- 7A Poisons
- 20 7B Oxidizers
- 21 7C Class 9/Combustible
- 22 7D Washington Only/Combustible
- 23 7E Flammable Solids
- 24 7F Corrosive Base/Combustible
- 25 7G Corrosive Acid/Combustible
- 26 7H Corrosive/PCB s/Combustible
- 27 7I Corrosive Acid/PCB s/Combustible
- 28 7J PCB s/Combustible
- 29 7K Washington Only/Class 9/PCB s/Combustible
- 30 7L Non Regulated/Combustible
 - 7M Washington State Waste/ Class 9/ Non Regulated/Combustible/Compatibles
 - HOOD 121 9cm L x 54 2cm D x 228 6cm H

32 33 34

35

31

All PCB waste stored in Cell 7 will be segregated according to chemical compatibility and stored in any of the four stainless steel container pans complying with 40 CFR 761 65(b)




Table 4 1 Exempt Amounts of Hazardous Materials Liquids & Chemicals Presenting a Physical Hazard

BASIC QUANTITIES PER CONTROL AREA

_	vvnen t	NO UNITS E	re given va	ilues within	parenthes	<u>es are in ci</u>	ubic feet (C	Cu Ft) or p			
<u></u>	CONDITION	,	STORAGE ²				LOSED S'	YSTEMS		OPEN SY	STEMS
	MATERIAL	CLASS	Solid Lbs	Liquid	Gas	Solid Lbs	Liquid	Gas	Solid Lbs	Liquid	Gas
			(Cu Ft)	Gallons	(Cu Ft)	(Cu Ft)	Gallons	(Cu Ft)	(Cu Ft.)	Gallons	(Cu Ft)
-		ļ		(Lbs)			(Lbs)			(Lbs)	
111	Combustible liquid ³	11	-	120 5	-	_	120	-	-	30	-
		III A	-	330 5	-	-	330	-	_	80	-
1		III B	-	13 200 ⁵	-	-	13 200	-	-	3 300 ⁶	-
12	Combustible dust lbs/1000 Cu Ft		1	_	-	1	-	_	ı	_	-
13	Combustible fiber			_	_		_	<u> </u>	-	_	_
l	(loose)		(100)			(100)		Ì	(20)		
]	(baled)		(1 000)			(1 000)		•	(200)		Į.
14	Cryogenic flammable		(1 500)			(1.000)			(200)		ļ
	or oxidizing			45	-	-	45	_	-	10	-
21	Explosives		1 8	(1)	-	/	(/) ⁸	_ ;	/ 8	(/)	_
31	Flammable solid		125 5		_	25	_	_	25	_	_
3 2		1								_	_
	(gaseous)	[_	750	_	_	750 ⁵	_	_	_
	(liquefied)		_	15 5	'20	_		7.50	_	_ _	_
31	Flammable liquid ³			30 5	_	_	30	_	_	10	_
			_	60	_	_	60	_	_	15	_
			_	90	_ ;	_	90	_	- -	20	_
Con	bination I A I B I C		_	120 5	_	_	1204		_	30	_
	Organic peroxide		}		_	_		-	_	30	_
' '	unclass fied detonable		1	(1)5	-	/	(/)		/	(/)	-
42		ı	5 5	(5)	_	(1)	(1)	_	1	1	_
ł		11	50 5	(50)	_	50	(50)	_	10	(10)	_
		ш	125 5	(125)	_	125	(125) 5	_	25	(25)	_
		IV	500	(500)	_	500	(500)	_	100	(100)	_
		v	NL	NL	_	NL	NL	_	NL	NL	_
43	Oxidizer	4	1	(1)5	_	/8	(/)	-	7	(/)	_
		3	10	(10) 5	_	2	(2)	_	2	(2)	_
		2	²⁵⁰ 4 5	(250) 5	_	250	(250)	_	50	(50)	_
		1	1 00045	(1 00)	_	1 000	(1 000)	_	200	(200)	_
41	Oxidizer—Gas			. /			``,			`,	
	(gaseous)	[_]	-	1 500	-	_	1 500	_	_	_]
	(liquefied)		_	15	-	_	15	_	_	_	_
5 1	Pyrophor c		458	(4)	50 ^{5 8}	1	(1)	10	0	0	0
61	Unstable (eacti e)	4	15	(1)	1058	,	(/)	2 5	ž	(/)	ő
		3	5	(5)	50 5	1	(1)	10	í	1	ő
		2	50	(50)	250	50	(50)	250	10	(10)	o
	-	<u>-</u>	125	(125)	750	125	(125)	750	25	(25)	ő
71	Water (reactive)	3	5	(5)	-	5	(5)	- 1	1	(1)	
	(· - /	2	50	(50)	_	50	(50)	_	10	(10)	_
		1	125	(125)	_	125	(125)	_ i	25	(25)	_

Control area is a space bounded by not less than a one hour fire resisting occupancy separation within which the exempted amounts of hazardous materials may be stored dispensed handled or used. The number of control areas within a building used for retail and wholesale stores shall not exceed two. The number of control areas in buildings with other uses shall not exceed four. The aggregate quantity in use and storage shall not exceed the quantity listed for storage. The quantities of alcoholic be erages in retail sales uses are unlimited provided the liquids are packaged in individual containers not exceeding four liters. The quantities of medicines foodstuffs and cosmetics containing not more than 50 percent of volume of water miscible liquids and with the remainder of the solutions not being flammable in retail sales or storage occupancies are unlimited whe packaged in individual containers.

C ta es of exceeding four litters

Q ant t es may be no eased 100 percent in sprinklered buildings. When Footnote 5 also applies the increase for both footnotes may be applied.

When Footnote 5 also applies the increase for both footnotes may be applied. When Footnote 4. Quantities may be increased 100 percent when stored in approved storage cabinets or safety cans as specified in the fire code. When Footnote 4 also applies the increase for both may be applied.

The q a t t s perm tted a sprinklered building are not limited

A d t e plos o potent al s cons dered to exist if I pound or more of combustible dust per 1 000 c b c feet of olume is normally in suspens on or on horizontal's rfaces i side build ngs or equipment and which could be put into suspension by an acc dent sudden force or small explosion

Permitted in sprinklered buildings only None is allowed in unsprinklered buildings

One pound of black sporting powder and 20 pounds of smokeless powder are permitted in sprinklered or unsprinklered buildings Containing not more than the exempt amounts of Class I A Class I B Class I C flammable liquids

Table 4 1 Exempt Amounts of Hazardous Materials Liquids & Chemicals Presenting a Physical Hazard

2 (cont) 3

MAXIMUM QUANTITIES PER CONTROL AREA 2 units are given, values within parentheses are in pounds (Lbs.)

	STORAGE					LOSED SY	STEMS	USE3-OPEN SYSTEMS			
	MATERIAL ³	Solid (Lbs) ^{5 6}	Liquid Gallons (Lbs.) 5 6	Gas (Cu Ft) ⁵	Solid (Lbs) ⁵	Liquid Gallons (Lbs) ⁵	Gas (Cu Ft.)	Solid (Lbs) ⁵	Liquid Gallons (Lbs) ⁵	Gas (Cu Ft)	
1	Corrosives	5 000	500	650	5 000	500	650	1 000	100	-	
2	Highly Toxics	1 1	(1)	20"	1	(1)	20	/	(/)	-	
3	Irritants	5 000	500	650	5 000	500	6505	1 000	100	-	
4	Sensitizers	5 000	500	650	5 000	500	650 ⁵	1 000	100	-	
5	Other Health Hazards	5 000	500	650	5 000	500	650	1 000	100	_	

1 Control area is a space bounded by not less than one hour five resistive occupancy separation within which the exempted amounts of hazardous materials may be stored Dispensed handled or used. The number of control areas within retail and wholesale stores shall not exceed two and the number of control areas in other uses shall not exceed four

² The quantities of medicines foodstuffs and cosmetics containing not more than 50 percent by volume of water miscible liquids and with the remainder of the solutions not being flammable in retail sales uses are unlimited when packaged in individual containers not exceeding 4 liters

³ The aggregate quantity in use and storage shall not exceed the quantity listed for storage

⁴ For carcinogenic and radioactive materials see the Fire Code

⁵ Quantities may be increased 100 percent in sprinklered buildings. When Footnote 6 also applies the increase for both footnotes may be applied

⁶ Quantities may be increased 100 percent when stored in approved storage cabinets or safety cans as specified in the fire code When Footnote 5 also applies the increase for both footnotes may be applied

⁷ For special provisions see the Fire Code

⁸ Permitted only when stored in approved exhausted gas cabinets exhausted enclosures or fume hoods

33 34

4 1 1 8 Removal of Liquids from Containment System [D 1a(8)]

- 2 Upon discovery of liquid accumulation in the containment resulting from a spill or other release the BED
- 3 must be contacted in accordance with the 305 B Storage Facility contingency plan (Chapter 7) The BED
- 4 may determine that the contingency plan should be implemented. If the incident is minor, and the BED
- 5 approves removal of the liquids will commence immediately following a safety evaluation. Appropriate
- 6 protective clothing and respiratory protection will be worn during removal activities a PNNL industrial
- 7 hygienist may be contacted to determine appropriate personnel protection requirements and any other
- 8 safety requirements that may be required such as chemical testing or air monitoring. In addition
- 9 ventilation of the spill impacted area may be performed if determined to be safe and if appropriate
- 10 monitoring of the air discharge(s) is performed
- Spills are normally contained either within the storage cabinet within the cell or within a secondary
- containment trench or berm as described in Section 4 1 1 5. In any case, spilled material will be
- recovered to the extent possible by pumping recovered liquids with a pump made of nonreactive materials
- 14 (either steel or PVC) to intact containers selected in accordance with the container selection procedure in
- 15 Section 4 1 1 1 Nonrecoverable liquids will be absorbed with an appropriate absorbent (after appropriate
- 16 chemical reaction to neutralize reactivity in the case of reactive waste or neutralization in the case of
- 17 corrosive materials) refer to Table 6.2 for list of available materials for this purpose. The absorbent
- material will then be recovered and placed in a container selected in accordance with Section 4 1 1 1
- using nonsparking shovels in the case of ignitable waste. The floor cabinets and any other impacted
- 20 containers may be cleaned with dry rags soap and water or a compatible solvent if necessary to remove
- 21 external contamination Contaminated rags and other cleanup material will be disposed of in an
- 22 appropriate manner Verification sampling shall be carried out in accordance with Section 11 1 4 4
- 23 (Methods for sampling and testing to demonstrate success of decontamination)

24 4 1 2 Containers Without Free Liquid That Do Not Exhibit Ignitability or Reactivity [D 1b]

- 25 This section is not applicable to 305 B Storage Facility because the storage area is used to store
- 26 containers both with and without free liquids 305 B Storage Facility does not meet the conditions for
- 27 reduced requirements for storing only containers without free liquid therefore the facility is subject to
- 28 the full requirements for containment

29 42 PROTECTION OF EXTREMELY HAZARDOUS WASTE IN CONTAINERS [D 2]

- 30 All waste are stored inside of 305 B Storage Facility within the storage areas described in
- 31 Section 4 1 1 6 These locations are completely enclosed from the weather as described in
- 32 Section 4 1 1 7 meeting the requirements of WAC 173 303 630(7)(d)

43 PREVENTION OF REACTION OF IGNITABLE REACTIVE AND INCOMPATIBLE WASTE IN CONTAINERS [D 3]

- 35 The following sections provide information on the management of ignitable reactive and incompatible
- 36 waste in containers Additional information on this subject can be found in Section 6.5

37 4 3 1 Management of Ignitable or Reactive Waste in Containers [D 3a]


- 38 Ignitable and reactive waste are stored in compliance with Uniform Fire Code Division II regulations for
- 39 Container and Portable Tank Storage Inside Buildings (International Conference of Building
- 40 Officials 1988) Containers of ignitable and reactive waste are stored in individual flammable material
- 41 storage cabinets within the storage cells

1 432 Management of Incompatible Waste in Containers [D 3b]

- 2 Section 6 5 2 describes procedures used at 305 B Storage Facility to determine the compatibility of
- 3 dangerous waste so that incompatible waste are not stored together Chemical waste stored in
- 4 305 B Storage Facility are separated by compatibility chemical makeup and hazard class and stored in
- 5 areas having appropriate secondary containment as described in Section 4 1 1 6
- 6 As shown in Figures 4 2 through 4 11 each storage area has individual storage configurations secondary
- 7 containment structures are provided to assure that incompatible materials will not commingle if spilled
- 8 Further segregation is provided by chemical storage cabinets located throughout the facility in various
- 9 areas as shown in Figures 4.1 through 4.10 Cabinet types are noted in those figures and capacities
- described in Table 4.2 Incompatible waste are never placed in the same container or in unwashed
- containers that previously held incompatible waste
- 12 Compliance with WAC 173 303 395(1)(b) is assured utilizing the reactivity groupings given in A Method
- for Determining the Compatibility of Hazardous Waste (EPA 1980) Use of this system and the
- 14 procedure for handling ignitable or reactive waste and mixing of incompatible waste as described in
- Section 6 5 2 fulfills the requirements of WAC 173 303 395(1)(c)Tank System [D 3c]
- 16 This section is not applicable to the 305 B Storage Facility because waste are not managed in tanks
- 17 4 3 3 Waste Piles [D 3d]
- 18 This section is not applicable to the 305 B Storage Facility because waste are not managed in waste piles
- 19 4 3 4 Surface Impoundments [D 3e]
- 20 This section is not applicable to the 305 B Storage Facility because waste are not placed in surface
- 21 impoundments
- 22 4 3 5 Incinerators [D 3f]
- 23 This section is not applicable to the 305 B Storage Facility because waste are not incinerated
- 24 436 Landfills [D 3g
- This section is not applicable to the 305 B Storage Facility because waste are not placed in landfills
- 26 437 Land Treatment [D 3h]
- 27 This section is not applicable to the 305 B Storage Facility because waste are not treated in land treatment
- 28 units

1 Table 4 2 Storage Devices Used at the 305 B Storage Facility

20	Storage Device	Typical Use	External	Capacity
			Dimensions (in)	(gal/ft³)
21	Small Cabinet	Storage of containers (5 gallons or less capacity)	43w x 18d x 65h	50 max
22	Medium Cabinet	Storage of containers (18 93 liter [5 gallons] or less capacity	31w x 31d x 65h	60 max
23	Large Cabinet	Storage of containers (5 gallons or less capacity)	34w x 34d x 65h	80 max
24	Small Drum Cabinet	Storage of drums (5 to 55 gallons capacity)	34w x 34d x 65h	65 max
25	Large Drum Cabinet	Storage of drums (5 to 55 gallons capacity)	59w x 34d x 65h	130 max
26	Small Shelving	Storage of containers (5 gallons or less capacity)	47w x 18d x 62h	65 max
27	Large Shelving	Storage of containers (5 gallons or less capacity)	72w x 18d x 62h	100 max
28	Flammable Storage Module	18 93 liter [5 gallons] to 208 18 liter [55 gallons] capacity	78w x 73d x 100h	240 max
29	Refrigerator/ Freezer	Storage of containers of organic peroxides and other temperature sensitive waste	34w x 29d x 67h	25 Cu Ft
30	Explosives Magazine	Storage of containers containing DOT classified explosives	36w x 36d x 36h	8 Cu Ft



This page intentionally left blank

1			6 0 CONTENTS					
2	6 0	CO	NTENTS	6 ı				
3	60	PRO	OCEDURES TO PREVENT HAZARDS [F]	6 1				
4 5	6 1	SEC	CURITY [F 1]	6 1				
6	611		curity Procedures and Equipment [F 1a]	6 1				
7	612		iver [F 1b(1) (2)]	6 3				
8 9	62	TNIS	SPECTION SCHEDULE [F 2]	6 3				
10	621		neral Inspection Requirements [F 2a]	63				
11	622		ecific Process Inspection Requirements [F 2b]	67				
12 13	63	337 A	AIVER OR DOCUMENTATION OF PREPAREDNESS AND PREVENTION					
14	0.5		QUIREMENTS [F 3]	69				
15	631		upment Requirements [F 3a]	6 9				
16	632		le Space Requirements [F 3b]	6 11				
17								
18	64	PR	EVENTIVE PROCEDURES STRUCTURES AND EQUIPMENT [F 4]	6 11				
19	641	Unl	loading Operations [F-4a]	6 11				
20	642	Rui	n Off [F 4b]	6 14				
21	643	Wa	ter Supplies [F 4c]	6 14				
22	644	Εqι	upment and Power Failure [F 4d]	6 14				
23	645	Per	Personnel Protection Equipment [F 4e]					
24								
25	6 5		EVENTION OF REACTION OF IGNITABLE REACTIVE OR					
26			COMPATIBLE WASTE [F 5]	6 15				
27	651		cautions to Prevent Ignition or Reaction of Ignitable or Reactive Waste [F 5a]	6 15				
28	652		neral Precautions for Handling Ignitable or Reactive Waste and Mixing of					
29		Inc	ompatible Waste [F 5b]	6 15				
30			FIGURES					
31 32	Figure	6 1	Normal Site Access Entrance at the Southern End of Wisconsin Avenue and the North End of the 300 Area Barrier and Means to Control Entry [F 1a(2)(a) (2)(b)]	6 2				
33	Figure	6 2	Example of Weekly Inspection Checklist Form	6 5				
34	Figure	6 3	Example of Monthly Inspection Checklist Form	6 8				
35	Figure	6 4	305 B Storage Facility Building Plan and Location of Emergency Equipment	6 13				
36								
37								

	TABLES	
Table 6 1	Emergency Signals and Responses	6 10
Table 6 2	Material and Equipment for Spill Containment and Cleanup	6 12

DOE RL 90 01 Rev 1H

3/2002

Class 1 Modification

1

2

3 4 5 Quarter Ending 3/31/2002

1	6 0 PROCEDURES TO PREVENT HAZARDS [F]
2 3	The 305 B Storage Facility is operated to minimize exposure of the general public and operating personnel to dangerous and mixed waste
4	61 SECURITY [F 1]
5 6 7	Security for 305 B Storage Facility is provided by a combination of the overall security system for the 300 Area and a specific security system for the waste storage unit. The former controls access to the 300 Area proper while the latter controls access to 305 B Storage Facility.
8 9 10 11	The 305 B Storage Facility is located within the Hanford 300 Area. As part of the Hanford Site, the 300 Area is subject to a restricted access and personnel security system for the protection of Government property classified information, and special nuclear materials. The 300 Area is a controlled access area with access limited to persons authorized to enter and having appropriate security clearances or escorts.
12 13 14 15 16 17	The security program for 305 B Storage Facility in addition to 300 Area access is designed to limit building access to those personnel within the 300 Area authorized to enter the unit. Access to 305 B Storage Facility can be gained through five walk in doors and two large roll up doors that facilitate loading and unloading activities. All doors to 305 B Storage Facility are kept locked at all times except when in use. All requests for keys are reviewed and approved by the unit operating supervisor and the building manager, and a record of the personnel issued keys is kept in the Operating Record at all times.
19 20 21	Keys to the unit are issued only to unit personnel security personnel and emergency response personnel. The unit operating supervisor approves any additions to this list, and the building. Specific aspects of the security programs for both the 300 Area and 305 B Storage Facility are described in more detail below.
22	6 1 1 Security Procedures and Equipment [F 1a]
23 24	The following sections describe the 24 hour surveillance system barrier and warning signs used to provide security and control access to the 305 B Storage Facility
25	6 1 1 1 24 Hour Surveillance System [F 1a(1)]
26 27 28 29 30	The 305 B Storage Facility does not maintain a 24 hour surveillance system. Entrances to the building are kept locked except when the building is in use to prevent unauthorized access. Normal working hours for the unit is 8 00 A M to 4 30 P M Monday through Friday except holidays. The Hanford Patrol maintains frequent drive by surveillance of the 300 Area buildings including 305 B Storage Facility on a 24 hour basis to ensure that no unauthorized access to the area has occurred
31 32 33 34	An 8 ft chain link fence topped with three strands of barbed wire surrounds the entire 300 Area. There is no separate fence surrounding the 305 B Storage Facility. All waste management activities however are conducted within the unit. The facility itself, therefore, provides a barrier completely surrounding the active waste management operations.

2

Figure 6 1 Normal Site Access Entrance at the Southern End of Wisconsin Avenue and the North End of the 300 Area Barrier and Means to Control Entry [F 1a(2)(a), (2)(b)]

- Entry to the unit is controlled through the use of locked entrances The 305 B Storage Facility is kept
- 2 locked at all times except when in use Physical control of keys and records of key distributions are
- 3 maintained by PNNL Security Distribution of keys to 305 B Storage Facility is subject to approval by
- 4 the building manager and the facility operating supervisor and a list of those personnel in possession of
- keys are kept in the Operating Record for 305 B Storage Facility Personnel in possession of keys have
- 6 been instructed to admit only persons having official business 305 B Storage Facility staff must escort all
- 7 untrained visitors (personnel without 24/40 hour hazwoper training) in the waste storage areas

8 6112 Warning Signs [F 1a(3)]

- 9 The 305 B Storage Facility is posted with DANGER UNAUTHORIZED PERSONNEL KEEP OUT
- and 305 B CHEMICAL WASTE STORAGE BUILDING signs near each entrance on all sides of the
- unit The signs are clearly visible from the required distance of 25 feet

12 6 1 2 Waiver [F 1b(1) (2)]

- Waivers of the security procedures and equipment requirements for 305 B Storage Facility are not
- 14 required and will not be requested

15 62 INSPECTION SCHEDULE [F 2]

- The purpose and intent of implementing inspection procedures at 305 B Storage Facility are to prevent
- 17 malfunctions deterioration operator errors and/or discharges that may cause or lead to the release of
- regulated waste to the environment or threats to human health. A system of daily weekly monthly
- quarterly once every four months and annual inspections involving various PNNL departments and
- 20 levels of management are implemented at 305 B Storage Facility

21 621 General Inspection Requirements [F 2a]

- The content and frequency of inspections performed at 305 B Storage Facility are described in this
- 23 section Also described is maintenance of inspection records

24 6 2 1 1 Types of Problems [F 2a(1)]

- 25 Daily weekly monthly quarterly once every four months and annual inspections are performed at
- 305 B Storage Facility The types of problems addressed by each of these inspections are described
- 27 below
- 28 <u>Daily Inspections</u> The 305 B Storage Facility is inspected daily whenever waste packaging transfer
- shipping or movement operations are being carried out Daily inspections monitor container condition
- and integrity the building waste containment system and other building areas where waste are handled
- 31 Specific inspection points include
- 32 Inspection of stored containers for leaks or damage
- 33 Mislabeled or opened containers
- 34 Improper storage (e.g. incompatible waste storage)
- 35 Disorderliness or uncleanliness of a storage unit
- 36 Check for accumulation of waste in containment systems

Results of these daily inspections are recorded in the daily operating logbook that is part of the permanent

- 38 305 B Storage Facility Operating Record
- 39 Weekly Inspections Waste management organization personnel conduct weekly inspections of both
- safety and operating equipment in 305 B Storage Facility Safety and emergency equipment are
- 41 inspected for functionality and adequacy of supply Two personnel on the last workday of each week

using the inspection Logbook and the most current version of the Weekly Inspection Checklist Form that is on file at 305 B Storage Facility conduct the weekly inspection. An example of a Weekly Inspection

- 3 Checklist is shown in Figure 6.2 The Inspection Checklist and Inspection Logbook become a permanent
- 4 part of the 305 B Storage Facility Operating Record
- 5 Specific problems to be looked for with each of the items inspected are identified on the Inspection
- 6 Checklist Form The use of this form enhances inspection effectiveness by providing a consistent and
- detailed listing of areas of potential problems and those safeguards in place to prevent them. There is
- 8 space provided on the form for the inventory summary comments required remedial actions (if any) as
- 9 well as the date such actions are accomplished. The inspector is required to sign and date the inspection
- 10 checklist after performing the inspection. In addition, a space is provided for the dated signature of the
- 11 co inspector. A copy of the completed inspection form with any assigned action items is distributed to
- the responsible operating personnel All corrective actions required must be completed within one week
- of the inspection which found them deficient unless there are documentation and reason for further
- delay When corrective action has been completed the responsible personnel date and initial the form
- 15 Monthly Inspections The manager of the Environmental Management Services Department or their
- designee conducts monthly oversight inspections. This monthly inspection is conducted on or near the
- 17 last workday of each month using the most current version of the Monthly Inspection Checklist Form
- An example of a Monthly Inspection Form is shown in (Figure 6 3) Items targeted for monthly
- 19 inspection include but are not limited to equipment function and condition housekeeping chemical
- 20 inventory weekly inspections and corresponding corrective actions safety equipment operation spill
- 21 control and cleanup supplies and general packaging material inventory Specific problems to be looked
- for with each of the items inspected are identified on the Inspection Checklist Form. Copies of the inspec
- tion report memorandum are provided to operations personnel and maintained in the files of the waste
- management organization. Any corrective action noted on the management inspection checklist or deterioration or malfunctions in equipment discovered by the inspector are delegated to responsible.
- 26 individuals in the operations group Corrective actions identified in the monthly management inspection
- 27 must be completed before the next inspection cycle unless there are documentation and reason for further
- delay Monthly management inspection reports memos and corrective action response documentation is
- 29 part of the 305 B Storage Facility Operating Record
- 30 Quarterly Once Every Four Months and Annual Inspections In addition to the several layers of
- 31 management inspection of 305 B Storage Facility safety inspections are performed to assure the fire
- protection system eye wash/shower unit and walk in hood ventilation systems are in working order. The
- Hanford 300 Area Fire Department performs once every four months a inspection of fire suppressant
- and notification systems (i.e. sprinkler system and pull boxes). This inspection includes flow tests of the
- 35 sprinklers to assure no blockage in the system lines as well as activation of the alarm system to assure
- proper operation of pull boxes On an annual basis the Fire Department performs a full inspection of the
- 37 sprinkler system heat detectors and pull boxes. A complete flow test is performed from the furthest
- 38 valve to assure flow through
- 39 the entire system. Fire extinguishers are also checked for proper pressure and function. Records of these
- fire inspections and the Hanford Fire Department keeps their results. Documentation of any required cor
- 41 rective actions is kept in the 305 B Storage Facility Operating Record
- 42 PNNL facilities support staff perform additional documented inspections of the two emergency eye
- wash/shower units and the walk in hood airflow. The safety showers and airflow of the walk in hood are
- 44 inspected quarterly The emergency eyewash/safety showers are checked for proper operation and the
- walk in hood ventilation face velocity must meet minimum requirements. Records of these safety
- 46 equipment inspections and their results as well as documentation of any required corrective actions are
- 47 maintained by the preventive maintenance staff in PNNL's Facilities Management Department and
- 48 Technical Services Department

Pgelf2

Figure 6 2 Example of Weekly Inspection Checklist Form

Weekly Inspection Form 305 B Storage Facility Chemical Waste Storage

Inspector Name (print)					Inspector Signature						Time/Date				
Co Inspector Name (print)			•		Co Inspector Signature							Time/Date			
Waste Containment Loc	ations	(Y=Y	es, N=N	D)								-			
Earliest PCB Accumulation D	ate in C	eli 2	······································	·····			Earliest	RMW PC	В Ассі	umulati	on Date _				
Cell	Ox szerr sds	2 son, PC lass	3 Caust W W Non eg	4 mmab Combus ib Aerosols	5 mmab Bulk ng ylinders	6 shestor	7 Non-Flammable RMW	8 Flammable Drum torage	9 Flammable RMW	10 Non-Reg ard	11 WSDW Class 9 on-Reg. Drum	12 Oxidizer Drum	13 Drums	14 lka me Drums	15 xplos ves Magaz ne
Container integrity good?															
Containers properly sealed?															
Containers properly labeled?															
Containers properly segregated?	Ì				 										
floor free of major cracks/gaps?						-					 				
sumps empty and dry?															
Minimum aisle space present?				(44 lead	ing to buil	dıng ex	ats 36 all	l other assle	s per NF	PA 101	UBS 3315((b)1 and	i WAC	173 30:	3
Inventory below 30 000 gallon design capacity? Estimate				Estimated	i Volume	⇒		gallons							
Inventory below UBC Class B limits? (<480 g				(<480 gal	llons 1 A	1 B 1	C total and	d/or <240 g	allons 11	3					
daily inspections logged?															

Figure 6 2 Example of Weekly Inspection Checklist Form (cont)

Weekly Inspection Form 305-B Storage Facility Chemical Waste Storage

Emergency Equipment and Supplies (Y=Yes N=No)		• • • • • • • • • • • • • • • • • • •	
North eyewash safety shower clear access?		Inventory as noted and in working order?	
South eyewash safety shower clear access?		4 each full face respirators with combination organic vapo	r/HEPA filters?
Portable eyewash outside of east bay door pressurized?		4 each full face shields?	*
Spill control station stocked for acid base solvent and other spills?		6 each Tyvek suits?	
Fire extinguishers (8) inspected and have clear access?		6 each acid suits?	
Facility phone (376-4293) operational?		20 pair eye protection glasses and/or goggles?	
Facility public address system (376-1885) operational?		synthetic rubber leather gloves stocked?	
Formaldehyde spill kit (Cell 2) fully stocked with 11 lbs neutralizer?		3 each SCBA units?	
Action			Date Corrected

1 6212 Frequency of Inspections [F 2a(2)]

- 2 Inspections are conducted on a daily weekly monthly quarterly and annual basis as described in
- 3 Section 6 2 1 1
- 4 The frequency of inspections is based on specific regulatory requirements and on the rate of possible
- deterioration of equipment and probability of environmental or human health incidents
- 6 Areas where dangerous and mixed waste are actively handled including the high bay area storage cells
- and flammable liquid bulking module are considered to be areas subject to spills. These areas are given
- 8 daily inspections when in use as required by WAC 173 303 320(2)(c)
- 9 The containment system (i.e. floors and sumps) is inspected daily when in use for accumulation of spilled
- material The containment system itself is inspected weekly for structural integrity (i.e. no cracks gaps
- leaks etc that could result in environmental release of waste in the event of a spill) This frequency is
- based on the need to perform timely corrective actions in the event that problems are noted
- Assle space between containers is inspected weekly. This frequency is based on the consideration of the
- rate of container transfers and movement within 305 B Storage Facility Weekly inspections will allow
- container spacing problems to be identified and corrected before they become major problems
- 16 Emergency and safety equipment and personal protective equipment is inspected weekly. This frequency
- 17 is based on consideration of the expected rate of use of this equipment. Use of emergency equipment
- should not occur more than once during any one week period. Weekly inspections will assure that this
- 19 equipment is always functional and available in adequate supply

20 6 2 2 Specific Process Inspection Requirements [F 2b]

- The following sections detail the inspections to be performed at the 305 B Storage Facility
- 22 6 2 2 1 Container Inspection [F 2b(1)]
- When in use dangerous and mixed waste storage areas as well as containers stored at 305 B Storage
- Facility is inspected daily for leakage evidence of damage or deterioration proper and legible labeling
- and proper lid and bung closure When work is being performed the containment system is also checked
- on a daily basis for accumulation of any waste that may have been spilled into them Structural integrity
- of the containment systems is checked on a weekly basis
- Daily and weekly inspections are performed and documented in accordance with Section 6 2 1 1
- Specific inspection items are enumerated in Section 6.2.1.1 in association with the inspection description
- and frequency Response to problems and documentation of corrective actions are as described in
- 31 Section 6 2 1 1
- 32 6 2 2 2 Tank Inspection [F 2b(2)]
- This section does not apply to the 305 B Storage Facility because waste are not stored or treated in tanks
- 34 6 2 2 3 Waste Pile Inspection [F 2b(3)]
- 35 This section does not apply to the 305 B Storage Facility because waste is not placed in waste piles

Figure 6-3 Example of Monthly Inspection Checklist Form

305 B Storage Facility Monthly Management Inspection Checklist

Inspector (Print/Sign) Date/Time Check if Working/ Present | Comments* Check for present and working condition: Exhaust fans (2 in highbay) Eye wash/showers (3) Fire extinguishers Required facility postings Check housekeeping: Inside Outside Aısles/walkway clear Sumps dry Check waste storage: Weekly inspection conducted/filed? Facility crowded? Container condition Proper segregation Check supply and condition of safety equipment: Gloves leather and disposable Goggles Face shields Coverall/lab coats Masks and cartridges Check spill control and cleanup supplies: Spill pillows - general Neutralizers Mercury Solvent Check packaging material: Drums 5 gallon Drums 30 gallon Drums 55 gallon Absorbent oil dry Absorbent - vermiculite Labels

Marking supplies pens/spray paint

^{*}Corrective actions are required within the next inspection cycle

1 6224 Surface Impoundment Inspection [F 2b(4)]

- This section does not apply to the 305 B Storage Facility because waste is not placed in surface
- 3 impoundments
- 4 6 2 2 5 Incinerator Inspection [F 2b(5)]
- 5 This section does not apply to the 305 B Storage Facility because waste is not incinerated
- 6 6 2 2 6 Landfill Inspection [F 2b(6)]
- 7 This section does not apply to the 305 B Storage Facility because waste is not placed in landfills
- 8 6227 Land Treatment Facility Inspection [F 2b(7)]
- This section does not apply to the 305 B Storage Facility because waste is not treated in land treatment
- 10 units
- 11 63 WAIVER OR DOCUMENTATION OF PREPAREDNESS AND PREVENTION 12 REQUIREMENTS [F 3]
- 13 The following documents the preparedness and prevention measures taken at the 305 B Storage Facility
- 14 631 Equipment Requirements [F 3a]
- The following sections describe the internal and external communications and emergency equipment in
- use at 305 B Storage Facility
- 17 6 3 1 1 Internal Communications [F 3a(1)]
- 18 Internal communication systems are used to provide immediate emergency instruction to personnel in
- 19 305 B Storage Facility Internal communications address general emergencies that may occur in the
- 20 300 Area as well as specific emergencies that may occur in 305 B Storage Facility
- Because of the nature of activities that occur in the 300 Area the potential exists for emergencies outside
- of 305 B Storage Facility (e.g. release of radioactive materials) that could impact operations and staff in
- 23 305 B Storage Facility For this reason the general emergency signals for the 300 Area are applicable to
- 24 305 B Storage Facility These signals are summarized in Table 6.1 Fire alarm signals are located in
- each building throughout the 300 Area. The nearest emergency siren for area evacuation and take
- 26 cover is located 300 yards southeast of 305 B Storage Facility on top of the 326 Building and is audible
- 27 in all parts of 305 B Storage Facility Because fissile materials are not handled in 305 B Storage Facility
- there is no criticality alarm for the unit
- 29 Internal communications to provide emergency instruction in the event of an emergency in 305 B Storage
- Facility are fire alarms public address (PA) system and telephones. The fire alarms are to be used to
- 31 provide notification for immediate evacuation of 305 B Storage Facility Fire alarm pull boxes are
- located at all exits of the facility such that operating personnel have immediate access to one in all
- portions of 305 B Storage Facility Four fire alarm bells are located within the 305 B Storage Facility
- and are audible at all locations within the building The locations of the fire alarm bells are shown in
- Figure 6 4 and are as follows (1) an office wing on the northeast hall (2) an office wing next to the east
- entrance (3) on the south wall of the basement and (4) on the northeast wall of the high bay The PA
- 37 system is to be used for building wide broadcasting of verbal emergency instructions to 305 B Storage
- Facility staff The PA system can be accessed from any unit telephone by dialing 376 1885 The PA

system speakers are located in the high bay in the basement and in the office wing of 305 B Storage Facility

The telephone system is to be used to provide verbal emergency instructions to 305 B Storage Facility staff. The telephone can also be used to verbally transmit emergency data to non 305 B Storage Facility staff, and to request emergency services. A network of telephones covers both floors of the facility Locations of telephones are shown in Figure 6.4.

Table 6-1 Emergency Signals and Responses

Meaning	Response
Fire	Evacuate building Move upwind Keep clear of emergency vehicles
Area Evacuation	Proceed promptly to north parking area Stand by to follow instructions from emergency director
Take Cover	Close up the 305 B Building turn off all intake ventilation and go to the 314 Building south of the facility Contact Laboratory Safety (337 Building) with your whereabouts If this cannot be accomplished stay in the 305 B Building until notified that it is safe to leave
Criticality	Run immediately at least 100 yards away from the signal and take cover Personnel inside the 305 B Building should follow the take cover procedure and wait for further instructions
	Fire Area Evacuation Take Cover

6 3 1 2 External Communications [F 3a(2)]

As mentioned in Section 6 3 1 1 above both a fire alarm system and telephone network system are in place at 305 B Storage Facility. Both systems can be used to summon emergency assistance. The fire alarm system summons direct response from the Hanford Fire Department's 300 Area Station. The telephone system can be used to access Hanford's Emergency Network directly at 375 2400 or by dialing the emergency number 911. Locations of fire alarm pull boxes and telephones are given in Figure 6.4.

6 3 1 3 Emergency Equipment [F 3a(3)]

Emergency equipment available for trained 305 B Storage Facility personnel includes portable fire extinguishers a fire suppression system spill response equipment and decontamination equipment Seven portable 10 lb ABC fire extinguishers and one 15 lb (or larger) Class D fire extinguisher for combustible metals are available at various locations throughout 305 B Storage Facility as shown in Figure 6 4 The 10 lb ABC extinguishers are located (1) next to the east entrance (2) northwest end of the basement (3) southwest end of the high bay (4) outside of the bulking module door (5) north of Cell No 4 entrance and (6) north west end of high bay (7) office area A 15 lb ABC extinguisher is located outside cell 7 The 15 lb (or larger) class D extinguisher is located on the exterior of the organics cell wall north of the entrance

The facility is also equipped with an automatic fire suppression system consisting of galvanized steel schedule 40 per ASTM A120 pipe and 150 lb malleable iron per ANSI B16 3 fittings. All components are UL listed or FM approved and installation of the fire sprinkler system has been conducted in accordance with NFPA 13 for ordinary hazard. Spill cleanup supplies and equipment maintained are summarized in Table 6.2. Four emergency eye wash/showers are available for emergency personnel decontamination. The locations of the emergency eye wash/showers are shown in Figure 6.4. If needed

- the Hanford Fire Department can provide additional emergency equipment Emergency equipment avail able through the Hanford Fire Department for hazardous materials response is identified in Appendix 6A
- 3 6314 Water for Fire Control [F 3a(4)]
- 4 The large diameter linen that services 305 B Storage Facility for potable use and fire protection supplies
- 5 adequate water volume and pressure Three fire hydrants are located in immediate proximity to serve the
- 6 305 B Storage Facility (1) 80 ft directly north of the northwest corner of 305 B Storage Facility (2) 40 ft
- directly south of the southwest corner of 305 B Storage Facility and (3) 60 feet directly east of the
- 8 southeast corner of 305 B Storage Facility In addition the Hanford Fire Department's 300 Area Station
- 9 is located within 0 25 mile of 305 B Storage Facility
- 10 6 3 2 Aisle Space Requirements [F 3b]
- 11 Containers stored in the 305 B Storage Facility are placed to provide aisle space clearance in accordance
- with WAC 173 303 340(3) and applicable standards of the Uniform Building Code and Life Safety Code
- The proper maintenance of aisle space is inspected weekly and noted on the weekly inspection checklist
- 14 (Figure 6 2)
- 15 64 PREVENTIVE PROCEDURES STRUCTURES AND EQUIPMENT [F-4]
- The following sections describe preventive procedures structures and equipment
- 17 6 4 1 Unloading Operations [F-4a]
- Procedures have been developed at 305 B Storage Facility to prevent hazards and minimize the potential
- for breakage punctures or the accidental opening of containers during waste unloading. All waste
- 20 unloading is performed inside the 305 B Storage Facility. The large bay door is opened and the
- 21 appropriate transporting vehicle (usually a pickup truck) is driven inside. As described in Section 4 1 1 3
- 22 the unloading area has secondary containment. By unloading all waste inside the fully contained facility
- 23 spills during unloading operations will be contained Procedures for unloading and transferring waste to
- storage areas have been designed to minimize hazards. All waste is inspected prior to shipment to
- 25 305 B Storage Facility to ensure that they are in appropriate containers and that the containers are in good
- 26 condition Inspection of containers prior to acceptance at 305 B Storage Facility minimizes the potential
- for spills during unloading operations The potential for spills during waste handling is minimized
- through the use of appropriate container handling equipment. Large waste items such as drums of
- 29 nonflammable RMW are lowered into the basement of the facility for storage using an overhead crane or
- 30 winch assembly The containers are immediately transported via a hand lift into the concrete lined
- 31 storage vault Forklifts may also be used to unload heavy waste items. Small waste items can be
- 32 unloaded by hand Each small waste item is removed from the secondary containment unit in which it
- was transported (i.e. plastic storage tub) and placed in the appropriate storage location

Table 6 2 Material and Equipment for Spill Containment and Cleanup								
Materials/Equipment			Notes					
Diatomaceous Earth	30 gallon drum	To absorb small spills of oils solvents aqueous materials. Not used for acids or caustics unless first neutralized	Stored in high bay of 305 B Storage Facility					
Vermiculite	55 gallon drum	To absorb small spills of oils solvents aqueous materials. Not used for acids or caustics unless first neutralized	Stored in high bay of 305 B Storage Facility					
Absorbent Pillows or Booms	Three cartons each containing booms or 12 pillows	To be used for diking or damming and absorption of spilled materials	Each boom or pillow can absorb slightly more than I L of liquid					
Acid and base specific and solvent absorbents or neutralizers	50 lb box of each in 305 B Storage Facility and a 32 oz bottle of each in transport vehicle	Neutralization of known chemical spills	JT Baker TM brand or equivalent					
Citric Acid	30 gallon drum	Neutralization of alkaline spills	Stored in high bay of 305 B Storage Facility					
Sodium Bicarbonate	30 gallon drum	Neutralization of acid spills	Stored in high bay of 305 B Storage Facility					

Figure 6-4 305 B Storage Facility Building Plan and Location of Emergency Equipment

1

First Floor and High Bay Office o THEFT Office THE PROPERTY OF THE PROPERTY O PLAC Office 14 1 15 Toilet **High Bay** 2 P 3 10 8 Basement 郁 7 Equipment Office Storage

19 20

17

18

Legend

- 1 Acids Oxidizers
- 2 Poisons Class 9
- 3 Alkaline WSDW Organic Peroxides
- 4 Organics and Compressed Aerosols
- 5 Flammable Liquid Bulking and compressed gases
- 6 Asbestos Cabinet
- 7 RMW Storage Cell
- 8 Flammable Storage
- 9 Small Quantity Flammable RMW
- 10 Outdoor Non regulated Drum Storage
- 11 WSDW Non flammable Drums
- 12 Oxidizer Drums
- 13 Acid Drums
- 14 Alkaline Drums
- 15 Explosive Magazine

Safety Shower/Eyewash

Phone

🕽 Fire Alarm Bell

P Fire Alarm Pull Box

10 Lb ABC Fire Extinguisher

15 Lb Or larger Class D Fire Extinguisher

Removable Access to Basement

Emergency Equipment Cabinet

Collection Sump

6 4 2 Run Off [F-4b]

1

10

16

23

33

36

38

- The 305 B Storage Facility was designed to eliminate the likelihood of off site migration via run off
- Because the facility is completely enclosed (i.e. complete roof and no open walls) run off of
- 4 precipitation is not a factor. In addition, floors are bermed and sloped toward sumps in the
- loading/unloading area and each storage cell is similarly bermed sloped and individually sumped to
- 6 eliminate the possibility of spills interacting or migrating offsite. The main high bay area and each
- storage cell are fully contained by at least a 6 in high dike or ramp. Each door from the waste handling
- 8 areas to the outside has a collection trench to intercept any potential run off. The containment system for
- 9 305 B Storage Facility is described in more detail in Section 4 1 1 3

643 Water Supplies [F-4c]

- 305 B Storage Facility is designed and operated to safely contain waste and prevent any contamination of
- water supplies The containment system described in Section 4 1 1 3 prevents infiltration of waste that
- could contaminate groundwater and prevents run off of waste that could contaminate surface water. The
- nearest water supply is the 300 Area water intake which is located on the Columbia River 0.5 mile from
- 15 305 B Storage Facility

644 Equipment and Power Failure [F 4d]

- The 305 B Storage Facility does not have any systems that would cause release of dangerous waste or
- 18 RMW during a power failure or equipment failure. Interruption of power to any of the systems utilizing
- electrical power (HVAC system crane forklift) merely causes the equipment to stop operating. The unit
- 20 has an emergency lighting system that operates automatically during power failure incidents
- For actions to be taken in the event of power failure to unit systems or equipment refer to the unit
- 22 BEP/Contingency Plan (Section 7)

645 Personnel Protection Equipment [F-4e]

- 24 Protective clothing and equipment are provided to employees during normal and emergency operations
- During routine operations the maximum number of employees working in the 305 B Storage Facility is
- less than fifteen For dry chemical handling activities such as labpacking the minimum protection
- 27 requirement is eye protection (safety glasses with side shields or chemical goggles) lab coat and
- chemical resistant gloves (plastic or other construction as appropriate) Protection levels for other
- 29 operations such as bulking and emergency situations are determined in consultation with a PNNL
- 30 industrial hygienist and staffing levels are revised according to the availability of proper protective
- 31 equipment as shown below Protective clothing and equipment available in the 305 B Storage Facility
- 32 includes
 - 6 sets of chemically resistant suits aprons boots and gloves
- 34 20 pairs of extra protective eyeglasses
- 35 3 SCBA
 - 5 pairs of chemical goggles
- 37 4 face shields
 - 4 full face respirators with appropriate cartridges

This protective equipment is stored in cabinets located outside of the operating area east entrance and is well stocked at all times. The location of the storage cabinets is given in Figure 6.4. This equipment is

- 41 periodically replaced as it is used. The above inventory reflects the quantities of each type of PPE that
- 42 are typically present at 305 B Storage Facility Minimum quantities required to be present are given in
- the weekly inspection checklist found in the Hazardous & Miscellaneous Waste Operations Procedure

storage in cabinets are found in Section 4 3 1

1 2	6 5 PREVENTION OF REACTION OF IGNITABLE REACTIVE OR INCOMPATIBLE WASTE [F 5]
3	The following sections describe prevention of reaction of ignitable reactive and incompatible waste
4	651 Precautions to Prevent Ignition or Reaction of Ignitable or Reactive Waste [F 5a]
5 6 7 8 9	305 B Storage Facility may be used to store a variety of ignitable waste. Precautions to prevent ignition of ignitable waste involve separation of waste from sources of ignition and use of procedures which minimize the potential for accidental ignition. There are no routine sources of ignition or open flame in 305 B Storage Facility. Work with ignition or heat sources if required is limited and controlled by PNNL management and is performed in compliance with internal PNNL health and safety procedures for elimination of ignition sources. These internal procedures
11	Prohibit use of open flame equipment when working with flammable liquids
12	Prohibit smoking around flammable liquids [No smoking is allowed at 305 B Storage Facility]
13 14	Require electrical equipment used in flammable or explosive atmospheres to comply with the National Electrical Code NFPA 70
15 16	Require use of equipment with automatic adjustable temperature controls and high temperature limit switches to prevent overheating
17	Prohibit placement of flammable liquids on hot surfaces
18	Require all static electricity sources to be grounded in areas where ignitable vapors may be present
19	Require bonding of conductive containers when transferring flammable liquids
20	Require use of non sparking tools in flammable waste storage areas
21 22 23 24 25	All maintenance or modifications that require work with ignition sources must receive prior approval by a PNNL Safety Engineer Smoking is not allowed in 305 B Storage Facility at any time and the interior and exterior of the facility are clearly posted with No Smoking signs. Waste storage areas are not heated by any radiant heat source. All tools used to open ignitable waste containers are constructed of nonsparking materials.
26 27 28 29 30 31 32	A PNNL fire safety engineer familiar with the Uniform Fire Code inspects ignitable waste storage areas annually. This inspection is documented in the Operating Record. There are also storage restrictions at 305 B Storage Facility for combustible waste as part of fire safety requirements. The storage restrictions defined in the Uniform Building Code for Class B Occupancy apply to 305 B Storage Facility (International Conference of Building Officials 1988). The weekly inspection for 305 B Storage Facility includes checking to see if the inventory of combustibles is below these limits. These inspections are documented in the Operating Record.
33 34	6 5 2 General Precautions for Handling Ignitable or Reactive Waste and Mixing of Incompatible Waste [F 5b]
35 36 37 38 39 40	As described in Section 6.5.1 ignitable waste are managed in a manner that protects the waste from sources of ignition or open flame. Ignitable waste containers are maintained in good condition and inspected weekly to minimize the potential for releases that could result in fire. Containers of ignitable waste are protected from high temperature to prevent the potential for pressurization and buildup of ignitable vapors. Containers of ignitable waste are stored in flammable material storage cabinets within waste storage cells as described in Section 4.1.1.6 Limitations on sizes of containers and amounts of

Because of the wide variety of waste that may be accepted at 305 B Storage Facility the potential exists for storage of incompatible waste. Mixing of incompatible waste is prevented through waste segregation and storage procedures. Chemical waste stored in 305 B Storage Facility are separated by compatibility and hazard class and stored in separate storage cells. Separate storage shelves and cabinets are used within the storage cells as described in Section 4.1.1.6 to provide further waste segregation. The following general guidance is used to segregate and separate chemicals.
Store acids on a low storage shelf or in acid storage cabinets
Separate acids from bases and alkaline metals such as potassium or sodium
Separate oxidizing acids from organic acids and flammable or combustible materials
Store bases away from acids and store solutions of inorganic hydroxides in polyethylene containers
Store oxidizers away from flammable or combustible materials and reducing agents such as zinc alkaline metals and formic acid
Store peroxide forming chemicals in airtight containers in a dark cool and dry place (inside of cabinets)
Store flammable materials in approved containers or cabinets
Separate flammable materials from oxidizing acids and oxidizers and keep them away from sources of ignition
Clearly mark cabinets to identify the hazards associated with their contents
The potential for waste ignition or reaction at 305 B Storage Facility is also minimized through storage restrictions on hazardous material quantities. The storage restrictions defined in the Uniform Building Code for Class B Occupancy apply to 305 B Storage Facility (International Conference of Building Officials 1988). The weekly inspection of 305 B Storage Facility includes checking to see if waste inventories are below these limits. These inspections are documented in the Operating Record.

Hanford Facility RCRA Permit Modification Notification Forms Part III, Chapter 4 and Attachment 34 Liquid Effluent Retention Facility and 200 Area Effluent Treatment Facility

Page 1 of 5

Index

Page 2 of 5	Hanford Facility RCRA Permit Condition III 4 A
Page 3 of 5	Appendix 4A Table 4A 2
Page 4 of 5	Appendix 4B Table 4B 1
Page 5 of 5	Appendix 4B Table 4B 2

Page 2 of 5 Hanford Facility RCRA Permit Modification Notification Form Permit Part & Chapter Liquid Effluent Retention Facility and Part III Chapter 4 and Attachment 34 200 Area Effluent Treatment Facility Description of Modification Hanford Facility RCRA Permit Condition III 4 A COMPLIANCE WITH APPROVED PERMIT APPLICATION The Permittees shall comply with all requirements set forth in Attachment 34 including the Amendments specified in Condition III 4 B if any exist Enforceable portions of the application are listed below (All subsections figures and tables included in these portions are also enforceable unless stated otherwise) LERF Part A Form 3 Permit Application Revision 6 ETF Part A Form 3 Permit Application Revision 3 Section 2 2 Topographic Map non enforceable sections in Chapter 2 were modified in Class 1 Modification for quarter ending March 31 2001 Section 3 2 Waste Analysis Plan from Class 1 Modification for quarter ending March 31 2001 Chapter 4 0 Process Information from Class 1 Modification for quarter ending September 30 2001 Chapter 5 0 Ground Water Monitoring from Class 1 Modification for quarter ending June 30 2000 Chapter 6 0 Procedures to Prevent Hazards from Class 1 Modification for quarter ending September 30 2000 Chapter 7 0 Contingency Plan from Class 1 Modification for quarter ending September 30 2000 Chapter 8 0 Personnel Training from Class 1 Modification for quarter ending September 30 2001 Chapter 11 0 Closure and Financial Assurance from Class 1 Modification for quarter ending March 31 2001 Chapter 12 0 Reporting and Recordkeeping from Class 1 Modification for quarter ending March 31 2001 Chapter 13 0 Other Federal and State Laws from Class 1 Modification for quarter ending March 31 2001 Appendix 2A Topographic Map Appendix 3A Waste Analysis Plan for the Liquid Effluent Retention Facility and 200 Area Effluent Treatment Facility from Class 1 Modification for quarter ending March 31 2001 Detailed Drawings for the Liquid Effluent Retention Facility from Class 1 Modification for quarter ending Appendix 4A March 31 2002+ Detailed Drawings for the 200 area Effluent Treatment Facility Container Storage Area and Tank Systems from Appendix 4B Class 1 Modification for quarter ending March 31 20024 Liquid Effluent Retention Facility Final Ground Water Monitoring Plan PNNL 11620 See Appendix 5A Amendment III 4 B c Appendix 7A Building Emergency Plan for the Liquid Effluent Retention Facility and 200 Area Effluent Treatment Facility from Class 2 Modification dated February 2001 Enforceable portions include Sections 1 5 3 1 4 0 7 1 7 1 1 712 72 721 722 723 724 725 7251 73 82 83 84 90 91 92 93 94 95 96 110 120 and 13 0 Modification Class Class 11 Class 1 Class 2 Class 3 Please check one of the Classes X

						<u> </u>	
Relevant WAC 173	303 830	Appendix I Modification	n	A 1			
A General Permit	Provision	ation from WAC 173 30. s Iformational clamges	3 830, Apr	endix I citation			
Submitted by Co C		Reviewed by RL Progra		Reviewed by Ecology		Reviewed by Ecology	
J A Van Vliet	Date	G H Sanders	Date	F Jamison	Date	LE Ruud	Date

¹Class 1 modifications requiring prior Agency approval

² This is only an advanced notification of an intended Class ¹1 2 or 3 modification this should be followed with a formal modification request and consequently implement the required Public Involvement processes when required

³ If the proposed modification does not match any modification listed in WAC 173 303 830 Appendix I then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology or down graded to ¹1 if appropriate

Hanford Facility RCRA Permit Modification Notification Form

Unit

Liquid Effluent Retention Facility and 200 Area Effluent Treatment Facility

Permit Part & Chapter
Part III Chapter 4 and Attachment 34

Description of Modification

Appendix 4A Table 4A 2

Table 4A 2 Liquid Effluent Retention Facility Piping and Instrumentation

LERF System	Drawing Number	Outstanding ECNs	Drawing Title
Transfer Piping to 242 A Evaporator	H 2 79604 Sh 1 Rev 3	ECN 648330	Piping Plot and Key Plans 242 A Evaporator Condensate Stream (Sheet 1)
LERF Piping and Instrumentation	H 2 88766 Sh 1 Rev 36	ECN 648330 ECN 656789 ECN 658555	P&ID LERF Basin and ETF Influent (Sheet 1)
LERF Piping and Instrumentation	H 2 88766 Sh 2 Rev <u>\$7</u>	ECN 647209L ECN 648330 ECN 658555 ECN 664355	P&ID LERF Basin and ETF Influent (Sheet 2)
LERF Piping and Instrumentation	H 2 88766 Sh 3 Rev 6 §	ECN 648330 ECN 709380L ECN 658555 ECN 664319	P&ID LERF Basın and ETF Influent (Sheet 3)
LERF Piping and Instrumentation	H 2 88766 Sh 4 Rev 69	ECN 648330 ECN 658584 ECN 658555 ECN 664320	P&ID LERF Basin and ETF Influent (Sheet 4)
	H 2 89351 Sh 1 Rev 7	None HNF FMP 01 9507 R0	Piping & Instrumentation Diagram Legend

P&ID piping and instrumentation diagram

Modification Class 123	Class 1	Class 11	Class 2	Class 3
Please check one of the Classes	X			

Relevant WAC 173 303 830 Appendix I Modification A 1

Enter wording of the modification from WAC 173 303 830, Appendix I citation

A General Permit Provisions

1 Administrative and informational changes

	Submitted by Co O	perator Reviewed by RL Pro	gram Office	Reviewed by I	Ecology	Reviewed by I	Scology
4	publer	3/22/02 St Nevel	4/2/02				
- 4	J A Van Vliet	Date G H Sanders	Date	F Jamison	Date	LE Ruud	Date

¹ Class 1 modifications requiring prior Agency approval

² This is only an advanced notification of an intended Class ¹1 2 or 3 modification this should be followed with a formal modification request and consequently implement the required Public Involvement processes when required

³ If the proposed modification does not match any modification listed in WAC 173 303 830 Appendix I then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology or down graded to ¹1 if appropriate

Hanford Facility RCRA Permit Modification Notification Form

Unit
Liquid Effluent Retention Facility and
200 Area Effluent Treatment Facility

Permit Part & Chapter
Part III Chapter 4 and Attachment 34

Description of Modification

Appendix 4B Table 4B 1

Table 4B 1 Drawing of Effluent Treatment Facility and Load In Station Secondary Containment Systems

	•	-	•
ETF Process Unit	Drawing Number	Outstanding ECNs	Drawing Title
Surge Tank Process/Container Storage Areas and Trenches Foundation and Containment	H 2 89063 Sh 1 Rev 3	ECN 647892	STRUCT – Foundation and Grade Beam Plan (Sheet 1)
Sump Tank Containment	H 2 89065 Sh 1 Rev 3	None	STRUCT - Foundation Sections and Detail (Sheet 1)
Verification Tank Foundation and Containment	H 2 89068 Sh 1 Rev 3	ECN 647892	STRUCT - Verification Tank Foundation (Sheet 1)
Load In Facility Foundation and Containment	H 2 817970 Sh 1 Rev 1	ECN 641703 ECN 647247 ECN 649104	Structural – ETF Truck Load in Facility Plans and Sections (Sheet 1)
Load In Facility Foundation and Containment	H 2 817970 Sh 2 Rev 1	ECN 641703 ECN 649104	Structural – ETF Truck Load in Facility Sections and Details (Sheet 2)

P&ID piping and instrumentation diagram

STRUCT architectural/structural diagram

Modification Class 123		Class 1	Class 11	Class 2	Class 3
Please check one of the Classes	_	X			
Relevant WAC 173 303 830 Appendix I Modifica	ation A	1			
Enter wording of the modification from WAC 173 A General Permit Provisions 1 Administrative and informational changes	303 830, 4	Appendix I cita	ation		
Submitted by Co Operator Reviewed by RL Program	Office 4/2/02	Reviewed by	Ecology	Reviewed by	/ Ecology
J A Van Vliet Date G H Sanders	Date	F Jamison	Date	LE Ruud	Date

¹ Class 1 modifications requiring prior Agency approval

² This is only an advanced notification of an intended Class ¹1 2 or 3 modification this should be followed with a formal modification request and consequently implement the required Public Involvement processes when required

³ If the proposed modification does not match any modification listed in WAC 173 303 830 Appendix I then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology or down graded to ¹1 if appropriate

Hanford Facility RCRA Permit Modification Notification Form

Liquid Effluent Retention Facility and 200 Area Effluent Treatment Facility

Part III Chapter 4 and Attachment 34

Description of Modification.

Appendix 4B Table 4B 2

Table 4B	2 Drawings of Major Process Un	nts and Tan	iks at the Effluent Tr	eatment Facilit	y and Load In Station		
ETF Process Unit	Drawing Number		Outstanding ECN	ls	Drawing	Title	
Load In Facility	H 2 817974 Sh 1 Rev 12	None ECN-65	8555	P&ID - ETF Truck Load In Facility (Sheet 1)			
Load In Facility	H 2 817974 Sh 2 Rev 0	None			P&ID – ETF Truck I (Sheet 2)	oad In Facility	
Surge Tank	H 2 89337 Sh 1 Rev 13	ECN 644	4244		P&ID - Surge Tank	System (Sheet 1)	
UV/Oxidation	H 2 88976 Sh 1 Rev 910	ECN 64	7245 None		P&ID – UV Oxidize	Part 1 (Sheet 1)	
UV/Oxidation	H 2 89342 Sh 1 Rev 78	ECN 64	7245None		P&ID – UV Oxidize	Part 2 (Sheet 1)	
Reverse Osmosis	H 2 88980 Sh 1 Rev 10	NoneEC	N 662006		P&ID - 1st RO Stage	(Sheet 1)	
Reverse Osmosis	H 2 88982 Sh 1 Rev 12	NoneEC	N-662006		P&ID – 2nd RO Stag	ge (Sheet 1)	
IX/Polishers	H 2 88983 Sh 1 Rev 1112	ECN-642	2800 ECN 664323		P&ID - Polisher (Sh	eet 1)	
Verification Tanks	H 2 88985 Sh 1 Rev 9	None		P&ID - Verification (Sheet 1)	Tank System		
ETF Evaporator	H 2 89335 Sh 1 Rev 1416	ECN 65	1719 ECN 653080L 1583 ECN 664332 1P 01 9013 R0		P&ID – Evaporator (Sheet 1)		
Thin Film Dryer	H 2 88989 Sh 1 Rev 17 20	ECN 66 2	8765 6781L ECN 6567811 2046 ECN 664330 4331 HNF FMP 01		P&ID – Thin Film Dryer (Sheet 1)		
Transfer Piping from LERF to ETF	H 2 88768 Sh 1 Rev 1	None			Piping Plan/Profile 4 – 60M 002 M17 and 3 60M 001 M17 (Sheet 1)		
Transfer Piping from Load In Facility to ETF	H 2 817969 Sh 1 Rev 1	ECN W	291 015 1703 ECN-649104		Civil - ETF Truck Load In Facility Site Plan (Sheet 1)		
P&ID piping and instrumental STRUCT architectural/struct	ation d agram ural diagram						
Modification Class 123			Class 1	Class 11	Class 2	Class 3	
Please check one of the	Classes		х				
Relevant WAC 173 303	830 Appendix I Modification		A 1				
A General Permit Provi	dification from WAC 173 303 isions and informational changes	830, App	endix I citation				
Submitted by Co Opera	tor Reviewed by RL Program	n Office リレル				y Ecology	
	ate G H Sanders	Date	F Jamison	Date	LE Ruud	Date	

¹ Class 1 modifications requiring prior Agency approval

² This is only an advanced notification of an intended Class ¹1 2 or 3 modification this should be followed with a formal modification request and consequently implement the required Public Involvement processes when required

³ If the proposed modification does not match any modification listed in WAC 173 303 830 Appendix I then the proposed modification should automatically be given a Class 3 status. This status may be maintained by the Department of Ecology or down graded to 11 if appropriate

Hanford Facility RCRA Permit Modifications Part III Chapter 4 and Attachment 34 Liquid Effluent Retention Facility and 200 Area Effluent Treatment Facility

Replacement Sections

Index

Appendix 4A

Appendix 4B

1	APPENDIX 4A
2	
3	
4	DETAILED DRAWINGS FOR THE LIQUID EFFLUENT RETENTION FACILITY

- 1 Drawings of the containment systems at the LERF are summarized in Table 4A 1 Because the failure of
- 2 these containment systems at LERF could lead to the release of dangerous waste into the environment
- 3 Engineering Change Notices (ECNs) which affect these containment systems will be submitted to the
- 4 Washington State Department of Ecology as a Class 1 2 or 3 permit modification as required by
- 5 WAC 173 303 830

Table 4A 1 Liquid Effluent Retention Facility Containment System

LERF System	Drawing Number	Outstanding ECNs	Drawing Title
Bottom Liner	H 2 79590 Sh 1 Rev 3	None	Civil Plan Sections and Details Cell Basin Bottom Liner (Sheet 1)
Top Liner	H 2 79591 Sh 1 Rev 3	None	Civil Plan Sections and Details Cell Basin Bottom Liner (Sheet 1)
Catch Basın	H 2 79593 Sh 1 Rev 4	None	Civil Plan Section and Details Catch Basin (Sheet 1)

- 6 P&ID piping and instrumentation diagram
- 7 The drawings identified in Table 4A 2 illustrate the piping and instrumentation configuration within
- 8 LERF and of the transfer piping systems between the LERF and the 242 A Evaporator These drawings
- 9 are provided for general information and to demonstrate the adequacy of the design of the LERF as a
- 10 surface impoundment. An update to these drawings and drawings identified in Table 4A 1 will be
- 11 provided annually to the Washington State Department of Ecology

Table 4A 2 Liquid Effluent Retention Facility Piping and Instrumentation


LERF System	Drawing Number	Outstanding ECNs	Drawing Title
Transfer Piping to 242 A Evaporator	H 2 79604 Sh 1 Rev 3	ECN 648330	Piping Plot and Key Plans 242 A Evaporator Condensate Stream (Sheet 1)
LERF Piping and Instrumentation	H 2 88766 Sh 1 Rev 6	ECN 658555	P&ID LERF Basin and ETF Influent (Sheet 1)
LERF Piping and Instrumentation	H 2 88766 Sh 2 Rev 7	ECN 647209L ECN 658555 ECN 664355	P&ID LERF Basin and ETF Influent (Sheet 2)
LERF Piping and Instrumentation	H 2 88766 Sh 3 Rev 8	ECN 658555 ECN 664319	P&ID LERF Basin and ETF Influent (Sheet 3)
LERF Piping and Instrumentation	H 2 88766 Sh 4 Rev 9	ECN 658555 ECN 664320	P&ID LERF Basin and ETF Influent (Sheet 4)
	H 2 89351 Sh 1 Rev 7	HNF FMP 01 9507 R0	Piping & Instrumentation Diagram Legend


P&ID piping and instrumentation diagram


12

Part III Chapter 4 and Attachment 34 Liquid Effluent Retention Facility and 200 Area Effluent Treatment Facility

Appendix 4A Table 4A 1








Part III Chapter 4 and Attachment 34 Liquid Effluent Retention Facility and 200 Area Effluent Treatment Facility

Appendix 4 A Table 4A 2



S CPF 13 5 D 1 4 CPF PF 18 PF PF

ORIGINAL

ENGINEERING CHANGE NOTICE

ESSENTIAL 14 18

1 ECN

648330

Proj ECN

2 ECN Category (mark one)	3 Originator's Name Organ	nization MSIN and Telephone	No 4	USQ Required?	5 Date
Supplemental O	MA Przybylski FF	S S5-50 376-4017	lo	Yes 📵 No	10/13/2000
Direct Revision O	0.00.00		/= ====================================		
Change ECN O	6 Project Title/No /Work Or		7 Bldg/Sys./Fa	C NO	8 Approval Designator
Temporary O	Site/Utility Syst Privatization Pha		242 27 /602		
Standby O			242-AL/601 10 Related EC		T E
Supersedure O	Document Numbers Char sheet no and rev	iges by title pold (illiciates	ID NAMED CO.	110(0)	11 Valend LO 140
Cancei/Void O	See Block 13a Bel	ow	A/N	,	N/A
12a Modification Work	12b Work Package No	12c Modification Work Compl	eted	12d Restored	to Onginal Condition (Temp y ECNs only)
Yes (fill out Bik 12b)				l .	y ECINS ORIY)
O No (NA Biks 12b	EL-00-00209	Design Authority/Con Engine	er Signature #	N/A	rity/Cog Engineer Signature &
720 120)		Design Authority/Cog Engine Date	ter Oliginature at	Design Admor	Date
13a Description of Change		13b Design Baseline Docume	nt? 📵 Yes 🤇	O No	
1H-2-88766 sh1 re	v 3 revise as sh	own on page 5			
1					
H-2-88766 sh2 re	v 5 revise as sho	own on page 6			
, a consta		_			
H-2-88766 sh3 re	v 6 revise as sho	own on page 7			
H-2-88766 sh4 re	v 6 revise as she	an was - 0			
1-2-00/00 SH4 FE	A O TEATSE 92 2U(own ou bade a			
H-2-88766 sb5 re	v 0 Page 9 of th	s ECN supercedes S	h S Rev A	of H-2-88	766 in ite
	riate changes show	-	3 1.00 0	01 11 2 00	/00 IN 103
,	22200 0, 00 2	on page 5			
H-2-88815 sh5 re	v 2 revise as sho	own on page 10			'
		• •			
H-2-88818 sh2 re	v 0 add elementar	ry ladder rungs 38	thru 44 as	s shown on	page 11
H-2-88836 sh3 re	v 1 add terminat:	on wiring as shown	on page 1.	L	
200 Dren 2 Den 6					
SEE PAGE 3 FOR C	ONTINUATION OF BLO	OCK 13a			
A					
14a Justification (mark one)	14b Justification Details	ies all modification		T	202/200
Criteria Change	1	gs caused by W519 t		existing L	ERF/ETF
Design Improvement		do consen by wate	.16 1115		
Environmental O	•				
Facility Deactivation					
As-Found O					
Facilitate Const					
Const Error/Omission					
Design Error/Omission	<u> </u>				
15 Distribution (include name		E6_02 BX Ma	30 P4-30	R	ELEASE STAMP
NHC Files G3-: RJ Parazin S5-		E6-02 BA Messi: S5-09 JM Isdel	nger B4-39. 1 B4-39		
ML Alexander E6-				חר	T.312800
MA Friedrich G3-	-	G3-11 MJ Brown	56-72		<i>.</i>
MA Hag B4-		S5-09 * Advanc	1	DATE.	HANFORD
JL Henderson G3-		S6-72	There	STA JO	RELEASE 3 10 (18
JJ Huston B4-		s6-72	1		
MA Przybylski S5-	50 MM Towne	\$6-7 4			
1					_
					A 7900-013-1

1 ECN (use no from pg 1) Page 2 of __/8 648330 16 Design Verification Required 17 Cost Impact 18 Schedule Impact (days) **ENGINEERING** CONSTRUCTION Additional O \$ N/A Improvement O N/A Additional O Yes s N/A N/A O No Savings Savings Delay Change Impact Review Change impact Review Indicate the related documents (other than the engineering documents identified on Side 1) that will be affected by the change described in Block 13. Enter the affected document number in Block 20. Seismic/Stress Analysis Tank Calibration Manual SDD/DD Functional Design Criteria Stress/Design Report Health Physics Procedure Spares Multiple Unit Listing Operating Specification Interface Control Drawing П Test Procedures/Specification Calibration Procedure Criticality Specification Conceptual Design Report Installation Procedure Component Index (2) П П ASME Coded Item Maintenance Procedure **Equipment Spec** Human Factor Consideration **Engineering Procedure** Const Spec Computer Software Procurement Spec Operating Instruction \mathbf{X} X Electric Circuit Schedule Vendor Information Operating Procedure **ICRS Procedure** Operational Safety Requirement OM Manual Process Control Manual/Plan FSAR/SAR IEFD Drawing Safety Equipment List Cell Arrangement Drawing Process Flow Chart П Purchase Requisition **Essential Material Specification** Radiation Work Permit Tickler File **Environmental Impact Statement** Fac Proc Samp Schedule 11/A- 254 Ø **Environmental Report** Inspection Plan Inventory Adjustment Request X **Environmental Permit** Other Affected Documents (NOTE: Documents listed below will not be revised by this ECN.) Signatures below indicate that the signing organization has been notified of other affected documents listed below Document Number/Revision Document Number/Revision Document Number/Revision See Page 3 and 4 for Other Affected Documents. pop 604 003 , ARP-60M-001 , HUF 50 Lef ALA 002 POP 60M-001 21 Approvals Date Signature Design Agent Wa Tayylyloh 10 10 31 00 Design Authority REUIGW) PE 10-31-00 QA → Cog Mgi Safety QA Design Safety 0 3/00 Environ Environ Other Other DEPARTMENT OF ENERGY Signature or a Control Number that tracks the Approval Signature ADDITIONAL

A 7900-013 3 (10/97)

ECN 648330 ENGINEERING CHANGE NOTICE CONTINUATION SHEET Page 3 of 18 Date 10/13/2000

13a CONTINUATION H-2-79668 sh5 rev 6 add additional heat trace loads to elementary diagrams as shown on page 12 H-2-85323 shl rev 0 add panelboard A as shown on page 13 H-2-85323 sh3 rev 2 revise as shown on page 14 H-2-85323 sh4 rev 4 revise as shown on page 15 H-2-85323 sh5 rev 2 revise as shown on page 16 H-2-85323 sh8 rev 0 add new sheet 8 as shown on page 17 744 10/26 90 -Block 20: Other Affected Documents. H-2-79604 shl / Rev 3 / This drawing is modified by project W519 drawing H-2-830093 sh 1 H-13-000198 sh 1 / Rev 1 / & sh 2 / Rev 1 / These drawings are modified by project W519 drawing H-2-830093 (648330) for pipeline information

H-13-000198 sh 3 / Rev 1 / Add the following pipelines to drawing Also see this ECN

4 -WTP-001-M17 3 -WTP-002-M17 4 -80W-001-M17 4 -80W-002-M17

4 -80W-Q03-M17 4 -80W-004-M17 4 -80W-005-M17

H-2-79609 Rev 3 / This drawing is modified by project W519 drawings H-2-830095 sh 1 H-2-830096 sh 1 and H-2-830097 sh 1 The 3 -WTP-002-M17 line ties into the PC5000 line at N41804 7 W47070 at STA 1+357 1 (Zone D-5)

H-2-79610 Rev 3 / This drawing is modified by project W519 drawings H-2-830097 sh 1 and H-2-830098 sh 1

H-2-79613 Rev 4 / This drawing is modified by project W519 drawing H-2-830099 sh 1-3

H-2-79614 7 Rev 4 / This drawing is modified by project W519 drawing H-2-830100 sh 1 3

H-2-79615 Rev 4 / This drawing is modified by project W519 drawing H-2-830101 sh 1-3

H-2-88738 sh 1 / Rev 1 / & sh 2 / Rev 1 / Modified by project W519 See drawings H-2-830105 through H-2-830109 for changes

H-2-86810 sh 1 / Rev 1 / sh 2 / Rev 1 / sh 3 / Rev 1 / sh 4 / Rev 0 / Modified by project W519 See drawings H-2-830105 through H-2-830109 for changes Kan 1 (31)00

H-2-88813 sh 1 / Rev 1 / & sh 2 / Rev 1 / $\frac{1}{2}$ sh 2 / Rev 1 / $\frac{1}{2}$ sh 4 / Rev 0 / Modified by project W519 See drawings H-2-830105 through H-2-830109 for changes

H-2-88817 sh 1 / Rev 2 / Modified by project W519 See drawings H-2-830105 through H-2-830109 for changes

H-2-88818 sh 2 / Rev 0 / Modified by project W519 See drawings H-2-830105 through H-2-830109 for changes

ENGINEERING CHANGE NOTICE CONTINUATION SHEET

Page 4 of 18

ECN 648330 Date 10/13/2000



Block 20+ Other Affected Documents (Cont d).


H-2-88836 sh 3 / Rev 1 / Modified by project W519 See drawings H-2-830105 through H-2-830109 for changes


H-2-140321 Sh 1 / Rev 1 / Modified by project W519 See drawings H-2-830093 for project drawing listing

 $\mbox{H-}2-140323$ Sh 1 / Rev 1 / Modified by project W519 See drawings H-2-830093 for project drawing listing

H-2-140342 Sh 1 / Rev 2 / Modified by project W519 See drawings H-2-830093 for project drawing listing The J line ties into the H line at N42281 5 W47238 6 at station 1+444 5

H-2-140377 Sh 1 / Rev 1 / Modified by project W519 See drawings H-2-830093 for project drawing listing







FLUOR FEDERAL SERVICES


ENGINEERING CHANGE NOTICE SKETCH

2 88766 3 6 CL UHLMAN Mok Frieder 648330 77


ADD ITEMS IN CLOUDED AREA AS SHOWN









_





FLUOR FEDERAL SERVICES			ERVICES	ENGINEERING CHANGE NOTICE SKETCH			
ref Dw	SA	Rev	Prepared By	Chec ed		Fage	
1-2-79668	5	6	CL UHLMAN	Mak Frederik	648330	12	

ADD TO H 2 79688 SHEET 5)




HEAT TRACE ELEMENTARY DIAGRAM

BASIN 242AL-42


(PRE WIRE NU 8 RS W)

MODIFY H 2-79688 SHEET 5 ZONE A4)




HEAT TRACE ELEMENTARY DIAGRAM
BASIN 242AL 43

(PREFIX WIRE NUMBERS WITH MPZ43)



ADD TO (H 2-79668 SHEET 5)



HEAT TRACE ELEMENTARY DIAGRAM


BASIN 242AL-44


(PRE WI NU BE WI)


FLUOR FEDERAL SERVICES				ENGINEERING CI	HANGE NOTICE SKET	СН
Re Dwg	Sh	84	repared By	he ked By	CN No.	Page
H-2-85323	1	0	CL UHLMAN	Mark Funder	648330	13

ADD TO SHEET 1 OF H-2-85323 AS NOTED

ANELBOA D	ORME L PN 80	S EET O	VO GE	HASE	O ER SOURCE	O E L E DWG NO	PANELBO D LOCA IO	NO ES
W105 DP		2	80 /2	3	TRANS O E 300 (C633)	2 79663	2 2 AL	NEAR SERVICE RO D. ORTHWEST Q. ETENTO BASINS
P2 2	NA.	3	208Y/ 20	3	CB 2 2	2 9663	2 2 AL	T RETE TIO BISI 2 2AL 2 O ELEC RICAL R C
W 2 3	NA .		208Y/ D	3	CB 3 2	2 6 3	2 2 AL	ETE O BAS 2 2AL 3 O ELEC RICA RAC
PΣ	NA	5	2 8Y/ 20	3	CB 4 2	2 7 663	2 2 AL	E E B SI 2 2AL O ELEC RICA RAC
	NA .	6	208Y/ 20	3	P ELBOARD W105 DP CRC 18	H 2 9563	2 2 AL	LOCATED IN O E THO S C ITY (O 269)
LTG PUREL			20017120	1	AMELBOA D P1 CR UIT 26	27000		LOOMED IN STORAGE DIMINOLINGS ON EAST TIME
	NA		2 0/	ĺ	CB 3	2 96 3	2 2 AL	OCA ED IN INS ET BULDING 2 2AL O EAS AL







FLUOR FEDERAL SERVICES

ENGINEERING CHANGE NOTICE SKETCH

Re Deg H-2-85323 1 0 CL UHLMAN More Frederick 648330 [7]

ADD NEW SHEET 8 TO H-2-85323

IF NEW SHEET IS REQUIRED CHANGE SHEET NUMBER ON SHEET 1 TO READ 1 OF 8

FG SQUARE D				PANELBOARD FED FROM CB 3 1	LOCATION INS RUMENT B DO	G 2 2AL7	V(DLTAGE 20/2 OVAC PH 3 NE LINE DWG NO: 2 79663			MPE SO E	
PE (MODEL) NOO BR TY E BD	o 			EMA TYPE SURF CE MOU T FLUSH OUNT	A BREA E D LUGS O D TOP B BOTTOM EED		P BUS EUT D BUS	E) ANELBOARD GROUD FAUL RO ECTION OT ER			RATING (AIC)	
Ε S	SCHE É	I	5/		SYS CKT I I	00 CT	SYS NO	LOUD DECCED DESCRIPTION	Г	5/ P	SC E E	RFMA S
	NUMBER	PH	PH B	LOAD DESCRI TIO	NO NO 204		Ю	LOAD DESCRIPTION	РН	PH B	NU BE	NEW- 3
		8		AC		20A 2		EUH	300			
						<u>-</u>	1 [EUH		300		
			1	CH S	5 204	20A 6		RECEP ACLES	20			
			00	LC PS POWER	20A	20A 8		PLC 20		80		
		250		C POWER	9 204	20A 0		LC U LTY	80			
		1		S E	204	2 2		S E				
		1	1	SPAC	3			SPACE		1		
				ACE		6		S C				
	SU 1 TAL	3177	32	TO L ATTS F TOT TTS F	HASE 5377 HASE B 697			SUBTOTAL	2200	80		
				1	OTAL							

ATTACHMENT B AUTHORIZATION BASES REVIEW FORM

Part A

REFERENCE ITEM # E	CN 648330
--------------------	-----------

Proposed Change	Disco	verv
	(cucl	one)

APPROVAL DESIGNATOR E.T

TITLE Install Effluent Transfer Lines For Future Waste Treatment Plant (W519 Project)

DESCRIPTION

Effluent transfer lines will be installed to transport liquid waste from the Waste Treatment Plant (yet to be built) to LWPF Three transfer lines will be installed Two lines for the radioactive/hazardous liquid waste transporting to LERF basins One line for the non rad/non hazardous waste transporting to the TEDF system

Originator Signature Date


Part B


Does	the referenced item	(heck one)
Α	Increase risk from a hazard to the workers &/or public beyond that previously analyzed evaluated and documented in the Authorization Bases?	NO <u>x</u> Yes/Maybe
В	Reduce the reliability or effectiveness of features controls procedures or processes used to mitigate hazards?	NOX Yes/Maybe_
С	Introduce a hazard not evaluated in the Authorization Bases?	NOx Yes/Maybe_
D	Reflect new information on existing hazards beyond that currently documented in the Authorization Bases?	NOx Yes/Maybe_


DETERMINATION BASES Record complete justification and reference information below. Use Attachment 3 for continuations. Maintain with submittal package.

Since the new effluent transfer lines will be capped and isolated from waste sources installation of these lines does not result in a configuration outside of the existing authorization basis identified within the ASA (HNF-SD LEF-ASA-002) and the Liquid Effluent Retention Facility Hazard Categorization Report (WHC-SD-LEF-HC-001) The authorization basis documents will be reviewed as part of the effort to support the connection to the future Waste Treatment Plant. Additionally the waste to be introduced will be evaluated per WMH 331. Section 3.11. New Waste Stream Acceptance at LERF/ETF, which ensures the criteria set in LERF ASA are not exceeded as result of introducing the new feed.

Potential Impact Item Remains Open	No Impact ABR Closed	
0	[x]	Authorization Bases Evaluator Date
Ω	[x]	LWPF OSE Team Leader Date







CPR

ESSENTIAL

1 ECN 658555

ENGINEERING CHANGE NOTICE 18, 13A, 13B

Page 1 of 19

Proj. EÇN

2 EC\ Category (mark one)	3 Originator Name, Or and I clophone N	ganization, MSIN	4 USQ Require	ed?	5 Date
,	AF (rane 32910 S	6 72, 372 3152	[] Yes [x] N		04/25/01
Direct Rovision	6 Project Title/N /Wor		7 Bldg./Sys/Ta 2025E/		8 Approval Designator E T, R
Standby Supersedure	9 Do ument Numbers C (neludes sheet no and		10 Related EC	•	11 Related PO No
12 Modif ation Work [A] Yes (t fl ut Bik 12b)	12b Work P okag N EL 00 00651/M	12c Modification Work Comple		12d Restore	d to Original Condi or Standby ECN only) N/A
N (NA Blk. 12b, 12 12d)		Design Authority/C _L . I Signature & Dat		Desig	gn Authority/Cog Engineer S gnature & Date
13a D. ript on of Chang Block 9 Document Numb		Des gn Baseline Document? X Y	ex []N		
	5)61 11 2 88766 Sh 2 Rev 5	H 2 88766 Sh 3 Rev 6 H : tem for the 3 M 17 pipeline		_	
the Surge containment sur instrument air junction bo	np as well as lincs 3 60 x (AJB 1) and the response	IM 001 M17 and 4 60M-002 extive line a. well as providing imminating condensation in the	2 M17 The ch ig a flow path i	ange installs or the air pur	connections between the
		e requirements for Pipe Codes ng shall be in accordance with			

ASMF B311 and	d ∧ddenda	•				
14a Just licati n (ma	urkon)	<u>-</u>				
C terra Change	[x]	Design Improvement	[]	Environmental	1]	Fac lify Deactivation []
As F nd	11	Facilitat Const	[]	Const. httor/Omiss o	U	Design Error/Omiss on []

Area ETF Collection System Construction Specification (C 018H C6) Install inspect and test the new installation in accordance with

14b Justif t Detail

I iping change were needed to install an air purge sy tem to climinate spurious alarm, caused by condensation in the piping annulus

id name MSI	viand no fcopes)			
S6 72 (1)	Ll Huth	56 72 (1)	RW Szelmeczka	56 72 (1)
SC 72 (1)	R Mabry	S(71 (1)	MJ Warn	\$6.72 (1)
S6 72 (1)*	BA Messinger	B4 3) (1)*	RH Wight	S6 72 (1)
S6 71 (1)	CD Skogley	SC 72 (1)	WCC Planning	S6 71 (1)4
B4 3) (1)*	NJ Sullivan	SC 72 (1)	(* = Advance Co	py)
	\$6 72 (1) \$6 72 (1) \$6 72 (1)* \$6 71 (1)	S6 72 (1) L1 Huth S6 72 (1) R Mabry S6 72 (1)* BA Messinger S6 71 (1) CD Skogley	S6 72 (1) L1 Huth S6 72 (1) S6 72 (1) R Mabry S6 71 (1) S6 72 (1)* BA Messinger B4 3) (1)* S6 71 (1) CD Skogley S6 72 (1)	S6 72 (1) LI Huth S6 72 (1) RW Szelmeczka S6 72 (1) R Mabry S6 71 (1) MJ Warn S6 72 (1)* BA Messinger B4 30 (1)* RH Wight S6 71 (1) CD Skogley S6 72 (1) WCC Planning

DATE MAY 0 8 2001
HANFORD
STA. RELEASE
30

<u> </u>	NGINEERING CHA	NGE NOTICE	P ge 2 i 19	1 ECN 658555	<u>.</u>
16 Des gn Verit cation Req red	17 Cost Impact ————————————————————————————————————		ONS FRUCTION	18 % hed 1 Impact (day	-
[x] Yes	Addrts nal	[] \$ Additional	<u> </u>	Improvement	U
IJ N		[] \$ Saings	jj s	Delay	Ď
		ments (other than the engineering do)	
DD/DD	[NA]	Sessines/Stress Analysis	[NA]	Tank Calibration Manual	[NA]
rotal Dating Criteria	[NA]	Stream/Deagon Report	[NA]	Health Physics Procedure	[NA]
persons specification	[NA]	I etface Control Drawing	[NA]	Spares M. luple Us. Listing	[NA]
nticality Specification	[NA]	Cabbration Proc chire	[NA]	Tes Procedures/Specification	[NA]
weephal Danga Report	[NA]	installation Procedure	[NA]	Cor ponent index	[x]
mbs ent pec	[NA]	Maint senc Procedure	[NA]	ASME Coded Item	[NA]
est Npec	[NA]	Engineering Procedure	[NA]	H wan Fact Co understoon	[NA]
reci cinent Spec	[NA]	peratug Instruction	[NA]	C nyuter & ftware	[NA]
end. I formation	[x]	Operating Procedure	[x]	Electri Circuit Schedule	[NA]
M Mamual	[X] [NA]	Operational Safety Requirement	• •	ICRS Procedure	
SAR AR		IEFO Drawing	[NA]	Process (strol Manual/Plan	[NA]
afety Equipm or 11s	[NA]	(ll Arrangen Drawing	[NA]	Propess Flow Chart	[NA]
actuation Work Penns	[NA]	Pages that Material Specification	[NA]	Purchase Reginstron	[NA]
	(NA)	•	[NA]	Tuckler File	[NA]
even unental li spect States en	[NA]	Fac Pri Sarrii Schedule	[NA]	Heiser Pac	[NA]
•	[NA]	li paction Plan	[NA]		[]
virone sental Permit	[NA]	inven sy Adjustment Request	[NA]		
indicat that the signing Document No I OP	[NA]	inven sy Adjustment Request	[NA] his ECN) Signatures below d hel w /Rev sio 0-001 Rev 6	Document Number R	[]
virons sental Permit 10 (Other Affected D cum indical that the signing Document No I OP	[NA] ment. (NOTE Document, corganization has been notificumber/Revis on 3() 001 59A 001	listed helow will not be revised by the ed of other affected documents listed Document Number. IINF SD ETF OCD	[NA] his ECN) Signatures below d bel w /Rov 840 1-001 Rev 6 Rev 6	Document Number R	[]
virons sental Permit O Other Affected D cum indicat that the signing Document No I OP POP 5	[NA] ment (NOTE Document organization has been notification has been notification has been notification has been notification of the control	inven sy Adjustment Request insted helow will not be revised by the sed of other affected documents listed Document Numbers INF SD ETF OCD POP-60M 003	[NA] his ECN) Signatures below d hel w /Rov sio -001 Rev 6 Rev 6 Design Agent PE		[]
O Other Affected D comindical that the signing Document No I OP POP 5	[NA] ment (NOTE Document organization has been notification has been notification has been notification has been notification of the control	inven sy Adjustment Req uest listed helow will not be revised by the dot other affected documents listed Document Number. IINF SD ETF OCD POP-60M 003	[NA] his ECN) Signatures below d hel w /Rev sto 0-001 Rev 6 Rev 6 Design Agent PE QA		D te
O Other Affected D cum indical that the signing Document No I OP POP 5 I Appro 1 Design Authority AF C in E. Eng. OL. Mgr NI Sull van	[NA] ment (NOTE Document organization has been notification has been notification has been notification has been notification of the control	inven sy Adjustment Request insted helow will not be revised by the sed of other affected documents listed Document Numbers INF SD ETF OCD POP-60M 003	[NA] his ECN) Signatures below d hel w /Rev sto 0-001 Rev 6 Rev 6 Design Agent PE QA S 1 ty		[]
O Other Affected D cum indical that the signing Document No I OP POP 5 1 Appro 1 Design Authority AF C in L. Eng. Ob. Mgr NJ Sull van OA afety	[NA] ment. (NOTE Document, gorganization has been notification ha	inven sy Adjustment Req uest listed helow will not be revised by ti sed of other affected documents liste Document Number. IINF SD ETF OCD POP-60M 003 D 1 1/25/64	[NA] his ECN) Signatures below d hel w /Rev sto 0-001 Rev 6 Rev 6 Design Agent PE QA		D te
O (Other Affected D cum indicat that the signing Document No I OP POP 5 1 Appro 1 Design Authority AF C in England Mills and DA affety n RWS Imerick Other LL Lim Half	[NA] ment (NOTE Document organization has been notification has been notification has been notification has been notification organization has been notification has been notifi	inven sy Adjustment Request insted helow will not be revised by the sed of other affected documents listed Document Numbers INF SD ETF OCD POP-60M 003	[NA] his ECN) Signatures below d hel w /Rev sto 0-001 Rev 6 Rev 6 Design Agent PE QA S t ty Design		D te
O (Other Affected D cum indicat that the signing Document No I OP POP 5 1 Appro 1 Design Authority AF C in England Mills and DA affety n RWS Imerick Other LL Lim Half	[NA] ment. (NOTE Document, gorganization has been notification ha	inven sy Adjustment Request insted helow will not be revised by the dot other affected documents listed Document Number. INF SD ETF OCD POP-60M 003	[NA] his ECN) Signatures below d hel w /Rev sto 0-001 Rev 6 Rev 6 Design Agent PE QA S i ty Design i.nviron		D te
O (Other Affected D cum indicat that the signing Document No I OP POP 5 1 Appro 1 Design Authority AFC 1 Eng. Op. Mgr N1 Sull van DA affety n RWS Imeezk Other LL Lem Hulh aftermal Design R 1 cw	[NA] ment (NOTE Document organization has been notification has been notification has been notification has been notification organization has been notification has been notifi	inven vy Adjustment Req uest listed helow will not be revised by ti ed of other affected documents liste Document Number. IINF SD ETF OCD POP-60M 003 D 1 1/25/66 1/-26-01	[NA] his ECN) Signatures below d hel w /Rev sto 0-001 Rev 6 Rev 6 Design Agent PE QA S i ty Design i.nviron		D te
O Other Affected D cum indical that the signing Document No I OP POP 5 I Appro 1 Design Authority AF C in L. Eng. Mgr NI Sull van DA infety In RW S Imerick Other LL Em Math at tormal Design R iew	[NA] ment (NOTE Document organization has been notification has been notification has been notification has been notification organization has been notification has been notifi	inven sy Adjustment Request insted helow will not be revised by the dot other affected documents listed Document Number. INF SD ETF OCD POP-60M 003	[NA] his ECN) Signatures below d hel w /Rev sto 0-001 Rev 6 Rev 6 Design Agent PE QA S i ty Design i.nviron	Signature	D to
Por Solution and Permit Order Affected Document Not and that the signing Document Not I OP POP Solution and Approx 1 Order on Authority AFC of the Logical May Approx 1 Order on RWS Innection and RWS Innection RWS Innection and Design R incomplete the RWS Innection and Design R incomplete RWS Innection RWS	[NA] ment (NOTE Document organization has been notification has been notification has been notification has been notification organization has been notification has been notifi	inven vy Adjustment Req uest listed helow will not be revised by ti ed of other affected documents liste Document Number. IINF SD ETF OCD POP-60M 003 D 1 1/25/66 1/-26-01	[NA] his ECN) Signatures below d hel w /Rev sto 0-001 Rev 6 Rev 6 Design Agent PE QA S i ty Design i.nviron Oth	Signature	D te
Por Son Authority AF C in Log. Mgr Ni Sull van JA Safety	[NA] ment (NOTE Document organization has been notification has been notification has been notification has been notification organization has been notification has been notifi	inven vy Adjustment Req uest listed helow will not be revised by ti ed of other affected documents liste Document Number. IINF SD ETF OCD POP-60M 003 D 1 1/25/66 1/-26-01	INA] his ECN) Signatures below d hel w /Rev sto -001 Rev 6 Rev 6 Design Agent PE QA S i ty Des gn i.nviron Oth DEPARTMENT OF E S gnature r Control	Signature	D to
O Other Affected D cum indicat that the signing Document No I OP POP 5 I Appro 1 Design Authority AFC in England Migran No Sull van DA safety In RWS Imerick Other LL Em Hulh automal Design R iew	[NA] ment (NOTE Document organization has been notification has been notification has been notification has been notification organization has been notification has been notifi	inven vy Adjustment Req uest insted helow will not he revised by the dot other affected documents listed Document Number. INF SD ETF OCD POP-60M 003 D1 1/25/66 1-26-01 8/14-01	INA] his ECN) Signatures below d hel w /Rev sto 0-001 Rev 6 Rev 6 Design Agent PE QA S t ty Des gn i.nviron Oth DEPARTMENT OF E S gnature r Control Approval Sign t c	Signature	D te
O Other Affected D cum indical that the signing Document No I OP POP 5 I Appro 1 Design Authority AF C in L. Eng. Mgr NI Sull van DA infety In RW S Imerick Other LL Em Math at tormal Design R iew	[NA] ment (NOTE Document organization has been notification has been notification has been notification has been notification organization has been notification has been notifi	inven vy Adjustment Req uest insted helow will not he revised by the dot other affected documents listed Document Number. INF SD ETF OCD POP-60M 003 D1 1/25/66 1-26-01 8/14-01	INA] his ECN) Signatures below d hel w /Rev sto 0-001 Rev 6 Rev 6 Design Agent PE QA S t ty Des gn i.nviron Oth DEPARTMENT OF E S gnature r Control Approval Sign t c	Signature	D te

ENGINEERING CHANGE NOTICE CONTINUATION SHEET

ECN 658555

Page 3 of 19

Dat 04/25/01

Block 13a (continued)

H 2-88766 SH 1 Zone E/F 1/2 Add text to Notes 3 4 & 9

H 2 88766 SH 2 Zone E 4 Add reference to Note 3 Remove blind flange from valve HV-42 15

H 2 88766 SH 3 Zone E 5 Add reference to Note 3 Remove blind flange from valve HV-43 2

H 2-88766 SH 3 Zone E-6 Add reference to Note 3 Remove blind flange from valve HV-43 13

H 2 88766 SH 3 Zone F 3 Add reference to Note 3 Remove cap & blind flange from valves HV-43 15 & 60M 12C

H 2 88766 SH 4 Zone B 1/2 Add detail with reference to Note 4

H 2 88766 SH 4 Zone D 2 Add material break & connections associated with Zone B 1/2 detail with reference to Note 3 associated with valves 60M 14E & 59A-018

H 2 88766 SH 4 Zone F 2 Add material break & connections associated with Zone B 1/2 detail with reference to Note 3 associated with valve 60M 14D

H 2 817974 SH 1 Zone B 2 Change valve 59A 016 to normally closed & add 3/4 SS tubing vent line


H 2 817974 SH 1 Zone B/C 4 Change valves 59A-013 & 59A-014 to normally closed


H 2 817974 SH 1 Zone B/C 6 Change valve 59A 011 to normally closed


Bolting for flanged joints shall be in accordance with Pipe Code M 17 requirements identified in the 200 Area ETF Collection System Construction Specification (C 018H C6)


Fibercast Company one of the manufacturers of the M 17 piping has identified the maximum allowable air pressure in the piping annulus is 15 psig and recommends 5 psig be utilized for the air purge. While no shielding is recommended for exposed piping with \leq 15 psig air pressure as there is not enough energy contained to present a safety hazard to personnel, the existing insulation will provide impact protection against external forces and restraint in the event of a bonded fitting failure. This information is per telephone conversations with Nathan Culberson and Craig Moore of the Fibercast Company. Ameron, the other manufacturer of M 17 piping concurred with the Fibercast Company recommendations per a telephone conversation with Hector Mercado.


	Hanford NEPA Screening Form					
	F NEPA requirements c IINL PR() 452 Answer q estions YES NO and list NUMBER if pp1 abi					
W k Itom Tal Annui	lus Air Purge					
Wrk Pakag Numbr	EL [00] 00651 / M					
Proj tD pt. (ple	as lmr tto 6 lines)					
(AJB-1) and and talk to	nstalls connections between the instrument air junction box underground piping as well as providing a flow path for the escape to atmosphere in each of the respective lines for of eliminating condensation in the piping annulus					
A	Integral ei ements					
CYFN	Will wirk threaten to late en ronmental law regulations perm to r fety requirements?					
CYEN	Will wirk nv i construction/ pansio if waste treatment, to rage, d. p. I facilities?					
C Yes © N	Will hazard us hata ces b disturb d all wing uncontrolled/inperm tied relesses					
В	ECOLOGICAL RESOURCES					
CYCHEN	Will wirk aft of Witla da/Aq afers/ALE Reserve'					
C Yes 6 N	Will wirk ocu within 1/4 m l f C lumbia River (Hanford Reach N ti 1 M ument)?					
C, CN	Wilwidlef tu i habitat be dusturbed					
If II nawer are NO	If any nawer i YES get Ecol g cal Review NUMBER N/A then					
С	CULTURAI RESOURCES					
C Yes @ N	D the wirk require exteriors and constant of the state of					
CYEN	Does the wirk require helding or e pment modification to it ted historia tru tures?					
	ad all cond to us have been m t d the SWCN pples 3 It yan wer is YES C Itural Resources Review is					
req red Lust review NU	MBLR N/A NOTE If adverse impacts re dentified					
D	SITF WIDE CATECORICAL EXCLUSION (SWCX)					
C Yes @ N	In eviluate gip tent i en er nmental mp ta w W te Minimizati n considered? S [IN] PR() 4/2					
€Y CN	I the wirk covered by SWCX7					
If YES lust SWCX th t	pples B25 prantionm and g If NO 11					
E	SITE WIDE CY DOES NOT APPLY					
CYCN	Does the DOE pproved NEPA doc mentats pply f this to ty? If yes provide ppl bl d ment umber					
	DOE/EA N/A DOE/EIS N/A Other- N/A					
If CX EA prep ration	may h needed co tact FILES 376 4373					
Signature	SWCX is t led ntil any appli bl C it UEcol gical Resource Rav w ar eceived and att hed t this f					
Review	SWCX cann the used if the act is pirt. If never the property of the state of the s					
	It tato C g Eng Sched ler Planner) MAINTAIN A COPY IN THE APPLICABLE PROJECT FILE OR WORK PACKAGE					
Co urrençar	(Ma sgetten Complian Offic PHES) WORK PACKAGE A-6001 497 (11/00)					
































ENGINEERING CHANGE NOTICE CONTINUATION SHEET Page 18 of 19

1 ECN 658555

PARTIAL PARTS LIST

NOT FOR DRAWING INCORPORATION


11	PN	QTY	OESCRIPTION	MATL/REF
3 AR	1	AR	TUBING 1/4 # AND MISC FITTINGS	PIPE CODE 153T
4 AR CHANNEL 1 5/8 x 1 5/8 12 GA, CALV 5 AR CHANNEL 2 7/16 x 1 5/8 12 GA, CALV 6 -LINE 812 6 AR CHANNEL 3 1/4 x 1 5/8 12 GA, CALV 7 B-LINE 812 7 29 SPRING NUT 1/4-20 GALV 8 B-LINE NUT 1/4-20 GALV 8 B-LINE NUT 1/4-20 GALV 8 B-LINE NUT 1/4 x 3/4 LONG ZINC-PLATED 1/4 x 3/4 SHHMS 9 3 TUBING CLAMP ONE HOLE 1/2 # B-LINE 82084 10 44 TUBING CLAMP ONE HOLE 1/2 # B-LINE 82087 11 AR ALL THREADED ROD 1/4 -UNC ZINC-PLATED 11 AR ALL THREADED ROD 1/4 -UNC ZINC-PLATED 12 4 NUT HEX 1/4 -20UNC-28 ZINC-PLATED 13 4 WASHERS, SPRING LOCK, ZINC-PLATED 14 18 ANCHORS CONCRETE 1/4 (MIN EMB 1 1/8") 15 14 ANCHORS CONCRETE 3/8 (MIN EMB 1 1/8") 15 14 ANCHORS CONCRETE 3/8 (MIN EMB 1 1/8") 16 3 1 S TYPE PRO NORFARGAMENTHO NICKEL RUPTURE DISK BURST PRESSURE 7 PSIG @ 72 DEGREES F 0% MANUFACTURING RANGE IN 1 5 TYPE PRO RUPTURE DISK BURST PRESSURE 150 LB ANS 3168S CONSTRUCTION 17 3 PRESSURE REDUCINISING VALVE W/PRESSURE FISHER CONTROLS 675S/C7 1/4 NPT SST BODY 5 SCFM REQU 1/4 N	2	AR	TUBING 1/2 # AND MISC FITTINGS	PIPE CODE 153T
5 AR CHANNEL 2 7/16 x 1 5/8 12 GA GALV B-LINE 612 6 AR CHANNEL 3 1/4 x 1 5/8 12 GA GALV B-LINE 611 7 29 SPRING NUT 1/4-20 GALV B-LINE 611 8 32 SLOTTED HEX HEAD MACHINE SCREWS	3	AR	PIPE 1 1/2 SCHED 40S AND 3000# SWLDG FITTINGS	PIPE CODE 153
6 AR CHANNEL 3 1/4 x 1 5/8 12 GA, GALV 8 -LINE B11 7 29 SPRING NUT 1/4-20 GALV 8 -LINE, N224 8 32 SLOTTED HEX HEAD MACHINE SCREWS 1/4 x 3/4 LONG ZINC-PLATED 1/4 x 3/4 LONG ZINC-PLATED 9 5 TUBING CLAMP ONE HOLE 1/4 # 9 6-LINE B2084 10 44 TUBING CLAMP ONE HOLE 1/2 * 10 44 TUBING CLAMP ONE HOLE 1/2 * 11 AR ALL THREADED ROD 1/4 -UNC ZINC-PLATED 12 4 NUT HEX 1/4 -ZOUNC-28 ZINC-PLATED 13 4 WASHERS, SPRING LOCK, ZINC-PLATED 14 18 ANCHORS CONCRETE 3/8 (MIN EMB 1 1/8") 15 14 ANCHORS CONCRETE 3/8 (MIN EMB 1 5/8") 16 3 15 TYPE PLR NONFRAGMENTING NICKEL RUPTURE DISK BURST PRESSURE 7 PSIG * 17 BY PRESSURE 7 PSIG * 18 17 PRESSURE REDUCINGING VALVE W/PRESSURE INDICATING GAGE 100 PSIG - 5 PSIG AIR SERVICE 1/4 NPT SST 800Y 5 SCFW REQD CAPACITY PART #FS67SS-1/C7 18 17 FLOWMETER MULTI-TUBE PURGE MANIFOLD DESIGN 1/4 COMPRESSION FITTINGS ON INLETS & OUTLETS WITH (3) INLET VALVES (HOFFMAN INSTRUMENTATION SUPPLY INC (503)466-2200 DENNIS) 19 1 ENCLOSURE WALL-MOUNT 16 x20 x8 SST 20 3 PRESSURE CAUGE 1/4 MNPT 0-10psig PART #FS50-14 21 3 1-1/2 304SS RAISED FACE BLIND FLANGE DRILLED & TAPPED PIPE CODE 153 22 3 1-1/2 304SS RAISED FACE BLIND FLANGE DRILLED & TAPPED PIPE CODE 153 23 4 BULKHEAD REDUCING UNION 1/2 x1/4 SWAGELOK SS-810-61-4 25 3 PIPE CLAMP 1 1/2 B-LINE 82012	4	AR	CHANNEL 1 5/8 x 1 5/8 12 GA, CALV	B-LINE B22
7 29 SPRING NUT 1/4-20 CALV 8 32 SLOTTED HEX HEAD MACHINE SCREWS 1/4 x 3/4 LONG ZINC-PLATED 1/4 x 3/4 LONG ZINC-PLATED 9 3 TUBING CLAMP ONE HOLE 1/4 Ø 9	5	AR	CHANNEL 2 7/16 x 1 5/8 12 GA GALV	B-LINE B12
B 32 SLOTTED HEX HEAD MACHINE SCREWS 1/4 x 3/4 LONG ZINC-PLATED 1/4 x3/4 SHHMS 1/4 x3/4 SHMS 1/4 x3	6	AR	CHANNEL 3 1/4 x 1 5/8 12 GA, GALV	8-LINE 811
1/4 x 3/4 LONG ZINC-PLATED 1/4 x 3/4 SHHMS 9 3 TUBING CLAMP ONE HOLE 1/4 #	7	29	SPRING NUT 1/4-20 CALV	B-LINE, N224
10	8	32		
11	9	3	TUBING CLAMP ONE HOLE 1/4 #	8-LINE 82084
12	10	44	TUBING CLAMP ONE HOLE 1/2 #	B-LINE 82087
13 4 WASHERS, SPRING LOCK, ZINC-PLATED COML 14 18 ANCHORS CONCRETE 1/4 (MIN EMB 1 1/8") COML SST 15 14 ANCHORS CONCRETE 3/8 (MIN EMB 1 1/8") COML SST 15 14 ANCHORS CONCRETE 3/8 (MIN EMB 1 5/8") COML SST 16 3 15 TYPE PLR NONFRAGMENTING NICKEL RUPTURE DISK BURST PRESSURE 7 PSIG 6 72 DEGREES F 0% MANUFACTURING RANGE IN 15 TYPE PRDI RUPTURE DISK HOLDER 150 LB ANSI 316SS CONSTRUCTION G800)395-3475 LARRY SCOTT LARRY SCOTT 17 3 PRESSURE REDUCINGING VALVE W/PRESSURE INDICATING GAGE 100 PSIG - 5 PSIG AIR SERVICE FISHER CONTROLS 19 1 FLOWMETER MULTI-TUBE PURGE MANIFOLD DESIGN 1/4 BROOKS INSTRUMENT MODEL 1/1370CB3C3EL W/ (3) TUBES (425)487-9600 18 1 FLOWMETER MULTI-TUBE PURGE MANIFOLD DESIGN 1/4 BROOKS INSTRUMENT MODEL 1/1370CB3C3EL W/ (3) TUBES (503)466-2200 DENNIS) W/ (3) TUBES (503)466-2200 DENNIS) FISHER CONTROLS 19 1 ENCLOSURE WALL-MOUNT 16 ×20 ×8 SST HOFFMAN C-SD1620BSS 20 3 PRESSURE GAUGE 1/4 MNPT 0-10psig FISHER CONTROLS TYPE SO 21 3 1-1/2 304SS RAISED FACE BLIND FLANGE DRILLED & TAPPED PIPE CODE 153 22 3 1-1/2 SWAGELOK MALE NPT CONNECTOR PIPE CODE 153 23 4 BULKHEAD REDUCING UNION 1/2 ×1/4 SWAGELOK SS-B-TA-7-4 24 3 FEMALE ADAPTER 1/2 TUBE × 1/4 FNPT SWAGELOK SS-B-TA-7-4 25 3 PIPE CLAMP 1 1/2 B-LINE, B2012	11	AR	ALL THREADED ROD 1/4 -UNC ZINC-PLATED	B-UNE ATR-1/4"
14	12	4		COML
14	13	4	WASHERS, SPRING LOCK, ZINC-PLATED	COML
16 3 15 TYPE PLR NONFRAGMENTING NICKEL RUPTURE DISK BURST PRESSURE 7 PSIG © 72 DEGREES F 0% MANUFACTURING RANGE IN 15 TYPE PRDI RUPTURE DISK HOLDER 150 LB ANSI 316SS CONSTRUCTION 17 3 PRESSURE REDUCINGING VALVE W/PRESSURE INDICATING GACE 100 PSIG – 5 PSIG AIR SERVICE 1/4 NPT SST BODY 5 SCFM REQD CAPACITY PART #F567SS-1/C7 18 1 FLOWMETER MULTI-TUBE PURGE MANIFOLD DESIGN 1/4 COMPRESSION FITTINGS ON INLETS & OUTLETS WITH (3) INLET VALVES (HOFFMAN INSTRUMENTATION SUPPLY INC (503)466-2200 DENNIS) 19 1 ENCLOSURE WALL-MOUNT 16 ×20 ×8 SST PRESSURE GAUGE 1/4 MNPT 0-10psig 19 2 PRESSURE GAUGE 1/4 MNPT 0-10psig PART #F550-14 20 3 PRESSURE GAUGE 1/4 MNPT 0-10psig PART #F550-14 21 3 1-1/2 304SS RAISED FACE BLIND FLANGE DRILLED & TAPPED PORT 1/2 SWAGELOK MALE NPT CONNECTOR 22 3 1-1/2 304SS RAISED FACE FLANGE 150# SWLDG PIPE CODE 153 PIPE CODE 153 PRESSURE ADAPTER 1/2 TUBE × 1/4 FNPT SWAGELOK SS-8-TA-7-4 B-LINE, B2012	14	18		COML SST
BURST PRESSURE 7 PSIG	15	14	ANCHORS CONCRETE 3/8 (MIN EMB 1 5/8")	COML SST
INDICATING CAGE 100 PSIG - 5 PSIG AIR SERVICE 1/4 NPT SST BODY 5 SCFM REQD 1/4 NPT SST BODY 5 SCFM REQD 1/4 CAPACITY PART #FS67SS-1/C7 1/4 NPT SST BODY 5 SCFM REQD 1/4 CAPACITY PART #FS67SS-1/C7 1/4 NPT SST BODY 5 SCFM REQD 1/4 CAPACITY PART #FS67SS-1/C7 1/4 NPT COMPRESSION FITTINGS ON INLETS & OUTLETS WITH (3) NILET VALVES (HOFFMAN INSTRUMENTATION SUPPLY INC (503)466-2200 DENNIS) 1/4 NPT	16	3	BURST PRESSURE 7 PSIG 5 72 DEGREES F 0% MANUFACTURING RANGE IN 1 5 TYPE PROI RUPTURE	(800)395-3475
COMPRESSION FITTINGS ON INLETS & OUTLETS WITH (3) INLET VALVES (HOFFMAN INSTRUMENTATION SUPPLY INC (503)466-2200 DENNIS) 19 1 ENCLOSURE WALL-MOUNT 16 x20 x8 SST PRESSURE CAUGE 1/4 MNPT 0-10psig PART #FS50-14 20 3 PRESSURE CAUGE 1/4 MNPT 0-10psig PART #FS50-14 21 3 1-1/2 304SS RAISED FACE BLIND FLANGE DRILLED & TAPPED FOR 1/2 SWAGELOK MALE NPT CONNECTOR 22 3 1-1/2 304SS RAISED FACE FLANGE 150# SWLDG PIPE CODE 153 23 4 BULKHEAD REDUCING UNION 1/2 x1/4 24 3 FEMALE ADAPTER 1/2 TUBE x 1/4 FNPT SWAGELOK SS-8-TA-7-4 25 3 PIPE CLAMP 1 1/2 B-LINE, B2012	17	3	INDICATING GAGE 100 PSIG - 5 PSIG AIR SERVICE 1/4 NPT SST BODY 5 SCFM REQD	67SS/C7 PCE PACIFIC INC CRAIG JEANE
C-SD16208SS C-SD16208SS C-SD16208SS PRESSURE GAUGE 1/4 MNPT 0-10psig FISHER CONTROLS PART #FS50-14 TYPE 50 1-1/2 304SS RAISED FACE BLIND FLANGE DRILLED & TAPPED FOR 1/2 SWAGELOK MALE NPT CONNECTOR PIPE CODE 153 1-1/2 304SS RAISED FACE FLANGE 150# SWLDG PIPE CODE 153 BULKHEAD REDUCING UNION 1/2 x1/4 SWAGELOK SS-B10-61-4 TYPE 50 PIPE CODE 153 SWAGELOK SS-B10-61-4 SWAGELOK SS-B-TA-7-4 PIPE CLAMP 1 1/2 PIPE CLAMP 1 1/2 B-LINE, B2012	18	1	COMPRESSION FITTINGS ON INLETS & OUTLETS WITH (3) INLET VALVES (HOFFMAN INSTRUMENTATION SUPPLY INC	MODEL#1370CB3C3EL W/ (3) TUBES
PART #FS50-14 1-1/2 304SS RAISED FACE BLIND FLANGE DRILLED & TAPPED FOR 1/2 SWAGELOK MALE NPT CONNECTOR 22 3 1-1/2 304SS RAISED FACE FLANGE 150# SWLDG PIPE CODE 153 23 4 BULKHEAD REDUCING UNION 1/2 x1/4 SWAGELOK SS-B10-61-4 24 3 FEMALE ADAPTER 1/2 TUBE x 1/4 FNPT SWAGELOK SS-8-TA-7-4 25 3 PIPE CLAMP 1 1/2 8-LINE, B2012	19	1	ENCLOSURE WALL-MOUNT 16 x20 x8 SST	HOFFMAN C-SD1620BSS
FOR 1/2 SWAGELOK MALE NPT CONNECTOR 22 3 1-1/2 304SS RAISED FACE FLANGE 150# SWLDG PIPE CODE 153 23 4 BULKHEAD REDUCING UNION 1/2 x1/4 SWAGELOK SS-B10-61-4 24 3 FEMALE ADAPTER 1/2 TUBE x 1/4 FNPT SWAGELOK SS-8-TA-7-4 25 3 PIPE CLAMP 1 1/2 B-LINE, B2012	20	3	PRESSURE CAUGE 1/4 MNPT 0-10psig PART #FS50-14	
23 4 BULKHEAD REDUCING UNION 1/2 x1/4 SWAGELOK SS-B10-61-4 24 3 FEMALE ADAPTER 1/2 TUBE x 1/4 FNPT SWAGELOK SS-8-TA-7-4 25 3 PIPE CLAMP 1 1/2 B-LINE, B2012	21	3		PIPE CODE 153
24 3 FEMALE ADAPTER 1/2 TUBE x 1/4 FNPT SWAGELOK SS-8-TA-7-4 25 3 PIPE CLAMP 1 1/2 B-LINE, B2012	22	3	1-1/2 304SS RAISED FACE FLANGE 150# SWLDG	PIPE CODE 153
25 3 PIPE CLAMP 1 1/2 B-LINE, B2012	23	4	BULKHEAD REDUCING UNION 1/2 x1/4	SWAGELOK SS-810-61-4
	24	3	FEMALE ADAPTER 1/2 TUBE x 1/4 FNPT	SWAGELOK SS-8-TA-7-4
26 AR CASKET STUDS AND NUTS PIPE CODE 153	25	3	PIPE CLAMP 1 1/2	B-LINE, B2012
	26	AR	CASKET STUDS AND NUTS	PIPE CODE 153

1 ECN

NOT FOR DRAWING INCORPORATION

NOTES

- 1) FIELD RUN PIPE TUBING AND MISCELLANEOUS FITTINGS PER SPECIFICATION S-136H-001 PIPE CODE 153 AND 153T
- 2) ALL TUBE FITTINGS TO BE INSTALLED PER MANUFACTURER'S SPECIFICATIONS
- 3) FABRICATION AND TESTING SHALL BE IN ACCORDANCE WITH ASME B31 1
- 4) DIMENSIONS SHOWN ARE APPROXIMATE FIELD ADJUST AS NECESSARY
- 5) FIELD ROUTE AND SUPPORT TUBING IN APPROXIMATE LOCATIONS SHOWN ADJUSTMENTS MAY BE MADE DUE TO FIELD CONDITIONS
- 6) MAXIMUM SPACING OF SUPPORTS 5 -0
- 7) SUPPORT TUBING USING TYPICAL FIELD FABRICATED SUPPORTS OR WHERE CALLED OUT ON ECN AS FOLLOWS
 - TYPE 1 CHANNEL PN4 STRAPPED TO W6x15 WITH 1/4" Ø THREADED ROD PN11 NUTS PN12 AND WASHERS PN13
 - TYPE 2 CLAMP PN10 AND ANCHOR PN14
 - TYPE 3 CHANNEL PN4 ANCHORS PN15 MIN SPACING 5" CLAMP PN10 NUT PN7 AND SCREW PN8
 - TYPE 4 CLAMP PN10 AND SCREW PN8 DRILL AND TAP 3" TUBE STEEL
- 8) PCV-1D-001 PCV-1D-002 & PCV-1D-003 ARE TO BE SET TO MAINTAIN MAXIMUM DOWNSTREAM LINE PRESSURE AT LESS THAN OR EQUAL TO 5 PSIG
- 9) PCV-1D-004 PCV-1D-005 & PCV-1D-006 ARE TO BE SET TO RELIEVE AT 7 PSIG
- 10) FIELD LOCATE APPROX AS SHOWN MOUNT ENCLOSURE TO WALL WITH (4) 1/4" ø CONCRETE ANCHORS PN14
- 11) DRILL AND TAP BLIND FLANGE ON CENTER TO ACCEPT 1/2" SWAGELOK MALE CONNECTOR
- 12) REPLACE EXISTING 2 FIBERGLASS FLANGE WITH 2 STAINLESS STEEL FLANGE PIPE CODE 153S USE FLAT FACE BLIND FLANGE DRILLED THROUGH AND TAPPED TO ACCEPT 1/2 SWAGELOK MALE CONNECTOR GASKET SHALL BE 3/16" THK EPDM FULL FACE 6" OD x 3 1/2 ID TORQUE FASTENERS TO 25 FT/LBS



ENGINEERING CHANGE NOTICE ESSENTIAL


1 ECN 647209L

Proj.

2 ECN Category (mark one)					
(11mm P. Otto)	3 Originator's Name, Org and Telephone N	ranazat on, MSIN	4 USQ Require	sd?	5 Dat
01	LL Lin/32910/S6 72	/372 2759] Yes [X] N	0	December 1 1998
Supplemental Direct Revision [6 Project Title/No./Work Order N		ıc No	8 Approval Designator
Change ECN	Install Hose Adaptor	s on Basın 42 Sample	LERF		NA.
Temporary [] Standby	Ports/Charge # 1016		Lend	,00141	
Standby [Supersedure [10 Related EC	N No()	11 Related PO No
Cancel/V d			100 11111111111111111111111111111111111	()	
	H 2 887	66 Sh 2 Rev 4	N	Α	NA
12 M distation Work	12b Work Package N	12 Modification W rk Comp	lete		to Original Cond Standby ECN only)
[X] Yes (fill out Blk. 12b)	EL 98 00840/L			(Standby ECN only)
[] No (NA Blks, 1 b 12 12d)	l	Design Authority/Cog Signature & Da		Desig	n Authority/Cog. Engineer Signature & Date
					Signature at Date
13a. Descript in of Change	13b	Design Baselin Document? [X]	res []N		
		age 3 of this ECN The adap			
		ves 60M TEMP 1 and 60M		pe 2 gate val	ves or engineering
approved equal install l	1/2 pipe nipple down st	ream of the 2 x 1 1/2 reduce	cer		
		ain water at a maximum pres	sure of 100 psi,	g Use EPD	M gasket or engineering
approved equal Perform	in service leak test on the	e new installation.			
14a Just f ton (mark one)					
	Design Improvement	Environmental	[x]	Facility	Deactivation []
	Design Improvement		[x]	•	Deactivation []
Criteri Cha g []	- •	[] Environmental [] Const. Error/Omis		•	Deactivation [] Error/Omiss on []
Criteri Cha g [] As-i ound [] 14b Justili ation Detail	Fac Irtate Const	[] Const. Error/Omis	BS 002 []	Des gn	Error/Omiss on []
Criteri Cha g [] As-I ound [] 14b Justili ation Detail Temporary adaptors are no	Fac litate Const	[] Const. Error/Omn	ns on [] on LERF Basin	Des gn 42 cover Th	Error/Omiss on []
Criteri Cha g [] As-I ound [] 14b Justili ation Detail Temporary adaptors are no radioactivity which is above	Fac litate Const	[] Const. Error/Omis	ns on [] on LERF Basin	Des gn 42 cover Th	Error/Omiss on []
Criteri Cha g [] As-I ound [] 14b Justili ation Detail Temporary adaptors are no	Fac litate Const	[] Const. Error/Omn	ns on [] on LERF Basin	Des gn 42 cover Th	Error/Omiss on []
Criteri Cha g [] Aw-Lound [] 14b Justifi ation Detail Temporary adaptors are no radioactivity which is above	Fac litate Const	[] Const. Error/Omn	ns on [] on LERF Basin	Des gn 42 cover Th	Error/Omiss on []
Criteri Cha g [] As-i ound [] 14b Justifi ation Detail Temporary adaptors are no radioactivity which is above	Fac litate Const	[] Const. Error/Omn	ns on [] on LERF Basin	Des gn 42 cover Th	Error/Omiss on []
Criteri Cha g [] As-I ound [] 14b Justifi ation Detail Temporary adaptors are no radioactivity which is above float pump back to the base.	Fac intate Const eeded to expedite the pur- ve the limits for dischargi sin	[] Const. Error/Omn	ns on [] on LERF Basin	Des gn 42 cover Th he transfer of	Error/Omiss on [] is water contains the water using the basin
Criteri Cha g [] As-i ound [] 14b Justili ation Detail Temporary adaptors are no radioactivity which is above float pump back to the base of the ba	Fac litate Const eeded to expedite the purve the limits for dischargism MSIN and no f copies)	[] Const. Error/Omn	ns on [] on LERF Basin	Des gn 42 cover Th he transfer of	Error/Omiss on []
Criteri Cha g [] As-l ound [] 14b Justili ation Detail Temporary adaptors are no radioactivity which is above float pump back to the base of the ba	Fac litate Const eeded to expedite the purve the limits for dischargism MSIN and no feoples) 1 J M Petty	[] Const. Error/Omns nping of the standing water of ing to the ground The adapt S6-74 i	ns on [] on LERF Basin	Des gn 42 cover Th he transfer of	Error/Omiss on [] is water contains the water using the basin
Criteri Cha g [] Aw-I ound [] 14b Justifi ation Detail Temporary adaptors are no radioactivity which is above float pump back to the base of the ba	Fac litate Const eeded to expedite the purve the limits for dischargism MSIN and no f copies)	[] Const. Error/Omns Inping of the standing water of the ground The adapt S6-74 i S6-72 i	ns on [] on LERF Basin	Des gn 42 cover Th he transfer of	Error/Omass on [] is water contains the water using the basin ELEASE STAMP DEC 0 2 1998
Criteri Cha g [] Ax-1 ound [] 14b Justifi ation Detail Temporary adaptors are no radioactivity which is above float pump back to the base of the ba	Fac intate Const eeded to expedite the purve the limits for dischargisin MSIN and no f copies) 1 J M Petty 1 A K Yoakum	[] Const. Error/Omns Inping of the standing water of the ground The adapt S6-74 i S6-72 i	ns on [] on LERF Basin	Des gn 42 cover Th he transfer of	Error/Omass on [] is water contains the water using the basin ELEASE STAMP DEC 0 2 1998
Criteri Cha g [] Ax-1 ound [] 14b Justili ation Detail Temporary adaptors are no radioactivity which is above float pump back to the base float pump back to the back to the back float pump back to the back float pump back to the back float pump back t	receive the pure the limits for discharges in MSIN and no f copies) J M Petty A K. Yoakum M W Bowman B S Da ling A F Crane	Const. Error/Omes Inping of the standing water of the ground. The adaption of the ground is a second secon	ns on [] on LERF Basin	Des gn 42 cover Th he transfer of	Error/Omiss on [] is water contains the water using the basin
Criteri Cha g [] Ax-1 ound [] 14b Justin atron Detail Temporary adaptors are no radioactivity which is above float pump back to the base of the bas	eeded to expedite the purve the limits for dischargisin MSIN and no feepies) J M Petty A K Yoakum M Bowman B S Da ling	Const. Error/Omns Inping of the standing water of the ground. The adaption of the ground is a second secon	ns on [] on LERF Basin	Des gn 42 cover Th he transfer of	Error/Omass on [] is water contains the water using the basin ELEASE STAMP DEC 0 2 1998
Criteri Cha g [] As-1 ound [] 14h Justiti ation Detail Temporary adaptors are no radioactivity which is above float pump back to the base float pump back to the back to the back float pump back to the back float pump back to the back float pump back t	receive the pure the limits for discharges in MSIN and no f copies) J M Petty A K. Yoakum M W Bowman B S Da ling A F Crane	Const. Error/Omns Inping of the standing water of the ground. The adaption of the ground is a second secon	ns on [] on LERF Basin	Des gn 42 cover Th he transfer of	Error/Omass on [] is water contains the water using the basin ELEASE STAMP DEC 0 2 1998

				· 	
			II	1 ECN 647209	L
E	ngineering chai	NGE NOTICE	Page 2 of 3		
16 Design Verit cation Required	17 Cost Impact ————— ENGINEERI		CONSTRUCTION	18 Schodule Impact (day	-
[X] Yes	Addit onal	S Additional	[] \$	Impro emeni	D
) N		\$ Savings	j s	Del y	Ü
		ents (other than the engineering d 13 Enter the affected document)	
CONCO?	_ [NA]	Semmic/Stress Analysis	[NA]	Tank Calibration Manual	[NA]
Fanctional Design Criteria	[NA]	Stress/Design Report	[NA]	Health Physics Procedure	[NA]
Operating Spe Bostown	[NA]	Interface Control Drawing	[NA]	Spaces Multiple Unit Listing	[NA]
Concelity Specification	[NA]	Calibration Procedure	[NA]	Test Precedures/Specification	[NA]
Conceptual Design Report	[NA]	le tallation Procedure	[NA]	Component index	[NA]
Еушрина рес	[NA]	Magiterance Procedure	[NA]	ASME Coded Item	[NA]
Cri Spic	[NA]	Enganeering Procedur	[NA]	Human Factor Consideration	
Procurane Spec	* -	Operating justinetien	[NA]	Computer Software	[NA]
Vendor la formation	[NA]	Operating Procedure		Electric Carout Schedule	[NA]
OM Mannai	[NA]	Operational Safety Requirement	[NA]	ICRS Proceds	[NA]
FSAR/SAR	[NA]	IEFD Drawing	[NA]	Process Coutrol Marsual/Plan	[NA]
Safety Forupther Las	[NA]	Cell Arrangement Drawing	[X]	Process Flow Chart	[NA]
Radiotori Work Permit	[NA]	Essential Material Specification	[NA]	Purchase Requisition	[NA]
	[NA]		[NA]	•	[NA]
Enveroumental I appor Statemen	[NA]	Fac Proc Samp Sci dul	[NA]	Tickler File	[NA]
Environmental Report	[NA]	Inspertion Phu	[NA]		[]
Es vez nes tal Person t	[NA]	Inventory Adjustment Request	[NA]		
		sted below will not be revised by a			
Document N	mber/Revision	Document Number	r/Revision	Document N mher R	êvision
No other docum	ents affected by				
this ECN					
21 Approvals					
~· cd/Maxem	Signature	/ /Date	s	gnature	Date
Des gn Authority L. L. I	in while the	12/2/98	Design Agent - L. L. L		12/0/58
CgFb-ILLm	700 Z	1 <u>4/47</u> 58	PE	- •	
C b Mgr N J Sull van	m/Sull	/2 2- 76	QA		
QA	V ·		S faty		
Safety Environ			Des gn Environ.		
Other R J Huth	The HA	12298	Other		
(Internal Design Review)	Many	/ 			
Operations	/				
					
			DEPARTMENT OF E		
			S gnature or Control Approval Signature	Number that tracks the	
		 -	-		
			ADDITIONAL		
					

ENGINEERING CHANGE NOTICE CONTINUATION SHEET	Page 3 of 3	1 ECN (use no from pg 1)
		647209L



242 A EVA COND 2 2AL-42 ILJON CAL CA ACITY 8

DON'T SAY IT ---- Write It!

Date 11/8/00 From L L Lin

TO J L Cushman

CC N J Sullivan

Subject Temporary ECN 647209L Extension

Please extend temporary ECN 647209L Install Hose Adptor On Basin 42 Sample Ports for 180 days from the date of this DSI. This is due to the continued need for pumping standing water from the basin cover The permanent ECN which will close out this temporary ECN will be pursued once the priority is assigned

NOV 0 8 2000


ENGINEERING CHANGE NOTICE ESSENTIAL 1 SCH 6472094

2

2. ECN Category (mark eas)		3. Originator's Neste, Organ and Telephone No.	deather, MECK,	4. USQ Require	47	5. Dute	
- 4		LL Lin/32910/86-72/3	72-2759	DY XX	.	December 1 19	98
Supplemental Direct Revision	U O	6. Project TitleNe/Work C		7 Bldg/Bys/Fr		8. Asprovel Designator	
Change ECN	D)	Install Hose Adaptors	on Basin 42 Semple	LERF	150M	NA	
Temperary Standby	增以	Ports/Charge # 10169	7, COA AJ60	<u> </u>			
Supersedure	ă	9. Document Numbers Che (Inchese thest no. and re-		10. Related BC	N No(s).	11 Related PO No.	
Canuti/Void	ŧı	1	-, 6 Sh.2 Rev 4	l N		NA.	
12s. Meddication We		12b. Week Package	.12e. Medification Work Corne		44.4		
[X] Yes (fill out Bik.		No. EL-98-00840/L	JAN 13 199		tion (Timp. or	o Original Candi- Standay BCN only NA	5
12b) [] No (NABika 1.b, 12a, 12d)	•		Design Authority/Cog.	Baginaur to		Amberity/Cog. Ingineer Signature & Date	
13s. Description of C	hange	136. D	usign Bassiline Dommunt? [X] 1	res [] No	'		
approved equal. 1	Perform in	II be computible with rei -envice leak test on the	n water at a maximum pres pew anstallation.	eure of 100 per	g. Ueo RPDA	f gasket or engmeen	ig
approved equal. I	Perform in	-eervice leak test on the	new spetallation.	· · · · · · · · · · · · · · · · · · ·			eg .
approved equal. I 14a. Jestification (mer Criteria Change	Perform in	-eervace leak test on the	pew spetallation. Bevireamental	(×)	Pankky)	Descrivation ()	eg .
approved equal. I 14a. Jestification (mar Criteria Change An-Found	ecform in	-eervace leak test on the	new spetallation.	×	Pankky)		
approved equal. I 14a. Justification (mar Crisera Change As-Found 14b. Justification Den Temporary adapte	Perform in	Design Improvement Facilists Count ded to expedite the pump the immis for discharging	pew spetallation. Bevireamental	(X) nine () m LERF Besin	Pacifity: Design E	Descrivation [] Error/Canlesion []	
approved equal. I 14a. Instification (mar Crisera Change As-Yound 14b. Justification Determined to the content of the content	ck ens) [] alle ore are nee is above to the basi	Design Improvement Facilists Count ded to expedite the pump the immis for discharging	[] Bevirenmental [] Court. Error/Conf.	(X) nine () m LERF Besin	Pacifity I Design E 42 cover The the transfer of (Descrivation [] Error/Canlesion []	·
approved equal. I 14a. Instification (mar Crisera Change As-Yound 14b. Justification Determined to the content of the content	the man, Miles of the basis of	Design Improvement Facilists Const ded to expedite the pure the leasts for dischargin	[] Bevirenmental [] Court. Error/Conf.	(X) nine () m LERF Besin	Pacifity I Design E 42 cover The the transfer of (Descrivation [] Error/Ondesion [] Water contains the water using the base of	

				1 ECN 6472091	
E	NGINEERING CHA	NGE NOTICE	Pag 2 f 3		,
16 Design		> NA <		18 Schedul Impact (days)
Verification	ENGINEER		INSTRUCTION	>NA <	
Required [X] Yes	Addstronal f] \$ Additional	[] S	Improvement	n i
(1 No		Savings	i) \$	I -	ii l
		nents (other than the engineering door			
		(13 Enter the affected document no			
GOVOO	[NA]	Semmo/Stress Analysis	[NA]	Tank Calibration Manual	[NA]
Firmetic sal Design Criteria	[NA]	Stress/Design Report	[NA]	Health Physics Procedure	[NA]
Operating Specification	[NA]	Interface Coutrol Drawing	[NA]	Spaces Multiple Unit Listing	[NA]
Crescality Specification	[NA]	Calibration Procedure	[NA]	Test Procedures/Specification	[NA]
onceptual Datum Report	[NA]	Installation Procedure	[NA]	Component Index	[NA]
Едирана бре	[NA]	Manuferance Procedure	[NA]	ASME Coded Item	[NA]
Coms Spec	[NA]	Enganeering Procedure	[NA]	Human Faster Counderston	[NA]
Procuranei Spec	[NA]	Operating Justinotion	[NA]	Computer Software	[NA]
Vendor Information	[NA]	Operating Passedure	[NA]	Electric Curoust Schedule	[NA]
OM Manual	[NA]	Operatornal Safety Requirement	[NA]	ICRS Proceds	[NA]
FSAR/SAR	[NA]	IEPD Drawing	[XA]	Process Control Marsual/Plan	[NA]
Satety Equipment Last	[NA]	Cell Attangement Drawing	[NA]	Process Flow Chart	[NA]
Radistion Work Permit	[NA]	Essential Material Specification	[NA]	Perchase Requisition	[NA]
Envagorumental Impact tatemen		Fac Proc Samp Schedule		Tickler Fil	,
Envisore stal Report	[NA]	Inspection Plu	[NA]		[NA]
Environ neptel Permit	[NA]	Inventory Adjustment Request	[NA]		0
· CATTACK INSTITUTE C SOLUTION	[NA]	and account a submanion a submanion	[NA]		0
ndicate that the signing Document No		usted below will not be revised by the ed of other affected documents listed Document Number/l	below	Document N mber R	tS1ON
Coghgan LLL o CgMgan NJ Sull an QA Sfety		12/2/78 12/78 12/2/78		gnature	12/0/58
En ro Other R J Huth (Informal Design Review) Operations	* Huth	/2298	Other		
			DEPARTMENT OF E S gnature or Control I Approval Signature		
			ADDITIONAL		

ENGINEERING CHANGE NOTICE CONTINUATION SHEET	Page 3 of 3	1 ECN (use no from pg 1)
		647209L



DON'T SAY IT - Write It

Date 11/8/00

TO J L Cushman

From L L Lin

CC N J Sullivan

Subject Temporary ECN 647209L Extension

Please extend temporary ECN 647209L Install Hose Adptor On Basin 42 Sample Ports for 180 days from the date of this DSI. This is due to the continued need for pumping standing water from the basin cover. The permanent ECN which will close out this temporary ECN will be pursued once the priority is assigned.

NOV 0 8 2000



FSSENTIAL


ENGINEERING CHANGE NOTICE CPF 18, 134, + 13B Page 1 of 4 Proj ECN	LJJLITIAL	-¹ ^{€©N} 664355
CPF /8 / 134 / + /3B Page 1 of Page 1 of	ENGINEERING CHANGE NOTICE	
	CPF 18, 134, + 13B Page 1 of T	ECN ECN

2 ECN Category (mark one) 3	CN Category (mark one) 3 Originator's Name Organization MSIN and Telephone No				5 Date			
Supplemental K	KD JUNT/3M500/S6-72/372-2771			☐ Yes ⊠ No	9-12-01			
Direct Revision					9-12-01			
i cultuide from fm	Project Title/No Work Or		7 Bldg /Sys	/Fac. No	8 Approval Designator			
	NSTALL HOSE CONN		l]			
I Standby I I I—	BASIN 42 /101697		2427		T			
Supersedure 🗵	sheet no and rev)	nged by this ECN (includes	10 Related I	ECN No(s)	11 Related PO No			
Cancel/Void	SEE BLOCK 13a	l	ECN66	2042	N/A			
12a Modification Work 1	2b Work Package No	12c Modification Work Comp	eted	12d Restored	to Original Condition (Temp			
Yes (fill out Blk 12b)				or Stands	y ECNs only)			
☐ No (NA Biks 12b 12c, 12d)	T 00 00040	Decum AuthoritiCan English	61		N/A			
126, 120)	L-98-00840	Design Authority/Cog Engine Date	se. Oldularnie o	L Design Autho	rity/Cog Engineer Signature & Date			
13a Description of Change		13b Design Baseline Docume	int? 🛛 Yes	□ No				
THIS ECN SUPERSEDES	S ECN662042 DATE	D 8/21/01 IN FULL						
, · · · · · · · · · · · · · · · · · · ·	V 1							
	V 0							
H-2-88766 SH 2 RE	ν 5							
DESCRIPTION/LOCATION	רא ער המאמבים							
A) P&ID CHANGES AR		2						
l ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '		OWN ON PAGES 3 AND	A					
C) FABRICATION DETA			7					
	inde into chomic of	, 11100 4						
ADDENDA FOR CATE 2) FIELD VERIFY DIS	EGORY D FLUID : MENSIONS BEFORE							
(de fueldiertes (seed	44h fuctioning Poteile							
ا بحيرًا المسال	14b Justification Details							
· 1					}			
! '' — 1	ADAPTORS ARE NEE	DED TO EXPEDITE TH	E PUMPING	OF THE STAN	IDING WATER ON LERF			
Environmental		ASIONALLY THIS WAT						
	ABOVE THE LIMITS	FOR DISCHARGING TO	THE GRO	UND THE AC	DAPTORS WILL ALLOW			
	THE TRANSFER OF	THE WATER USING TH	HE BASIN	FLOAT PUMP	BACK TO THE BASIN			
Facilitate Const					Ì			
Const Error/Omission								
Design Error/Omission			4.7		THE STAMP			
15 Distribution (include name N KD JUNT \$6-72		GER B4-39 1	74/15		THE PERSON NAMED			
JM ISDELL B4-39		s6-72 1 *		SE	P-1970H			
CD SKOGLEY S6-71	_			DATE	7 - 2 - 201			
NJ SULLIVAN S6-72		S6-72 1		1 mie 1	HANFORD			
LL HUTH S6-72	2 1* HL ROACH	s6-72 1		STA.	RELEASE 10			
DL FLYCKT S6-71	1 1 KJ LUECK	S6-72 1	i	11 マカ				
advanced copy								


	 						1 ECN (us	e no fro	m pg 1)
	ENC	SINEERING	S CHANGE NO	TICE		Page 2 of4	ECN 664	355	
16 Design Verification Required	17 Cost Impac					IOTION	18 Schedu	ila Impa	t (days)
<u>.</u>		ENGINEERING			ONSTR				
⊠ Yes	Additional L	S NA	^	dditional [_]	\$ <u>NP</u>	<u> </u>	improvemė	_	NA .
□ No	Savings 🗆	5 <u>NA</u>		avings 🔲	\$ <u>NA</u>		Delay		NA
19 Change Impact Revi	ew Indicate the d in Block 13 En	related document	its (other than the eng document number in E	ineering docu lock 20	iments id	entified on Side 1) that	will be affect	ed by	
SDD/DD			Seismic/Stress An				ibration Man		
Functional Design C	rderia		Stress/Design Reg	•		Health Pi	hysics Proce	dure	
Operating Specifical			interface Control I			Spares N	fultiple Unit L	.isting	
Criticality Specificati			Calibration Proced	lure		Test Prod	cedures/Spe	cification	
Conceptual Design	Report		installation Proced	lure		Compone	ent Index		⊠
Equipment Spec			Maintenance Proc	edure		ASME C	oded item		
Const Spec		□	Engineering Proce	dure		Human F	actor Consid	eration	
Procurement Spec			Operating Instruct	ion		•	r Software		
Vendor Information			Operating Procedu		⊠		Circuit Schedi	ule	
OM Manual			Operational Safety	Requiremen		ICRS Pro			
FSAR/SAR		님	IEFD Drawing	_	Ø		Control Manu	JavPian	片.
Safety Equipment Li			Cell Arrangement	•			Flow Chart		
Radiation Work Pen		片	Essential Material	•		Purchase Tickler Fr	Requisition		
Environmental Impa Environmental Repo		H	Fac Proc Samp Inspection Plan	Schedule	H	HCKIST F1	lie		i i
Environmental Perm		Ħ	Inventory Adjustme	ent Request	ñ				
20 Other Affected Docu	ments (NOTE	Documents listed	below will not be revi		CN) Sig	natures below indicate	that the signi	ing	·
organization has bee	in notified of othe	r affected docum	ents listed below				ent Number/		
POP-60	it Number/Revisk	on N		imber/Revisio	an	NA NA	CUI MAIIMEIL	L/EAISIO11	ĺ
POP00	M-002	14	A			MA.			
21 Approvals									
, a.,	Signatur e		Date			Signature			ite ,
Design Authority M3	BROWN V43	nuv	1/1/1	Design Ag	ent <u>KD</u>	JUNT K. W. Ken	*	<u> 7/1.</u>	<u> 3/01</u>
Cog Eng MJ BROW	107 NI	7Lm	- 4. 1 ·	PE		· · · · · · · · · · · · · · · · · · ·			
Coa Mar KJ LUEC		14.14	Hiles	QA					
Cod Mgr KO LOEC	· <u>·</u>	MIC I							
QA				Safety					!
Safety	 _			Design					
Environ	· · · · · · · · · · · · · · · · · · ·			Environ					
Other HL ROAC	:H 191 Moas	h.	9/13/01	Other					
(PEER REVIEW)				<u> </u>					
							<u></u>		
						ENERGY			
				Signature Approval	or a Con Signature	troi Number that tracks	tne		
				ADDITION	VAL				
				····		····			
						_			<u> </u>
								-000 Od	3 3 (10/97)


ENGINEERING CHANGE NOTICE CONTINUATION SHEET 3 of 4 NO 664355

H-2-79592 SH 2 ADD FIELD NOTES AS SHOWN IN CLOUDED AREAS



H-2-88766 SH 2 ZONE C2 ADDITIONS ARE SHOWN IN CLOUDED AREAS





ESSENTIAL 1 ECN 664319


ENGINEERING CHANGE NOTICE

	ENGINEERING	CHANGE NOTICE	SEIA	IIAL	1 ECN 664319
CPF 18.	_	O OTANGE NOTICE	P	ge 1 of <u>3</u>	Proj
CPF 18,	134 , 13B				ECN
2 ECN Category (mark one)	3 Originatore Name Orga	nization MSIN and Telephone	No.	4 USQ Required?	Te Date
Supplemental	KD JUNT/3M500/S6-		NO	_	5 Date
Direct Revision	10 00017 383007 50	- 12/312-2111		☐ Yes No	7-23-01
Change ECN	6 Project Title/No Work O	rder No	7 Bidg /Sys	/Fac. No	8 Approval Designator
Temporary	INSTALL HOSE CON	—			
Standby	BASIN 43 /101697			AL43	T
Supersedure	9 Document Numbers Cha sheet no and rev)	inged by this ECN (includes	10 Related	ECN No(s)	11 Related PO No
Cancel/Void	SEE BLOCK 13a	1	N/A		N/A
12a Modification Work	12b Work Package No	12c Modification Work Compl	leted	12d Restored	to Original Condition (Temp
Yes (fill out Blk 12b)				or Standb	y ECNs only)
No (NA Biks 12b 12c 12d)	EL-98-00840	Design Authority/Cog Engine	eer Signature 8	B Design Autho	N/A enty/Cog Engineer Signature &
					Date
13a Description of Change		13b Design Baseline Docume	ent? 🖾 Yes	∐ No	
H-2-79592 SH 3 B	REV 0				
H-2-88766 SH 3 F	REV 6				
DESCRIPTION/LOCAT		n			
	ARE SHOWN ON PAGE S ADDITIONS ARE SH				
	TAILS ARE SHOWN O		3 OF H-2	-79592 REF	ECN-662042
			0 01	, , , , , , , , , , , , , , , , , , , ,	Den Vozvaz
FABRICATION NOTES					
1 ·		IPING IN ACCORDANCE	WITH AS	ME B31 3-199	3 EDITION AND
ADDENDA FOR CA	ATEGORY D FLUID DIMENSIONS BEFORE	SERVICE FARRICATION			
1 '	HOLTING MATERIAL		-LBS 1.00	BRICATE ALL.	THREADS AND W . H_F
J, MBOOD EMIGITAL	, bolling landaring	5 101202 10 140 11	HDS HO.	DICTORIL ADD	THREADS AND WEALT
[
14a Justification (mark one)	14b Justification Details				
Criteria Change					
Design Improvement		DED TO EXPEDITE THE	PUMPTNO	י אמדי פידאו	TOING WATER OF LEDE
Environmental	l I	CASIONALLY THIS WATE			
Facility Deactivation	! I	FOR DISCHARGING TO			DAPTORS WILL ALLOW
As Found	THE TRANSFER OF	THE WATER USING TH	HE BASIN	FLOAT PUMP	BACK TO THE BASIN
Facilitate Const	l ; i				
	; <u>†</u>				
Design Error/Omission 15 Distribution (include name	<u> </u>				ELEACE CTAMO
		GER B4-39 1			
	39 1 MJ BROWN	S6-72 1]	AUG	2T2001
	71 1 WCC PLANN		I	harr J	
1	72 1 MW BOWMAN	\$6-72 1		1 1	ANFORD
· ·	72 1 HL ROACH 71 1 KJ LUECK	S6-72 1 S6-72 1		STA. F	RELEASE) 10
advanced copy		00 12 I	ł	30	(25)41
				. ~ ~	NAME OF TAXABLE PARTY.

September Page 2 of 3 ECN 664319	_											1 ECN (use no fr	om pg 1)
15			E	NGINE	ERING	CHANGE N	OTICE				>	ECN 66	.4210	
Required BASINEERING CONSTRUCTION Yes Additional S.NA Additional S.NA Improvement NA								_		Page 2 o	<u>'</u>			
No Savings S NA Savings S NA Delay NA	16	Design Ventication Required	17 Cost im	•	INEERING			CC	NSTRU	JCTION		18 Sche	ause impa	act (days)
19 Change impact Review Indicate the related accuments often than the engineering documents identified on Sole 1) that will be effected by the change described in Block 30 Solido Sol		⊠ Yes	Additional	□ \$	NA		Additional		\$ <u>NA</u>	·		Improvem	ent 🔲	_NA
SDIDIOD SeismoStress Analysis Tank Calibration Manual Pructonal Design Orthoria Stress/Design Report Health Physical Procedure Operating Specification Interface Control Drawing Spere Multiple Unit Liking Conceptible Design Report Interface Control Drawing Spere Multiple Unit Liking Test Procedures/Specification Conceptible Design Report Interface Control Drawing Test Procedures/Specification Component Indian		□ No	Savings	□ <u>\$</u>	NA		Savings		\$ <u>NA</u>			Delay		_NA
SDIDIOD SeismoStress Analysis Tank Calibration Manual Pructonal Design Orthoria Stress/Design Report Health Physical Procedure Operating Specification Interface Control Drawing Spere Multiple Unit Liking Conceptible Design Report Interface Control Drawing Spere Multiple Unit Liking Test Procedures/Specification Conceptible Design Report Interface Control Drawing Test Procedures/Specification Component Indian	19	Change Impact Reviet the change described	w Indicate I	he relate Enter the	d documents	(other than the a	ngineering on Block 20	docum	ents ide	entified on	Side 1) that	will be affe	cted by	
Functionel Design Criteria Stress/Design Report Health Physics Procedure Operating Specification Candration Calibration Procedure Test Procedure Test Procedure Test Procedure Component Listing Candration Procedure Camponent Index Spares Multiple Link Listing Candration Procedure Camponent Index Spares Multiple Link Listing Candration Procedure Camponent Index Spares Multiple Link Listing Candration Camponent Index Candration Camponent Spec Operating Procedure Camponent Spec Operating Procedure Electric Cortical Schedule Candration Multiple Listing Candration Camponent Listing Candration Multiple Listing Candration Multiple Listing Candration Multiple Listing Candration Camponent Listing Candration Candration Camponent Listing Candration C														
Operating Specification Interface Control Drawing Speres Multiple Unit Listing Criticality Specification Calibration Procedure Test Procedures/Specification Component Index Statement Component School Component Scho			riteria	$\overline{\Box}$			-		$\bar{\Box}$					
Criticality Specification Calibration Procedure Test Procedures/Specification Conceptual Design Report Installation Procedure Component Index State Component Index Component In		•		$\overline{\Box}$		-	•					•		
Conceptual Design Report							•				•	•	-	n 🗆 :
Equipment Spec. Maintenance Procedure ASME Coded Item Const Spec. Engineering Procedure Human Factor Consideration Procurement Spec. Coparating Instruction Computer Software Condition Cond		• •				Installation Proc	edure				Compone	ent Index		×
Procurement Spec. Operating Instruction Computer Software Operating Instruction Computer Software Operating Procedure Electric Circuit Schedule Operating Procedure Electric Circuit Schedule Operating Stafety Requirement LICRS Procedure ICRS Procedure Operating Stafety Requirement ICRS Procedure ICRS			·			Maintenance Pr	ocedure				ASME C	oded Item		
Vendor Information		Const Spec.				Engineering Pro	cedure				Human F	actor Cons	deration	
OM Manual Operational Safety Requirement ICRS Procedure Process Control Manual/Plan Safety Equipment List Cell Arrangement Drawing Process Flow Chart Radiation Work Permit Essential Material Specification Purchase Requisition Purcha		Procurement Spec.				Operating Instru	uction				Compute	r Software		
FSANSAR IEPD Drawing Process Control Manual/Plan Radiation Work Permit Essential Material Specification Purchase Requisition Environmental Impact Statement Fac Proc Samp Schedule Tickler File Environmental Report Inspection Plan Environmental Remail Plant Inventory Adjustment Request Environmental Remail Plant Inventory Adjustment Request Environmental Remail Environmental Remail Environmental Remail Environmental Remail Plant Environmental Remail Environmental Remail Environmental Remail Environmental Remail Environmental Remail Environmental Remail Environ Env		Vendor Information				Operating Proce	edure		\boxtimes		Electric (Circuit Sche	dule	
Safety Equipment List Cell Arrangement Drawing Process Flow Chart Radiation Work Permit Essential Material Specification Purchase Requisation Purchase Requisation Purchase Requisation Revironmental Report Repetion Plan Provider File Provider Register Plan Purchase Requisation Revironmental Report Inventory Adjustment Request Purchase Requisation Revironmental Report Inventory Adjustment Request Purchase Requisation Purchase Requisat		OM Manual				Operational Saf	ety Require	ment	_		ICRS Pro	ocedure		
Radiation Work Permit		FSAR/SAR				IEFD Drawing			X		Process	Control Mar	nual/Pian	
Environmental Impact Statement		Safety Equipment Lis	st			Cell Arrangeme	ot Drawing				Process	Flow Chart		
Environmental Report Inspection Plan Inventory Adjustment Request Inventory Adjustment		Radiation Work Pern	nrt			Essential Mater	ial Specifica	tion			Purchase	Requisitio	n	닏
Environmental Permit Inventory Adjustment Request 20 Other Affected Documents (NOTE Documents Island below will not be revised by this ECN.) Signatures below indicate that the signing organization has been notified of other affected documents island below Document Number/Revision Document Number/Revision Document Number/Revision Document Number/Revision Document Number/Revision NA NA NA NA NA NA NA N		Environmental Impac	d Statement	닏		Fac Proc Sam	p Schedule		닏		Tickler Fi	ile		
20 Other Affected Documents (NOTE Documents listed below will not be revised by this ECN.) Signatures below indicate that the signing organization has been notified of other affected documents listed below in Document Number/Revision Document Number/Revision Document Number/Revision NA						•			片					- []
Document Number/Revision POP-60M-002 NA Document Number/Revision NA Date Date Signature Date Distance Date NB Signature Date NB Design									<u> </u>					
21 Approvals Signature Dete Design Authority LILLY L HUTH Cog Eng LILLY L HUTH A 15-0/ Cog Mgr MS COULDEN M Safety Environ Other HL ROACH 11 March DEPARTMENT OF ENERGY Signature Dotte Signature Date Signature Design Agent KD JUNT B 15-0/ PE Cog Mgr MS COULDEN M Safety Design Environ Other HL ROACH 11 March DEPARTMENT OF ENERGY Signature or a Control Number that tracks the Approval Signature ADDITIONAL	20	organization has been	nents (NO 11 n notified of c	ther affect	nents listed b decume	its iisted below	evised by th	IIS EUI	A) 2iği	ustries de	iow indicate	fuat tue sig	ning	
21 Approvals Design Authority LILLY L HUTH Self P(0) Cog Eng LILLY L HUTH Self PE Cog Mgr Self Lilly R HUTH Self PE Cog Mgr Self Lilly R HUTH Self R Self PE Cog Mgr Self Lilly R HUTH Self R Sel		Document	Number/Rev	/1\$1011		Document	Number/Re	VISION			Docum	ent Numbe	r/Revisio	п
Design Authority LILLY L HUTH A HALL STOCK Signature Date Design Agent KD JUNT A B 15-01 Cog Eng LILLY L HUTH A STOCK SIGNAGENT KD JUNT A B 15-01 Cog Mgr ST SULLEY K SIGNAGENT SIGNAG		POP-60	M-002		NA					МA				
Design Authority LILLY L HUTH A HALL STOCK Signature Date Design Agent KD JUNT A B 15-01 Cog Eng LILLY L HUTH A STOCK SIGNAGENT KD JUNT A B 15-01 Cog Mgr ST SULLEY K SIGNAGENT SIGNAG														
Design Authority LILLY L HUTH A HALL STOCK Signature Date Design Agent KD JUNT A B 15-01 Cog Eng LILLY L HUTH A STOCK SIGNAGENT KD JUNT A B 15-01 Cog Mgr ST SULLEY K SIGNAGENT SIGNAG														
Design Authority LILLY L HUTH SALE BIS-01 Cog Eng LILLY L HUTH SALE BIS-01 PE Cog Mgr KS LUCLUM SALE SALE SALE SALE SALE SALE SALE SALE	21	Approvals	Signature			Date				Signatui	re _			Date
Cog Eng LILLY L HUTH TO HAND & 15-0/ PE Cog Mgr WS LUCLY X ZIO1 QA Safety Design Environ Other HL ROACH 11 Mount 8-20 Ul Other (INDEPENDENT DESIGN REVIEW) DEPARTMENT OF ENERGY Signature or a Control Number that tracks the Approval Signature ADDITIONAL		Declar Authority T T	•	. .	#.K	R I ol	Deele		at KD .	-	HD Q	y	81	5-01
Cog Mgr K3 LUCL X 2101 QA Safety Design Environ Other HL ROACH MAN More 8-20 01 Other (INDEPENDENT DESIGN REVIEW) DEPARTMENT OF ENERGY Signature or a Control Number that tracks the Approval Signature ADDITIONAL							_	II Agei	10 100 0	, <u>VIII.</u>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
Safety Design Environ Other HL ROACH 111 Mosul. 8-20 01 Other (INDEPENDENT DESIGN REVIEW) DEPARTMENT OF ENERGY Signature or a Control Number that tracks the Approval Signature ADDITIONAL					-	<u> </u>	PE	-			'			
Environ Cher HL ROACH 141 (Maruh 8-20 0) Other (INDEPENDENT DESIGN REVIEW) DEPARTMENT OF ENERGY Signature or a Control Number that tracks the Approval Signature ADDITIONAL		Cog Mgr No CULL	A A	تالد	week.	X ZI OI	QA	_						 - ;
Environ Other HL ROACH 141 Moral (INDEPENDENT DESIGN REVIEW) DEPARTMENT OF ENERGY Signature or a Control Number that tracks the Approval Signature ADDITIONAL		QA					Safety	<i>,</i> _					·	
Environ Other HL ROACH 141 Moral (INDEPENDENT DESIGN REVIEW) DEPARTMENT OF ENERGY Signature or a Control Number that tracks the Approval Signature ADDITIONAL		Cafabi					Desig	n						
Other Ht ROACH 141 Museur 8-20 0 Other (INDEPENDENT DESIGN REVIEW) DEPARTMENT OF ENERGY Signature or a Control Number that tracks the Approval Signature ADDITIONAL		•												
DEPARTMENT OF ENERGY Signature or a Control Number that tracks the Approval Signature ADDITIONAL		Environ					Enviro	_ חכ						
DEPARTMENT OF ENERGY Signature or a Control Number that tracks the Approval Signature ADDITIONAL		Other HL ROAC	н 741	week	<u> </u>	8-20 0	Other	_						
Signature or a Control Number that tracks the Approval Signature ADDITIONAL		(INDEPENDENT DE	SIGN REVII	EW)										
Signature or a Control Number that tracks the Approval Signature ADDITIONAL	İ													
Signature or a Control Number that tracks the Approval Signature ADDITIONAL							DEDA		NT OF	ENERGY				
ADDITIONAL												the		
			·				Appro	val Si	nature					
	l													
A 7000.013.3 (10/97)							ADDI	TIONA	T					
A 7000.013.3 (10/97)														
A 7000.013.3 (10/07)														
A 7000.013.3 (10/07)														
													7000-04	13_3 (10/97)

1 ECN NO. 664319

H-2-88766 SH 3 ZONE C2 ADDITIONS ARE SHOWN IN CLOUDED AREAS



H-2-79592 SH 3 REVISE DETAIL 30 PLAN NOTE BY ADDING BASIN 43 TO BASIN 42

DETAIL 30 PLAN NOTE SHOWN. (REF ECN662042)

PLAN
SAMPLE PORT RISER #3 CENTER EAST SIDE OF BASIN 42
(PORT CAN BE USED TO CONNECT TO EXISTING BASIN FLOAT PUMP
AT FLEX HOSE USING A 1 1/2 TWIN KAM KAMLOCK COUPLER FEMALE NPT #633 D 0740)

S

ESSENTIAL

1 ECN 664320

	ENGINEERING	CHANGE NOTICE	OFI	I I I A L	004320
CPF 18, 131			Po	ige 1 of <u>3</u>	Proj ECN
2 ECN Category (mark one)	1 -	nization MSIN and Telephone	No (USQ Required?	5 Date
Supplemental 🗵	KD JUNT/3M500/S6-	-72/372-2771)(Yes 🛭 No	7-23-01
Direct Revision	6 Project Title/No Work O	edur No	7 Bidg /Sys	Fac No	8 Approval Designator
Change ECN	INSTALL HOSE CON		/ Diug /Oys	mac No	o Approvar Designator
Temporary	BASIN 44 /101697		242	NI.44	T
Standby	9 Document Numbers Cha sheet no and rev)		10 Related		11 Related PO No
Supersedure					
Canoel/Void	SEE BLOCK 13a		N/A		N/A
12a Modification Work	12b Work Package No	12c. Modification Work Comp	leted	12d Restored or Standb	to Onginal Condition (Temp by ECNs only)
Yes (fill out Blk 12b)	1				N/A
No (NA Biks 12b 12c, 12d)	EL-98-00840	Design Authority/Cog Engin Date	eer Signature t	Design Autho	rity/Cog Engineer Signature & Date
13a Description of Change		13b Design Baseline Docume	ent? 🛛 Yes	□ No	
B) PIPING DRAWING C) FABRICATION DE FABRICATION NOTES 1) INSTALL INSPE ADDENDA FOR CA 2) FIELD VERIFY I	ARE SHOWN ON PAGE ADDITIONS ARE SHOWN OF ETAILS A	OWN ON PAGES 3 N DETAIL 30 SHEET PIPING IN ACCORDANCE SERVICE FABRICATION		ME B31 3-199	ECN-662042 3 EDITION AND THREADS AND WASHERS
14a Justification (mark one)	14b Justification Details		······································	· · · · · · · · · · · · · · · · · · ·	
Criteria Change					
Design Improvement Environmental Facility Descrivation As-Found Facilitate Const Const Error/Omission Design Error/Omission	ADAPTORS ARE NEI BASIN COVER OCC ABOVE THE LIMITS THE TRANSFER OF	EDED TO EXPEDITE TH CASIONALLY THIS WAT 5 FOR DISCHARGING TO THE WATER USING T	ER MAY CO O THE GRO	NTAIN RADIOA UND THE AL FLOAT PUMP	DAPTORS WILL ALLOW BACK TO THE BASIN
15 Distribution (include name		CEP DA 30 1	ſ		ELEASE STAMP
	·72 1 BA MESSIN ·39 1 MJ BROWN	GER B4-39 1 S6-72 1	l	AHA	2.1 2001
	-71 1 WCC PLANN			700	71 (104)
	72 1 MW BOWMAN		ĺ	DATE.	HANFORD

S6-72 1

S6-72 1

advanced copy

S6~72 1

S6-71 1

HL ROACH

KJ LUECK

LL HUTH


Dr eracki

RELEASE

				<u> </u>				1 ECN (use no	from pg 1)
		E	NGINEERIN	G CHANGE NO	TICE		Page 2 of3	ECN 66432	0
16	Design Verification	17 Cost Im	inact.					18 Schedule I	mnact (days)
	Required	17 Ogat III.	ENGINEERIN	G	c	ONSTR	UCTION		
	⊠ Yes	Additional	s NA	^	dditional 🔲	\$ <u>NF</u>	<u>. </u>	_ Improvement [NA
	□ No	Savings	S NA	s	avings 🔲	\$ NA	1	_ Delay [NA
19	Change Impact Revis		he related docume	ents (other than the eng	-	nents id	entified on Side 1) th	at will be affected t	у
		l in Block 13	Enter the affected			_			_ [
	SDD/DD		님	Seismic/Stress An	•	님		alibration Manual	片
	Functional Design Ci	_	님	Stress/Design Rep				Physics Procedure	
i	Operating Specificati			Interface Control I		끔	·	Multiple Unit Listin	
	Criticality Specification		H	Calibration Proces				rocedures/Specific 	ation 🗆 🗸
	Conceptual Design F	кероп		Installation Proced Maintenance Proc			•	nent Index Coded Item	
	Equipment Spec		H	Engineering Proce	-	ä		Factor Considera	
	Const Spec Procurement Spec		H	Operating Instruct				ter Software	
	Vendor Information		H	Operating Proceds		⊠	- " •	Circuit Schedule	
	OM Manuai		Ħ	Operational Safety				Procedure	
	FSAR/SAR		Ħ	IEFD Drawing	risquitomont	⊠	,	s Control Manual/F	!
	Safety Equipment Lis	st	ā	Cell Arrangement	Drawing	□	*	s Flow Chart	
	Radiation Work Perm			Essential Material	-		Purchs	se Requisition	
	Environmental Impac			Fac Proc Samp	•		Tickier	File	
	Environmental Rapo			Inspection Plan					□ ↓
ļ	Environmental Perm	rt		Inventory Adjustm	ent Request				🗆
20	Other Affected Docur organization has bee	nents (NOT	E Documents list	ed below will not be nev	ised by this EC	N) Sig	natures below indica	e that the signing	
	-	Number/Rev			umber/Revision	1	Docu	ment Number/Rev	ision
	POP-60			NA			NA]
	101 00			•					
21	Approvals								
-	, 46, 21, 21, 21, 21, 21, 21, 21, 21, 21, 21	Signature	,	Date			Signature	O 4 -	Date
	Design Authority LI	LLY L HUTH	ve - 2 HH	8/14/	Design Age	nt <u>KD</u>	JUNT A. D.	funt E	1501
	Cog Eng LILLY L	нати 🛫	144	8/13/0/	PE _		,	·	
	KJ Luci	KK KK	duck	8/21/01	_				
	Cog Mgr NJ SULL		CAUCE.	- oferior	QA _				
	QA		·		Safety _				
	Safety				Design _				
	Environ				Environ _				
		242	Morch	8 20 01	Other				
ļ	Other HL ROAC				Olilei _				
i	(INDEPENDENT DE	SIGN REVI	EW)						
									 _
ł					DEPARTM				
[-	_			Signature of Approval S	r a Cor	ntrol Number that trace	ks the	
1					· privile a				
	***************************************				ADDITION	A1			
ļ					ADDITION	<u> </u>			,
			<u>.</u>	-					
								 _	
1	_ <u>-</u>								
								A-790	0-013-3 (10/97)

1 ECN NO 664320

ZONE C2 ADDITIONS ARE SHOWN IN CLOUDED AREAS H-2-88766 SH 4



H-2-79592 SH 3 REVISE DETAIL 30 PLAN NOTE BY ADDING BASIN 44 TO BASIN 42

DETAIL 30 PLAN NOTE SHOWN. (REF ECN662042)

SAMPLE PORT RISER #3 CENTER EAST SIDE OF BASIN 42 [PORT CAN BE USED TO CONNECT TO EXISTING BASIN FLOAT PUMP AT FLEX HOSE USING A 1 1/2 TWIN KAM KAMLOCK COUPLER PL<u>AN</u> FEMALE NPT #633 D 0740)

ESSENTIAL

	uired? USQ#	N/A				Lead Engineer:	The Second Secon	Authority:
	CX#				KH B	ergsman	KH Ber	rgsman
The second secon	io./Work Package No.: EL-01-0686	6. Area 200	E	7. Building 2025E	8. System No 60C, 6	.: 60D, 60J	Appro	val Designator. T
9. Related	FMPs/Changes: N/A	10. Incorpor	ates ECN/I N/A	CNs:	11. Contract	Mod. No.: V/A	12. Chan	ge Proposal No N/A
13. Lead Er	ngineering Discipline: Process	14. Affected N/A	Engineeri	ng Disciplines:		e Malley		hossi.
Section 2:	Nocument Index							
16. Action	Document		Revision	FM	P.Section	Revision	FMP	Release T
16. Action	Document H-2-89332, Sheet 1		Revision	FM.	P Section	Revision	Page	Work?
RWC				DWG-1	P Section	0	Page 15,16	Work? Yes
RWC	H-2-89332, Sheet 1	di siria.	11		P Section	0	15,16	Work? Yes Yes
RWC RWC	H-2-89332, Sheet 1 H-2-88977, Sheet 1,		11	DWG-1	P Section	0	Page 15,16	Yes Yes Yes
	H-2-89332, Sheet 1 H-2-88977, Sheet 1, H-2-88988, Sheet 1		11 12 20	DWG-1 DWG-2 DWG-3	P Section	0 0 0	15,16 17 18	Work? Yes Yes
RWC RWC	H-2-89332, Sheet 1 H-2-88977, Sheet 1, H-2-88988, Sheet 1		11 12 20	DWG-1 DWG-2 DWG-3	P Section	0 0 0	15,16 17 18	Yes Yes Yes
RWC RWC RWC	H-2-89332, Sheet 1 H-2-88977, Sheet 1, H-2-88988, Sheet 1 H-2-89351, Sheet 1		11 12 20 7	DWG-1 DWG-2 DWG-3 DWG-3	P Section	0 0 0 0	Page 15,16 17 18 18	Yes Yes Yes
RWC RWC RWC	H-2-89332, Sheet 1 H-2-88977, Sheet 1, H-2-88988, Sheet 1 H-2-89351, Sheet 1		11 12 20 7	DWG-1 DWG-2 DWG-3 DWG-3	P Section	0 0 0 0	Page 15,16 17 18 18	Yes Yes Yes
RWC RWC RWC	H-2-89332, Sheet 1 H-2-88977, Sheet 1, H-2-88988, Sheet 1 H-2-89351, Sheet 1		11 12 20 7	DWG-1 DWG-2 DWG-3 DWG-3	P Section	0 0 0 0	Page 15,16 17 18 18	Work? Yes Yes Yes Yes

HNF-FMP-_01__-9507__-R_0_ Page 2 of 30 FMP-CS (Facility Madification Package - Covershoot) (Block 17, 38, 22)* Section 4: Approval/Distribution (Nam., Signatur, Date) Approval Designator Raviews (Raf. HNF-PEO-233) Commercial Approvate 37. Project Engi 19. Design Engineer (if different from the DA and 28. Quality Assurance Load Engineer) N/A 38. Project Engineering Manager (when different 29. Safety 20. Lead Engineer from Engineering Management) KH Bergsman N/A N/A KH Bergsman 21. Engineering Mana 30. Environmental 39. Project Manager N/A NJ Sullivan N/A 1-11-02 31. Fire Protection 40. Operations Manager (OM) 22. Squad Check (when required; if more than one DA Vasquez discipline involved, sign below) N/A UL ISMOZ 32. Radiological Control 41. Ergonomics (when required by OM) ST Willet, DA for H-2-88988 1/11/02 N/A N/A 33. ALARA Review 42. Field Execution Manager / Startup Manager RJ Huth, DA for H-2-89351 N/A NA 34. Other 43. Other 25. Other N/A N/A N/A 26. Other 35. Other 44. Other N/A NA NA 36. Other 45. Other 27. Other N/A N/A 46. Modification work complete and field verified as complete for the construction activity (Block 22)* Design Authority Date 47. Distribution 48. Release: MSIN Name 86-72 (1)* KH Bergsman MW Bowman \$6-72 (1) DA Vasquez 86-72 (1) LL Huth \$6-72(1) DATE JM Isdell B4-39 (1)* RELEASE NJ Sullivan \$6-72(1) SW Willis \$6-51 (1)* CD Skogley 86-72 (1) RW Szelmeczka 86-72 (1) RJ Huth 86-72 (1) [] Not Approved/Archive 86-72 (1) ST Willet Design Authority/Date WCC Planning

(* = Advance Copy)

HNF-FMP-01 - 9507 -R 0 Page 30

FMP-1 (Eacility Modification Package - Engineering Request/Evaluation)

Date

11/20/01

2025E/131/60D

Need Date 12/31/01

Building/Room Number/System Number

Engineering Request (Block 1)*

Problem Statement/Proposed Modification

Add PDM sample valves at accessible locations

Requestor

FMP Title

KH Bergsman

The Peroxide Destruct Module reduces the concentration of peroxide, from that needed to destroy organics in Process Condensate feed at the Ultraviolet Light Oxidation units to a lower value tolerable by the Reverse Osmosis membranes. The inlet water to the PDM columns is routinely sampled and analyzed for peroxide concentration. There is an intermittent need to sample the liquid leaving each PDM column and the combined flow from both columns, to determine the performance of the PDM columns. Currently, the valves controlling the sample flows are ball valves located at a 7' to 8' elevation. The valve for the combined flow sample is behind other piping. The valve types and locations increase the risk of splashing and contamination, when personnel draw these samples. The proposed solution is to: replace the 3 screwed-end ball valves with screwed-end needle valves to provide adequate flow control, extend the tubing at these sampling locations to allow the sample to be taken safely, and add quick disconnect caps. Lead Engineer Assigned (Block 2)* Assigned Lead Engineer (Block 2)* Date 11/20/01 KH Bergsman Approve for Engineering Evaluation (Block 3)* Work Package Number **Estimated Evaluation Cost** EL-01-00686 \$100 Engineering Management If not approved, reason not approved: [x] Yes [] No 11/20/01

Alternatives Considered • Do Nothing • Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Engineering Evaluation (Block 4)* Problem Analysis See attached page of for details Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afer access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page of for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost S7000 Approve for Conceptual Phase (Block 6)*	internatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Perered Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide its access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. Total Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Parter Conceptual Phase (Block 6)*	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Perred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Cost Stood Total Estimated Cost Stood Sto	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install pall valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Perred Solution to proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Total Estimated Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost S2000 Parter Cost Account Charge Numer regions Manager	blem Analysis e attached page for details ematives Considered • Do Nothing • Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. **Gerred Solution** • proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a '4'' screwed in eedle valve to provide adequate flow control and to add two '4'' needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. e attached page for discussion of alternatives not chosen. **State and Schedule Estimate (Block 5)** **Imated Construction Cost (Materials and Labor) **Stimated Construction Cost (Materials and Labor) **Store Cost Account Charge Num **Date Cost Account Charge Num **Total Estimated Cost Cost Account Charge Num	blem Analysis e attached page of for details ematives Considered • Do Nothing • Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. Forest Solution • proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a '4'' screwed in needle valve to provide adequate flow control and to add two '4'' needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. e attached page of discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) • \$1000; L=\$4000 Sprove for Conceptual Phase (Block 6)* Frations Manager [] Ver [] No Date Cost Account Charge Numerations Manager	blem Analysis e attached page for details ematives Considered • Do Nothing • Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. Forest Solution • proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in eedle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wiinstalled. e attached page for discussion of alternatives not chosen. Dest and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) • S1000; L= \$4000 Sprove for Conceptual Phase (Block 6)* Forestions Manager [] Ver [] No Date Cost Account Charge Numerations Manager	blem Analysis e attached page for details ematives Considered • Do Nothing • Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. **Gerred Solution** • proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a '4'' screwed in eedle valve to provide adequate flow control and to add two '4'' needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. e attached page for discussion of alternatives not chosen. **State and Schedule Estimate (Block 5)** **Imated Construction Cost (Materials and Labor) **Stimated Construction Cost (Materials and Labor) **Store Cost Account Charge Num **Date Cost Account Charge Num **Total Estimated Cost Cost Account Charge Num	demanalysis the attached page of for details ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Jetreed Solution** The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stimated Construction Cost (Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num	Description (Block 4)* Descri	Demandering Evaluation (Block 4)* Description Analysis e attached page of for details Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a '4'' screwed in each valve to provide adequate flow control and to add two '4'' needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stown Manager Cost Account Charge Num Cost Account Charge Num	blem Analysis e attached page for details ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Jerred Solution To provide adequate flow control and to add two ½" needle valves on the existing piping to provide a access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. To attached page for discussion of alternatives not chosen. Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost S2000 Provices for Conceptual Phase (Block 6)* Total Estimated Cost S7000 Provices for Conceptual Phase (Block 6)* Total Estimated Cost S7000 Cost Account Charge Number of the page for the page of the page for the page fo	ernatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Iferred Solution To proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost Stood Prove for Conceptual Phase (Block 6)* Total Estimated Cost Stood Prove for Conceptual Phase (Block 6)* Total Cost Account Charge Nun 111230/FA20	Deferred Solution To proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed dinedle valve to the individual PDM column outlet flows. Deferred Solution To provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. To attached page 5 for discussion of alternatives not chosen. Total Estimated Construction Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Poprove for Conceptual Phase (Block 6)* Total Estimated Cost \$7000 Poprove for Conceptual Phase (Block 6)* Total Cost Account Charge Numerations Manager [] Yes [] No Date Cost Account Charge Numerations Manager Cost Account Charge Numerations Cost A	Deferred Solution Total Extinated Construction Cost (Materials and Labor) Total Estimated Cost Account Charge Num Page Atlandard Estimated Construction Cost (Materials and Labor) Sign Authority Total Cost Account Charge Num Page Atlandard Page Page At	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwered needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Approve for Conceptual Phase (Block 6)* Design Authority KH Bergsman KHELLALLER [X] Yes [] No Date 2Cost Account Charge Num 111230/FA20 Date 1120/601 Pages [A] No Date 2Cost Account Charge Num 111230/FA20	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide affe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Schedule Estimated Cost (Schedule Estimated Phase (Block 6)* Design Authority [1] Yes [1] No Date 2 Cost Account Charge Num 2 Cost Accoun	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Peferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwe and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide in stalled. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Perentions Manager [] Yes [] No Date Cost Account Charge Num Perentions Manager [] Yes [] No Date Cost Account Charge Num Perentions Manager [] Yes [] No Date Cost Account Charge Num Perentions Manager [] Yes [] No Date Ul20/01	Engineering Evaluation (Block 4)* Problem Analysis See attached page of details Alternatives Considered • Do Nothing • Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screend needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide adequate flow control and to add two 1/2" needle valves on the existing flow control and to add two 1/2" needle valves
Alternatives Considered • Do Nothing • Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Perferred Solution Schedule Estimate (Block 5)* Department Manager Date Cost Account Charge Number Cost Account Charge Cost Account Charge Cost Account Charge Cost Account Charge Cost Account Charg	thernatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Peferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost Total Estimated Cost S2000 Page Cost Account Charge Numbers of Cost Account Charge Numberstions Managery Cost Account Charge Numbers of Cost Account Charge Numberstions Managery	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Peferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed need to valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stomatory Cost Cost (Materials and Labor) Stomatory Cost Cost (Materials and Labor) Stomatory Cost (Materials	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Petered Solution To proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. To atlantate the page of the discussion of alternatives not chosen. Dost and Schedule Estimate (Block 5)* Total Estimated Cost S2000 Page Cost Account Charge Numerations Manager	centives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves on the existing piping to provide a caces to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 8 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of altern	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution or proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. e attached page 5 for discussion of alternatives not chosen. Dest and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Story for Conceptual Phase (Block 6)* Foreigness Manager La No. Date Cost Account Charge Num	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution or proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed in eedle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Stand Schedule Estimate (Block 5)* Estimated Engineering Cost Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Stand Schedule Estimate (Block 5)* Estimated Engineering Cost Stand Schedule Estimate (Block 5)*	centives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves on the existing piping to provide a caces to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 8 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of altern	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves on the existing piping to provide a needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Total Estimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stomath No. Date Cost Account Charge Num	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install description of alternatives not chosen. Install description cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stomator Cost (M	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves on the existing piping to provide an earlier valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install defend the sample of the combined PDM outlet flow, with a ½" screwed on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install defend the sample of the combined PDM outlet flow, with a ½" screwed on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost \$2000 Total Estimated Cost \$7000 Poprove for Conceptual Phase (Block 5)* Estimated Engineering Cost Total Estimated Cost \$7000	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution or proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. e attached page 5 for discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) = \$1000; L=\$4000 Perrove for Conceptual Phase (Block 6)* Foreign Manager Total Estimated Cost S7000 Cost Account Charge Numerations Manager	ernatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Iferred Solution To proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwed needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. To atlantice the attached page of for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost (School 1)*	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM outlet flow, with a ½" screwed a needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed and existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed and existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install page of the combined PDM outlet flow, with a ½" screwed and existing piping to provide for existing piping to provide access to the individual PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flow ½" needle valves o	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Gerred Solution** The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page for discussion of alternatives not chosen. See attached page for discussion of alternatives not chosen. See attached Construction Cost (Materials and Labor) See attached Page for Conceptual Phase (Block 5)* Total Estimated Cost Total Estimated Cost Stono Total Estimated Cost Total Cost Account Charge Num 111230/FA20 Date Cost Account Charge Num 111230/FA20	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Schedule Estimated Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Preference Solution [] Yes [] No Date 2	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide affe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Schedule Estimated Cost (Materials and Labor) Per ations Manager [] Yes [] No Date 2 Cost Account Charge Num 111230/FA20 Per ations Manager [X] Yes [] No Date Ul 20 for Date Ul 20 for Page 1	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wile installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Sistimated Construction Cost (Materials and Labor) Mes 11000; L= \$4000 Sport of Conceptual Phase (Block 6)* Design Authority [1] Yes [1] No Date 2Cost Account Charge Num 111230/FA20 Persitins Manager [2] Yes [1] No Date 1120/6/6/1	Problem Analysis See attached page for details Alternatives Considered • Do Nothing • Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screend needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provisafe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
Alternatives Considered • Do Nothing • Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Perferred Solution Schedule Estimate (Block 5)* Department Manager Date Cost Account Charge Number Cost Account Charge Cost Account Charge Cost Account Charge Cost Account Charge Cost Account Charg	thernatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Peferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost Total Estimated Cost S2000 Page Cost Account Charge Numbers of Cost Account Charge Numberstions Managery Cost Account Charge Numbers of Cost Account Charge Numberstions Managery	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Peferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed need to valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stomatory Cost Cost (Materials and Labor) Stomatory Cost Cost (Materials and Labor) Stomatory Cost (Materials	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Petered Solution To proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. To atlantate the page of the discussion of alternatives not chosen. Dost and Schedule Estimate (Block 5)* Total Estimated Cost S2000 Page Cost Account Charge Numerations Manager	centives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves on the existing piping to provide a caces to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 5 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 6 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 7 for discussion of alternatives not chosen. Install page 8 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of alternatives not chosen. Install page 9 for discussion of altern	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution or proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. e attached page 5 for discussion of alternatives not chosen. Dest and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Story for Conceptual Phase (Block 6)* Foreigness Manager La No. Date Cost Account Charge Num	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution or proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed in eedle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Stand Schedule Estimate (Block 5)* Estimated Engineering Cost Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Stand Schedule Estimate (Block 5)* Estimated Engineering Cost Stand Schedule Estimate (Block 5)*	centives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves on the existing piping to provide a needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 6)* Cost Account Charge Num Partieurs Manager La No. Date Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves on the existing piping to provide a needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Total Estimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stomath No. Date Cost Account Charge Num	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install description of alternatives not chosen. Install description cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stomator Cost (M	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves on the existing piping to provide an earlier valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install defend the sample of the combined PDM outlet flow, with a ½" screwed on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install defend the sample of the combined PDM outlet flow, with a ½" screwed on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost \$2000 Total Estimated Cost \$7000 Poprove for Conceptual Phase (Block 5)* Estimated Engineering Cost Total Estimated Cost \$7000	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution or proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. e attached page 5 for discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) = \$1000; L=\$4000 Perrove for Conceptual Phase (Block 6)* Foreign Manager Total Estimated Cost S7000 Cost Account Charge Numerations Manager	ernatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Iferred Solution To proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwed needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. To atlantice the attached page of for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost (School 1)*	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM outlet flow, with a ½" screwed a needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed and existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed and existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install page of the combined PDM outlet flow, with a ½" screwed and existing piping to provide for existing piping to provide access to the individual PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flow ½" needle valves o	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Gerred Solution** The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page for discussion of alternatives not chosen. See attached page for discussion of alternatives not chosen. See attached Construction Cost (Materials and Labor) See attached Page for Conceptual Phase (Block 5)* Total Estimated Cost Total Estimated Cost Stono Total Estimated Cost Total Cost Account Charge Num 111230/FA20 Date Cost Account Charge Num 111230/FA20	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Schedule Estimated Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Preference Solution [] Yes [] No Date 2	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide affe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Schedule Estimated Cost (Materials and Labor) Per ations Manager [] Yes [] No Date 2 Cost Account Charge Num 111230/FA20 Per ations Manager [X] Yes [] No Date Ul 20 for Date Ul 20 for Page 1	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wile installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Sistimated Construction Cost (Materials and Labor) Mes 11000; L= \$4000 Sport of Conceptual Phase (Block 6)* Design Authority [1] Yes [1] No Date 2Cost Account Charge Num 111230/FA20 Persitins Manager [2] Yes [1] No Date 1120/6/6/1	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screen needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provisafe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed end needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Alternatives Considered • Do Nothing • Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 \$7000 **Poperations Manager** **Date ** **Cost Account Charge Number Page Cost Accou	e Do Nothing • Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. **Perered Solution** **Referred Solution** **Install quick connects downstream of PDM column outlet sample valves. **Perered Solution** **Install quick connects downstream of PDM column outlet flow, with a ½" screwe and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. **Referred Solution** **Install quick connects downstream of PDM outlet flow, with a ½" screwe and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. **Referred Solution** **Referred	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Eferred Solution** Install quick connects downstream of PDM column outlet sample valves. **Eferred Solution** In proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed in needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost Total Estimated Cost Total Estimated Cost Total Cost Account Charge Number of Cost Account Charge Number Stations Manager Total Page Cost Account Charge Number Stations August Charge Number Stations Manager	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install publication outlet flow with a ½" screwed to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install publication outlet flow with a ½" screwed to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install publication outlet flow with a ½" screwed to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install publication outlet flow with a ½" screwed to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install publication outlet flow with a ½" screwed to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with a ½" screwed to provide fe access to the individual PDM column outlet flows. To provide fe access	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Forred Solution or proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. e attached page 5 for discussion of alternatives not chosen. Dost and Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) Solution Estimated Engineering Cost Total Estimated Cost Total Estimated Cost Solution Total Estimated Cost Total Estimated Cost Provove for Conceptual Phase (Block 6)* Foreions Manager Total Phase (Cost Account Charge Num	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution or proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. e attached page 5 for discussion of alternatives not chosen. Stating Schedule Estimate (Block 5)* Install Construction Cost (Materials and Labor) Stating Schedule Estimate (Block 5)* Stating Schedule Estimate (Block 6)* Stating Manager Cost Account Charge Num	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution or proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. e attached page 5 for discussion of alternatives not chosen. Stand Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) Schedule Estimated Cost	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Forred Solution or proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. e attached page 5 for discussion of alternatives not chosen. Dost and Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) Solution Estimated Engineering Cost Total Estimated Cost Total Estimated Cost Solution Total Estimated Cost Total Estimated Cost Provove for Conceptual Phase (Block 6)* Foreions Manager Total Phase (Cost Account Charge Num	ernatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Eferred Solution to proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Strong For Conceptual Phase (Block 6)* Estimated Engineering Cost Strong Cost Strong Power for Conceptual Phase (Block 6)* Estimated In No. Date Cost Account Charge Num	Permatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Perred Solution Reproposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Reattached page 5 for discussion of alternatives not chosen. Dost and Schedule Estimate (Block 5)* Limated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stories Cost Account Charge Num	Do Nothing Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Perred Solution** The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Cost with a disconnect caps with a standard Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost \$2000 Spood \$7000 **Prove for Conceptual Phase (Block 6)** Total Cost Account Charge Number of the province of the provential phase (Block 6)* Total Estimated Cost Cost Account Charge Number of the provential Phase (Block 6)* Total Estimated Cost Cost Account Charge Number of the provential Phase (Block 6)* Total Estimated Cost Cost Account Charge Number of the provential Phase (Block 6)* Total Estimated Cost Cost Account Charge Number of the provential Phase (Block 6)*	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Iderted Solution Total Estimate Cost Porove for Conceptual Phase (Block 6)* Porove for Conceptual Phase (Block 6)* Porove for Conceptual Phase (Block 6)* Parallel Down outlet flow Downstream of each needle valve, quick disconnect caps with the combined page of the combined PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with the combined page of the combined PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with the combined PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with the combined PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with the combined PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with the combined PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with the combined PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with the combined PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with the combined PDM column outlet flows. Total Estimated Cost \$2000 \$2000 \$7000 \$	ematives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution To proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost S2000 Poprove for Conceptual Phase (Block 6)* Total Estimated Cost S2000 Cost Account Charge Nun 111230/FA20	Pon't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Perred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Cost Account Charge Nun 111230/FA20	ternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **The proposed solution** The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Screwed on the combined PDM outlet flow, with a ½" screwed needle valve and the existing piping to provide fer attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Screwed on the combined PDM outlet flow, with a ½" screwed needle valve and the existing piping to provide fer attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Screwed on the combined PDM outlet flow, with a ½" screwed needle valve, quick disconnect caps with installed. Total Estimated Cost Screwed on the existing piping to provide for Conceptual Phase (Block 6)* Total Estimated Cost Screwed on the existing piping to provide for Conceptual Phase (Block 6)* Total Estimated Cost Screwed on the existing piping to provide for Conceptual Phase (Block 6)* Total Estimated Cost Screwed on the combined PDM outlet flow, with a ½" screwed needle valve, on the combined PDM outlet flow, with a ½" screwed needle valve, on the combined PDM outlet flow, with a ½" screwed needle valve, on the combined PDM outlet flow, with a ½" screwed needle valve, on the combined PDM outlet flow, with a ½" screwed needle valve, on the combined PDM outlet flow, with a ½" screwed needle valve, on the combined PDM outlet flow, with a ½" screwed needle valve, on the combined PDM outlet flow, with a ½" sc	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed-end needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Selimated Engineering Cost Total Estimated Cost S7000 Approve for Conceptual Phase (Block 6)* Description Manager [] Yes [] No Description Cost Account Charge Num 2	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwe find needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Special Authority Total Estimated Cost \$7000 Approve for Conceptual Phase (Block 6)* Design Authority Cost Account Charge Num 2 Cos	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwe and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Sperve for Conceptual Phase (Block 6)* Design Authority If Yes [] No Date Cost Account Charge Num 2 COST ACCOUNT (11230/FA20) Design Authority CH Bergsman KHELLIMEN Date [X] Yes [] No Date Da	Alternatives Considered Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screend needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provisafe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide that access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afea access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page ∫ for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M= \$1000; L=\$4000 Schedule Phase (Block 6)* Page Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)*	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Peterred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will einstalled. Downstream of each needle valve, quick disconnect caps will einstalled. Dost and Schedule Estimate (Block 5)* Stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Petersions Manager Cost Account Charge Number and Cost (Cost Account Charge Numberstains Manager)	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Total Estimated Cost \$2000 Prove for Conceptual Phase (Block 6)* Page Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Cost Cost Cost Cost Cost	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description of alternatives not chosen. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Solution Solution Total Estimated Cost \$7000 Deprove for Conceptual Phase (Block 6)* Descriptions Manager Cost Account Charge Number of the Cost Account Charge Number and Cost Account Charge Number and Cost (Cost Account Ch	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Install quick connects downstream of PDM column outlet sample valves. Description Install quick connects downstream of PDM column outlet sample valves. Description Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed in eedle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to t	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Patternatives not chosen. Dest and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) ■ \$1000; L=\$4000 Descriptions Manager Stimated Engineering Cost Total Estimated Cost \$7000 Cost Account Charge Num Poste Cost Account Charge Num Post	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Install quick connects downstream of PDM column outlet sample valves. Description Install quick connects downstream of PDM column outlet sample valves. Description Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Installed page Solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed deceded valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Solution Cost (Material	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ⅓" screwed de needle valve to provide adequate flow control and to add two ⅓" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Description Manager Total Account Charge Number of the provide of	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed a needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stomated Cost Account Charge Number of Cost Account Charg	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution To provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost S7000 Deprove for Conceptual Phase (Block 6)* Total Estimated Cost S7000 Cost Account Charge Numerations Manager	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed de needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Deprove for Conceptual Phase (Block 6)* [] Yes [] No Date 26 Note of Cost Account Charge Nun 111230/FA20	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed de needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Poste Solution Sol	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet flow, with a ¼" screwer and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwer and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Scienting Manager [] Yes [] No Date Cost Account Charge Num 2 CNDO 1 111230/FA20 Design Authority CH Bergsman KHBALLIMAN [X] Yes [] No Date (V) Yes [] No Date	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engin	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 Total Estimated Cost S7000 Approve for Conceptual Phase (Block 6)* Design Authority CH Bergsman KHBarman [X] Yes [] No Date Lil20/01 Date Lil20/01	 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screen and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed end needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afea access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page ∫ for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M= \$1000; L=\$4000 Schedule Phase (Block 6)* Page Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)*	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Peterred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will einstalled. Downstream of each needle valve, quick disconnect caps will einstalled. Dost and Schedule Estimate (Block 5)* Stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Petersions Manager Cost Account Charge Number and Cost (Cost Account Charge Numberstains Manager)	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Total Estimated Cost \$2000 Prove for Conceptual Phase (Block 6)* Page Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Cost Cost Cost Cost Cost	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description of alternatives not chosen. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Solution Solution Total Estimated Cost \$7000 Deprove for Conceptual Phase (Block 6)* Descriptions Manager Cost Account Charge Number of the Cost Account Charge Number and Cost Account Charge Number and Cost (Cost Account Ch	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Install quick connects downstream of PDM column outlet sample valves. Description Install quick connects downstream of PDM column outlet sample valves. Description Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed in eedle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to t	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Patternatives not chosen. Dest and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) ■ \$1000; L=\$4000 Descriptions Manager Laborated No. Deste Cost Account Charge Numerations Manager Laborated No. Deste Cost Account Charge Numerations Manager	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Post and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Storage Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Installed page Solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed deceded valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Solution Cost (Material	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ⅓" screwed de needle valve to provide adequate flow control and to add two ⅓" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Description Manager Total Account Charge Number of the position of the provide o	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed a needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stomated Cost Account Charge Number of Cost Account Charg	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution To provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost S7000 Deprove for Conceptual Phase (Block 6)* Total Estimated Cost S7000 Cost Account Charge Numerations Manager	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed de needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Deprove for Conceptual Phase (Block 6)* [] Yes [] No Date 26 Note of Cost Account Charge Nun 111230/FA20	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed de needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Poste Solution Sol	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet flow, with a ¼" screwer and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwerend needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Scott Conceptual Phase (Block 6)* Design Authority KH Bergsman KH Surman [X] Yes [] No Date Lilzofol Lilzofol Lilzofol Lilzofol	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engin	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 Total Estimated Cost S7000 Approve for Conceptual Phase (Block 6)* Design Authority CH Bergsman KHBarman [X] Yes [] No Date Lil20/01 Date Lil20/01	 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screend needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provisafe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide that access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afea access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page ∫ for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M= \$1000; L=\$4000 Schedule Phase (Block 6)* Page Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)*	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Peterred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will einstalled. Downstream of each needle valve, quick disconnect caps will einstalled. Dost and Schedule Estimate (Block 5)* Stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Petersions Manager Cost Account Charge Number and Cost (Cost Account Charge Numberstains Manager)	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Total Estimated Cost \$2000 Prove for Conceptual Phase (Block 6)* Page Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Cost Cost Cost Cost Cost	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description of alternatives not chosen. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Solution Solution Total Estimated Cost \$7000 Deprove for Conceptual Phase (Block 6)* Descriptions Manager Cost Account Charge Number of the Cost Account Charge Number and Cost Account Charge Number and Cost (Cost Account Ch	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Post and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Storage Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed in eedle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to t	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Patternatives not chosen. Dest and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) ■ \$1000; L=\$4000 Descriptions Manager Stimated Engineering Cost Total Estimated Cost \$7000 Cost Account Charge Num Paste Cost Account Charge Num Past	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Post and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Storage Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Installed page Solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed deceded valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Solution Cost (Material	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ⅓" screwed de needle valve to provide adequate flow control and to add two ⅓" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Description Manager Total Account Charge Number of the position of the provide o	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed a needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stomated Cost Account Charge Number of Cost Account Charg	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution To provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost S7000 Deprove for Conceptual Phase (Block 6)* Total Estimated Cost S7000 Cost Account Charge Numerations Manager Total Phase (Block 6)* Total Cost Account Charge Numerations Manager	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed de needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Deprove for Conceptual Phase (Block 6)* [] Yes [] No Date 26 Note of Cost Account Charge Nun 111230/FA20	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed de needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Poste Solution Sol	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet flow, with a ¼" screwer and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwer and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Scienting Manager [] Yes [] No Date Cost Account Charge Num 2 CNDO 1 111230/FA20 Design Authority CH Bergsman KHBALLIMAN [X] Yes [] No Date (V) Yes [] No Date	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engin	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 Total Estimated Cost S7000 Approve for Conceptual Phase (Block 6)* Design Authority CH Bergsman KHBarman [X] Yes [] No Date Lil20/01 Date Lil20/01	 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screen and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed end needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afea access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page ∫ for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M= \$1000; L=\$4000 Schedule Phase (Block 6)* Page Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)*	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Peterred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will einstalled. Downstream of each needle valve, quick disconnect caps will einstalled. Dost and Schedule Estimate (Block 5)* Stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Petersions Manager Cost Account Charge Number and Cost (Cost Account Charge Numberstains Manager)	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Total Estimated Cost \$2000 Prove for Conceptual Phase (Block 6)* Page Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Cost Cost Cost Cost Cost	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description of alternatives not chosen. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Solution Solution Total Estimated Cost \$7000 Deprove for Conceptual Phase (Block 6)* Descriptions Manager Cost Account Charge Number of the Cost Account Charge Number and Cost Account Charge Number and Cost (Cost Account Ch	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Post and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Storage Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed in eedle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to t	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Patternatives not chosen. Dest and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) ■ \$1000; L=\$4000 Descriptions Manager Stimated Engineering Cost Total Estimated Cost \$7000 Cost Account Charge Num Paste Cost Account Charge Num Past	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Post and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Storage Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Installed page Solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed deceded valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Solution Cost (Material	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ⅓" screwed de needle valve to provide adequate flow control and to add two ⅓" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Description Manager Total Account Charge Number of the position of the provide o	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed a needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stomated Cost Account Charge Number of Cost Account Charg	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution To provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost S7000 Deprove for Conceptual Phase (Block 6)* Total Estimated Cost S7000 Cost Account Charge Numerations Manager Total Phase (Block 6)* Total Cost Account Charge Numerations Manager	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed de needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Dot attached page for discussion of alternatives not chosen. Dest and Schedule Estimate (Block 5)* Total Estimated Cost \$2000 S7000 Deprove for Conceptual Phase (Block 6)* Total Estimated Cost \$2000 Cost Account Charge Nun 111230/FA20	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed de needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Poste Solution Sol	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet flow, with a ¼" screwer and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwerend needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Scott Conceptual Phase (Block 6)* Design Authority KH Bergsman KH Surman [X] Yes [] No Date Lilzofol Lilzofol Lilzofol Lilzofol	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engin	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 Total Estimated Cost S7000 Approve for Conceptual Phase (Block 6)* Design Authority CH Bergsman KHBarman [X] Yes [] No Date Lil20/01 Date Lil20/01	 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screend needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provisafe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed end needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afea access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page ∫ for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M= \$1000; L=\$4000 Schedule Phase (Block 6)* Page Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)*	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Peterred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will einstalled. Downstream of each needle valve, quick disconnect caps will einstalled. Dost and Schedule Estimate (Block 5)* Stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Petersions Manager Cost Account Charge Number and Cost (Cost Account Charge Numberstains Manager)	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Total Estimated Cost \$2000 Prove for Conceptual Phase (Block 6)* Page Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Cost Cost Cost Cost Cost	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description of alternatives not chosen. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Solution Solution Total Estimated Cost \$7000 Deprove for Conceptual Phase (Block 6)* Descriptions Manager Cost Account Charge Number of the Cost Account Charge Number and Cost Account Charge Number and Cost (Cost Account Ch	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Post and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Storage Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed in eedle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to t	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Patternatives not chosen. Dest and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) ■ \$1000; L=\$4000 Descriptions Manager Stimated Engineering Cost Total Estimated Cost \$7000 Cost Account Charge Num Paste Cost Account Charge Num Past	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Post and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Storage Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Installed page Solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed deceded valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Solution Cost (Material	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ⅓" screwed de needle valve to provide adequate flow control and to add two ⅓" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Description Manager Total Account Charge Number of the position of the provide o	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed a needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stomated Cost Account Charge Number of Cost Account Charg	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution To provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost S7000 Deprove for Conceptual Phase (Block 6)* Total Estimated Cost S7000 Cost Account Charge Numerations Manager Total Phase (Block 6)* Total Cost Account Charge Numerations Manager	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed de needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Dot attached page for discussion of alternatives not chosen. Dest and Schedule Estimate (Block 5)* Total Estimated Cost \$2000 S7000 Deprove for Conceptual Phase (Block 6)* Total Estimated Cost \$2000 Cost Account Charge Nun 111230/FA20	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed de needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Poste Solution Sol	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet flow, with a ¼" screwer and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwerend needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Scott Conceptual Phase (Block 6)* Design Authority KH Bergsman KH Surman [X] Yes [] No Date Lilzofol Lilzofol Lilzofol Lilzofol	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engin	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 Total Estimated Cost S7000 Approve for Conceptual Phase (Block 6)* Design Authority CH Bergsman KHBarman [X] Yes [] No Date Lil20/01 Date Lil20/01	 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screend needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provisafe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed end needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afea access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page ∫ for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M= \$1000; L=\$4000 Schedule Phase (Block 6)* Page Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)* Cost Account Charge Number 1000 Schedule Phase (Block 6)*	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Peterred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will einstalled. Downstream of each needle valve, quick disconnect caps will einstalled. Dost and Schedule Estimate (Block 5)* Stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Petersions Manager Cost Account Charge Number and Cost (Cost Account Charge Numberstains Manager)	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Total Estimated Cost \$2000 Prove for Conceptual Phase (Block 6)* Page Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Account Charge Number and Cost Cost Account Charge Number and Cost (Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Cost Cost Cost Cost Cost	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description of alternatives not chosen. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Solution Solution Total Estimated Cost \$7000 Deprove for Conceptual Phase (Block 6)* Descriptions Manager Cost Account Charge Number of the Cost Account Charge Number and Cost Account Charge Number and Cost (Cost Account Ch	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Post and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Storage Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet sample valves. Detered Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed in eedle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM column outlet flow ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Detered Solution Install quick connects downstream of PDM outlet flow, with a ½" screwed in each provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed access to t	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Patternatives not chosen. Dest and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) ■ \$1000; L=\$4000 Descriptions Manager Stimated Engineering Cost Total Estimated Cost \$7000 Cost Account Charge Num Paste Cost Account Charge Num Past	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Description Proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Post and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Storage Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num Cost Account Charge Num	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Installed page Solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed deceded valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Solution Cost (Material	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ⅓" screwed de needle valve to provide adequate flow control and to add two ⅓" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Description Manager Total Account Charge Number of the position of the provide o	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ½" screwed a needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stomated Cost Account Charge Number of Cost Account Charg	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution To provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Total Estimated Cost S7000 Deprove for Conceptual Phase (Block 6)* Total Estimated Cost S7000 Cost Account Charge Numerations Manager Total Phase (Block 6)* Total Cost Account Charge Numerations Manager	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed de needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Dot attached page for discussion of alternatives not chosen. Dest and Schedule Estimate (Block 5)* Total Estimated Cost \$2000 S7000 Deprove for Conceptual Phase (Block 6)* Total Estimated Cost \$2000 Cost Account Charge Nun 111230/FA20	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwed de needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Estimated Engineering Cost Solution Solution Cost (Materials and Labor) Poste Solution Sol	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet sample valves. ■ Install quick connects downstream of PDM column outlet flow, with a ¼" screwer and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. ■ Install quick connects downstream of PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flow	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwerend needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Scott Conceptual Phase (Block 6)* Design Authority KH Bergsman KH Surman [X] Yes [] No Date Lilzofol Lilzofol Lilzofol Lilzofol	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Construction Cost (Materials and Labor) Sciumated Engineering Cost Sciumated Engin	Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 Total Estimated Cost S7000 Approve for Conceptual Phase (Block 6)* Design Authority CH Bergsman KHBarman [X] Yes [] No Date Lil20/01 Date Lil20/01	 Do Nothing Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screend needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
 Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page ∫ for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Setimated Construction Cost (Materials and Labor)	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Petered Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed an needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will enstalled. The attached page ∫ for discussion of alternatives not chosen. Sost and Schedule Estimate (Block 5)* Stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Prove for Conceptual Phase (Block 6)* Petersions Manager Cost Account Charge Number of the stimate of the power of the power of the power of the province of the province of the power of the province of the power of the province of the p	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet sample valves. Deferred Solution Install quick connects downstream of PDM column outlet flow, with a ¼" screwer and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Description Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Prove for Conceptual Phase (Block 6)* Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Cost Cost Cost Cost Cost	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Deferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page ∫ for discussion of alternatives not chosen. Descriptions Manager Cost Account Charge Number and Cost Cost Cost Account Charge Number and Cost Cost Cost Cost Account Charge Number and Cost Cost Cost Cost Cost Cost Cost Cost	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Served Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Simated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Schedule Estimated Cost School Schedule Estimated Cost School	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install quick connects downstream of each needle valve, quick disconnect caps wi installed. Install place in the combined PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install place in the combined PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install place in the combined PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install place in the combined PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install place in the combined PDM outlet flow, with a ½" screwed needle valve. Install place in the combined PDM outlet flow, with a ½" screwed needle valve.	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Simated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Schedule Estimated Engineering Cost Schedule Estimated Cost School Schedule Estimated Cost School Schoo	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Served Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Total Estimated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Simated Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Schedule Estimated Cost School Schedule Estimated Cost School	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Eferred Solution** **Le proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. **Le attached page 5 for discussion of alternatives not chosen.** **Dost and Schedule Estimate (Block 5)** **Limited Construction Cost (Materials and Labor)	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Eferred Solution** The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$2000 Sprove for Conceptual Phase (Block 6)* **Estimated Engineering Cost **Sprove for Conceptual Phase (Block 6)** **Estimated Engineering Cost **Sprove for Conceptual Phase (Block 6)** **Estimated Engineering Cost **Sprove for Conceptual Phase (Block 6)** **Estimated Engineering Cost **Sprove for Conceptual Phase (Block 6)** **Estimated Engineering Cost **Sprove for Conceptual Phase (Block 6)** **Estimated Engineering Cost **Sprove for Conceptual Phase (Block 6)** **Estimated Engineering Cost	• Don't sample the combined PDM column outlet flow • Install ball valves in accessible locations for sampling • Install needle valves in accessible locations for sampling • Install quick connects downstream of PDM column outlet sample valves. **Eferred Solution** • proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. • attached page 5 for discussion of alternatives not chosen. **Stimated Construction Cost (Materials and Labor)** - \$1000; L=\$4000 **Stimated Construction Cost (Materials and Labor)** - \$2000 **Stimated Construction Cost (Materials and Labor)** - \$1000; L=\$4000 **Stimated Construction Cost (Materials and Labor)** - \$2000 - \$7000 **Prove for Conceptual Phase (Block 6)** - Cost Account Charge Numeral Cost (Materials and Cost (Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Gerred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Stand Schedule Estimate (Block 5)* The standed Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Total Estimated Cost \$2000 Sprove for Conceptual Phase (Block 6)* Total Estimated Cost Cost Account Charge Numerations Manager [1] Yes [1] No. Date Cost Account Charge Numerations Manager	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. Installed the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. Installed the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. Install pulse flow, with a ¼" screwed feedle valve on the existing piping to provide feedle valve, quick disconnect caps will installed. Install pulse flow, with a ¼" screwed needle valve on the existing piping to provide feedle valve, quick disconnect caps will installed. Install pulse flow, with a ¼" screwed needle valve, quick disconnect caps will install pulse feedle valve, quick disconnect caps will install pulse feedle valve, quick disconnect caps will install pulse flow feedle valve, quick disconnect caps will install pulse feedle valve, quick disconnect caps will install pulse feedle valve, quick disconnect caps will install pulse flow feedle valve, quick disconnect caps will needle valve, quick	■ Don't sample the combined PDM column outlet flow ■ Install ball valves in accessible locations for sampling ■ Install needle valves in accessible locations for sampling ■ Install quick connects downstream of PDM column outlet sample valves. **Referred Solution** ■ proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. **Referred Solution** ■ proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. **Referred Solution** **Referred Solut	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afee access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Approve for Conceptual Phase (Block 6)* Design Authority KH Bergsman KH Surman [X] Yes [] No Date Lilzofol Lilzofol Lilzofol Date Lilzofol Lilzofol	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Instituted Construction Cost (Materials and Labor) Setimated Engineering Cost Total Estimated Cost Setimated Cost Account Charge Num 2 Cost Account Charge Num	Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 S7000 Sperations Manager [] Yes [] No Date 26 NO 00 1111230/FA20 Date (X) Yes [] No (X) Yes [] No	 Don't sample the combined PDM column outlet flow Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screend needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
 Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page S for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Total Estimated Cost \$7000 Approve for Conceptual Phase (Block 6)* Descriptions Manager Date Cost Account Charge Number Date Cost Account Charge Number Date Cost Account Charge Number Cost Account Charge	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a %" screwe and needle valve to provide adequate flow control and to add two %" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will existalled. Install needle valves in accessible locations for sampling Install needle valves Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow %" needle valves on the existing piping to provide the access to the individual PDM column outlet flow %" needle valves on the existing piping to provide access to the individual PDM column outlet flow %" needle valves on the existing piping to provide access to the individual PDM column outlet flow %" needle valves on the existing piping to provide access to the individual PDM column outlet flow %" needle valves on the existing piping to provide access to the individual PDM column outlet flow %" needle valves on the existing piping to provide access to the individual PDM column outlet flow %" needle valves on the existing piping to provide access to the individual PDM column outlet flow %" needle valves on the existing piping t	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Referred Solution** Install quick connects downstream of PDM column outlet sample valves. **Referred Solution** Install quick connects downstream of PDM column outlet sample valves. **Referred Solution** Installed valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. **Referred Solution** Installed valves on the combined PDM outlet flow, with a ½" screwed the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. **Referred Solution** **Referred So	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Referred Solution** Install quick connects downstream of PDM column outlet sample valves. **Referred Solution** Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valve, on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed needle valve, quick disconnect caps with insta	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valves.	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution To proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Cost Stand Schedule Estimate (Block 5)* Install public provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Estimated Engineering Cost Stand Schedule Estimate (Block 5)* Total Estimated Cost \$2000 S7000 Deprove for Conceptual Phase (Block 6)* Total Estimated Cost S2000 Cost Account Charge Num Cost Account Charge Num	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$2000 Total Estimated Cost \$7000 Deprove for Conceptual Phase (Block 6)* Total Estimated Cost \$2000 Cost Account Charge Numerations Manager Laborated Numerations Manager Cost Account Charge Numerations Manager Cost Account Charge Numerations Manager	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valves.	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Eferred Solution** The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$2000 Total Estimated Cost \$7000 **Poprove for Conceptual Phase (Block 6)** **Perations Manager** **Language Poprove Cost Account Charge Numerations Mana	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Eferred Solution** The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide for access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Cost Solution Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Solution Solution Cost (Materials and Labor) Solution Solution Cost (Materials and Labor)	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Gerred Solution** The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Total Estimated Cost Stono L=\$4000 Total Estimated Cost \$7000 Stono Conceptual Phase (Block 6)* Fertations Manager La Ves. [1] No. Date Cost Account Charge Numerations Account Charge Numerations Manager Cost Account Charge Numerations Account Charge Numerations Account Charge Numerations Manager	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution To provide a proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Cost (Block 5)* Imated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor)	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install quick connects downstream of each needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valve, on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick discount of each needle valve, on the existing piping to provide fe access to the individual PDM column outlet flows. To exist the existing piping to provide fe access to the individual PDM column outlet flows. To exist the existing piping to provide fe access	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. **Eferred Solution** The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Estimated Page 5 for discussion of alternatives not chosen. Estimated Construction Cost (Materials and Labor) Solution Schedule Estimate (Block 5)* Estimated Engineering Cost Total Estimated Cost \$2000 \$7000 Poprove for Conceptual Phase (Block 6)* [] Yes [] No Date Cost Account Charge Num 111230/FA20	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed on eedle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Installed to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed to reach needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed to reach needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed to reach needle valve, on the existing piping to provide fe access to the individual PDM outlet flows. Downstream of each needle valve, on the existing piping to provide fe access to the individual PDM outlet flows. Downstream of each needle valve, on the existing piping to provide fe access to the individual PDM outlet flows. To reach needle valve, on the existing piping to provide fe access to the individual PDM outlet flows. To reach needle valve, on the existing piping to provide fe access to the individual PDM outlet flows. To reach needle valve, on the existing piping to provide fe ac	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwered needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20 Design Authority KH Bergsman KH Summan [X] Yes [] No Date U/20/01	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwe and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Sporove for Conceptual Phase (Block 6)* Design Authority CH Bergsman KHBLLLANG [X] Yes [] No Date LIZO/61 Date LIZO/61 Date LIZO/61	Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwe and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Sestimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sporove for Conceptual Phase (Block 6)* Sporove for Conceptual Phase (Block 6)* Sporove for Conceptual Phase (Block 6)* Sestimated Cost Account Charge Num 111230/FA20 Design Authority CH Bergsman KHSLLLLLLL Greginsering Management Sestimated Management Sestimated Cost Num 111230/FA20 Date Sestimated Cost Account Charge Num 111230/FA20 Date Sestimated Cost Account Charge Num 111230/FA20 Date Sestimated Cost Account Charge Num 111230/FA20 Design Authority CH Bergsman KHSLLLLLL Sestimated Cost Num 111230/FA20	 Install ball valves in accessible locations for sampling Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screend needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
 Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M= \$1000; L= \$4000 Sporove for Conceptual Phase (Block 6)* Descriptions Manager Cost Account Charge Number 1	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwe and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will exist installed. Install quick connects flow, with a ½" screwe and needle valves on the existing piping to provide a caps will be installed. Install quick connects flow, with a ½" screwe and needle valves on the existing piping to provide a caps will be installed. Install quick connects flow, with a ½" screwe and needle valves on the existing piping to provide a caps will be installed. Install quick connects downstream of PDM column outlet flow ½" needle valves on the existing piping to provide a caps will be installed. Install quick connects downstream of PDM outlet flow, with a ½" screwe and needle valves on the existing piping to provide a caps will be installed. Install quick connects downstream of PDM outlet flow, with a ½" screwe and needle valves on the existing piping to provide a caps will be installed. Install quick connects downstream of PDM outlet flow, with a ½" screwe and needle valves on the existing piping to provide a caps will be a caps	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed and needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed discounter flow, with a ½" screwed d	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed decedle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ½" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects flow, with a ½" screwed needle valve, on the combined PDM outlet flow, with a ½" screwed needle valve, on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed needle valve, quick disconnect caps with	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed in needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$2000 Total Estimated Cost \$7000 Total Estimated Cost \$7000 Total Cost Account Charge Number and Manager	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed in needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ½" screwed in needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ½" screwed in needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM could the combined PDM outlet flow, with a ½" screwed in needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed in needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valves on the exist	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed in needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ½" screwed in needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ½" screwed in needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM could the combined PDM outlet flow, with a ½" screwed in needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed in needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valves on the exist	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Ferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed in needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$2000 Total Estimated Cost \$7000 Total Estimated Cost \$7000 Total Cost Account Charge Number and Manager	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed to needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ½" screwed to exist the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ½" screwed to exist the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ½" screwed to exist the construction of each needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed to exist the connects of the construction of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Install quick connects device the provide access to the individual PDM outlet flow, with a ½" screwed to exist the provide feature provide access to the individual PDM outlet flows. Install quick connects device pre	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed on the existing piping to provide defeaces to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed on the existing piping to provide feaces to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ½" screwed on the existing piping to provide feaces to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ½" screwed on the existing piping to provide feaces to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed on the existing piping to provide feaces to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed on the existing piping to provide defeaces to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of the combined PDM outlet flow, with a ½" screwed on the existing piping to provide defeaces to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed outlet flows. Install quick connects downstream of each needle valve, quick disconnect caps with installed outlet flows. Install quick con	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Eferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwed do needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$2000 Total Estimated Cost \$7000 Install quick connects downstream of PDM column outlet flow, with a 1/2" screwed do needle valve on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$7000 Total Estimated Cost \$7000 Poprove for Conceptual Phase (Block 6)* Estimated Engineering Cost \$7000 Cost Account Charge Num Total Estimated Cost \$7000	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed in needle valve on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed in needle valve on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed in needle valve on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of the combined PDM outlet flow, with a ¼" screwed in needle valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve, on the existing piping to provide access to the individual PDM outlet flow. Install quick connects downstream of the combined PDM outlet flow, with a ¼" screwed in needle valve, on the combined PDM outlet flow. Install quick connects downstream of the combined	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of each needle valve, quick disconnect caps with installed. Install	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will installed. Install quick connects downstream of PDM outlet flow, with a ½" screwed needle valve on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will install the provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will install the provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will install the provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will install the provide fe access to the individual PDM column outlet flows. Downstream of each nee	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet sample valves. Install quick connects downstream of PDM column outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Installed PDM column outlet flows and the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Install quick connects downstream of PDM outlet flow, with a ¼" screwed needle valve, on the existing piping to provide fe access to the individual PDM outlet flow, with a ¼" screwed needle valve, on the existing piping to provide fe access to the individual PDM outlet flow, with a ¼" screwed needle valve, on the existing piping to provide fe access to the individual PDM outlet flow, with a ¼" screwed needle valve, on the existing piping to provide fe access to the individual PDM outlet flow, with a ¼" screwed needle valve, on the existing piping to provide fe access to the individual PDM outlet flow, with a ¼" screwed needle valve, on the existing piping to provide fe access to the individual PDM outlet flow, with a ¼" screwed needle valve, on the existing piping	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20 Design Authority KH Bergsman KHEMMMEAN [X] Yes [] No Date Ul20/61	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide afea access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Sporove for Conceptual Phase (Block 6)* Design Authority (H Bergsman KHELLIMIAN Total Estimated Cost \$2000 \$7000 Cost Account Charge Num 111230/FA20 Design Authority CH Bergsman KHELLIMIAN Total Estimated Cost \$2000 Cost Account Charge Num 111230/FA20 Design Authority CH Bergsman KHELLIMIAN Total Estimated Cost \$2000 Cost Account Charge Num 111230/FA20 Design Authority CH Bergsman KHELLIMIAN Total Estimated Cost \$2000 Cost Account Charge Num 111230/FA20 Design Authority CH Bergsman KHELLIMIAN Total Estimated Cost \$2000 Cost Account Charge Num 111230/FA20	Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Istimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sporove for Conceptual Phase (Block 6)* Perentions Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20 Design Authority CH Bergsman KHELLIMIAN [X] Yes [] No Date Ul/20/61	 Install needle valves in accessible locations for sampling Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screend needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provisafe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
• Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed end needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Schedule Estimate (Block 6)* Deterations Manager Cost Account Charge Number 1	Install quick connects downstream of PDM column outlet sample valves. **Peterred Solution** The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwe and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. The attached page 5 for discussion of alternatives not chosen. **Cost and Schedule Estimate (Block 5)** **Stimated Construction Cost (Materials and Labor) **Estimated Engineering Cost** **Stimated Engineering Cost** **Total Estimated Cost** **Stimated Construction Cost** **Total Estimated Cost** **Stimated Cost** **Stimated Engineering Cost** **Stimated Cost** **Stimated Engineering Cost** **Stimated Cost** **Stimated Engineering Cost** **Stimated Cost** **Story Cost Account Charge Number and Cost** **Story Cost Account Charge Number and Cost** **Cost Account Charge Number and Cost**	Install quick connects downstream of PDM column outlet sample valves. **Peferred Solution** **Referred Solution*	Install quick connects downstream of PDM column outlet sample valves. **Eferred Solution** the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed decedle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. **Example 1.5** **Example valves* **Install quick connects downstream of PDM outlet flow, with a ½" screwed deceded to provide for a cach needle valve, quick disconnect caps with installed. **Example 1.5** **Example valves* **Example valves* **Install quick connects flow, with a ½" screwed deceded to provide for each needle valve, quick disconnect caps with installed. **Example 1.5** **Example 2.5** **Example 3.5** **Example 2.5** **Example 3.5** **Example 2.5** **Example 3.5**	Install quick connects downstream of PDM column outlet sample valves. **Gerred Solution** **Le proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. **Le attached page 5 for discussion of alternatives not chosen.** **Dest and Schedule Estimate (Block 5)** **Imated Construction Cost (Materials and Labor)	Install quick connects downstream of PDM column outlet sample valves. **Gerred Solution** **e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. **e attached page 5 for discussion of alternatives not chosen.** **post and Schedule Estimate (Block 5)** **imated Construction Cost (Materials and Labor)	Install quick connects downstream of PDM column outlet sample valves. **Gerred Solution** **e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. **e attached page 5 for discussion of alternatives not chosen.** **post and Schedule Estimate (Block 5)** **imated Construction Cost (Materials and Labor)	Install quick connects downstream of PDM column outlet sample valves. **Gerred Solution** **Le proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. **Le attached page 5 for discussion of alternatives not chosen.** **Dest and Schedule Estimate (Block 5)** **Imated Construction Cost (Materials and Labor)	eferred Solution the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$2000 Sprove for Conceptual Phase (Block 6)* Total Estimated Cost \$2000 Cost Account Charge Numerations Manager Labor Date Cost Account Charge Numerations Manager	eferred Solution the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Cost \$2000 \$7000 Prove for Conceptual Phase (Block 6)* **Cost Account Charge Num **Total Estimated Cost Cost Cost Account Charge Num **Total Estimated Cost Cost Cost Cost Cost Cost Cost Cost	Install quick connects downstream of PDM column outlet sample valves. **Eferred Solution** **Le proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. **Estimated Page of the Individual PDM column outlet flows and construction Cost (Materials and Labor) **Estimated Engineering Cost Solution Solution (Solution Cost (Materials and Labor) Solution (Solution Cost (Materials	Install quick connects downstream of PDM column outlet sample valves. Gerred Solution Gerred Solu	Install quick connects downstream of PDM column outlet sample valves. **Gerred Solution** **Le proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed do needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. **Le attached page 5 for discussion of alternatives not chosen.** **Dest and Schedule Estimate (Block 5)** **Imated Construction Cost (Materials and Labor)	Install quick connects downstream of PDM column outlet sample valves. **Referred Solution** **Le proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwed needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. **Le attached page 5 for discussion of alternatives not chosen.** **Dost and Schedule Estimate (Block 5)** **Limated Construction Cost (Materials and Labor)	eferred Solution ne proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached Construction Cost (Materials and Labor) See \$1000; L=\$4000 See 1000; L=\$4	Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed and needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date Cost Account Charge Num 2 & Nov 0 111230/FA20 Design Authority KH Bergsman KHBLLAMA [X] Yes [] No Date Cost Account Charge Num 2 & Nov 0 1120/6/	Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Sestimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sporove for Conceptual Phase (Block 6)* Design Authority CH Bergsman KHGLUMMEN Total Estimated Cost \$2000 Sporove for Conceptual Phase (Block 6)* [X] Yes [] No Date Ul20/61 Date Ul20/61	Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Stimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sporove for Conceptual Phase (Block 6)* Design Authority H Bergsman KHELLIMIAN [X] Yes [] No Date Ul 20/01 Date Ul 20/01	• Install quick connects downstream of PDM column outlet sample valves. Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screend needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwed and needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 \$7000 Approve for Conceptual Phase (Block 6)* Descriptions Manager Cost Account Charge Number 1	referred Solution he proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will a installed. Total Estimated Cost Section Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Section Cost (Materials and Labor) Section Cost (Materials and Labor) Section Cost (Materials and Labor) Page Cost Account Charge Number and C	referred Solution the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Estimated Construction Cost (Materials and Labor) Solution Cost (Materials and Labor)	eferred Solution the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed decided valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 \$7000 Sprove for Conceptual Phase (Block 6)* Estimated Construction Cost (Cost Account Charge Numbergions Manager	e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor)	Gerred Solution e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. e attached page 5 for discussion of alternatives not chosen. est and Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor)	Ferred Solution e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. The attached page 5 for discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Total Estimated Cost \$7000 Total Phase (Block 6)* Page of Conceptual Phase (Block 6)* Total Cost Account Charge Num Total Cost Account Charge Num	e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor)	eferred Solution the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps wi installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$1000; L=\$4000 Set and Schedule Estimate (Block 5)* Set and Schedule Estimate (Block 5)* Total Estimated Cost \$7000 Sprove for Conceptual Phase (Block 6)* Set al. No. Date Cost Account Charge Num	eferred Solution the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwed needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$1000; L=\$4000 Perove for Conceptual Phase (Block 6)* Total Estimated Cost \$7000 Cost Account Charge Number of the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow in the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow, with a 1/2" screwed and the combined PDM outlet flow in the combined PDM outle	eferred Solution the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwed deceded valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Solution 1	Gerred Solution e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwed in needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide a access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Impact Construction Cost (Materials and Labor) Schedule Estimate (Block 5)* Schedule Estimate (Block 6)* Schedule Estimate (Block 6)* Schedule Estimate (Block 6)* Cost Account Charge Number of the provide and page of the page of the provide and page of the pa	eferred Solution the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed do needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost with a 1/4" screwed for caps with a 1/4" screwed	referred Solution the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed dependence of needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Solution (Cost (Materials and Labor) Solution (Cost (Ma	eferred Solution ne proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwed defeated valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Stand Schedule Estimate (Block 5)* Total Estimated Cost \$2000 \$7000 Sprove for Conceptual Phase (Block 6)* Secretions Manager [] Yes [] No Date Cost Account Charge Numerations Manager [] Yes [] No Date Date	Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwered needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide safe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 S7000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date 26 NOU 0 1 111230/FA20 Design Authority KH Bergsman KH Surman [X] Yes [] No Date Cost Account Charge Num 26 NOU 0 1 111230/FA20	Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwe and needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 School S	The proposed solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwe and needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Setimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 School S	Preferred Solution The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screend needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed and needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed and needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide affe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 See attached Phase (Block 6)* Determines Manager Cost Account Charge Number 1	he proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwer and needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will enstabled. The entire the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwe and needle valve on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will enstable and a screw and s	Total Estimated Cost Stimated Construction Cost (Materials and Labor)	ne proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed defeated to provide adequate flow control and to add two ½" needle valves on the existing piping to provide featcess to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost \$2000 \$7000 Stand Schedule Estimate (Block 5)* Total Estimated Cost \$2000 \$7000 Person Conceptual Phase (Block 6)* Total Estimated Cost \$2000 \$7000 Total Estimated Cost \$2000 \$7000 Total Estimated Cost \$2000 Total Estimated Co	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed of needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Stimated C	e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Simulated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stimated Engineering Cost Stimated Engineering Cost Stimated Engineering Cost Story Conceptual Phase (Block 6)* Story Conceptual Phase (Block 6)* Story Cost Account Charge Num	e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Simulated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Solution Cost (Materials and Labor)	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed of needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Stimated C	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed defeated to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide feateress to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Stimated Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stown	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed decedle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Summated Construction Cost (Materials and Labor) Summated Cost (Materials and Labor)	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed defeated to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide feateress to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Solvential Estimated Cost (Materials and Labor) Solvential Estimated Cost (Solvential Phase (Block 6)** Solvential Estimated Cost (Solvential Phase (Block 6)** Total Estimated Cost (Solvential Phase (Block 6)** Cost Account Charge Number (Solvential Phase (Block 6)**	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Schedule Estimated Cost (Materials and Labor)	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed do needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Cost Stand Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Engineering Cost Stand Schedule Stand Cost Stand Schedule Stand Schedule Estimated Cost School Total Estimated Cost Sc	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed decedle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Stand Schedule Estimate (Block 5)* Interpretation Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Engineering Cost Schedule Estimated Cost Schedule Es	ne proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$7000 See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$7000 See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$7000 See attached page 5 for discussion of alternatives not chosen.	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 4" screwed and needle valve to provide adequate flow control and to add two 4" needle valves on the existing piping to provide affe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20 Date Congineering Management [X] Yes [] No Date Congineering Management	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwe and needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide afee access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sporove for Conceptual Phase (Block 6)* Design Authority [Yes [] No Date Cost Account Charge Num 26 NOU 1 111230/FA20 Date Cost Account Charge Num 27 Yes [] No Date Cost Account Charge Num 28 Nou 1 Cost Account Charge Num 29 Nou 1 Cost Account Charge Num 20 Nou 1 Cost Account Charge Num 20 Nou 1 Cost Account Charge Num 20 Nou 1 Cost Account Charge Num 21 Yes [] No Date	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 4" screwe and needle valve to provide adequate flow control and to add two 4" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Sporove for Conceptual Phase (Block 6)* Design Authority [Yes [] No Date Cost Account Charge Num 26 NOU 111230/FA20 Date (1/20/0/ Ingineering Management [Yes [] No Date (1/20/0/ Date	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screend needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed and needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed and needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide affe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Separations Manager Date Cost Account Charge Number of the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow in the combined	he proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwer and needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will enstabled. The entire the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwe and needle valve on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will enstable and a screw and s	Total Estimated Cost Stimated Construction Cost (Materials and Labor)	ne proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed defeated to provide adequate flow control and to add two ½" needle valves on the existing piping to provide featcess to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost \$2000 \$7000 Stand Schedule Estimate (Block 5)* Total Estimated Cost \$2000 \$7000 Person Conceptual Phase (Block 6)* Total Estimated Cost \$2000 \$7000 Total Estimated Cost \$2000 \$7000 Total Estimated Cost \$2000 Total Estimated Co	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed of needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Stimated C	e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Simulated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stimated Engineering Cost Stimated Engineering Cost Stimated Engineering Cost Story Conceptual Phase (Block 6)* Story Conceptual Phase (Block 6)* Story Cost Account Charge Num	e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Simulated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Solution Cost (Materials and Labor)	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed of needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Stimated C	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed defeated to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide feateress to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Stimated Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stown	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed decedle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Summated Construction Cost (Materials and Labor) Summated Cost (Materials and Labor)	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed defeated to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide feateress to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Solvential Estimated Cost (Materials and Labor) Solvential Estimated Cost (Solvential Phase (Block 6)** Solvential Estimated Cost (Solvential Phase (Block 6)** Total Estimated Cost (Solvential Phase (Block 6)** Cost Account Charge Number (Solvential Phase (Block 6)**	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Schedule Estimated Cost (Materials and Labor)	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed do needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Cost Stand Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Engineering Cost Stand Schedule Stand Cost Stand Schedule Stand Schedule Estimated Cost School Total Estimated Cost Sc	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed decedle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Stand Schedule Estimate (Block 5)* Interpretation Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Engineering Cost Schedule Estimated Cost Schedule Es	ne proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$7000 See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$7000 See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$7000 See attached page 5 for discussion of alternatives not chosen.	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwed and needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sporove for Conceptual Phase (Block 6)* Design Authority [Yes [] No Date Cost Account Charge Num 111230/FA20 Date Cost Account Charge Num 26 Nov 111230/FA20 Cost Account Charge Num 11120/6/ Congineering Management [Yes [] No Date Cost Account Charge Num 111230/FA20	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwe and needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide afee access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sporove for Conceptual Phase (Block 6)* Design Authority [Yes [] No Date Cost Account Charge Num 26 NOU 1 111230/FA20 Date Cost Account Charge Num 27 Yes [] No Date Cost Account Charge Num 28 Nou 1 Cost Account Charge Num 29 Nou 1 Cost Account Charge Num 20 Nou 1 Cost Account Charge Num 20 Nou 1 Cost Account Charge Num 20 Nou 1 Cost Account Charge Num 21 Yes [] No Date	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 4" screwe and needle valve to provide adequate flow control and to add two 4" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Sporove for Conceptual Phase (Block 6)* Design Authority [Yes [] No Date Cost Account Charge Num 26 NOU 111230/FA20 Date (1/20/0/ Ingineering Management [Yes [] No Date (1/20/0/ Date	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screend needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed and needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/4" screwed and needle valve to provide adequate flow control and to add two 1/4" needle valves on the existing piping to provide affe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Separations Manager Date Cost Account Charge Number of the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow, with a 1/4" screwed and the combined PDM outlet flow in the combined	he proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwer and needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide after access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will enstabled. The entire the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwe and needle valve on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will enstable and a screw and s	Total Estimated Cost Stimated Construction Cost (Materials and Labor)	ne proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screwed defeated to provide adequate flow control and to add two ½" needle valves on the existing piping to provide featcess to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost \$2000 \$7000 Stand Schedule Estimate (Block 5)* Total Estimated Cost \$2000 \$7000 Person Conceptual Phase (Block 6)* Total Estimated Cost \$2000 \$7000 Total Estimated Cost \$2000 \$7000 Total Estimated Cost \$2000 Total Estimated Co	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed of needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Stimated C	e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Simulated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stimated Engineering Cost Stimated Engineering Cost Stimated Engineering Cost Story Conceptual Phase (Block 6)* Story Conceptual Phase (Block 6)* Story Cost Account Charge Num	e proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Simulated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Solution Cost (Materials and Labor)	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed of needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Stimated C	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed defeated to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide feateress to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost Stimated Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stown	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed decedle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Summated Construction Cost (Materials and Labor) Summated Cost (Materials and Labor)	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed defeated to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide feateress to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Total Estimated Cost (Materials and Labor) Solvential Estimated Cost (Materials and Labor) Solvential Estimated Cost (Solvential Phase (Block 6)** Solvential Estimated Cost (Solvential Phase (Block 6)** Total Estimated Cost (Solvential Phase (Block 6)** Cost Account Charge Number (Solvential Phase (Block 6)**	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed in needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Set and Schedule Estimate (Block 5)* Installed Construction Cost (Materials and Labor) Solution Schedule Schedule Estimate (Block 5)* Solution Cost (Materials and Labor)	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed do needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. Total Estimated Cost Stand Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) Stand Schedule Estimate (Block 5)* Estimated Engineering Cost Stand Schedule Stand Cost Stand Schedule Stand Schedule Estimated Cost School Total Estimated Cost Sc	the proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed decedle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. Stand Schedule Estimate (Block 5)* Installed Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Construction Cost (Materials and Labor) Stimated Engineering Cost Stimated Cost Stono Stono Stono Stono Total Estimated Cost Stono	ne proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ¼" screwed needle valve to provide adequate flow control and to add two ¼" needle valves on the existing piping to provide fe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps with installed. The attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$7000 See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$7000 See attached page 5 for discussion of alternatives not chosen. See attached page 5 for discussion of alternatives not chosen. Total Estimated Cost \$7000 See attached page 5 for discussion of alternatives not chosen.	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwed and needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sporove for Conceptual Phase (Block 6)* Design Authority [Yes [] No Date Cost Account Charge Num 111230/FA20 Date Cost Account Charge Num 26 Nov 111230/FA20 Cost Account Charge Num 11120/6/ Congineering Management [Yes [] No Date Cost Account Charge Num 111230/FA20	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 1/2" screwe and needle valve to provide adequate flow control and to add two 1/2" needle valves on the existing piping to provide afee access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sporove for Conceptual Phase (Block 6)* Design Authority [Yes [] No Date Cost Account Charge Num 26 NOU 1 111230/FA20 Date Cost Account Charge Num 27 Yes [] No Date Cost Account Charge Num 28 Nou 1 Cost Account Charge Num 29 Nou 1 Cost Account Charge Num 20 Nou 1 Cost Account Charge Num 20 Nou 1 Cost Account Charge Num 20 Nou 1 Cost Account Charge Num 21 Yes [] No Date Cost Account Charge Num 26 Nou 1 Cost Account Charge Num 27 Nou 1 Cost Account Charge Num 28 Nou 1 Cost Account Charge Num 29 Nou 1 Cost Account Charge Num 20 Nou 1 Cost Account Charge Num 27 Nou 1 Cost Account Charge Num 28 Nou 1 Cost Account Charge Num 29 Nou 1 Cost Account Charge Num 20 Nou 1 Cost Account Charge Num 21 Nou 1 Cost Account Charge Num 22 Nou 1 Cost Account Charge Num 23 Nou	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a 4" screwe and needle valve to provide adequate flow control and to add two 4" needle valves on the existing piping to provide afe access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps will be installed. See attached page 5 for discussion of alternatives not chosen. Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Sporove for Conceptual Phase (Block 6)* Design Authority [Yes [] No Date Cost Account Charge Num 26 NOU 111230/FA20 Date (1/20/0/ Ingineering Management [Yes [] No Date (1/20/0/ Date	The proposed solution is to replace one screwed-end ball valve, on the combined PDM outlet flow, with a ½" screend needle valve to provide adequate flow control and to add two ½" needle valves on the existing piping to provide access to the individual PDM column outlet flows. Downstream of each needle valve, quick disconnect caps be installed.
see attached page 5 for discussion of alternatives not chosen.	stimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Separations Manager Estimated Engineering Cost Separations Manager Cost Account Charge Number 1	stimated Construction Cost (Materials and Labor) [= \$1000; L= \$4000 [= \$1000 \$2000 [= \$1000 \$7000 [= \$1000 \$7000 [= \$1000 \$7000 [= \$1000 \$1000	timated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* perations Manager Date Cost Account Charge Num	timated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* Perations Manager Date Cost Account Charge Number of Conceptual Phase Cost Account Charge Number of C	imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 Sprove for Conceptual Phase (Block 6)* erations Manager [] Ver. [] No. Date Cost Account Charge Num	imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 Sprove for Conceptual Phase (Block 6)* erations Manager [] Ves. [] No. Date Cost Account Charge Num	imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 Sprove for Conceptual Phase (Block 6)* erations Manager [] Ves. [] No. Date Cost Account Charge Num	imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 Sprove for Conceptual Phase (Block 6)* erations Manager [] Ver. [] No. Date Cost Account Charge Num	timated Construction Cost (Materials and Labor) = \$1000; L=\$4000 pprove for Conceptual Phase (Block 6)* erations Manager [] Ves. [] No. Date Cost Account Charge Num	timated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* terations Manager [] Yes [] No Date Cost Account Charge Num	imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* erations Manager [] Yes [] No Date Cost Account Charge Num	imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 Separation Conceptual Phase (Block 6)* Separation Conceptual Phase (Block 6)* Separation Conceptual Phase (Block 6)* Separation Cost (Materials and Labor) Estimated Engineering Cost	Estimated Construction Cost (Materials and Labor) = \$1000; L=\$4000 \$2000 \$7000 \$7000	Estimated Construction Cost (Materials and Labor) = \$1000; L=\$4000 pprove for Conceptual Phase (Block 6)* erations Manager [] Yes [] No 26 NOVO Total Estimated Cost \$7000 Cost Account Charge Num 26 NOVO 111230/FA20	timated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* perations Manager [] Yes [] No Date Cost Account Charge Num 26 NOU 0 1 111230/FA20 Sign Authority	Stimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sport for Conceptual Phase (Block 6)* Perations Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20 Perigin Authority [X] Yes [] No Date [X] Yes [] No Date [X] Yes [] No Date	Stimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 S7000 Spprove for Conceptual Phase (Block 6)** Perations Manager [] Yes [] No Date Cost Account Charge Num 26 NOVO CH Bergsman KHENGMAN [X] Yes [] No Date [X] Yes [] No Date [X] Yes [] No Date	Stimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sport Conceptual Phase (Block 6)* Perations Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20 Perigin Authority [X] Yes [] No Date (X) Yes [] No Date (X) Yes [] No Date	
	M=\$1000; L=\$4000 \$2000 \$7000 Approve for Conceptual Phase (Block 6)* Operations Manager Cost Account Charge Number 1	[= \$1000; L= \$4000 \$2000 \$7000 pprove for Conceptual Phase (Block 6)* perations Manager Cost Account Charge Num	pprove for Conceptual Phase (Block 6)* perations Manager Date Cost Account Charge Num	= \$1000; L= \$4000 \$2000 \$7000 pprove for Conceptual Phase (Block 6)* perations Manager Cost Account Charge Num	= \$1000; L= \$4000 \$2000 \$7000 Oprove for Conceptual Phase (Block 6)* erations Manager Cost Account Charge Num	sprove for Conceptual Phase (Block 6)* erations Manager [] Ver. [] No. Date Cost Account Charge Num	= \$1000; L= \$4000 \$2000 \$7000 Oprove for Conceptual Phase (Block 6)* erations Manager Cost Account Charge Num	= \$1000; L= \$4000 \$2000 \$7000 Oprove for Conceptual Phase (Block 6)* erations Manager Cost Account Charge Num	= \$1000; L= \$4000 \$2000 \$7000 pprove for Conceptual Phase (Block 6)* perations Manager Cost Account Charge Num	pprove for Conceptual Phase (Block 6)* erations Manager [] Yes [] No Date Cost Account Charge Num	pprove for Conceptual Phase (Block 6)* erations Manager [] Yes [] No Date Cost Account Charge Num	sprove for Conceptual Phase (Block 6)* erations Manager [] Yes [] No Date Cost Account Charge Num	\$1000; L=\$4000 \$2000 \$7000	sprove for Conceptual Phase (Block 6)* erations Manager [] Yes [] No Date Cost Account Charge Num 26 NOVO 111230/FA20	pprove for Conceptual Phase (Block 6)* perations Manager [] Yes [] No Date Cost Account Charge Num 26 NOVO 111230/FA20	M=\$1000; L=\$4000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Dete 26 NOVO Ill230/FA20 Cost Account Charge Num 26 NOVO Ill20/0/ Engineering Management [X] Yes [] No Dete	Sesign Authority (H Bergsman KH Garganean (I) Yes [] No	S2000 \$7000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date Cost Account Charge Num 26 NOVO (X) Yes [] No Date (X) Yes [] No Date (X) Yes [] No Date	
	Approve for Conceptual Phase (Block 6)* Determines Manager Determines Manager	pprove for Conceptual Phase (Block 6)* Date Cost Account Charge Num	pprove for Conceptual Phase (Block 6)* Date Cost Account Charge Num	pprove for Conceptual Phase (Block 6)* Perations Manager Date Cost Account Charge Num	oprove for Conceptual Phase (Block 6)* erations Manager	oprove for Conceptual Phase (Block 6)* erations Manager Cost Account Charge Num	oprove for Conceptual Phase (Block 6)* erations Manager	oprove for Conceptual Phase (Block 6)* erations Manager	pprove for Conceptual Phase (Block 6)* erations Manager Cost Account Charge Num	pprove for Conceptual Phase (Block 6)* erations Manager [] Yes [] No Date Cost Account Charge Num	pprove for Conceptual Phase (Block 6)* erations Manager [] Ves. [] No. Date Cost Account Charge Num	Oprove for Conceptual Phase (Block 6)* Perations Manager [] Yes [] No Date Cost Account Charge Num	pprove for Conceptual Phase (Block 6)* Secretions Manager	pprove for Conceptual Phase (Block 6)* Page No Date Cost Account Charge Num	pprove for Conceptual Phase (Block 6)* Secretions Manager	Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date 26 NOVO! 111230/FA20 Design Authority KH Bergsman KHBW men Engineering Management [X] Yes [] No Date U 20/0/	Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date Cost Account Charge Num 26 NOVO 111230/FA20 Design Authority CH Bergsman KHEN aman Congineering Management [X] Yes [] No Date	Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date 26 NOVO! 111230/FA20 Design Authority CH Bergsman KHEN sure [X] Yes [] No Date Congineering Management [X] Yes [] No Date	Settimated Construction Cost (Materials and Labor) Estimated Engineering Cost
Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost	Operations Manager Date Cost Account Charge Num	perations Manager Date Cost Account Charge Num	perations Manager Date Cost Account Charge Nun	erations Manager Date Cost Account Charge Nun	erations Manager Cost Account Charge Num	erations Manager [] Ves. [] No. Date Cost Account Charge Num	erations Manager Cost Account Charge Num	[] Yes [] No Date Cost Account Charge Nun	[] Yes [] No Date Cost Account Charge Num	Yes No Date Cost Account Charge Num 26 NOU 0 111230/FA20 Sign Authority Date	Yes No Date Cost Account Charge Num 26 NOVO 111230/FA20 Oesign Authority Ch Bergsman KH & Series and Cost Account Charge Num Cost Account Charge Num	Yes No Date Cost Account Charge Num 26 NOVO 111230/FA20 Oesign Authority CH Bergsman KH & Series No Cost Account Charge Num Cost Account Charge Nu	Yes No Date Cost Account Charge Num 26 NOVO 111230/FA20 Oesign Authority CH Bergsman KH Gergeman (X) Yes No Date						
Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost M=\$1000; L=\$4000 \$2000 \$7000	Perations Manager Dete Cost Account Charge Numi	perations Manager Cost Account Charge Num	perations Manager Date Cost Account Charge Nun	Date Cost Account Charge Nun	I Ver [] No	I Vee I No	I Ver I No	I Ver [] No	I Van I I No	1 Yes No	1 Yes No	1 Yes No	[] Yes [] No 26NOVO! 111230/FA20	[] Yes [] No 26NOVO! 111230/FA20	Sign Authority Date	[] Yes [] No 26NOVO 111230/FA20 Design Authority (H Bergsman KH Gergement Engineering Management [X] Yes [] No Date [X] Yes [] No	Yes No 26NOVO 111230/FA20 Design Authority X Yes No U/20/0/ Engineering Management One Date	Yes No 26NOVO 111230/FA20 Date No No No No No No No N	M= \$1000; L= \$4000 \$2000 \$7000
Estimated Construction Cost (Materials and Labor) Estimated Engineering Cost Total Estimated Cost M=\$1000; L=\$4000 \$2000 \$7000	1 Yes No	1 Yes No	1 Yes No	1 Yes NO			7	7			26 AND 1111230/FA20	Z6NOU01 111230/FA20	26 NOJO 111250/FA20	26 NOJO 111250/FA20	sign Authority Date	Design Authority KH Bergsman KH Serieuren [X] Yes [] No U/20/0/ Engineering Management [Y] Yes [] No	Design Authority (H Bergsman KH Gergeman (I) Yes [] No Date (I) Ves [] No	Design Authority [X] Yes [] No U 20/0/ Date U 20/0/ Congineering Management Date	M= \$1000; L= \$4000 \$2000 \$7000
Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 Approve for Conceptual Phase (Block 5)* Operations Manager Labor Date Cost Account Charge Num	26NOU01 111250/FA20	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	26 NO. 21 111230/FA20	26 NO. 01 111230/FA20	1 1 200 [] 110 [] 2 (10 (0) [111230/FA20		26 NOVA 111230/FA20	26NOU01 111230/FA20				tion Authority		KH Bergsman KH Gersman [X] Yes [] No 11/20/01 Engineering Management	CH Bergsman KH German [X] Yes [] No 11/20/01 Engineering Management Date	CH Bergsman KH German [X] Yes [] No U/20/0/ Ingineering Management Date	M=\$1000; L=\$4000 \$2000 \$7000 Approve for Conceptual Phase (Block 6)* Operations Manager Cost Account Charge 1
Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 S7000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date 26N000 111230/FA20		26 NOVO 111250/FA20	26 NOVO 111250/FA20									tion Authority	sign Authority Date		IX Yes I No	Engineering Management Date	Engineering Management Date	Ingineering Management Date	M=\$1000; L=\$4000 \$2000 \$7000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date Cost Account Charge 1 26 NOVO 111230/FA20
Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Second Sec		esign Authority Date	Sign Authority Date	sign Authority Date	sign Authority Date	tign Authority Date	tign Authority Date	sign Authority Date	sign Authority Date	sign Authority Date				TD		[YI Vac [] No /2 /	[VI Vec [] No /2 /	[VI Vac [] No /2/	M=\$1000; L=\$4000 \$2000 \$7000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date Cost Account Charge 1 26 NOU 0 111230/FA20 Design Authority Date
Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 S7000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date 26N010 1 111230/FA20 Date KH Bergsman KH Bergsman KH Bergsman [X] Yes [] No U/20/01	CH Bergsman KH Gersaman [X] Yes [] No 11/20/01	Esign Authority H Bergsman KH Seviguran [X] Yes [] No 11/20/01	Esign Authority H Bergsman KH Seviguran [X] Yes [] No 11/20/01	H Bergsman KH Gerjaman [X] Yes [] No U(20/01	H Bergsman KH Berjaman [X] Yes [] No U(20/01	I Bergsman KH Berjaman [X] Yes [] No U(20/01	H Bergsman KH Bergsman [X] Yes [] No U/20/01	H Bergsman KH Berjaman [X] Yes [] No U(20/01	H Bergsman KH Serjaman [X] Yes [] No U(20/01	H Bergsman KHBerjaman [X] Yes [] No U/20/01	H Bergsman KHBerjaman [X] Yes [] No 11/20/01	Bergsman KHBerjaman [X] Yes [] No 11/20/01	H Bergsman KHBerjaman [X] Yes [] No 11/20/01	1 Deigsman 4 April and 11/20/01	11 Belginal Angeljanan	9 _ 11 11			M=\$1000; L=\$4000 \$2000 \$7000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date 26N010 111230/FA20 Design Authority KH Bergsman KH Sergman [X] Yes [] No U(20/0)
Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Second Sec	CH Bergsman KH Gergunan [X] Yes [] No 11/20/01 Engineering Management Date	Esign Authority H Bergsman KH Gergsman [X] Yes [] No Date	Sign Authority H Bergsman KH Gergsman [X] Yes [] No Date 1/20/0/	H Bergsman KHBerjaman [X] Yes [] No Date [X] Yes [] No Date	H Bergsman KHBerjaman [X] Yes [] No Date [X] Yes [] No Date	H Bergsman KHBerjaman [X] Yes [] No Date [X] Yes [] No Date	H Bergsman KHBerjaman [X] Yes [] No Date [X] Yes [] No Date	H Bergsman KHBerjaman [X] Yes [] No Date [X] Yes [] No Date	H Bergsman KH Serjaman [X] Yes [] No U/20/0/ gineering Management Date	H Bergsman KHEwisman [X] Yes [] No Date 1/20/0/	H Bergsman KH Seriaman [X] Yes [] No 11/20/01 gineering Management Date	Bergsman KHBerjaman [X] Yes [] No 11/20/01	H Bergsman KH Seriaman [X] Yes [] No 11/20/01 gineering Management Date	gineering Management Date	gineering Management [Y] Vac [] No	1 113-1-1	N'XX///h M	LXXX - VOL	M=\$1000; L=\$4000 \$2000 \$7000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date Cost Account Charge? 26 NOVO! 111230/FA20 Design Authority KH Bergsman KH Gergungen [X] Yes [] No Date U/20/0/
See attacked and See diameter of the still and the	Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Spprove for Conceptual Phase (Block 6)* Determines Manager Cost Account Charge N	stimated Construction Cost (Materials and Labor) [= \$1000; L= \$4000 [Symmetric (Block 6)* Estimated Engineering Cost Symmetric (Symmetric (Block 6)* Symmetric (Block 6)* Sy	ost and Schedule Estimate (Block 5)* timated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* perations Manager Date Cost Account Charge	ost and Schedule Estimate (Block 5)* timated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* Perations Manager Date Cost Account Charge	inst and Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 Sprove for Conceptual Phase (Block 6)* erations Manager [] Ver. [] No. Date Cost Account Charge No. Cost Accou	inst and Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 Sprove for Conceptual Phase (Block 6)* erations Manager [] Ves. [] No. Date Cost Account Charge No. Cost Accou	ost and Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 Sprove for Conceptual Phase (Block 6)* erations Manager [] Ves. [] No. Date Cost Account Charge No. Cost Account C	inst and Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 Sprove for Conceptual Phase (Block 6)* erations Manager [] Ver. [] No. Date Cost Account Charge No. Cost Accou	inst and Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) = \$1000; L=\$4000 pprove for Conceptual Phase (Block 6)* erations Manager [ost and Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* erations Manager [] Yes [] No Date Cost Account Charge N	ost and Schedule Estimate (Block 5)* imated Construction Cost (Materials and Labor)	inst and Schedule Estimate (Block 5)* Imated Construction Cost (Materials and Labor) = \$1000; L=\$4000 Sprove for Conceptual Phase (Block 6)* Perations Manager [] Yes [] No Date Cost Account Charge No.	imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* erations Manager [] Yes [] No 26 NOVO 1 Total Estimated Cost \$7000 Cost Account Charge N 26 NOVO 1 111230/FA20	imated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* erations Manager [] Yes [] No 26 NOU 01 Total Estimated Cost \$7000 Cost Account Charge N 26 NOU 01 111230/FA20	timated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* rerations Manager [] Yes [] No Date Cost Account Charge No. 111230/FA20 Sign Authority Date	Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date 26N010 111230/FA20 Design Authority KH Bergsman KHENGMAN Engineering Management [X] Yes [] No Date [X] Yes [] No Date [X] Yes [] No Date	Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date 26N000 Cost Account Charge N 111230/FA20 Date (X) Yes [] No Date (V) Yes [] No Date	Cost and Schedule Estimate (Block 5)* Stimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 S2000 S2000 S7000 Approve for Conceptual Phase (Block 6)* Operations Manager [] Yes [] No Date 26N010 111230/FA20 Date (M] Yes [] No Date (M) Yes [] No Date (M) Yes [] No Date (M) Yes [] No Date	See attached page 3 for discussion of atternatives not chosen.
					1 I I VAC I I NO I	1 Yes I No I	I I I VAR I I NA I	I I I VAN I I NA I	1 Yes I No I	1 Yes No	Yes No 2 c v c c 111230/FA20	[] Yes [] No 26NOVO 111230/FA20	26 NOJO 111250/FA20	26 NOJO 111250/FA20	sign Authority Date	Design Authority KH Bergsman KH Serieum an [X] Yes [] No U/20/0/ Engineering Management [Y] Yes [] No	Design Authority (H Bergsman KH Gergeman (I) Yes [] No Date (I) Ves [] No	Design Authority [X] Yes [] No U 20/0/ Date U 20/0/ Congineering Management Date	Cost and Schedule Estimate (Block 5)* Estimated Construction Cost (Materials and Labor) Estimated Estimated Cost
stimated Construction Cost (Materials and Labor) Estimated Engineering Cost S2000 Total Estimated Cost \$7000 Special Phase (Block 6)* Perations Manager Cost Account Charge Num	1 Yes No	1 Yes No	Yes No -	Yes NO	[] I I I I 7 111230/FA20		[] 163 [] 170 [2	[] ICS [] INO [] 111220/FA20	1 1 200 [] 1 100 [] 1 11 1230/FA20	102 11 11 1730/KA70		26 NOVO 111250/1720			sign Authority Date	esign Authority [X] Yes [] No Date (X) Yes [] No Date	esign Authority [X] Yes [] No Date (X) Yes [] No Date	esign Authority [X] Yes [] No Date (X) Yes [] No Date	A= \$1000; L= \$4000 \$2000 \$7000 Approve for Conceptual Phase (Block 6)* Approxions Manager Cost Account Charge Cost Account C
stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 \$7000 Sperations Manager Cost Account Charge Num	26NOVO 1 111230/FA20	1111000000000		[] 100 [] 110 [] 1111220/EA20	26 NO. 01 111230/FA20	76 NO. 01 111230/FA20	1 1 10 1 1 10 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 100 1 1 110 12 1111230/FA20	26 NOVA 111230/FA20	26NOU01 111230/FA20	2600001 11125011120			sion Authority		H Bergsman KH Serieman [X] Yes [] No 11/20/01 Ingineering Management Date	H Bergsman KH Gergaman [X] Yes [] No 11/20/01 Ingineering Management Date	H Bergsman KH Gergsman [X] Yes [] No 11/20/01 Ingineering Management Date	A=\$1000; L=\$4000 \$2000 \$7000 Approve for Conceptual Phase (Block 6)*
stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 S7000 S7000 S7000 Perations Manager [] Yes [] No Date Cost Account Charge Num			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		17 2 110 101 1 111230 11 470	17.2 AID IN 1 111230/FAZU			12.6 ADOLD 1 111230/17A20	126 NOJO 111230/1720			Audh anibi			H Bergsman KH Gersman [X] Yes [] No 11/20/01 Ingineering Management Date	H Bergsman KH Gersman [X] Yes [] No 11/20/01 Ingineering Management Date	H Bergsman KH Gersman [X] Yes [] No 11/20/01 Ingineering Management Date	f= \$1000; L= \$4000 \$2000 \$7000 approve for Conceptual Phase (Block 6)* perations Manager Cost Account Charge 1
stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 S7000 S7000 S7000 Perations Manager [] Yes [] No Date Cost Account Charge Num		26NOU01 11123U/FAZU	26NOUD1 111230/FA20	126 NOUD 111230/FAZU			LG NOUD ILLESVITALU	LG NONO ILLES VITALO					sign Authority Date	og is a normal of the state of		H Bergsman KH Gergaman [X] Yes [] No U/20/0/	H Bergsman KH Gergaman [X] Yes [] No 11/20/01 If Yes [] No Date	H Bergsman KH Gergaman [X] Yes [] No 11/20/01 If Yes [] No Date	f= \$1000; L= \$4000 \$2000 \$7000 approve for Conceptual Phase (Block 6)* perations Manager Cost Account Charge 1
stimated Construction Cost (Materials and Labor) [= \$1000; L= \$4000 S2000 S7000 Perations Manager [] Yes [] No Date Cost Account Charge Num		26NOVO 111230/FA20	26NOU01 111230/FA20	Z6N000 111250/FA20	200001 111100111110	~~~~~	26 NOVO 111250/1720	26 NOVO 111250/FA20	120,000				sign Authority Date		The state of the s	ngineering Management Date	ngineering Management Date	ngineering Management Date	f= \$1000; L= \$4000 \$2000 \$7000 approve for Conceptual Phase (Block 6)* perations Manager [1] Yes [1] No Date Cost Account Charge 1
stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 S7000 S7000 S7000 Perations Manager [] Yes [] No Date Cost Account Charge Num		26 NOU 0 111230/FAZU	26NOU01 111230/FA20	26 NOVO 111250/FA20		200001	26 NOVO 111250/1720	26 NOVO 111250/17420	120,000				sign Authority Date			ngineering Management Date	ngineering Management Date	ngineering Management Date	f= \$1000; L= \$4000 \$2000 \$7000 approve for Conceptual Phase (Block 6)* perations Manager Cost Account Charge 1
stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 S7000 S7000 S7000 Perations Manager [] Yes [] No Date Cost Account Charge Num		26NOVO 111230/FA20	26NOU01 111230/FA20	Z6N000 111250/FA20	200001 111100111110	~~~~~	26 NOVO 111250/1720	26 NOVO 111250/FA20	120,000				sign Authority Date			H Bergsman KH Gergaman [X] Yes [] No U/20/0/	H Bergsman KH Gergaman [X] Yes [] No 11/20/01 If Yes [] No Date	H Bergsman KH Gergaman [X] Yes [] No 11/20/01 If Yes [] No Date	f= \$1000; L= \$4000 \$2000 \$7000 approve for Conceptual Phase (Block 6)* perations Manager Cost Account Charge 1
stimated Construction Cost (Materials and Labor) [= \$1000; L= \$4000 S2000 S7000 Perations Manager [] Yes [] No Date Cost Account Charge Num		126 NO. 61 111123U/FAZU	26 A10 (A) 1111230/FA20	17 6 A10 (0) 1 111123U/FA2U									Time Authority			H Bergsman KH German [X] Yes [] No 11/20/01 Ingineering Management Date	H Bergsman KH German [X] Yes [] No 11/20/01 Ingineering Management Date	H Bergsman KH German [X] Yes [] No 11/20/01 Ingineering Management Date	f= \$1000; L= \$4000 \$2000 \$7000 approve for Conceptual Phase (Block 6)* perations Manager [1] Yes [1] No Date Cost Account Charge 1
stimated Construction Cost (Materials and Labor) [= \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* perations Manager [] Yes [] No Date Cost Account Charge Num	26NOU01 111250/FA20				126 NO. 01 1111230/FA70	17.6 MOLOL 1111230/FA20			26A10101 1111230/FA20	26 NOVO 1 111230/FA20				tion Authority		H Bergsman KH German [X] Yes [] No 11/20/01 Ingineering Management Date	H Bergsman KH German [X] Yes [] No 11/20/01 Ingineering Management Date	H Bergsman KH German [X] Yes [] No 11/20/01 Ingineering Management Date	[= \$1000; L= \$4000 \$2000 \$7000 pprove for Conceptual Phase (Block 6)* perations Manager Cost Account Charge 1
stimated Construction Cost (Materials and Labor) [= \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* perations Manager [Z6NOVO 111230/FA20	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1111220/FA20	26 NO. 01 111230/FA20	76ANALO 1111230/FA20	1 1 200 [] 110 [] 2 (1) (1) [1) [1) [1) [1) [1] [1) [1] [1]		26 NOVA 111230/FA20	26NOU01 111230/FA20	126 0000 11125011120				sign Authority Date	H Bergsman KH Serjaman [X] Yes [] No Date 1/20/0/	H Bergsman KH Serjaman [X] Yes [] No Date 1/20/0/	H Bergsman KH Serjaman [X] Yes [] No Date 1/20/0/	pprove for Conceptual Phase (Block 6)* perations Manager [] Ves. [] No. Date Cost Account Charge 1
stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$7000 Estimated Engineering Cost \$7000 For Conceptual Phase (Block 6)* For Conceptual Phase (Block 6)* For Conceptual Phase (Block 6)*	1 1 tes 1 1 No 26 NO 10 111230/FA20	111000/5400	1 1 163 1 170 - 1111000 17100	111220/5420		26A0040 111230/FA20	[] 163 [] 170 [2	[] ICS [] INO [] 111220/FA20	26A)Q1Q1 111230/FA20	26 NO. 01 1111230/FA20		20,000			sign Authority Date	H Bergsman KH Serjaman [X] Yes [] No Date Ingineering Management Date	H Bergsman KH Serjaman [X] Yes [] No Date Igineering Management Date	H Bergsman KH Serjaman [X] Yes [] No Date Ingineering Management Date	pprove for Conceptual Phase (Block 6)* Perations Manager Cost Account Charge Date Cost Account Charge
Estimated Construction Cost (Materials and Labor) = \$1000; L=\$4000 pprove for Conceptual Phase (Block 6)* Perations Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20 Date Cost Account Charge Num Co		sign Authority Date	sign Authority Date	sign Authority Date	sign Authority Date	tign Authority Date	tign Authority Date	sign Authority Date	sign Authority Date	sign Authority Date					IN I I'M I I	gineering Management Date	gineering Management Date	gineering Management Date	sign Authority \$2000
timated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* regrations Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20 Date Cost Account Charge Num Co		sign Authority Date	sign Authority Date	sign Authority Date	sign Authority Date	tign Authority Date	tign Authority Date	sign Authority Date	sign Authority Date	sign Authority Date				I IAI TPE I I (NA I		gineering Management Date	gineering Management Date	gineering Management Date	pprove for Conceptual Phase (Block 6)* perations Manager [] Yes [] No Date Cost Account Charge 1 26 NOVO 111230/FA20
timated Construction Cost (Materials and Labor) = \$1000; L= \$4000 pprove for Conceptual Phase (Block 6)* regrations Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20 Date Cost Account Charge Num Co		sign Authority Date	sign Authority Date	sign Authority Date	sign Authority Date	tign Authority Date	tign Authority Date	sign Authority Date	sign Authority Date	sign Authority Date				I December 1/1/2 [A 105 1 NO 1/2 /		gineering Management Date	gineering Management Date	gineering Management Date	pprove for Conceptual Phase (Block 6)* perations Manager [] Yes [] No Date Cost Account Charge 1 26 NOVO 111230/FA20
timated Construction Cost (Materials and Labor) = \$1000; L=\$4000 pprove for Conceptual Phase (Block 6)* perations Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20		Sign Authority Date	Sign Authority Date	sign Authority Date	sign Authority Date	tign Authority Date	tign Authority Date	sign Authority Date	sign Authority Date	sign Authority Date				Bergsman KHRest mage	ti Bergsman KH6gg tungga	igineering Management	igineering Management	igineering Management	pprove for Conceptual Phase (Block 6)* perations Manager [] Yes [] No Date Cost Account Charge Page Cost Account Charge P
Stimated Construction Cost (Materials and Labor) [= \$1000; L= \$4000 Sport Conceptual Phase (Block 6)* Perations Manager [] Yes [] No Date Cost Account Charge Numeration Authority Date Cost Account Charge Numeration Authority Cost Account Charge Numeration Authority Cost Account Charge Numeration Authority Cost Account Charge		esign Authority Date	Sign Authority Date	sign Authority Date	sign Authority Date	tign Authority Date	tign Authority Date	sign Authority Date	sign Authority Date	sign Authority Date				H Bergsman KHBerjaman [A] 100 11/20/01	H Bergsman KHBW suren (1/20/01	[Y] Vac [] No	[Y] Vac [] No	[Y] Vac [] No	\$1000; L=\$4000 \$2000 \$7000
Stimated Construction Cost (Materials and Labor) A = \$1000; L = \$4000 Sport Conceptual Phase (Block 6)* Sperations Manager [] Yes [] No Sesign Authority [X] Yes [] No [X] Yes [] No [X] Yes [] No [X] Yes [] No	H Bergsman KH Bergsman [X] Yes [] No 11/20/01	Esign Authority H Bergsman KH Seviguran [X] Yes [] No 11/20/01	Esign Authority H Bergsman KH Seviguran [X] Yes [] No 11/20/01	H Bergsman KH Gerjaman [X] Yes [] No U(20/01	H Bergsman KH Berjaman [X] Yes [] No U(20/01	I Bergsman KH Berjaman [X] Yes [] No U(20/01	H Bergsman KH Bergsman [X] Yes [] No U/20/01	H Bergsman KH Berjaman [X] Yes [] No U(20/01	H Bergsman KH Serjaman [X] Yes [] No U(20/01	H Bergsman KHBerjaman [X] Yes [] No U/20/01	H Bergsman KHBerjaman [X] Yes [] No 11/20/01	Bergsman KHBerjaman [X] Yes [] No 11/20/01	H Bergsman KHBerjaman [X] Yes [] No 11/20/01	1 Deigsman 4 April and 11/20/01	11 Belginal Angeljanan	[Y] Vac [] No	[Y] Vac [] No	[Y] Vac [] No	Sperations Manager [] Yes [] No Resign Authority [H Bergsman KHBaraman S2000 S7000 S7000 S7000 S7000 S7000 [X] Yes [] No Date (X] Yes [] No U/20/01
Stimated Construction Cost (Materials and Labor) Estimated Engineering Cost \$2000 Sperations Manager [] Yes [] No Date 26 NOVO [X] Yes [] No Date 111230/FA20 [X] Yes [] No	TH Bergsman KHBerjaman [X] Yes [] No 11/20/01	Esign Authority H Bergsman KH Seviguran [X] Yes [] No 11/20/01	Esign Authority H Bergsman KH Seviguran [X] Yes [] No 11/20/01	H Bergsman KH Gerjaman [X] Yes [] No U(20/01	H Bergsman KH Berjaman [X] Yes [] No U(20/01	I Bergsman KH Berjaman [X] Yes [] No U(20/01	H Bergsman KH Bergsman [X] Yes [] No U/20/01	H Bergsman KH Berjaman [X] Yes [] No U(20/01	H Bergsman KH Serjaman [X] Yes [] No U(20/01	H Bergsman KHBerjaman [X] Yes [] No U/20/01	H Bergsman KHBerjaman [X] Yes [] No 11/20/01	Bergsman KHBerjaman [X] Yes [] No 11/20/01	H Bergsman KHBerjaman [X] Yes [] No 11/20/01	1 Deigsman 4 April and 11/20/01	11 Belginal Angeljanan	1 101 153 1 130 1 1/1./01	\(\(\) \(7 - MU [[NO] [[NO]	Sesign Authority [X] Yes [] No
Stimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Separations Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20 Cost Account Charge Num 26 Nov 0 1 Cost Account Charge Num 111230/FA20	CH Bergsman KH Serjaman [X] Yes [] No 11/20/01	esign Authority H Bergsman KH bergsman [X] Yes [] No U/20/0/ Ingineering Management	Esign Authority H Bergsman KH Gersaman [X] Yes [] No U/20/0/ Igineering Management	H Bergsman KH Serson an [X] Yes [] No Date [X] Yes [] No Date	I Bergsman KH Serjaman [X] Yes [] No Date 11/20/01	I Bergsman KH Swigman [X] Yes [] No Date U/20/0/	I Bergsman KH Swigman [X] Yes [] No Date U/20/0/	I Bergsman KH Serjaman [X] Yes [] No Date 11/20/01	H Bergsman KH Serson an [X] Yes [] No Date 11/20/01	H Bergsman KH Gersman [X] Yes [] No U/20/01 gineering Management Date	H Bergsman KH Sevisman [X] Yes [] No 11/20/01	H Bergsman KH Bergsman [X] Yes [] No 11/20/01	H Bergsman KH Serjaman [X] Yes [] No 11/20/01	gineering Management	gineering Management	9 _ 1/1/			Sesign Authority CH Bergsman KHBurguran [X] Yes [] No [X] Yes [] No [X] Yes [] No [X] Date [X] Yes [] No [X] Date
Stimated Construction Cost (Materials and Labor) M=\$1000; L=\$4000 Sport for Conceptual Phase (Block 6)* Perations Manager [] Yes [] No Date Cost Account Charge Num 111230/FA20 Perigin Authority [X] Yes [] No Date [X] Yes [] No Date [X] Yes [] No Date	TH Bergsman KH Gergaman [X] Yes [] No 11/20/01 Ingineering Management Date	Esign Authority H Bergsman KH Gergsman [X] Yes [] No Date	Sign Authority H Bergsman KH Gergsman [X] Yes [] No Date 1/20/0/	H Bergsman KHBerjaman [X] Yes [] No Date [X] Yes [] No Date	H Bergsman KHBerjaman [X] Yes [] No Date [X] Yes [] No Date	H Bergsman KHBerjaman [X] Yes [] No Date [X] Yes [] No Date	H Bergsman KHBerjaman [X] Yes [] No Date [X] Yes [] No Date	H Bergsman KHBerjaman [X] Yes [] No Date Was [] No Date	H Bergsman KH Serjaman [X] Yes [] No U/20/0/ gineering Management Date	H Bergsman KHEwisman [X] Yes [] No Date 1/20/0/	H Bergsman KH Seriaman [X] Yes [] No 11/20/01 gineering Management Date	Bergsman KHBerjaman [X] Yes [] No 11/20/01	H Bergsman KH Seriaman [X] Yes [] No 11/20/01 gineering Management Date	gineering Management Date	gineering Management [Y] Vac [] No				Sesign Authority (H Bergsman KHburman (I) Yes [] No [X] Yes [] No

^{*}Block numbers refer to block numbers on the FMP Flowchart (HNF-PRO-2001, Appendix A) and procedure steps within HNF-PRO-2001.

HNF-FMP-_01_-_9507__-R_0_ Page _5 of 30

FMP-8 (Facility Modification Package -- Continuation Page)

FMP Section 2

Problem Analysis

Periodic sampling/analysis of the combined outlet from the PDM columns is a valuable tool in troubleshooting column performance. There are several locations where samples have been taken. Some are at convenient locations and elevations, others are not. The valves that control sample flow are ½" ball valves at all PDM locations.

Periodic sampling/analysis of the outlet from the individual PDM columns has not been done in the past, however considering the difficulty that ETF has had in operating the columns in the past, having the ability to conveniently and safely take these samples would improve troubleshooting capability. There are no locations where samples can be taken conveniently and safely. There are two locations where simple modifications, at screwed fittings, would provide this capability. At one, ½" ball valves would have to be lowered to a more convenient elevation. At the other, new valves would have to be added.

Needle valves provide much better control over flow than do ball valves. Replacing the ½" ball valves used for sampling with needle valves will reduce the risk of splashing and contamination. This is especially important when processing higher radiation feeds such as Basins 42 and 44, and has been identified as a desired feature by Rad Con and Operations.

All the existing valves that could be used for PDM column outlet samples are capped with screwed caps. Craft support is required to loosen these caps before samples can be taken. Adding quick connect fittings with caps will allow Operations to monitor PDM column performance when desired, even on off-shifts.

1) Do nothing, on the combined outlet sample, continues a low, but unnecessary, risk of splashing/contamination. Do nothing, for the individual column outlet samples, prevents the acquisition of information useful to troubleshooting the routine, poor PDM column performance. 2) Not sampling the combined outlet eliminates necessary information for controlling the water treatment process. 3) Installing ball valves rather than needle valves continues the low, but unnecessary, risk of splashing/contamination for little incremental benefit. 4) Using pipe caps rather than quick connects hinders acquiring samples when desired, especially during the off-shifts.

HNF-FMP-_01__-9507___-R_0_ Page _6_ of 30

ng jeng	Black 4)*	
	ual Place Plac	and the second second
Needed	Bodge layer formand ()	Notes -
N/A	Functional Requirements Document (required for Line Item Projects)	
N/A	Scope Description Document (required for General Plant Projects)	
X	Identify/Review Applicable Codes and Standards	ASME B31.3, LWPF pipe code
N/A	Applicable Regulatory Requirements	
X	Research Vendor Information	New valves
N/A	Make/Buy Decision	
N/A	Resource Plan for Engineering/Project Support	
X	Identify Engineering Drawings	Page 9
N/A	Identify Need for Procurement Specification	
N/A	Identify Need for Construction Specification	
	Design Analysis Documents	
N/A	Engineering Study	
N/A	Preliminary Design Calculations	
N/A	Preliminary Safety Analysis/USQ Screen	
N/A	Preliminary Environmental (NEPA) Review	
N/A	Structures, Systems, and Components Functional Analysis	

HNF-FMP-_01_-9507__-R_0_Page__7_ of 30

ugue) kom	(Block 7)*	
Conceptu	al Phase Plan	
Needed	Document management of the second second	Nome
x	Design Criteria	page 11
x	List of Baseline Documents to be modified	Page 9
x	List of Affected Documents	Page 10
х	Design Verification Method/Plan	Page 13
x	Applicable Codes and Standards	ASME B31.3, LWPF pipe codes
N/A	Conceptual Design Cost and Schedule	March Co.
N/A	Preliminary USQ Screen	
. X	Environmental Screen/NEPA	Page 22
N/A	Preliminary Job Hazard Analysis/Automated Job Hazard Analysis (AJHA)	
N/A	Formal Hazards Analysis (if required)	ES-18th anist control
N/A	Preliminary Safety Analysis Report	Anjabetas I ma
N/A	Identify/Review Fire Hazards Analysis (FHA)	
N/A	Identify/Review Criticality Safety Evaluation Report (CSER)	
N/A	Perform Preliminary ALARA, Ergonomics, and Safety Review	Essential Essential
N/A	3rd Party Inspector Review (e.g. NEC, Water Purveyor, Pressure Vessel)	
N/A	Engineering Walkdowns/Surveys	
N/A	Drawing Searches	Walter Control
x	Plant Forces Work Review	Included in EL-01-00686
N/A	System Design Description	Prigary many
N/A	Long-Lead Equipment Specifications/Procurement	
N/A	Identify Construction Work Authorization Envelope	
N/A	Identify need for Interface Control Documents/ Memoranda of Understanding/Memoranda of Agreement	
N/A	Identify need for Engineering Work Plan	
N/A	Prepare Formal Conceptual Design	
N/A	Prepare Quality Assurance Plan (Required for Line Items/General Plant Projects) N/A	or and the second second second
	N/A	DEPART AND

HNF-FMP-_01_ - 9507_ -R_0 Page 9 of 30

		FMP-3C (Facility Modification Package - Execution	n Plan)
egie P	en (Elle	ck 7)* ce s supre contra promoting to the state of the st	
Ebrecuti			
Detail De			
		of Documents	
Needed		Document Document	Notes
х	Vendo	or Information	Pages 23-30
Other Dea	ign Ana	yais Documents	
N/A	Desig	n Calculations	
x	Job H	azards Analysis/Automated Job Hazard Analysis	Included in EL-01-00686
Х	Desig	n Verification	Page 13
Design O	atput Do	auments	
N/A	Detail	ed Design Drawings	
N/A	Final	USQ Screen	
N/A	Procu	rement Specification	
N/A	Const	ruction Specification	×
Х	Accep	stance Test Plan / Inspection Plan	Page 14
X	Install	ation Instructions	In EL-01-00686
х	Bill of	Materials	parts shown on pages 18-21
N/A	Requi	red Permits	
	N/A	Hot Work Permit	
	N/A	Excavation Permit	
	N/A	Confined Space Permit	
	N/A	Radiation Work Permit	
	N/A	Elevated Work Permit	
х	Work	Package	EL-01-00686
N/A	Redlin	ne Drawing Set (s)	
Acceptan	e Testin	g and Turnover	
х	Accep	tance Testing	Page 14
N/A	-	rty Inspector Review (e.g. NEC, Water Purveyor, Pressure Vessel)	
N/A		ilt Set of Drawings	
N/A	Punch		

HNF-FMP-_01__-9507__-R_0_ Page _9_ of 30

KUKACIONA MARKATAN M	'scility Modification Package l locuments to be Modified (Block		
Document Number (Sheet/Pages, Rev)	no-	Onteresting ECN(s) DCN(s)/FACP(s)	Work Complete?
H-2-88977, sht 1, Rev 12	P&ID pH Adjustment System	None	N/A
H-2-89332, sht 1, Rev 11	P&ID H2O2 Decomposer System	None	N/A
H-2-89351, sht 1, Rev 7	P&ID Legend	None	N/A
H-2-88988, sht 1, Rev 20	P&ID Concentrate Receiving System	ECN 656788	No
TO AU		ECN 662046	No
ubmit to Document	Control? (Block 10)*		
] Yes [X] No	Lead Engineer KH Bergoman		Date 4/9/02

HNF-FMP-_01__-9507__-R_0_ Page__10__of 30

FMP-5 (Facility Modification Package - Potentially Affected Documents) Potentially Affected Document (Blocks 7)* Decument Owner (organization) Document Technical Authority Notified Date Notified Number/Revision 1/3/02 Vendor information of all LWPF Engineering Yes included valves 1/3/02 Component index of all **LWPF** Engineering Yes included valves 1/3/02 POP-60-006 **LWPF** Operations Yes 1/9/02 POP-55F-001 **LWPF** Operations Yes

HNF-FMP-01 - 9507 -R 0 Page 11 of 30

PMP-6 (Racility Modification Package... Preliminary Evaluations/Functional Requirements) Payfore Probateury Rentestions (Black I)* See page 22 for Hanford NEPA Screening Form. Problem Analysis Revision During the detailed design development, additional information was identified that modified the problem analysis. See page 12 for details. Preferred Solution Revision During the detailed design development, additional information was identified that modified the preferred solution. See page 12 for details. Functional Regulerments, Design Criteria, and Acceptance Criteria (Block 9)* Design Criteria -1. Needle valves will be used to provide flow control during sampling. Valves having flow characteristics that are similar to the valves currently used at ETF are preferred. (Swagelok -SS-26VS8, 22-1VS8, SS-1RS8 and SS-1VS4 are currently used for similar sample flow control). 2. Valves/plug combination will be located for convenient, simultaneous use by ETF Operators. There will be sufficient room for a catch bucket and sample container under the plug. Easily removed plugs will be used, when possible to facilitate sample collection. 4. Piping, fittings and jointing methods will meet the requirements of ASME B31.3, Category D fluid service and Pipe Code 153T, in accordance with ETF Pipe Class Specification (Adtechs S-136H-001), except wall thickness of tubing used may be 0.035" for 1/4" and 3/8" tubing, and 0.049" for 1/2" tubing; and tell-tale plugs downstream of sampling points may be clamped flexible tubing. 5. Pipe and fitting sizes will be at least 1/4" diameter Acceptance Criteria --1. Design meets the design criteria. Detailed Conceptual Design Document Required? (Block 11) Yes [X] No Design Authority KH Bergsman KH Bugsman 1/11/02 (If Conceptual Design Document Required) Engineering Management

^{*}Hlock numbers refer to block numbers on the FMP Flowchart (HNF-PRO-2001, Appendix A) and procedure steps within HNF-PRO-2001.

HNF-FMP-_01_ - 9507_ -R_0_ Page 12_ of 30

FMP-8 (Facility Modification Package - Continuation Page)

FMP Section

Problem Analysis Revision

During the detailed design development, additional information was identified that modified the preferred solution.

- quick-disconnect plugs are used at numerous locations throughout the ETF. Those that are spring-loaded require significant force to separate the pieces. If the valve upstream of the quick-disconnect plug leaks, the downstream tubing will accumulate liquid. Then when the quick-disconnect plug is opened by the required force, the contained liquid will be thrown free, creating a small liquid spill and possibly contaminating the people removing the plug. Use of a plug that disengages easily and without the use of tools, such a cam locking plug or a clamped tube (a tell-tale) would minimize this contamination issue without hindering sample collection.
- 2. the piping used to obtain samples of the UV/OX outlet flow and the CT slurry have similar concerns. For the UV/OX outlet flow, a 3/8" ball valve is used for flow control during the periodic sampling, while for the CT slurries, ½" ball valves are used. Using a needle valve with an easily removed plug would improve control when taking these samples too. Because of the potential for the particulate in the CT slurries to plug the needle valve, these needle valves should be easily removable.
- 3. adding a needle valve downstream of a ball valve, rather than replacing a ball valve with a needle valve, provides better, positive shutoff. Existing ball valves should be left in service, unless this unduly complicates the modification.
- 4. the flow from the existing PDM inlet sample point is controlled with a ½" needle valve. Using ½" needle valves with the same flow characteristics as the inlet valve, rather than the ½" needle valves initially identified, will eliminate potential operator confusion on how far the needle valves need to be opened to safely obtain the sample.

Preferred Solution Revision

The proposed solution is to

- a. add 1/2" needle valves on the PDM column outlet flows, downstream of the existing ball valves.
- b. add 3/8" needle valves on the CT slurry sample points, downstream of the existing ball valves.
- c. add a 1/4" needle valve, on the UV/OX outlet flow, downstream of the existing ball valves.
- d. add easily removable plugs, downstream of each needle valve.

HNF-FMP-_01 -R_0 Page 13 of 30

EMP-7 (Eschicy Modification Package - Design Verification) busyn Verification Becard Oblick 1554 [See driving, calculations, specifications, and other forgo products] Design Verification Method (Select method(s) and provide explanation of how to be performed): [X] Peer Review [] Alternate Calculations [] Qualification Testing KH Bergman KH Buspanian Date 1/11/2 Durge Verification Design within spirited in Pap-6. (Pii)	Betailed Besign Verification) our specification and other design products; deprovide explanation of how to be performed): [] Formal Design Review [] Qualification Testing Date
Durin muits high outine provided in FA	

^{*}Block numbers refer to block numbers on the FMP Flowchart (HNF-PRO-2001, Appendix A) and procedure steps within HNF-PRO-2001.

HNF-FMP-_01__-9507__-R_0_ Page _/4_ of 30

PMP-8 (Facility Modification Package -- Continuation Page)

FMP Section

Inspection and Acceptance

Examination shall be in accordance with ASME B31.3 Paragraph 341.4.2

Verify materials and components comply with specifications and are free of defects by visual examination of a sufficient number necessary to satisfy the examiner. Verify materials and components are of the specified grade through the use of certifications, records, or other evidence.

Verify erected piping contains no defects requiring repair or replacement and there are no deviations from the intent of the design evident. Include a random visual examination of threaded, bolted and other non-welded type joints to verify compliance to the applicable requirements of ASME B31.3 Paragraph 335.


Leak testing shall be in accordance with ASME B31.3 Paragraph 345.7

Perform an initial service leak test at normal operating pressure and temperature for a minimum of 10 minutes. Examine all joints and connections for leaks. Record the test fluid in the work package. Verify there are no leaks.

HNF-FMP-01-9507-R0 Page 15 of 30 FMP-8 (Facility Modification Package — Continuation Page) DWG-1 Page 1 of 2 FMP Section H-2-89332 SH 1 ZONE B6 REVISE AS SHOWN IN CLOUDED AREA (ADD NEEDLE VALVES) SEE SKETCH-1 PAGE 1 of 1 THIS FMP FOR MATL CHANGES "IS" **∆**2x1 -600 - 318 - 1535**X**60D-405 -**○**-| ∯-D-3x2 2×3/4 H2 O2 DECOMPOSER H2O2 DECOMPOSER 60D-CO-1B 60D-CO-1A 500-401 60D-411 P 150 T 180 P 150 T 180 3x2 3x2 60D-414 AREA OF CHANGE "WAS" •**₹**60D−405 -다| 3x2 2x1-1/2 2×1/2 H2 D2 DECOMPOSER H202 DECOMPOSER 60D-404 3x2|60D-50D-411 P 150 T 180 P 150 T 180 60D-455 3×2 3×2 600-414 600-402


FMP-8 (Facility Modification Package - Continuation Page) Page 2 of 2 DWG-1 FMP Section H-2-89332 SH 1 ZONE F4 REVISE AS SHOWN IN CLOUDED AREA (ADD 3/4x1/2 REDUCER AND ADD NEEDLE VALVE) SEE SKETCH 2 PAGE 1 of 1 THIS FMP FOR MATL CHANGES "IS" V-SP60D006 AREA OF 600-006 3 -60D-003-153S 3/4x1/2 CHANGE -SP60D006-F -**□** 3x2 V-SP600006 V-SP60D006-G FLOW PROPORTIONAL V-SP60D006-E SAMPLER V-SP60D006-A SP-60D006 •¥V-SP60D006-B V-SP600006-D -SP60D006-K V-SP60D006~C 600-005 3/4x1/23/4x1/2 3x3/4 V-SP60D006-H V--AIT60D005-F "WAS" V-SP60D006 800 = 006 3 -60D-003-15<u>3</u>S 3/4x1/23/4x1/2 SP600006-F V-SP60D006-I V-SP60D006-G FLOW PROPORTIONAL SAMPLER V-SP600006-A V-SP60D006-E SP-600006 **-**¥v-sp60D006-8 V-SP600006-D V-SP60D006-K V-SP60D006-C 60D-005 3/4x1/2 V-SP60D006-H 3/4x1/2 3x3/4 V-AIT60D005-F

HNF-FMP-01-9507-R0 Page 17 of 30 FMP-8 (Facility Modification Package - Continuation Page) DWG-2 Page 1 of 1 FMP Section H-2-88977 SH 1 ZONE E7 REVISE AS SHOWN IN CLOUDED AREA (ADD 1/2x1/4 REDUCER AND ADD NEEDLE VALVE) SEE SKETCH-3 PAGE 1 of 1 THIS FMP FOR MATL CHANGES "IS" P 120 T 120 AREA OF CHANGE V-AIT60C102-G 1/2x1 **♥** 3/4x3/8 "WAS"




HNF-FMP-01-9507-R0 Page 18 of 30 FMP-8 (Facility Modification Package - Continuation Page) DWG-3 Page 1 of 1 FMP Section H-2-89351 SH1 ZONE E3 REVISE AS SHOWN CAP SCREWED
OR QUICK DISCONNECT
OR TELL TALE WITH CLAMP "IS" CAP SCREWED "WAS" OR QUICK DISCONNECT H-2-88988 SH 1 ZONE F8 ADD VALVE V-16 AND V-17 AS SHOWN V-16 = V-AIT60J012A-G ZONE C6 V-17 = V-AIT60J012B-G, ZONE C3 H-2-88988 SH 1 ZONE C6 AND C3 REVISE AS SHOWN IN CLOUDED AREA (ADD NEEDLE VALVE WHITEY 3/8 -SS-1VS6 AND 3/8 O.D. TUBING CODE 153T) ADDITIONAL SUGGESTED PARTS 3/8 INSERT SWAGELOK SS-605-4 TYGON TUBING 3/8 OD x 1/4 ID AND TUBE CLAMP AREA OF CHANGE "IS"

"WAS"




60J-060 60J-048

60J-004



HNF-FMP-01-9507-R0 Page /9 of 3C

FMP-8 (Facility Modification Package - Continuation Page) Sketch-2 Page 1 of 1 FMP Section NOT FOR DRAWING INCORPORATION NOTES 1) FIELD ROUTE AND SUPPORT TUBING APPROXIMATE AS SHOWN ADJUSTMENTS MAY BE MADE DUE TO FIELD CONDITIONS 2) SEE DWG-1 PAGE 2 OF 2 THIS FMP FOR SUPPORTING P&ID CHANGES 3) TUBE AND SUPPORT COMPONENTS MAY BE CHANGED WITH CONCURRENCE OF DA 11 11 11 11 Π 11 11 11 11 11 11 H/H Π Π 11 11 V-SP60D006-G Π Π 1/2 OD TUBING Π CODE 153T -11 11 11 11 TUBING CLAMP B-LINE Π 1/2 B2087 11 11 SLOTTED ROUND HD MACHINE SCREW H HB-LINE 1/4 x1 SRHMS Π SPRING NUT 1/4 B-LINE N224]| 11 Ш V-SP60D006-L ADD 1/2 NEEDLE VALVE 11 11 WHITEY 1/2 -SS-26VS8 علملك **ADDITIONAL** SUGGESTED PARTS INSERT SWAGELOK 11 11 1/2 SS-815-6 11 11 Z TYGON TUBING Π 1/2 OD x 3/8 ID 11 11 TUBE CLAMP CONCRETE FLOOR EVATION VIEW LOOKING SOUTH




HNF-FMP-9507-RO Page 22 of 30

	Hanford NEPA Scre For NEPA requirements see Answer questions YES or NO, and list	HNF RD-8808.
Work Item Title: PD	M Sample Valve Installation	
Work Package Number	EL 01 00686 / M	
Project Descriptson. (pl	nese limit to 6 lines)	
	valves to several MTT process ty of liquid sampling for pro-	
		_
A C Yes ■ No	INTEGRAL ELEMENTS Will work threaten to violate environmental laws, regulate	ous permits or safety requirements?
C Yes Wo	Will work zevolve countraction/expansion of waste treatm	mt, storage, dusposal facilities?
C Yes 6 No	Will hazardous substances be disturbed allowing uncontrol	iled/expermetted releases?
В	ECOLOGICAL RESOURCES	
C Yes € No	Will work affect Wetlands/Aquifars/ALE Reserve? Will work occur within 1/4 mile of Cohumbia River (Hanf	red Reach National Monument?
C You F No	Will wildlife or natural habitat be disturbed?	
	o to C. If any answer is YES, get Roological Review. NUN	A
C	CULTURAL RESOURCES	IBER. then go to C.
C Yes F No	Does the work require excavations or surface disturbing a	strutum? Obtain permit if required.
C Yes F N	Does the work require building or equipment modification	u to listed historic structures?
		to D. If any answer is YES, a Cultural Resources Review is
required. List review N	UMBER. NOTE. If as	verse ampacts are identified, go to E
P	SITE-WIDE CATEGORICAL EXCLUSION (SWCX) In evaluating potential environmental impacts, was Waste	
Yes C No	Is the work covered by SWCX?	
You No	D2 E	
If YES hat SWCX that	sypties DE prant form an	d sign, If NO Go to B
C Yee C No		r the activity? If yes provide applicable document number
If CX or BA preparation	DOE/EA- DOE/EIS- Other- m y be needed, contact FH ES 376-4373	
Signature		SWCX is not valid until any applicable Cultural/Ecological Resource Reviews are received and attached to this form
Reviewer	KHBergsman Phone. 373 346	
<u></u>	(Instator Cog. Enganeer Scheduler Planner)	of an activity under review in an EA/EIS. MAINTAIN A COPY IN THE
Совситтепся	Mukeuman Date 1302 (Manager Eav Compliance Officer FHES)	APPLICABLE PROJECT FILE OR WORK PACKAGE A-6001-497 (11/00)




Integral **Bonnet** Needle **Valves**




"O", "1" & "18" Series

FEATURES/BENEFITS



LIVE LOADED PACKING SYSTEM

- Packing nut makes external adjustments fast and easy.
- Packing springs live-load packing to reduce fugitive emissions.
- 2-piece chevron packing offers improved sealing over conventional packing designs.
- Fully supported packing reduces need for adjustment.
- ... Pressures to 5000 psig (345 bar)
- ☐ Temperatures to 450°F (232°C) with standard PFA packing; up to 600°F (315°C) with optional PEEK packing
- ☐ Panel mounting standard
- Metal-to-metal and soft seat stems
- Choice of materials 316 stainless steel, alloy 400, brass, and plated carbon steel
- Straight, angle, and cross pattern body styles
- Variety of end connections include gageable SWAGELOK $^{\textcircled{8}}$ Tube Fittings, male NPT, temale NPT, and ISO, BSP, DIN and JIS tapered pipe ends
- Onfice sizes of 0.080" ("O" Series), 0.172" ("1" Series), 0.250" ("1" Series), and 0.375" ("18" Series)
- Flow coefficients (C_v) from 0.09 to 1.80
- " Every valve is factory tested



TECHNICAL DATA

These ratings are for a standard valve having PFA packing. Optional seal materials will affect the temperature rating. See Stem Packing Seals on Page 4.

VALVE MATERIAL	STEM TYPE	TEMPERATURE RATING	PRESSURE RATING @ 100°F (38°C)
316	Metal-to- metal	-65°F to 450°F (-54°C to 232°C)	5000 psig
Stainless Steel	Kel-F	-65°F to 200°F (-54°C to 93°C)	(345 bar)
400	Metal-to- metal	-65°F to 450°F (-54°C to 232°C)	
Alloy 400	Kel-F	-65°F to 200°F (-54°C to 93°C)	
	Metal-to- metal	-65°F to 400°F (-54°C to 204°C)	3000 psig
Brass	Kel-F	-65°F to 200°F (-54°C to 93°C)	(207 bar)
Plated	Metal-to- metal	-20°F to 350°F (-29°C to 176°C)	emouen)
Carbon Steel	Kel-F	-20°F to 200°F (-29°C to 93°C)	

WORKING PRESSURE

	ANSI	GROUP	2.	2	N,	/A	N,	/A	3.	4
N	CLAS	L NAME S (ANSI)	316 20		Bra N		Ste N,		Alloy 15	
TEMPERATUR	RE@ PRI	SSURE	psig	bar	psig	bar	psig	bar	psig	bar
	(100°F	(38°C)	5000	345	3000	207	3000	207	3000	207
	200°F	(93°C)	4295	296	2350	162	2730	188	2640	182
-65°F (-54°C) to	300°F	(148°C)	3875	267	2050	141	2660	183	2470	170
-05 1 (-54 0) 10	350°F	(176°C)	3715	256	1470	101	2615	180	2430	167
	400°F	(204°C)	3560	245	390	27	-	-	2390	165
	450°F	(232°C)	3435	238	-	-	-	-	2380	164

Carbon steel valves are rated at a low temperature of -20°F (-29°C).

To determine kPa, multiply psig by 6.89. For complete information on ANSI Class ratings, refer to *Technical Bulletin No.4*.

© 1987, 1988, 1990, 1993, 1994 Swagelok Co., all rights reserved

Pressure ratings for tubing used with SWAGELOK Tube Fitting ended valves are determined by the tubing material and wall thickness. Please see the Tubing Data sheet, located in subsection 5 Technical Information of your Master Product Binder. It contains suggested working pressures for various tubing sizes, materials and wall thicknesses.




A SWAGELOK COMPA

WHITEY Co.

318 Bishop Rd., Highland Heights, OH 44143 U.S.A.

HNF-FMP-9507-RO Page 24 of 30

MATERIALS OF CONSTRUCTION
Knob handles are standard on the "O" and "1" Series Valves. Bar handles are standard on the "18" Series Vaives. Optional handles are available on all series -Refer to Page 4 for selection and ordering information.



Wetted parts numbered in red.

Lubrication: Tungsten disulfide and fluorocarbon base.

T	FC	TI	N	G

Standard Production Test - Every valve is factory tested @ 1000 psig (68 bar) for leakage at the seats to a maximum allowable leak rate of 0.1 scc/min. The packings are tested for no detectable leakage.


Optional Hydrostatic Test - This hydrostatic shell test is performed with deionized water at 1-1/2 times the working

Other optional tests are available. Consult your Authorized SWAGELOK Sales & Service Representative.


			VALVE BODY	Y MATERIA	LS
		316SS	Brass	Steel	Alloy 400
		G	RADE/ASTM	SPECIFICA	TION
1a	Bar Handle		Alum	ninum	
1b	Knob Handle		Phe	nolic	
2	Handle Pin			1	
3	Set Screw		51	eel	
4	Packing Nut	316SS/A276	Brass 360/B16	12L14/A108	Alloy R-405/B164
5	Gland ²		Stainle	ss Steel	
6	Packing Springs ¹		17-7P	H/A693	
7	Packing Gland		316SS/A276	, A167, B783	
8	Upper Packing				
9	Lower Packing		P	FA	
10	Lower Gland		316SS/A167		Alloy 400/B127
11a	Regulating Stem				
11b	Vee Stem		316SS/A276		Alloy R-405/B164
11c	Soft Seat Stem				N-400/8104
12	Stem Tip (Soft Seat)		Kel-F	(CTFE)	
13	Panel Nut	Stainless Steel	Brass 36	60/B16	Stainless Steel
14	Body	316SS/A182	Brass 377/B283	11L17/A108	Alloy 400/B564

² Utilized in valves with the following onlice size: 0.080 and 0.172 in. (2.0 and 4.4 mm).

FLOW COEFFICIENT (Cv) @ TURNS OPEN



"18" Series



³ Number of springs will vary depending on valve series.




TABLE OF DIMENSIONS

BASIC	ORI	FICE		CONNEC	TION SIZE				D	IMENSION	NS (inche	(S)	1000	2007	1012
ORDERING NUMBER	in.	mm	C,	INLET	OUTLET	A	В	B1	B2	C	D	E	F	G	OPE
-ORF2 ·				1/8 Fen	nale NPT	1.88	.94	.94	.94	1.25					
-ORM2				1/8 M	ale NPT	1.50	.75	.75	.75	1.06	ENGINE .	7	320-16	3 (3)	10.1
-ORM2-S2	0.080	2.0	0.09	1/8 Male NPT	1/8 SWAGELOK	1.72	./5		./5		.44	.31	1.00	.47	2.29
-ORS2	MAX	1		1/8 SW	AGELOK	1.94	.97	.97	.97	1.28			100		
-ORS3MM				3mm SV	VAGELOK	1.54	.97		.57						
-1RF2				1/8 Fen	nale NPT	1.62	.81	.81	.81	1.19					
-1RM2				1/8 M	ale NPT	1.02	.01	.61	.01	1.19					
-1RM4				1/4 M	ale NPT	1.96	.98	.98	.98	1.36	Mile View		Beauty		
-1RM4-S4	0.172	4.4	0.37	1/4 Male NPT	1/4 SWAGELOK	2.11	.98		.98		.44	.38	1.38	.53	2.34
-1RS6MM	800		100	6mm SV	VAGELOK		1.13	1.13	1.13	1.51				-	
-1RS4				1/4 SW	AGELOK	2.26	1.13		1.13					910	1
-1RS8MM				8mm SV	VAGELOK	2.34	1.17	1.17	1.17	1.55					
-1RF4				1/4 Fen	nale NPT	0.40	4.00		4.00						
-1RF4RT®		100	1	1/4 ISO Fer	nale Tapered	2.12	1.06	1.06	1.06	1.56	Maria III				
-1RM4-F4				1/4 Male NPT	1/4 Female NPT	2.19								Con Section	
-1RM4-S6			E ATTE	1/4 Male NPT	3/8 SWAGELOK	2.42		1.29		1.79	.50				Labor 1
-TRM6				3/8 M	ale NPT	2.26	1.13	1.13	1.13	1.63					laca.
-1RM6-S6	0.250	6.4	0.73	3/8 Male NPT	3/8 SWAGELOK	2.42	100	1.29		1.79		.50	1.88	.78	2.81
-1RM6-S8				3/8 Male NPT	1/2 SWAGELOK	2.53		1.40		1.90	.56				
-1RS10MM				10mm S	WAGELOK	2.60	1.30	1.30	1.30	1.80				- 3	1000
-1RS6	1			3/8 SW	AGELOK	2.58	1.29	1.29	1.29	1.79	.50				
-1RS12MM	1			12mm S	WAGELOK										
-1RS8	1			1/2 SW	AGELOK	2.80	1.40	1.40	1.40	1.90	.55	lek in the			
-18RF6				3/8 Fen	nale NPT			1000	DE CHEI						
-18AF6AT®				3/8 ISO Female Tapered		e usi			- 1110		Para la				
-18RF8				1/2 Fen	nale NPT		380			100				1	
-18RF8RT®				1/2 ISO Fer	nale Tapered	3.00	1.50	1.50	1.50	2.25		-			
-18RM8	0.375	9.5	1.80	1/2 M	ale NPT						.75	.75	3.00	1.03	3.91
-18RM8-F8				1/2 Male NPT	1/2 Female NPT				I VOCE	0000	100-12			g make	1
-18RS8		1 1 1 1		1/2 SW	AGELOK			400							
-18RS12				. 3/4 SW	AGELOK	3.80	1.90	1.90	1.90	2.65					

© Valves with RT ends conform to ISO 7/1. The following are various descriptions of the 7/1 thread: DIN-2899, BS 21, and JIS 80203. Consult your Authorized SWAGELOK Sales & Service Representative for further information.

ORDERING INFORMATION

Materials: Use B for brass, SS for 316 stainless steel, S for carbon steel, or M for alloy 400 as a prefix to the Basic Ordering Number. Example: §-1RF4

Stems: Basic Ordering Numbers specify Regulating stems (R). For a Vee stem, replace the R with V; for a Kel-F stem, replace the R with K. Example: SS-1<u>V</u>S4

Patterns: To order angle pattern valves, use -A as a suffix to the Ordering Number. Example: SS-1RF2-A. Some of the above valves are available in a cross pattern. Cross pattern valves offer uninterrupted flow between side ports at all times; on-off or metered flow through bottom port. Contact your Authorized SWAGELOK Sales & Service Representative for more information.

Dimensions shown with SWAGELOK nuts finger-tight, where applicable. All dimensions are for reference only, subject to change.

SOUR GAS SERVICE

Materials for wetted valve components are selected in accordance with N.A.C.E. standard MR0175-94 for sulfide stress cracking resistant materials. Stem and lower gland are alloy 400 or alloy R-405. To order, use -SG as a suffix to the valve Ordering Number. Example: SS-ORF2-SG

For information on the use of stainless steel instrument tube fittings in sour gas service, please refer to the N.A.C.E. MR0175-94 specification.

CAUTION:

Do not mix or interchange parts with those of other manufacturers

HNF-FMP-9507-RO Page 26 of 30

OPTIONS/ACCESSORIES

STEM PACKING SEALS

Factory-Assembled in Valve

Valves are standard with a two-piece chevron style PFA packing. Optional packing materials are described below.

UHMWPE (Ultra-high Molecular Weight Polyethylene) is intended for service where fluorocarbons are not acceptable. Maximum temperature rating is 250°F (121°C). To order valves with factory assembled UHMWPE seals, use -P as a suffix to the valve Ordering Number. Example: SS-1RF4-P

PEEK (Polyetheretherketone) is a two-piece chevron packing which can extend the valve's temperature rating.

316 stainless steel: -65°F to 600°F @ 3130 psig (-54°C to 315°C @ 215 bar)

Alloy 400: -65°F to 500°F @ 2375 psig (-54°C to 260°C @ 163 bar) Carbon steel and brass valve ratings do not change.

To order valves with factory-assembled PEEK seals, use -PK as a suffix to the valve Ordering Number. Example: SS-1RS4-PK

Stem Packing Kits

PFA, UHMWPE and PEEK packing kits are available. Kits contain stem packings, springs, lubrication, and instructions.

VALVE SERIES	ORIFICE	PACKING KIT ORDERING NUMBERS						
	SIZE	PFA	UHMWPE	PEEK				
.O.	0.080*	PFA-91K-O	PE-91K-O	PK-91K-O				
-1-	0.172*	PFA-91K-14	PE-91K-14	PK-91K-14				
-1-	0.250*	PFA-91K-16	PE-91K-16	PK-91K-16				
18	0.375*	PFA-91K-18	PE-91K-18	PK-91K-18				
	Lubrication:	Tungsten disulfide and fluorocarbon base	Molybdenum disulfide and hydrocarbon base	Molybdenum disulfide, Tungsten disulfide, and fluorocarbon base				

HANDLES

Factory-Assembled to Valve

The "O" and "1" Series Valves are standard with black phenolic knob -handles. To order valves with colored handles factory-assembled, use the desired color designator in the chart below as a suffix to the valve Ordering Number. Example: SS-1RF4-GR. To order valves with black aluminum bar handles factory-assembled, use -BKB as a suffix to the valve Ordering Number. Example: SS-ORS2-BKB

VALVE SERIES	COLOR DESIGNATORS							
	BLUE	GREEN	ORANGE	RED	YELLOW			
"O" & "1"	-BL	-GR	-OG	-RD	-YW			

The "18" Series Valve is standard with a black aluminum bar handle. To order valves with black phenolic knob handles, use -BKP as a suffix to the valve Ordering Number. Example: SS-18RF8-BKP

To order valves with 316 stainless steel bar handles, for all series, use -SH as a suffix to the valve Ordering Number. Example: M-1RS4-SH

Handles as Spare Parts

To order handles as spare parts, reference chart below.


		ORDERING NUMBERS						
VALVE SERIES	ORIFICE SIZE	BLACK PHENOLIC KNOB	BLACK ALUMINUM BAR	316 STAINLESS STEEL BAR				
"O"	0.080"	PH-5K-OK-BK [©]	A-5K-14B-BK	SS-5K-14B				
-1-	0.172*	PH-5K-14K-BK ⁵	A-5K-14B-BK	55-5K-14B				
"1"	0.250	PH-5K-4K-BK [₹]	A-5K-6NB-BK	SS-5K-6NB				
"18"	0.375"	PH-5K-7K-BK	A-5K-18B-BK	SS-5K-7B				

To order colored phenolic knob handles, replace -BK in the Ordering Number with one of these color designators: -BL (Blue), -GR (Green), -OG (Orange), -RD (Red), -YW (Yellow).

Example: PH-5K-14K-BL

O-RING STEM SEALS

O-Ring Stem Seals are available for special applications, factory assembled in the valve or as a maintenance kit. Conversion requires a special gland, back-up ring, and O-Ring.



Factory-Assembled in Valve

To order valves with factory-assembled O-Ring Stem Seals, use the desired O-Ring material designator listed below as a suffix to the valve Ordering Number. Example: SS-1RM4-BC

Viton A: -V

Buna N: -B

Silicone: -SI Kalrez: -KZ

Buna C: -BC Ethylene Propylene: -E

O-Ring Stem Seal Kits

These kits are to maintain valves having O-Ring seals. Each kit contains O-Ring(s), back-up ring, and lubrication. Kits are standard with a TFE back-up ring, except the Ethylene Propylene kit, which has a polyethylene back-up ring.

To order, combine Material, Kit, and Valve Designators from chart below. Example: VA70-9K-16

O-RING MATERIAL	MATERIAL DESIGNATOR	TEMPERATURE RATING	KIT DESIGNATOR	VALVE DESIGNATOR	
Viton A	VA70	-20°F to 450°F			
Kalrez	KZ70	(-29°C to 232°C)			
Buna N	BN70		1	O (0.080") 14 (0.172") 16 (0.250")	
Silicone	S170	-20°F to 250°F (-29°C to	-9K-		
Ethylene Propylene	EP70	121°C)	31	18 (0.375*)	
Buna C	BC70	-65°F to 250°F (-54°C to 121°C)			

SAFE COMPONENT SELECTION


When selecting a component, the total system design must be considered to ensure safe, trouble-free performance, Component function, materials compatibility, adequate ratings, proper installation, operation and maintenance are the responsibility of the system designer and user.

Kel-F - TM 3M Company/ Viton, Kalrez - TM DuPont/ 17-7PH - TM Armco Steel



Your Local Authorized SWAGELOK Sales & Service Representative:

Printed in U.S.A. August 199)



TECHNICAL DATA

These ratings are for a standard valve having PFA packing. Optional seal materials will affect the temperature rating. See Stem Packing Seals on Page 4.


VALVE MATERIAL	STEM TYPE	TEMPERATURE RATING	PRESSURE RATING @ 100°F (38°C)	
316 Stainless	Vee	-65°F to 450°F (-54°C to 232°C)	6000 psig	
Stainless Steel	Kel-F	-65°F to 200°F (-54°C to 93°C)	(413 bar)	

TESTING

Standard Production Test-Every valve is factory tested with nitrogen @ 1000 psig (68 bar) for leakage at the seat to a maximum allowable leak rate of 0.1 scc/min. The packings are tested for no detectable leakage.


Optional Hydrostatic Test-This hydrostatic shell test is performed with deionized water at 11/2 times the working pressure.


Other optional tests are available. Consult your Authorized SWAGELOK Sales & Service Representative.






Integral **Bonnet** Needle **Valves**





FEATURES/BENEFITS



LIVE LOADED PACKING SYSTEM

- Packing nut makes external adjustments fast and easy.
- Packing springs liveload packing to reduce fugitive emissions.
- 2-piece chevron packing offers improved sealing over conventional packing designs.
- I Fully supported packing reduces need for adjustment.
- 및 Pressures to 6000 psig (413 bar)
- □ Temperatures to 450°F (232°C) with standard PFA packing; up to 600°F (315°C) with optional PEEK packing
- Soft seat or metal-to-metal shut-off
- ☐ Rugged 316 stainless steel construction
- El Straight and angle pattern body styles
- SI Variety of end connections include gageable SWAGELOK® Tube Fittings, male NPT, female NPT, and ISO, BSP, DIN and JIS tapered pipe ends
- Orifice sizes of 0.080" ("20K" Series), 0.125" ("20V" Series) and 0.250" ("26" Series)
- Flow coefficients (C_v) from 0.09 to 0.73
- El Every valve is factory tested

WORKING PRESSURE


ANSI GROUP		2.	2
MA	316SS 2500		
TEMPERATURE	psig	bar	
-65°F (-54°C) to	100°F (38°C) 200°F (93°C)	6000 5160	413 355
	300°F (148°C) 350°F (176°C)	4660 4470	321 308
	400°F (204°C) 450°F (232°C)	4280 4130	294 284

To determine kPa, multiply psig by 6.89.

For complete information on ANSI Class ratings, refer to Technical Bulletin No. 4.



WHITEY Co. 318 Bishop Road Highland Heights, Ohio 44143, U.S.A. HNF-FMP-9507-RD



Page 28 of 30 MATERIALS OF CONSTRUCTION

A knob handle is standard on the "20K" Series Valve. A bar handle is standard on the "20V" and "26" Series Valves. Optional handles are available. Refer to Page 4 for selection and ordering information.


	GRADE/ASTM SPECIFICATION
1a Knob Handle	Aluminum
1b Bar Handle	316SS/A276
2 Handle Pin	17-4PH/A564
3 Set Screw	17-4PH/A304
4 Packing Nut	316SS/A276
5 Gland ^D	Stainless Steel
6 Packing Springs ²	17-7PH/A693
7 Packing Gland	316SS/A276, A167
8 Upper Packing	DEA
9 Lower Packing	PFA
10 Lower Gland	316SS/A167
11a Stem (Vee)	04000/4070
11b Stem (Soft Seat)	316SS/A276
12 Stem Tip (Soft Seat)	Kel-F(CTFE)
13 Body	316SS/A479

Utilized in "20" Series Valves


Wetted parts numbered in red.

Lubrication: Tungsten disulfide and fluorocarbon based.

FLOW COEFFICIENT (C_v) @ TURNS OPEN



² Number of springs will vary depending on valve size.



	ORIFICE			CONNECTION SIZE		No.			DIMEN	SIONS	(inches)															
ORDERING NUMBER	in.	mm	Cv	INLET	OUTLET	A	В	B1	c	D	E	F	G	OPEN													
SS-20KF4				1/4 Fer	nale NPT	1.88	.94	.94	70-C	-			-														
SS-20KM4	0.080			1/4 M	ale NPT	1.94	.97	.97	-	-	.42	1.130	-	1.66													
SS-20KM4-F4	0.080	2.0	0.09	1/4 Male NPT	1/4 Female NPT	1.91	.97	.94	-	-		1.13	-	1.00													
SS-20KM4-F4-A			100	1/4 Male NPT	1/4 Female NPT	-	-	1.00	1.44	.44	-		1.03														
SS-20VF4	The state of			1/4 Fer	nale NPT	1.88	.94	.94	-	-	.42	BARTER	10-	11047													
SS-20VF4-A				1/4 Fer	nale NPT	-	-	1.00	1.44	.44	-	No. Visit	1.00	SDE													
SS-20VF4RT®	0.125 3.2	1			1/4 ISO Fer	male Tapered	1.88	.94	.94	-	-			-													
SS-20VM4		1		1/4 M	ale NPT	1.94	.97	.97	-	-	.42		-	10													
SS-20VM4-F4		0.125	0.125	0.125	0.125	0.125	0.125	0.125	0.125	0.125	0.125	0.125	0.125	0.125	0.125	0.125	3.2	0.21	1/4 Male NPT	1/4 Female NPT	1.91	.9/	.94	-	OF THE PARTY OF TH	1.75	-
SS-20VM4-F4-A				1/4 Male NPT	1/4 Female NPT	-	-	1.00	1.44	.44	-		1.03														
SS-20VM4-S4-A			-	1/4 Male NPT	1/4 SWAGELOK	-	-	1.13	1.57	.44	-		1.03	Di te O													
SS-20VS4										-	1/4 SW	AGELOK	2.46	1.23	1.23	-	-	.42		-	aeno o 7						
SS-20VS4-A														1/4 SW	AGELOK	-	-	1.13	1.57	.44	-		1.17	Agree .			
SS-26VF6		200		3/8 Fer	nale NPT		0.50	0.50	0.50				0.50	105	-	-		9	-								
SS-26VF8		700		1/2 Fer	nale NPT	2.50	1.25	1.25	-	-	.66		-														
SS-26VF8-A				1/2 Fer	nale NPT	-	-	1.40	2.06	.66	-	115	1.41	Post													
SS-26VF8RT®			1/2 ISO Female Tapered	nale Tapered	0.50	4.05	105	-	-			-															
SS-26VM6-F6				3/8 Male NPT	3/8 Female NPT	2.50	1.25	1.25	-	-	.66		-														
SS-26VM6-F6-A	0.250 6.4	0.250	6.4	0.73	3/8 Male NPT	3/8 Female NPT	-	-	1.40	2.06	.66	-	2.50	1.22	2.31												
SS-26VM8-F8				1/2 Male NPT	1/2 Female NPT	2.55	1.30	1.25	-	-	.66		-														
SS-26VM8-F8-A				1/2 Male NPT	1/2 Female NPT	-	-	1.40	2.06	.66	-		1.41														
SS-26VM12-F8		100	la all	3/4 Male NPT	1/2 Female NPT	2.50	1.25	1.25	-	-			-	-													
SS-26VS6	1 10	CS LAU		3/8 SW	AGELOK .	3.08	1.54	1.54	-	-	.66	10.28 9	-	MED Y SE													

1/2 SWAGELOK

³ Dimension for aluminum knob handle.
⁴ Valves with RT ends conform to ISO 7/1. The following are various descriptions of the 7/1 thread: DIN-2999, BS 21, and JIS B0203. Consult your Authorized SWAGELOK Sales & Service Representative for turther information.

Ordering Information

Stems: "20K" Series Valves are available with Kel-F stem tips only. "20V" Series Valves are available with Vee stem tips only. Ordering Numbers for "26" Series Valves specify a Vee stem (V). For a Kel-F stem tip, replace the V with K. Example: SS-26KF8

CAUTION:

SS-26VS8

Do not mix or interchange parts with those of other manufacturers.

Dimensions shown with SWAGELOK nuts tinger-tight, where applicable All dimensions are for reference only, subject to change.

Sour Gas Service

1.65

1.65

Materials for wetted valve components are selected in accordance with N.A.C.E. standard MR0175-94 for sulfide stress cracking resistant materials. Stems and lower gland are alloy 400 or alloy R-405. To order, use -SG as a suffix to the valve Ordering Number. Example: SS-20KF4-SG

For information on the use of stainless steel instrument tube fittings in sour gas service, please refer to the N.A.C.E. MR0175-94 specification.

OPTIONS/ACCESSORIES

STEM PACKING SEALS

Factory-Assembled in Valve

Valves are standard with a two-piece chevron style PFA packing. Optional packing materials are described below.

UHMWPE (Ultra-High Molecular Weight Polyethylene) is intended for service where fluorocarbons are not acceptable. Maximum temperature rating is 250°F (121°C). To order valves with factory-assembled UHMWPE seals, use -P as a suffix to the valve Ordering Number. Example: SS-20VF4-P

PEEK (Polyetheretherketone) packing can extend the valve's temperature rating to -65°F to 600°F @ 3760 psig (-54°C to 315°C @ 259 bar).

To order valves with factory-assembled PEEK seals, use -PK as a suffix to the valve Ordering Number. Example: SS-26VF8-PK

Stem Packing Kits

PFA, UHMWPE and PEEK packing kits are available. Kits contain stem packings, springs, lubrication, and instructions.

VALVE	PACKING KIT ORDERING NUMBERS						
SERIES	PFA	UHMWPE	PEEK				
"20V" & "20K"	PFA-91K-O	PE-91K-O	PK-91K-O				
"26V" & "26K"	PFA-91K-16	PE-91K-16	PK-91K-16				
Lubrication:	Tungsten disulfide and fluorocarbon base	Molybdenum disulfide and hydrocarbon base	Molybdenum disulfide, Tungsten disulfide, and fluorocarbon base				

HANDLES

Factory-Assembled to Valve

The "20K" Series Valve is standard with a black aluminum knob handle. The "20V" and "26" Series Valves are standard with a 316 stainless steel bar handle. All three series can be ordered with factory-assembled colored phenolic knob handles by using the desired color designator listed below to the valve Ordering Number.

Example: SS-20VF4-GRP

-BKP (Black)

-BLP (Blue)

-GRP (Green)

-OGP (Orange)

-RDP (Red)

-YWP (Yellow)

To order a "20K" Series Valve with a 316 stainless steel bar handle, use -SH as a suffix to the valve Ordering Number.

Example: SS-20KF4-SH

Handles as Spare Parts

To order handles as spare parts, reference chart below.


	ORDERING NUMBERS				
VALVE SERIES	BLACK PHENOLIC KNOB ⁵	316 STAINLESS STEEL BAR			
"20V" & "20K"	PH-5K-14K-BK	SS-5K-14B			
"26V" & "26K"	PH-5K-4K-BK	SS-5K-6NB			

² To order colored phenolic knob handles, replace -BK in the Ordering Number with one of these color designators: -BL (Blue), -GR (Green), -OG (Orange), -RD (Red), -YW (Yellow). Example: PH-5K-4K-BL

To order black aluminum knob handles for the "20K" Series Valve, use Ordering Number A-5S-20K-BK.

O-RING STEM SEALS

O-Ring Stem Seals are available for special applications, factory-assembled in the valve or as a maintenance kit. Conversion requires a special gland, back-up ring, and O-Ring.



Factory-Assembled in Valve

To order valves with factory-assembled O-Ring Stem Seals, use the desired O-Ring material designator listed below as a suffix to the valve Ordering Number. Example: SS-20VM4-<u>V</u>

Viton A: -V

Buna N: -B

Silicone: -SI

Buna C: -BC

Ethylene Propylene: -E

Kalrez: -KZ

O-Ring Stem Seal Kits

These kits are to maintain valves having O-Ring seals. Each kit contains O-Ring(s), back-up ring, and lubrication. Kits are standard with a TFE back-up ring, except the Ethylene Propylene kit, which has a polyethylene back-up ring.

To order, combine Material, Kit, and Valve Designators from chart below. Example: VA70-9K-O

O-RING MATERIAL	MATERIAL DESIGNATOR	TEMPERATURE RATING	KIT DESIGNATOR	VALVE DESIGNATOR		
Viton A	VA70	-20°F to 450°F	-20°F to 450°F			
Kalrez	KZ70	(-29°C to 232°C)				
Buna N	BN70			O (0.080°		
Silicone	SI70	-20°F to 250°F	-9K-	& 0.125")		
Ethylene Propylene	EP70	(-29°C to 121°C)		16 (0.250")		
Buna C	BC70	-65°F to 250°F (-54°C to 121°C)				

SAFE COMPONENT SELECTION

When selecting a component, the total system design must be considered to ensure safe, trouble-free performance. Component function, materials compatibility, adequate ratings, proper installation, operation and maintenance are the responsibility of the system designer and user.

Kel-F - TM 3M Company/Viton, Kalrez - TM DuPont/17-4PH, 17-7PH - TM Armco Steel




Your Local Authorized SWAGELOK Sales & Service Representative:

Printed in U.S.A SP (E) July 1999

Part III Chapter 4 and Attachment 34 Liquid Effluent Retention Facility and 200 Area Effluent Treatment Facility

Appendix 4A Table 4A 2



FAGINFEDIA OLIANOF NOTICE		1 ECN	647892
ENGINEERING CHANGE NOTICE	Page 1 of 3:3	Proj ECN	


(mark one)	3 Originator s Name and Telephone No	Organization MSIN	4 USQ Requi	red?	5 Date
Supplemental [X] Direct Revision []	AF Crane, 32230, S6-72, 372-3152		[] Yes [X] No	09/21/98
Change ECN D	6 Project Title/No	/Work Order Ko	7 Bldg /Sys	s /Fac No	8 Approval Designator
Standby 🛛	Access Stairs/A4055		2025E		N/A
Supersedure [] Cancel/Vold []	9 Document Numbers Changed by this ECN (includes sheet no and rev)		10 Related ECN No(s)		11 Related PO No
	See Blk 13a		N/A		N/A
12a Modification Work	12b Work Package No EL-98-	12c Modification Work	Complete		ed to Original Condi or Standby ECN only) N/A
[X] Yes (fill out Blk 12b)	00588/M			}	"/^
[] No (NA Blks 12b 12c 12d)	07C.	Design Authority/Cog Engineer Signeture & Date		Design Authority/Cog Engineer Signature & Date	
13a Description of Change		13b Design Baseline	Document?	X] Yes [No
H-2-89033, Sh 1, Re		H-2-89063, Sh 1,			†
H-2-89036, Sh 1, Re		H-2-89068, Sh 1,			
H-2-89039, Sh 1, Re H-2-89040, Sh 1, Re		H-2-89069, Sh 1, H-2-89078, Sh 1,]
H-2-89044, Sh 1, Re		11-2-05070, 511 1,	NCV T		1
i i					
See Continuation SI	neet				}
]
ļ					
14a Justification (mark o	ne)				
14a Justification (mark o	ne) Design Improvement	[X] Environmental	. []	Facili	ty Deactivation []
F	=	[X] Environmental			ty Deactivation [] Error/Omission []
Criteria Change []	Design Improvement Facilitate Const	I_7			·
Criteria Change [] As Found []	Design Improvement Facilitate Const	[] Const Error/	Omission []	Design	Error/Omission []
Criteria Change [] As Found [] 14b Justification Details Installation of stairways	Design Improvement Facilitate Const is required to provide	[] Const Error/	Omission []	Design	Error/Omission []
Criteria Change [] As Found [] 14b Justification Details Installation of stairways containments Informal design review per	Design Improvement Facilitate Const is required to provide formed by RJ Kuth	[] Const Error/	Omission []	Design	Error/Omission []
Criteria Change [] As Found [] 14b Justification Details Installation of stairways containments Informal design review per 15 Distribution (include	Design Improvement Facilitate Const is required to provide formed by RJ Nuth	[] Const Error/ le mafe access when carry of copies)	Omission []	Design	Error/Omission [] ge and verification
Criteria Change [] As Found [] 14b Justification Details Installation of stairways containments Informal design review per	Design Improvement Facilitate Const is required to provide formed by RJ Nuth name MSIN and no of 72 (1)	[] Const Error/ de mafe access when carry of copies) RJ Huth S6 JM Isdell G3	70mission [] ring equipment -72 (1) -17 (1)*	Design	Error/Omission []
Criteria Change [] As Found [] 14b Justification Details Installation of stairways containments Informal design review per 15 Distribution (include MW Bowman S6-AF Crane S6-BS Darling T4-	Design Improvement Facilitate Const is required to provide rformed by RJ Nuth name MSIN and no of (2 (1) (2 (1) (1)	[] Const Error/ de mafe access when carry of copies) RJ Huth S6 JM Isdell G3 NJ Sullivan S6	70mission [] ring equipment -72 (1) -17 (1)* -72 (1)	Design	Error/Omission [] ge and verification RELEASE STAMP EP 2-5 1598 HANFORD
Criteria Change [] As Found [] 14b Justification Details Installation of stairways containments Informal design review per 15 Distribution (include MW Bowman S6-AF Crane S6-BS Darling T4-6DL Flyckt S6-	Design Improvement Facilitate Const is required to provide rformed by RJ Nuth rame MSIN and no of 72 (1) 72 (1) 71 (1)	[] Const Error/ de mafe access when carry of copies) RJ Huth S6 JM Isdell G3 NJ Sullivan S6 AK Yoakum S6	70mission [] ring equipment -72 (1) -17 (1)* -72 (1) -71 (1)	Design into the sur	Error/Omission [] ge and verification RELEASE STAMP EP 2-3-1598 HANFORD
Criteria Change [] As Found [] 14b Justification Details Installation of stairways containments Informal design review per 15 Distribution (include MW Bowman S6- AF Crane S6- BS Darling T4-	Design Improvement Facilitate Const is required to provide rformed by RJ Nuth rame MSIN and no of (2 (1) (2 (1)* (1) (1) (1)	[] Const Error/ de mafe access when carry of copies) RJ Huth S6 JM Isdell G3 NJ Sullivan S6 AK Yoakum S6	70mission [] ring equipment -72 (1) -17 (1)* -72 (1)	Design	Error/Omission [] ge and verification RELEASE STAMP EP 25 1598 HANFORD RELEASE


A 7900 013-2 (05/96) GEF095


- --


Page 2 or 2/ Ot/032 Page 2 or 2/ Ot/032 Page 2 or 2/ Ot/032
Page 2 of 2/ ENGINEERING ENGINEERING Additional [] \$ Additional [] \$ Improved the related documents (other than the engineering document in the change described in Block 13 Enter the affected document in Selando/Strees Analysis [] Suess/Design Report [] Healt [] Suess/Design Report [] Spare [] Calibration Procedure [] Comp
Page C of C/ ENGINEERING CONSTRUCTION Additional [] \$ Additional [] \$ Improved the related documents (other than the engineering document is tested by the change described in Block 13 Enter the affected document in Selando/Stress Analysis [] Suess/Design Report [] Healt Suess/Design Report [] Suess/Design Report [] Tank-Interface Control Drawing [] Test F the Addition Procedure [] Asaks
Page 2 of 2/ Page 2 of 2/
Page 2 of 2/ Page 2 of 2/ Page 2 of 2/ 18 Page 2 of 2/ 18 Additional [] \$ Additional [] \$ Imprise Savings [] \$ Dela
`


		ECN 647892
ENGINEERI	ING CHANGE NOT	TICE CONTINUATION SHEET Page 3 of 27 Date 9/21/98
H-2-89033, S	h 1, Zone D-3	Replace ladder with stairway
H-2-89036, S	h 1, Zone E-4	Replace ladder with stairway
H-2-89039, S	h 1, Zone B-4	Replace ladder with stairway & show new sidewalk
	Zone E-4	Replace ladder with stairway
H-2-89040 S	h 1, Zone B-4	Replace ladder with stairway & show new sidewalk
	Zone E-4	Replace ladder with stairway
H-2-89044, S	h 1, Zone B-4	Replace ladder with stairway & show new sidewalk
	Zone E-4	Replace ladder with stairway
'	ladder & crosso	Replace ladder with stairway Delete 8'-9" dimension and ver centerline callout Change Section 4, Dwg 89069 "See Section For Foundation Information"
	dimensions, lan	Replace ladder with starrway Delete 10'-0" & 3'-5 1/2 ding and ladder & crossover centerline callout Change "See Section For Foundation Information" with reference to tion 4
	callout Chang Foundation (Loc "Aluminum Pre-E	Add "minimum" to foundation width dimension (2'-0") e foundation text to read "Ladder Or Stairway Concrete ate In Field)" Change ladder description text to read ingineered Ship Ladder With Platform & Return, O'Keefe's Equal, Or Aluminum Pre-Engineered Stairway See VI Supp way Detail "
H-2-89078, S	h 1, Zone A-7	Change detail title to "Ladder Or Stairway Step Off Pad"
	Zone B-6	Change callout to "Ladder Or Stairway" from "Ladder"
	Zone B-7	Add "minimum" to step off pad length dimension (38")
	Zone B-8	Add "minimum" to step off pad width dimension (30")



























<u>who</u>

ECN 641892 Pg 16 05 27 H-2-69044, SH 1




BELOW GRADE


I's

ECD 647892 Pg 17 of 27


H 2-89014 SH 1




— € PIPE (-)4'-6" BELOW GRADE




ECYS CALBAS BY 18 CF ST







ECN 647892 PG ZI of 27 H 2 89065 SH 1



(Was




ECN 647892 Pg 23 of 27 H 2-89068, SH 1



7 ノエの ECO 647892 14.2 SADGA

3





ECN 647892 pg 25 of 27


4

" Was

ECY CALBUS 68 SC 06 51









SHIP'S LADDER PLAN VERIFICATION TANK


8

7

,







_

	ENGINEERING	G CHANGE NOTICE	Page 1 of	1 ECN 647892
2 ECN Category (mark one) Supplemental [X	and Telephone AF Crane, 32	3 Originator's Name Organization MSIN and Telephone No AF Crane, 32230, S6-72,		5 Date 09/21/98
Direct Revision [Change ECW [372-3152	No /Nork Order No	7 Bldg /Sys /Fac No	8 Approval Designator
Standby E	Access	Stairs/A4055	2025E	N/A
Supersadure [Gancel/Void [9 Document Number	rs Changed by this ECN t no and rev)	10 Related ECN No(s)	11 Related PO No
	Sec	Blk 13a	N/A	N/A
12a Modification Work [X] Yes (fill out Blk 12b)	12b Work Packag No EL-98- 00588/M	e 12c Modification Work		red to Original Condi or Standby ECN only) N/A
[] No (NA Biks 12b 12c 12d)	(SIC. 9/25/6	Design Authority/Cog Signature & Da		uthority/Cog Engineer ignature & Date
H-2-89039, Sh 1, H-2-89040, Sh 1, H-2-89044, Sh 1, See Continuation	Rev 2 Rev 4 Sheet	H-2-89069, Sh 1, H-2-89078, Sh 1,	Rev 4	
14a Justification (mer	-	fw1	£1	
Criteria Change []	Design Improveme	; <u> </u>	===	ity Deactivation []
As Found [] 14b Justification Data			Missian [] ocsişi	n Error/Omission []
containments Informal design review		Vioc saire abuces mion carry	reg equipment. This the ser	
AF Crane S6 BS Darling T4 DL Flyckt S6	de name MSIN and no 5-72 (1) 5-72 (1)* 4-61 (1) 5-71 (1) 5-71 (1)	of copies) RJ Huth S6- JM Isdell G3- NJ Sullivan S6- AK Yoakum S6- WCC Planning S6-	17 (1)* C 72 (1) DATE 71 (1)	RELEASE STANP EP 23 1998 HANFORD RELEASE 10:


A 7900 013 2 (05/96) GEF095


*Advance Copy

EN	CINEEDING	CHANGE		1 ECH (use no from pg 1)			
ENGINEERING CHANGE NOTICE				Page 2 of 2	7 647892		
16 Design	17 Cost Impa	ct	•		18 Schedule Impact (days)		
Verification Required	ENGINEERING CONSTRUCT			CTION	:		
[X] Yes	Additional	[] \$	Additional	[] \$	Improvement []		
[] No	Savings	[] \$	Savings	[] \$	Delay []		
19 Change Impact Review Indicate the related documents (other than the engineering documents identified on Side 1) that will be affected by the change described in Block 13 Enter the affected document number in Block 20							
that will be af		hange desc	ribed in Block 13 Enter t Seismic/Stre Analy is		Tank Calibration Manual		
Functional Design Criterio	· []		Stress/Design Report	[] []	Health Physics Procedure		
Operating Specification			Interface Control Drawing		Speres Multiple Unit Listing		
Criticality Specification	[] []		Calibration Procedure	[]	T st Procedures/Specification		
Conceptual Design Repor	r []		Installation Procedure	ij	Component Index		
Equipment Spec			Maintenance Procedure		ASME Coded Item		
Const. Spec	==		Engineering Procedure		Human Factor Consideration		
Procurement Spec.	[]		Operating Instruction		Computer Software		
Vendor information	[]		Operating Procedure	[]	Electric Circuit Schedule		
OM Manual	[] []		Operational S fety Requirement		ICRS Procedure		
FSAR/SAR	[]		EFD Drawing		Process Control Manual/Plan		
Sefety Equipment List	[]		Cell Arrangement Drawing	[]	Process Flow Chart		
Radiation Work Permit	[]		Essential Material Specification		Purchase Regulation		
Environmental Impact St			Fac Proc, Samp. Schedule	[]	Tickler File		
Environmental Report	[]		Inspection Plan	[]	ii		
Environmental Permit	[]		Inventory Adjustment Request	ří	f1		
20 Other Affected Documents (NGTE Documents listed below will not be revised by this ECN) Signatures below indicate that the signing organization has been notified of other affected documents listed below Document Number/Revision Document Number Revision N/A							
21 Approvals		•					
	Signature	_	Date	•	nature Date		
Design Authority A	F Crahe Co-4-	تمسو	7 61-98	ign Agent Ar Cr	ene Of Care 92198		
Cog Eng	200	00	> PE				
Cog Mgr NJ Sulli	May Adm		4-11-10	ety			
QA Podobio	-			ign			
Safety Environ				iron			
Other			Oth				
Officer				••			
RJ Huth Informal Design Rev	new JA	版	922 98				
	V		nei	ARTMENT OF ENERG			
				nature or a Cont			
				cks the Approval			
				TTTOWAL			
				ITIONAL			
			·				
							

_


ENGINEE	RING CHANGE NO	TICE CONTINUATION SHEET
 		Page 3 of 27 Date 9/21/98
H-2-89033,	Sh I, Zone D-3	Replace ladder with starrway
H-2-89036,	Sh 1, Zone E-4	Replace ladder with stairway
H-2-89039,	Sh 1, Zone B-4	Replace ladder with stairway & show new sidewalk
	Zone E-4	Replace ladder with stairway
H-2-89040	Sh 1, Zone B-4	Replace ladder with stairway & show new sidewalk
	Zone E-4	Replace ladder with stairway
H-2-89044,	Sh 1, Zone B-4	Replace ladder with stairway & show new sidewalk
	Zone E-4	Replace ladder with stairway
H-2-89063,	ladder & crosso	Replace ladder with stairway Delete 8'-9" dimension and over centerline callout Change Section 4, Dwg 89069 i "See Section For Foundation Information"
H-2-89068,	dimensions, lan	Replace ladder with stairway Delete 10'-0" & 3'-5 1/2" ding and ladder & crossover centerline callout Change "See Section For Foundation Information" with reference to ction 4
H-2-89069,	callout Chang Foundation (Loc "Aluminum Pre-E	Add "minimum" to foundation width dimension (2'-0) ge foundation text to read "Ladder Or Stairway Concrete cate In Field)" Change ladder description text to read Engineered Ship Ladder With Platform & Return, O'Keefe's Fequal, Or Aluminum Pre-Engineered Stairway See VI Supprway Detail "
H-2-89078,	Sh 1, Zone A-7	Change detail title to "Ladder Or Stairway Step Off Pad"
	Zone B-6	Change callout to "Ladder Or Stairway" from "Ladder"
	Zone B-7	Add "minimum" to step off pad length dimension (38")
	Zone 8-8	Add "minimum" to step off pad width dimension (30")








0 165 ECN 641892 pg 6 of 27 H-2-89036 SH 1 Sass 9 169 ---- 0 169 -


ECW 641845 62 1 of 54

























ECN 647892 Pg 16 06 27




© PIPE (-)4'-6" BELOW GRADE · In


ECD 647892, pg 17 of 27




© PIPE (-)4'-6" BELOW GRADE



ECO 647892 Pg 19 of 27




ECN 647892 Pg ZI of 27 H 2 89063 SH I




(W) 22 ECS 647892 Pg 22 of 27


H-5-84068, 2H 1



H 2-89068, SH 1




l



14-2-89069 SH 1


50





ECN 647892 PG 25 of 27

7

ECON 647892 PG 26 OF ZY









SHIP'S LADDER PLAN VERIFICATION TANK

8

7

5





0	ENGINEERING	CHANGE NOTICE	ESSE	NTIA		
CPF /8	3 Originator a Name	Organization MSIN	4 USQ Requ		5 Date	
(mark one)	and Telephone No				Į	
Supplemental (X) Direct Revision []		0/S6 71/376 4460	[] Yes [X] No 7 Bldg/Sys/Fac No		May 13 1997 8 Approval Designator	
Change ECN []	6 Project Title/No /Work Order No		2025E/59A 60M/			
Temporary [] Standby []	Misc Mods and As Builts for ETF Load In Station		200 Area ETF		NA I	
Supersedure [] Cancel/Void []	9 Document Numbers		10 Related ECN No(s)		11 Related PO No	
Cancer/void []	(includes sheet n	no and rev)	N/A			
	See B	lock 13A			NA NA	
12a Modification Work	12b Work Package	12c Modification Work (Complete		red to Original Condi or Standby ECN only)	
[X] Yes (fill out Blk	EL 96 00208			riou (temb	NA	
12b)	EL 97 00343					
[] No (NA Blks 12b 12c 12d)		Design Authority/Cog Signature & Da			uthority/Cog Engineer	
12a Description of Chance	_ <u>l</u>			1/3 F	No.	
13a Description of Change This ECN implements		13b Pesign Baseline changes	pocument? [∧j tes į	#O	
Add drain linAdd bell reduReplace Fact	mes and valves to ucer funnels and ulity with Sta- tus of Load In S and Jointing meth of M 9 Install ME B31 3 and Add	inspect and test	n of Load In drawing Essentia quirements	In Static g titles l or Suppo s of Hanfo	ort ord Site piping	
14a Justification (mark o						
Criteria Change []	Design Improvement	[X] Environmental	[]	Facili	ty Desctivation []	
As Found [X]	Facilitate Const	[] Const Error/O	mission []	Design	Error/Omission []	
As build mample vous Add drain lines an Add bell reducer in Replace facility? 200 Area ETF rath identify status of the Add to the Ad	te in transfer line fr sive and tanker vent v nd valves to Loed In S funnels and valving to with Station in dr her than a stand alone f Loed In Station draw name MSIN and no o R J Micklas A K Yoakum S P Biglin	uings to Essential or Supp of copies) S6 72 1 S6 71 1 S6 74 1	control roved contami Station pump he status of	nation contro the Load In S priate		
C M Towne S6 74 1 J L Vigue S6 74 1	S S Darling	56 74 1 \$6 72 1 \$6 71 1	Ī	PATE	HAMFORD	
J F Berger S6 74 1 T W Dellas S6 71 1 (* Advance Copies)			j	eta:	RELEASE	

A 7900 013 2 (05/96) GEF095

FN	IGINEERING C	HANGE NOT	ICE			no from pg 1)
				Page 2 of		
16 Design Verification Required	17 Cost Impact ENGII	HEERING N	4 con	STRUCTION	18 Schedule I	npact (days) NA
[X] Yes	Additional	[] \$	Additional	[] \$	Improvement	[]
[] No	Savings	[] \$	Savings	[] \$	Detay	[]
19 Change Impact R that will be af SDD/DD	eview Indicate fected by the ch	enge described		n the engineering or the affected doc []	documents identifi ument number in Bi Tank Calibration Ma	ock 20
Functio al Design Criterio	• []	Stress/	De ign Report	[]	Health Physics Proc	edure []
Operating Specification	[]	Interfec	e Control Drawing	[]	Spares Multiple Unit	Listing []
Criticality Specification	[]	Calibrat	tion Procedure	[]	Test Procedures/Spe	ecification []
Conceptual Design Repor	¹ []	inetalla	tio Procedure	[]	Component Inde	[X]
Equipment Spec	[]	Mainter	nance Procedute	[]	ASME Coded Item	[]
Const Spec	[]	Enginee	ring Procedure	[]	H man Facto Consi	deration []
Procurement Spec	[]	Operati	ng Instruction	[]	Computer Software	[]
Vendo information	[X]	Operati	ng Procedure	[]	Electric Circuit Sche	dule []
OM Menual	[]	Ope eti	onal Safety Requiremen	" []	ICRS Procedure	[]
FSAR/SAR	[]	IEFD D	rewing	[]	Process Control Mar	tuel/Plan
Sefety Equipment List	[]	Cell Arr	angement Drawing	[]	Process Flow Chart	[]
Rediet o Work Permit	[]	Essenti	al Material Specificatio	[]	Purchase Requisition	· []
Environmental Impact Sta	etement []	Fac Pro	oc Samp Schedule	[]	Tickler File	[]
Environmental Report	ĒĴ	Inspect	ion Plan	(j		[]
Environmental Permit	ĬΪ	invento	ry Adjustment Request	ĒĴ		[]
JCS Data	indicate that the signing organization has been notified of other affected documents listed below Document Number/Revision Document Number/Revision Document Number Revision JCS Database (Component Index)					
21 Approvals Design Authority Cog Eng R N Cog Mgr R J DA	Signature R H Wagner Wagner Wickies 4	The For	5/22/97 5/22/97 5/23-17	Design Agent PE QA Safety	insture	Date
Safety				Design		
Environ				Environ		
Other				Other		
				DEDIGTHENT OF ENER	acv	
				DEPARTMENT OF ENER Signature or a Cor tracks the Approva	ntrol Number that	
				ADDITIONAL		
						

Page 3 of 24

ECN 641703 Date 5/13/97

Documents changed by this ECN (also see attached drawing changes)

```
H 2 88766
            Sheet 4 Rev
H 2 88779
           Sheet 4 Rev
         Sheet 1
Sheet 4
H 9 203
                  Rev 0
  9 203
Н
                   Rev 0
H 2 817968
            Sheet 1
                      Rev
H 2 817969
             Sheet 1
                      Rev
  2 817969
             Sheet 2
                      Rev
Н
  2 817969
             Sheet 3
                      Rev
  2 817969
             Sheet 4
                      Rev
  2 817969
Н
             Sheet 5
                      Rev
  2 817970
Н
             Sheet 1
                      Rev
  2 817970
Н
             Sheet 2
                      Rev
  2 817971
Н
             Sheet 1
                      Rev
  2 817971
             Sheet 2
                      Rev
  2 817972
             Sheet 1
Н
                      Rev
  2 817973
             Sheet 1
Н
                      Rev
H 2 817974
             Sheet 1
                      Rev
H 2 817975
H 2 817976
             Sheet 1
                      Rev
             Sheet 1
                      Rev
  2 817977
             Sheet 1
H
                      Rev
  2 817978
Н
             Sheet 1
                      Rev
  2 817980
Н
             Sheet 1
                      Rev
H 2 817981
             Sheet 1
                      Rev
H 2 817981
             Sheet 2
                      Rev
  2 817981
             Sheet 3
                      Rev
  2 817981
             Sheet 4
Н
                      Rev
Н
  2 817981
             Sheet 5
                      Rev
  2 817983
             Sheet 1
                      Rev
  2 817983
             Sheet 2
                      Rev
  2 817983
             Sheet 3
Н
                      Rev
  2 817983
             Sheet 4
                      Rev
  2 817983
             Sheet 5
                      Rev
  2 817983
             Sheet 6
                      Rev
H 2 817983
             Sheet 7
                      Rev
H 2 817983
             Sheet 8
                      Rev
  2 817985
             Sheet 1
                      Rev
  2 817985
             Sheet 2
                      Rev
  2 817987
             Sheet 1
Н
                      Rev
  2 817987
             Sheet 3
                      Rev
  2 817987
             Sheet 4
                      Rev
  2 817988
             Sheet 1
                      Rev
  2 817988
             Sheet 2
                      Rev
  2 817988
             Sheet 3
                      Rev
  2 817989
             Sheet 1
                      Rev
Н
  2 817990
             Sheet 1
                      Rev
H 2 817991
             Sheet 2
                      Rev
```


^{(*} Title and/or Essential/Support status is changed for these drawings per this ECN)

Page H of 24

ECN 641703 Date 5/13/97

H 2 88766, Sheet 4, Rev 2, Zone D 2


IS



Page 5 of 24

ECN 641703 Date 5/13/97

H 2 88766, Sheet 4, Rev. 2, Zone D 2




Page 6 of 24

ECN 641703 Date 5/13/97

H 2 88779. Sheet 4. Rev. 0. Zone B 2


IS



Page 7 of 24

ECM 641703 Date 5/13/97

H 2 88779, Sheet 4, Rev. 0, Zone B 2




Page 8 of 24

ECN 641703 Date 5/13/97

Sketch for 3 spacer shown in above changes to H 2 88779 and H 2 88766

3 FLANGE SPACER FOR ECN 641703



T = 1/8 PLATE THICKNESS

A = 2 (APPROX) B = 3 (APPROX)

D = 300 + / - 05R = 525 + / - 05


MATERIAL = 304SS FLANGE CLASS = 150 LB

Page 9 of 24

ECN 641703 Date 5/13/97

H 2 817974, Sheet 1, Rev. 2, Zone C 5

IS




ENGINEERING	CHANGE NOTICE	CONTINUATION SHEET
LITORIELLINIAG	CHAILSE ITO HOL	

Page 10 of 24

ECN 641703 Date 5/13/97

H 2 817974. Sheet 1. Rev. 2. Zone C 5




Page II of 24

ECN 641703 Date 5/13/97

H 2 817974. Sheet 1, Rev. 2. Zone C 7 to D 7


IS



Page 12 of 24

ECN 641703 Date 5/13/97

H 2 817974, Sheet 1, Rev. 2, Zone C 7 to D 7




Page 13 of 24

ECN 641703 Date 5/13/97

H 9 203, Sheet 1, Rev. 0, Zone E 6

IS




CNONCEDING	CHARGE NOTICE	CONTRIBITATION	CHECT
ENGINEERING	CHANGE NOTICE	CUNIINUAIIUN	SHEEL

Page 14 of 24

ECN 641703 Date 5/13/97

H 9 203. Sheet 1. Rev. 0. Zone E 6




Page 15 of 24

ECN 641703 Date 5/13/97

H 9 203, Sheet 4, Rev 0, Zone D 7

IS




DETAIL 16 C6-2

ENGINEERING	CHANGE	NOTICE	CONTINUATION	SHEET
CHRIMEEVIIAR	CHANGE	MOLICE	COIL HILDY HOLE	ONEEL

Page 16 of 24

ECN 641703 Date 5/13/97

H 9 203, Sheet 4, Rev. 0, Zone D 7



Page 17 of 24

ECN 641703 Date 5/13/97

H 2 817968. Sheet 1, Rev 1. Title

IS

ETF TRUCK LOAD IN FACILITY LOCATION PLAN & DWG LIST

CHANGE TO

ETF TRUCK LOAD IN STATION LOCATION PLAN & DWG LIST

Drawing Status ESSENTIAL

H 2 817969. Sheet 1. Rev. 1. Title

IS

CIVIL ETF TRUCK LOAD IN FACILITY SITE PLAN

CHANGE TO

CIVIL ETF TRUCK LOAD IN STATION SITE PLAN

Drawing Status SUPPORT

H 2 817969. Sheet 2. Rev. 1. Title

IS

CIVIL ETF TRUCK LOAD IN FACILITY PLAN AND PROFILES

CHANGE TO

CIVIL ETF TRUCK LOAD IN STATION PLAN AND PROFILES

Drawing Status SUPPORT

H 2 817969, Sheet 3, Rev. 1, Title

IS

CIVIL ETF TRUCK LOAD IN FACILITY ENLARGED PLAN

CHANGE TO

CIVIL ETF TRUCK LOAD IN STATION ENLARGED PLAN

Drawing Status SUPPORT

H 2 817969, Sheet 4, Rev 1, Title

IS

CIVIL ETF TRUCK LOAD IN FACILITY MISCELLANEOUS DETAILS

CHANGE TO

CIVIL ETF TRUCK LOAD IN STATION MISCELLANEOUS DETAILS

Page 18 of 24

ECN 641703 Date 5/13/97

H 2 817969, Sheet 5, Rev 1, Title

IS

CIVIL ETF TRUCK LOAD IN FACILITY MISCELLANEOUS DETAILS

CHANGE TO

CIVIL ETF TRUCK LOAD IN STATION MISCELLANEOUS DETAILS

Drawing Status SUPPORT

H 2 817970, Sheet 1, Rev. 1, Title

IS

STRUCTURAL ETF TRUCK LOAD IN FACILITY PLAN AND SECTIONS

CHANGE TO

STRUCTURAL ETF TRUCK LOAD IN STATION PLAN AND SECTIONS

Drawing Status SUPPORT

H 2 817970, Sheet 2. Rev. 1. Title

IS

STRUCTURAL ETF TRUCK LOAD IN FACILITY SECTIONS AND DETAILS

CHANGE TO

STRUCTURAL ETF TRUCK LOAD IN STATION SECTIONS AND DETAILS

Drawing Status SUPPORT

H 2 817971, Sheet 1. Rev. 1. Title

IS

STRUCTURAL ETF TRUCK LOAD IN FACILITY STEEL PLAN & SECTIONS

CHANGE TO

STRUCTURAL ETF TRUCK LOAD IN STATION STEEL PLAN & SECTIONS

Drawing Status SUPPORT

H 2 817971, Sheet 2, Rev 1, Title

IS

STRUCTURAL ETF TRUCK LOAD IN FACILITY STEEL DETAILS

CHANGE TO

STRUCTURAL ETF TRUCK LOAD IN STATION STEEL DETAILS

Page 19 of 24

ECN 641703 Date 5/13/97

H 2 817972. Sheet 1. Rev. 1. Title

IS

STRUCTURAL ETF TRUCK LOAD IN FACILITY SECTIONS AND DETAILS

CHANGE TO

STRUCTURAL ETF TRUCK LOAD IN STATION SECTIONS AND DETAILS

Drawing Status SUPPORT

H 2 817973. Sheet 1. Rev 1. Title

IS

STRUCTURAL ETF TRUCK LOAD IN FACILITY MISC SECTIONS AND DETAILS

CHANGE TO

STRUCTURAL ETF TRUCK LOAD IN STATION MISC SECTIONS AND DETAILS

Drawing Status SUPPORT

H 2 817974. Sheet 1. Rev 2. Title

IS

P & ID ETF TRUCK LOAD IN FACILITY

CHANGE TO P & ID ETF TRUCK LOAD IN STATION

Drawing Status ESSENTIAL

H 2 817975. Sheet 1. Rev. 1. Title

IS

PIPING ETF TRUCK LOAD IN FACILITY PLAN

CHANGE TO PIPING ETF TRUCK LOAD IN STATION PLAN

Drawing Status ESSENTIAL

H 2 817976, Sheet 1, Rev 1, Title

IS

PIPING ETF TRUCK LOAD IN FACILITY SECTIONS AND DETAILS

CHANGE TO

PIPING ETF TRUCK LOAD IN STATION SECTIONS AND DETAILS

Page 25 of 21

ECN 641703 Date 5/13/97

H 2 817977. Sheet 1. Rev. 1. Title

IS

PIPING ETF TRUCK LOAD IN FACILITY DETAILS

CHANGE TO

PIPING ETF TRUCK LOAD IN STATION DETAILS

Drawing Status SUPPORT

H 2 817978. Sheet 1. Rev. 1. Title

IS

PIPING ETF TRUCK LOAD IN FACILITY PIPE SUPPORTS

CHANGE TO

PIPING ETF TRUCK LOAD IN STATION PIPE SUPPORTS

Drawing Status SUPPORT

H 2 817980. Sheet 1. Rev. 1. Title

IS

INSTRUMENTATION ETF TRUCK LOAD IN FACILITY LEGEND & SYMBOLS

CHANGE TO

INSTRUMENTATION ETF TRUCK LOAD IN STATION LEGEND & SYMBOLS

Drawing Status SUPPORT

H 2 817981. Sheet 1. Rev 1. Title

IS

INSTRUMENTATION ETF TRUCK LOAD IN FACILITY LOOP DIAGRAM

CHANGE TO

INSTRUMENTATION ETF TRUCK LOAD IN STATION LOOP DIAGRAM

Drawing Status SUPPORT

H 2 817981. Sheet 2. Rev. 1. Title

IS

INSTRUMENTATION ETF TRUCK LOAD IN FACILITY LOOP DIAGRAM

CHANGE TO

INSTRUMENTATION ETF TRUCK LOAD IN STATION LOOP DIAGRAM

ENGINEERING CHANGE NOTICE CONTINUATION SHEET

Page of 24

ECN 641703 Date 5/13/97

H 2 817981. Sheet 3. Rev. 1. Title

IS

INSTRUMENTATION ETF TRUCK LOAD IN FACILITY LOOP DIAGRAM

CHANGE TO INSTRUMENTATION ETF TRUCK LOAD IN STATION LOOP DIAGRAM

Drawing Status SUPPORT

H 2 817981, Sheet 4, Rev. 1, Title

IS

INSTRUMENTATION ETF TRUCK LOAD IN FACILITY LOOP DIAGRAM

CHANGE TO

INSTRUMENTATION ETF TRUCK LOAD IN STATION LOOP DIAGRAM

Drawing Status SUPPORT

H 2 817981. Sheet 5. Rev. 1. Title

IS

INSTRUMENTATION ETF TRUCK LOAD IN FACILITY LOOP DIAGRAM

CHANGE TO

INSTRUMENTATION ETF TRUCK LOAD IN STATION LOOP DIAGRAM

Drawing Status SUPPORT

H 2 817983. Sheet 1. Rev. 0. Title

CHANGE TO Drawing Status SUPPORT

H 2 817983. Sheet 2. Rev 1. Title

CHANGE TO Drawing Status SUPPORT

H 2 817983. Sheet 3. Rev. 0. Title

CHANGE TO SUPPORT Drawing Status

H 2 817983, Sheet 4, Rev 1. Title

CHANGE TO Drawing Status SUPPORT

H 2 817983. Sheet 5. Rev 0. Title

CHANGE TO Drawing Status SUPPORT

ENGINEERING CHANGE NOTICE CONTINUATION SHEET

Page Dof 24

ECN 641703 Date 5/13/97

H 2 817983, Sheet 6, Rev. 1, Title

CHANGE TO

Drawing Status SUPPORT

H 2 817983. Sheet 7. Rev. 0. Title

CHANGE TO Drawing Status SUPPORT

H 2 817983. Sheet 8. Rev. 0. Title

CHANGE TO Drawing Status SUPPORT

H 2 817985. Sheet 1. Rev. 1. Title

INSTRUMENTATION ETF TRUCK LOAD IN FACILITY SECTIONS AND DETAILS

CHANGE TO INSTRUMENTATION ETF TRUCK LOAD IN STATION SECTIONS AND DETAILS

Drawing Status SUPPORT

H 2 817985. Sheet 2. Rev. 1. Title

IS INSTRUMENTATION ETF TRUCK LOAD IN FACILITY SECTIONS AND DETAILS

CHANGE TO INSTRUMENTATION ETF TRUCK LOAD IN STATION SECTIONS AND DETAILS

Drawing Status SUPPORT

H 2 817987, Sheet 1, Rev. 1, Title

IS ELECTRICAL ETF TRUCK LOAD IN FACILITY SITE PLAN

CHANGE TO ELECTRICAL ETF TRUCK LOAD IN STATION SITE PLAN

Drawing Status SUPPORT

H 2 817987, Sheet 3, Rev. 1, Title

IS ELECTRICAL ETF TRUCK LOAD IN FACILITY SECTIONS & DETAILS

CHANGE TO ELECTRICAL ETF TRUCK LOAD IN STATION SECTIONS & DETAILS

Drawing Status SUPPORT

ENGINEERING CHANGE NOTICE CONTINUATION SHEET

Page 23 of 24

ECN 641703 Date 5/13/97

H 2 817987, Sheet 4, Rev. 1, Title

IS

ELECTRICAL ETF TRUCK LOAD IN FACILITY SECTIONS & DETAILS

CHANGE TO

ELECTRICAL ETF TRUCK LOAD IN STATION SECTIONS & DETAILS

Drawing Status SUPPORT

H 2 817988. Sheet 1. Rev. 1. Title

IS

ELECTRICAL ETF TRUCK LOAD IN FACILITY PLAN ONE LINE & DETAILS

CHANGE TO

ELECTRICAL ETF TRUCK LOAD IN STATION PLAN ONE LINE & DETAILS

Drawing Status ESSENTIAL

H 2 817988, Sheet 2, Rev. 1, Title

IS

ELECTRICAL ETF TRUCK LOAD IN FACILITY PLAN GND & HEAT TRACING

CHANGE TO

ELECTRICAL ETF TRUCK LOAD IN STATION PLAN GND & HEAT TRACING

Drawing Status ESSENTIAL

H 2 817988, Sheet 3, Rev. 1, Title

IS

ELECTRICAL ETF TRUCK LOAD IN FACILITY PANEL SCHEDULE & DETAILS

CHANGE TO

ELECTRICAL ETF TRUCK LOAD IN STATION PANEL SCHEDULE & DETAILS

Drawing Status ESSENTIAL

H 2 817989, Sheet 1, Rev 1, Title

IS

ELECTRICAL ETF TRUCK LOAD IN FACILITY ELEMENTARY DIAGRAM

CHANGE TO

ELECTRICAL ETF TRUCK LOAD IN STATION ELEMENTARY DIAGRAM

Drawing Status ESSENTIAL

ENGINEERING CHANGE NOTICE CONTINUATION SHEET		ECN 641703	
ENGINEERING CHANGE NOTICE CONTINOATION SHEET	Page 24 of 24	Date 5/13/97	
II A 017000 Chart 1 Day 1 Title			

H 2 817990. Sheet 1. Rev. 1. Title

IS ELECTRICAL ETF TRUCK LOAD IN FACILITY WIRE & CONDUIT SCHEDULE

CHANGE TO ELECTRICAL ETF TRUCK LOAD IN STATION WIRE & CONDUIT SCHEDULE

Drawing Status ESSENTIAL

H 2 817991, Sheet 2. Rev 1. Title

IS ELECTRICAL ETF TRUCK LOAD IN FACILITY TELECOMMUNICATIONS

CHANGE TO ELECTRICAL ETF TRUCK LOAD IN STATION TELECOMMUNICATIONS

Drawing Status SUPPORT

ENGINEERING CHANGE NOTICE

647247 1 ECN


Page 1 of 10


Proj. ECN


2 ECN Category (mark one)	3 Originator's Name Organd Telephone No	anization MSIN	4 USQ Require	:d ⁹	5 Date
, ,	RN Wagner/32230/S	6 72/376-4460	[] Yes [X] N	0	August 27 1998
Supplemental [X] Direct Revision []	6 Project Title/No /Work		7 Bldg./Sys./Fa		8 Approval Designator
Change ECN []	Install Tent Over ET	F Load In Station/A4055	2025E0		NA NA
Temporary [] Standby			200 An	ea ETF	ļ
Supersedure [] Cancel/Void []	9 Document Numbers Ch (includes sheet no and r		10 Related EC	N No(s)	11 Reinted PO No
	f '	Block 13	l N	A	NA I
12a. Modification Work	12b Work Package	12c Modification Work Compl			to Original Condi-
	No	1		tion (Temp or	Standby ECN only)
[X] Yes (fill out Blk 12b)	EL-97-00853		i	ı	N/A
[] No (NA Biks 12b		Design Authority/Cog.		Des gr	Authority/Cog Engineer
12¢ 12d)		Signature & Dat	e		Signature & Date
13a. Description of Change	13b I	Design Baseline Document? [X]	res []No		
This ECN installs a tent ov			- -	eather Mech	anical modifications to
the Load In Station necess					
		·			
Drawings affected are					
 H 2 817970 Sheet 1 F 					ţ
 H 2 817972 Sheet 1 F 					į
/ H 2 817975 Sheet 1 F					
H 2 817976 Sheet 1 F	Rev 1				!
			1 111 221	DO10045404	
Concrete anchor bolts for r					
KB II SS 58 812 Ext Trd					
of Piping Specification Cla Addenda for Category D fl		i, and test the new piping in	stanation in ac	cordance with	ASME B31 3 and
Addenda for Category D if	nig selvice				1
(Block 13a continued on P	age 3)				[
				 	
14a. Justification (mark one) Criteria Change	Design (manuscrip	[X] Environmental	п	Enalth	Description []
	Design Improvement		D	•	Deactivation []
As-Found []	Fecilitate Const	[] Const Error/Omis	sion []	Design	Error/Omussion []
14b Justification Details					
The tent will provide shelte	er to ensure operator sat	ery and allow continuity of	operations dur	ing inclemen	weather
]
					•
15 Distribution (include name M	SIN and no of copies)			- K	9999(5)>3>3V(1)
N J S Ilivan S6-72	J E Gearv	S6-71 l			
AK Yoskum S6-71	E A McNamar	S6-72 1		1	
_	2 M W Bowman	S6-72 I		DATE	/
	TWDallas DLTubbs	S6-74 1 S6-74 1			HAMFORD
D L Flyckt S6-71	I C M Town	S6-74 I		87A	
(= 1 Advance Copy)	IPE 7	5672 1		SED O	8 1998
	IPF 4 -	H6-26 1		VEF U	ש שבנו ס


				1 ECN (use no	from pg 1)
E	NGINEERING CH	ANGE NOTICE	Page 2 of 1 C	> 647247	
16 Design Verification	17 Cost Impect — ENGINEE	NA C	INSTRUCTION	18 Sched 1 Impact (day	, ,
Required [X] Yes	Additional	[] \$ Additional	[] \$	Improvement	n
[] No	Savings	[] S Savings	<u> </u>	Delay	Ö
this writt be affected by SDD/DD Functional Disago Criteria Operating Specification Criticality Specification Conceptual Disagn Report Equipment Spec Const Spec. Procurement Spec. Vendor Information	the ch described in P [NA] [NA] [NA] [NA] [NA] [NA] [NA] [NA]	cuments (other than the engineering de Lock 13 Enter the affected document Susse/Stress Analysis Stress/Dengs Rapon Inserface Control Drawing Calibration Procedure i aliston Procedure Maintenance Procedure Engineering Procedure Operating Instruction Operating Procedure	number in Block 20 [NA] [NA] [NA] [NA] [NA] [NA] [NA] [NA]	Tank Calibration Manual Health Physics Procedure Sparse Multiple Unit Lating Test Procedures/Specification Compound Index ASME Coded Item Human Factor Consideration Computer Software Electric Circuit Schadule	[AN] [AN] [AN] [AN] [AN] [AN] [AN] [AN]
OM Marsial	[NA]	Operational Safety Requirement	[NA]	ICRS Procedure	[NA]
FSAR/SAR	[NA]	TEFD Drawing	[NA]	Process Control Mensel/Plan	[NA]
Safety Equipment Last	[NA]	Cell Arrangement Drawing	[NA]	Process Flow Chart	[NA]
Radiation Work Permit	[NA]	Essential Material Specification	[NA]	Purchase Requisition	[NA]
Environmental Impact Statement	[NA]	Fac. Proc Samp Schedule	[NA]	Tickier Pile	[NA]
Environmental Report	[NA]	Inspection Plan	[NA]		Ö
Environmental Perset			[]		1.3
		Inventory Adjustment Request		,	П
mdicate that the signing Document No	ments (NOTE Documen		hss ECN) Signatures belowed below	Document Number R	
mdicate that the signing Document No No eth deco	s gnature Wagner Wagner S gnature Wagner Wagner Magner Ma	its listed below will not be revised by to tified of other affected documents list Document Number/l	his ECN) Signatures below de below Revision	Document Number R	

ECN 647247 - 8/27/98
Page 3 of 10
Block 13a Cont d
H 2-817970 Sh 1 Rev 1
Zones A3-F6
IS NOW











5 H 2 817977 C TEE

VIDT M9
LOAD-IN/OUT FRAME
SEE DRAWING H 2 817972


TIGAD-IN/OUT M9 H 9 203 SAFETY SHOWERZEYE WASH 3 H 2 817912 6 H 2-817977 HOSE REEL SWING MOUNT TYPE W/100 5/8

ECN 647247 - 8/27/98
Page 7 of 10
Block 13a Cont d
H 2-817975 Sh 1 Rev 5
Zones A3-F5
IS NOW





B SECTION H-2-817975 SCALE 3/8 = 1 -0 ECN 647247 - 8/27/98
Page 9 of 122
Block 13a Cont d
H 2-817976 Sh 1 Rev 1
Zones A4-D6
IS NOW



B SECTION H-2-817975 SCALE 3/8 =1 -0 Page 10 of 102 Block 13a Cont d H 2 817976 Sh 1 Rev 1